

August 24, 1989

L.V. Pavement	6353.2
Sand fencing needs repair	6355.2
25 MPH Sign (next 63 mi.)	6355.8
Sand fencing needs repair	6356.3
4 Wheel Dr. Sign	6358.0
Amaco En France	6359.2

There has been a caterpillar in here.

Parked by the beach along with flat bed truck.

10:49 Arrived at site

Pumping truck that is pumping out the pond.

Almost complete WHP 270

craft

Nueces Vacuum Services Robstown, Tx

Kenagy was the person I talked to He said:

"I don't know how that oil got in there."

"One of the 'bigshots' from Amaco came down yesterday and told us to get it cleaned up"

"The smell wasn't like something we make."

It smelled more like paint thinner."

The site was freshly painted last week. on my first trip. August 12.

Kenagy also said they tested the water coming out of the pipe and it was "clean".

The vegetation seems to be making a comeback. While I was here, the dozer came in but

did no work - 15 minutes later they all had left.

I will take water, soil, & insect samples.

Water Pipe is filling of drinking cup (6oz) every 9 sec. DLB

