

Pecos National Historical Park
Trading Post Restoration Project

Photo Sheet 1

Image No.	Unit	Notes	Direction	Date
001	PW1W1	Hand-hewn lintel	up	7/21/10
002	PW1W1	Window opening	E	7/21/10
003	PW1W1	Existing adobes, north side of opening	N	7/21/10
004	PW1W1	Existing adobes, north side of opening	N	7/21/10
005	PW1W1	Existing adobes, south side of opening	S	7/21/10
006	PW1W1	Existing adobes, south side of opening	S	7/21/10
007	PW1W1	Hand-hewn lintel	up	7/21/10
008	PW1W1	Existing adobes below sill, exterior	E	7/22/10
009	PW1W1	Possible continuous handhewn element ⁱ	E	7/22/10
010	PW1W1	“	E	7/22/10
011	PW1W1	“	E	7/22/10
012	PW1W2	Existing adobes, north side of opening	N	7/22/10
013	PW1W2	Existing adobes, north side of opening	N	7/22/10
014	PW1W2	Existing adobes, south side of opening	S	7/22/10
015	PW1W2	Existing adobes, south side of opening	S	7/22/10
016	PW1W2	Hand-hewn lintel	up	7/22/10
017	PW1W2	Hand-hewn lintel, detail	E	7/22/10
018	PW1W2	Hand-hewn lintel, detail	E	7/22/10
019	PW1W2	Window opening, exterior, prior to repair work.	E	7/22/10
020	PW1W2	Adobes below sill, exterior, prior to repair	E	7/22/10

Photographer: Sebastian Renfield

Pecos National Historical Park
Trading Post Restoration Project

Photo Sheet 2

Image No.	Unit	Notes	Direction	Date
021	PW1W1	Adobes below sill, interior, prior to repair	W	7/22/10
022	E1W2	Existing adobes, south side of window opening	S	7/22/10
023	E1W2	Existing adobes, south side of window opening	S	7/22/10
024	E1W2	Existing adobes, north side of window opening	N	7/22/10
025	E1W2	Existing adobes, north side of window opening	N	7/22/10
026	E1W2	Window opening, exterior, prior to repair	W	7/22/10
027	N1W1	Existing adobes, east side of window opening	E	7/22/10
028	N1W1	Existing adobes, west side of window opening	W	7/22/10
029	N1W1	Damaged adobes below sill, interior, prior to repair	N	7/22/10
030	N1W1	Exterior view of opening prior to repair	S	7/22/10
031	N1W1	Interior view of opening after installation of new adobes	N	7/23/10
032	N1W1	New adobes below sill, interior	N	7/23/10
033	PW1W1	Interior view, new adobes	W	7/23/10
034	PW1W1	Interior view, new adobes below sill	W	7/23/10
035	N1W1	Oblique view, new adobes below sill	NW	7/23/10
036	PW1W4	Lintels	up	7/29/10
037	PW1W4	Lintel detail	NE	7/29/10
038	PW1W4	Existing adobes, south side of window opening	S	7/29/10
039	PW1W4	Existing adobes, south side of window opening	S	7/29/10

Photographer: Sebastian Renfield

Image No.	Unit	Notes	Direction	Date
040	PW1W4	Existing adobes, north side of window opening	N	7/29/10
041	PW1W4	Existing adobes, north side of window opening	N	7/29/10
042	PW1W4	Window opening, exterior view, prior to repair	E	7/29/10
043	PW1W4	Below sill, exterior, prior to repair	E	7/29/10
044	PW1W4	Below sill, exterior, prior to repair	down	7/29/10
045	PW1W4	Window opening, interior view, prior to repair	W	7/29/10
046	PW1W2	Replacement lintel	up	7/29/10
047	PW1W2	Replacement lintel, interior view	W	7/29/10

Photographer: Sebastian Renfield

ⁱ One of the two side-by-side lintels observed over both PW1W1 and W1W2 is a hand-hewn timber. Based on the dimensions and appearance of both lintels and the height and surface contour of the door lintel between the two window openings, it is possible that the wall above all three openings is supported by a single rough-hewn timber.