



Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 1 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

SOLD TO

NATIONAL PARK SERVICE
3100 NATIONAL PARK RD
JUNEAU, AK 99801, United States

SHIP TO

NATIONAL PARK SERVICE
3100 NATIONAL PARK RD
JUNEAU, AK 99801, United States

CERTIFICATE OF COMPLIANCE

This is to certify that the materials, processes and finished products were controlled, tested, and accepted in accordance with our quality system and the applicable specifications.

Ron Geis
Vice President & General Manager

PICKUP DATE	PAYMENT TERMS	FREIGHT TERMS	SR NUMBER	F.O.B	TAX NAME	TAX NO.	Supplier No.
03-MAR-14	Net 30 Days	Prepaid	303251	Shipping Point	Exempt		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
10.1	R6136	651004		CREDIT CARD		Repair, Model 6136 6136 TURBIDITY PROBE SN#10C101562 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. UPDATED MOTOR ASSEMBLY REPLACED QUAD SEAL. REPLACED O-RINGS. TEST WIPER FUNCTION, NO DEFECT FOUND. PROBE READS: 125.6 IN 126 STANDARD ON THE UNCAL. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
12.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100353	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 2 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPORTED SYMPTOM: ANNUAL MAINTENANCE. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND. TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#11H100545) TEMPERATURE READS 18.95°C IN A 19.065°C BATH WITH A CELL CONSTANT OF 4.9519 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#13A) NO DEFECT FOUND. READINGS BELOW: 7: -21.5MV 10: -188.4MV 4: 146.6MV SLOPE: 166.9MV REPLACED ALL O-RINGS AS PART OF PM. MEETS YSI SPECIFICATIONS.					
14.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#08H101103 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 3 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.					
16.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#10E102022 REPORTED SYMPTOM: SENT IN FOR CHECKUP. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
2.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100354 REPORTED SYMPTOM: ANNUAL MAINTENANCE. ALSO INCLUDED ODO SENSOR FOR EVAL. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 4 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#13A100461) TEMPERATURE READS 22.07°C IN A 22.089°C BATH WITH A CELL CONSTANT OF 4.98947 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#11H) READINGS ARE OUT OF SPECS. NEED TO REPLACE PH PROBE (PART#006561) REPLACED ALL O-RINGS AS PART OF PM. REPLACED PH PROBE. NEW LOT#14A PH READINGS: 7: -0.9MV 10: -177.9MV 4: 173.0MV SLOPE: 177.0MV MEETS YSI SPECIFICATIONS.					
4.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#11E101714 REPORTED SYMPTOM: INCLUDED WITH SONDE FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
6.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100355	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 5 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPORTED SYMPTOM: ANNUAL MAINTENANCE. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND. TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#10F100521) TEMPERATURE READS 22.09°C IN A 22.109°C BATH WITH A CELL CONSTANT OF 4.82098 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#13A) NO DEFECT FOUND. READINGS BELOW: 7: -20.4MV 10: -188.1MV 4: 149.4MV SLOPE: 167.7MV REPLACED ALL O-RINGS AS PART OF PM. MEETS YSI SPECIFICATIONS.					
8.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#08H101102 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 6 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.					

GROSS WEIGHT(LB) : NET WEIGHT (LB) : VOLUME(CC) : TOTAL CARTONS: 0


ADDITIONAL INFO: Not Available

ADDITIONAL NOTE: Shipping Note: Invoice Note:

Tracking Number:

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 1 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

SOLD TO

NATIONAL PARK SERVICE
3100 NATIONAL PARK RD
JUNEAU, AK 99801, United States

SHIP TO

NATIONAL PARK SERVICE
3100 NATIONAL PARK RD
JUNEAU, AK 99801, United States

CERTIFICATE OF COMPLIANCE

This is to certify that the materials, processes and finished products were controlled, tested, and accepted in accordance with our quality system and the applicable specifications.

Ron Geis
Vice President & General Manager

PICKUP DATE	PAYMENT TERMS	FREIGHT TERMS	SR NUMBER	F.O.B	TAX NAME	TAX NO.	Supplier No.
03-MAR-14	Net 30 Days	Prepaid	303251	Shipping Point	Exempt		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
10.1	R6136	651004		CREDIT CARD		Repair, Model 6136 6136 TURBIDITY PROBE SN#10C101562 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. UPDATED MOTOR ASSEMBLY REPLACED QUAD SEAL. REPLACED O-RINGS. TEST WIPER FUNCTION, NO DEFECT FOUND. PROBE READS: 125.6 IN 126 STANDARD ON THE UNCAL. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
12.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100353	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List


Page 2 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPORTED SYMPTOM: ANNUAL MAINTENANCE. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND. TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#11H100545) TEMPERATURE READS 18.95°C IN A 19.065°C BATH WITH A CELL CONSTANT OF 4.9519 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#13A) NO DEFECT FOUND. READINGS BELOW: 7: -21.5MV 10: -188.4MV 4: 146.6MV SLOPE: 166.9MV REPLACED ALL O-RINGS AS PART OF PM. MEETS YSI SPECIFICATIONS.					
14.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#08H101103 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 3 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.					
16.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#10E102022 REPORTED SYMPTOM: SENT IN FOR CHECKUP. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
2.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100354 REPORTED SYMPTOM: ANNUAL MAINTENANCE. ALSO INCLUDED ODO SENSOR FOR EVAL. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 4 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#13A100461) TEMPERATURE READS 22.07°C IN A 22.089°C BATH WITH A CELL CONSTANT OF 4.98947 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#11H) READINGS ARE OUT OF SPECS. NEED TO REPLACE PH PROBE (PART#006561) REPLACED ALL O-RINGS AS PART OF PM. REPLACED PH PROBE. NEW LOT#14A PH READINGS: 7: -0.9MV 10: -177.9MV 4: 173.0MV SLOPE: 177.0MV MEETS YSI SPECIFICATIONS.					
4.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#11E101714 REPORTED SYMPTOM: INCLUDED WITH SONDE FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
6.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100355	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 5 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPORTED SYMPTOM: ANNUAL MAINTENANCE. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND. TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#10F100521) TEMPERATURE READS 22.09°C IN A 22.109°C BATH WITH A CELL CONSTANT OF 4.82098 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#13A) NO DEFECT FOUND. READINGS BELOW: 7: -20.4MV 10: -188.1MV 4: 149.4MV SLOPE: 167.7MV REPLACED ALL O-RINGS AS PART OF PM. MEETS YSI SPECIFICATIONS.					
8.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#08H101102 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 6 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.					

GROSS WEIGHT(LB) : NET WEIGHT (LB) : VOLUME(CC) : TOTAL CARTONS: 0


ADDITIONAL INFO: Not Available

ADDITIONAL NOTE: Shipping Note: Invoice Note:

Tracking Number:

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 1 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

SOLD TO

NATIONAL PARK SERVICE
3100 NATIONAL PARK RD
JUNEAU, AK 99801, United States

SHIP TO

NATIONAL PARK SERVICE
3100 NATIONAL PARK RD
JUNEAU, AK 99801, United States

CERTIFICATE OF COMPLIANCE

This is to certify that the materials, processes and finished products were controlled, tested, and accepted in accordance with our quality system and the applicable specifications.

Ron Geis
Vice President & General Manager

PICKUP DATE	PAYMENT TERMS	FREIGHT TERMS	SR NUMBER	F.O.B	TAX NAME	TAX NO.	Supplier No.
03-MAR-14	Net 30 Days	Prepaid	303251	Shipping Point	Exempt		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
10.1	R6136	651004		CREDIT CARD		Repair, Model 6136 6136 TURBIDITY PROBE SN#10C101562 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. UPDATED MOTOR ASSEMBLY REPLACED QUAD SEAL. REPLACED O-RINGS. TEST WIPER FUNCTION, NO DEFECT FOUND. PROBE READS: 125.6 IN 126 STANDARD ON THE UNCAL. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
12.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100353	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List


Page 2 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPORTED SYMPTOM: ANNUAL MAINTENANCE. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND. TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#11H100545) TEMPERATURE READS 18.95°C IN A 19.065°C BATH WITH A CELL CONSTANT OF 4.9519 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#13A) NO DEFECT FOUND. READINGS BELOW: 7: -21.5MV 10: -188.4MV 4: 146.6MV SLOPE: 166.9MV REPLACED ALL O-RINGS AS PART OF PM. MEETS YSI SPECIFICATIONS.					
14.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#08H101103 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 3 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.					
16.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#10E102022 REPORTED SYMPTOM: SENT IN FOR CHECKUP. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
2.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100354 REPORTED SYMPTOM: ANNUAL MAINTENANCE. ALSO INCLUDED ODO SENSOR FOR EVAL. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 4 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#13A100461) TEMPERATURE READS 22.07°C IN A 22.089°C BATH WITH A CELL CONSTANT OF 4.98947 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#11H) READINGS ARE OUT OF SPECS. NEED TO REPLACE PH PROBE (PART#006561) REPLACED ALL O-RINGS AS PART OF PM. REPLACED PH PROBE. NEW LOT#14A PH READINGS: 7: -0.9MV 10: -177.9MV 4: 173.0MV SLOPE: 177.0MV MEETS YSI SPECIFICATIONS.					
4.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#11E101714 REPORTED SYMPTOM: INCLUDED WITH SONDE FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.	9801.10.0000	EA	1	1	0
6.1	R6920V2	651004		CREDIT CARD		Repair, Model 6920V2 MODEL#6920V2-2 SN#08H100355	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 5 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPORTED SYMPTOM: ANNUAL MAINTENANCE. TEST AND CALIBRATE BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND. TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND. TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#10F100521) TEMPERATURE READS 22.09°C IN A 22.109°C BATH WITH A CELL CONSTANT OF 4.82098 PROBE READS ZERO SPCOND. IN AIR. TEST PH PROBE(SN#13A) NO DEFECT FOUND. READINGS BELOW: 7: -20.4MV 10: -188.1MV 4: 149.4MV SLOPE: 167.7MV REPLACED ALL O-RINGS AS PART OF PM. MEETS YSI SPECIFICATIONS.					
8.1	R6150	651004		CREDIT CARD		Repair, Model 6150 6150 ROX ODO PROBE SN#08H101102 REPORTED SYMPTOM: ATTACHED TO SONDE IN FOR PM. TEST AND CALIBRATE PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL.	9801.10.0000	EA	1	1	0

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

1700/1725 Brannum Lane
Yellow Springs OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

YSI
SonTek
Aanderaa
WaterLog / DAA
MJK

Packing List

Page 6 of 6

Delivery Number	Packing Slip Number	Date Shipped
1162454	YSI-346592	03-MAR-14
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						REPLACED O-RINGS. REPLACED MEMBRANE WITH PART#606155, LOT#14B100289 TEST WIPER FUNCTION, NO DEFECT FOUND. MEETS YSI SPECIFICATIONS.					

GROSS WEIGHT(LB) : NET WEIGHT (LB) : VOLUME(CC) : TOTAL CARTONS: 0

ADDITIONAL INFO: Not Available

ADDITIONAL NOTE: Shipping Note: Invoice Note:

Tracking Number:

-For terms and conditions refer to www.ysi.com/terms_conditions

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.

