


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



Isle Royale National Park Overview



Structure Groups	
Facility	Rock Harbor
Location	South Shore
Houghton	Tobin Harbor
North Shore	Washington Harbor
Passage Island	




0 50 100 Miles

Author: sszturm
8/25/2023 12:26 PM

Intermountain Region Geographic Resources Division
June 2023

Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project



Author: sszturm
8/25/2023 1:29 PM

0 500 Feet

Scale: 1:3,000



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Baggage Building, Houghton, B00603

Unit - Location: ISRO - Houghton

FMSS ID: 49666, **Local ID:**

Structure Type, Use: No Wildland Risk, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm (Virtual), July 12, 2023

Coordinates (DDM): 47° 07.36995924' N 088° 33.75454728' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Isle Royale NP HQ

Revisit Interval: 0 yrs

Map Label: 202

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane:

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Museum Storage, Houghton, Building

Unit - Location: ISRO - Houghton

FMSS ID: 49665, **Local ID:**

Structure Type, Use: No Wildland Risk, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm (Virtual), July 12, 2023

Coordinates (DDM): 47° 07.36880670' N 088° 33.76655118' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Isle Royale NP HQ

Revisit Interval: 0 yrs

Map Label: 201

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, 6in to 30in masonry exposed

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane:

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Houghton HQ Modular Office Building 02

Unit - Location: ISRO - Houghton

FMSS ID: 99495, **Local ID:**

Structure Type, Use: No Wildland Risk, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm (Virtual), July 12, 2023

Coordinates (DDM): 47° 07.36661034' N 088° 33.78753780' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Isle Royale NP HQ

Revisit Interval: 0 yrs

Map Label: 200

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane:

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Houghton HQ Modular Office Bldg. 01

Unit - Location: ISRO - Houghton

FMSS ID: 99492, **Local ID:**

Structure Type, Use: No Wildland Risk, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm (Virtual), July 12, 2023

Coordinates (DDM): 47° 07.36646304' N 088° 33.80560710' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Isle Royale NP HQ

Revisit Interval: 0 yrs

Map Label: 199

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane:

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Houghton HQ Modular office Building 03

Unit - Location: ISRO - Houghton

FMSS ID: 99496, **Local ID:**

Structure Type, Use: No Wildland Risk, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm (Virtual), July 12, 2023

Coordinates (DDM): 47° 07.36448442' N 088° 33.81481116' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Isle Royale NP HQ

Revisit Interval: 0 yrs

Map Label: 198

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane:

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Warehouse Garage Offices, Houghton, Building B00610

Unit - Location: ISRO - Houghton

FMSS ID: 49663, **Local ID:**

Structure Type, Use: No Wildland Risk, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm (Virtual), July 12, 2023

Coordinates (DDM): 47° 07.36355052' N 088° 33.83312838' W

Rating: No Wildland Risk

Protection Level: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Isle Royale NP HQ

Revisit Interval: 0 yrs

Map Label: 203

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane:

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Carpenter Shop/Boat Shop, Houghton, B00602

Unit - Location: ISRO - Houghton

FMSS ID: 49664, **Local ID:**

Structure Type, Use: No Wildland Risk, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm (Virtual), July 12, 2023

Coordinates (DDM): 47° 07.38186942' N 088° 33.85161192' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Isle Royale NP HQ

Revisit Interval: 0 yrs

Map Label: 196

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane:

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Houghton HQ Modular Office Building VC

Unit - Location: ISRO - Houghton

FMSS ID: 99497, **Local ID:**

Structure Type, Use: No Wildland Risk, Public

Owner: National Park Service

Field Crew, Visit Date: S Szturm (Virtual), July 12, 2023

Coordinates (DDM): 47° 07.38014598' N 088° 33.81911778' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Isle Royale NP HQ

Revisit Interval: 0 yrs

Map Label: 197

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane:

Overhead Hazards: Overhead hazards will limit aircraft

Comments:



2016-05-17 15:07

Lat: 47.123119 Lon: -88.564216

