


NPS Wildfire Risk Assessments

Assessment Locations

Saguaro National Park

National Park Service
U.S. Department of the Interior



Structure Locations

- Rincon Mountain - Backcountry (9)
- Rincon Mountains (36)
- Tucson Mountains (22)



0 10 20 Miles

Author: sszturm
1/27/2022 10:26 AM


Intermountain Region Geographic Resources Division
January 2021
Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project

Rincon Mountain-Backcountry

NPS Wildfire Risk Assessments

National Park Service
U.S. Department of the Interior



0

1

2

Miles

Author: sszturm
1/27/2022 1:27 PM

Intermountain Region Geographic Resources Division

February 2018

Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: SAGU - Rincon Mountain - Backcountry

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
2	Grass Shack vault toilet	NPS		Other	Public	N	2/1/13	Unknown	89	High	Not Designated	1	UNR
3	Manning Cabin Vault Toilet	NPS	0000003	Toilet	Admin	No	1/30/13	Unknown	93	High	Not Designated	Facility only accessible by Foot or Air	UNR
4	Mica Repeater	NPS		CommSite	Admin	N	4/21/21	Unknown	82	High	Critical		UNR
5	Rincon RAWS	BLM		RAWS	Admin	N	4/21/21	No	70	High	Unknown	QHVA3. WIMS ID 21207	UNR
6	RM Manning Cabin	NPS	79293	Building	Admin	Yes	1/30/13	Unknown	72	High	Not Designated	Facility only accessible by foot or air.	UNR
7	RM Manning Camp Comfort Station	NPS	97712	Toilet	Public	No	1/30/13	Unknown	89	High	Not Designated	Facility is only accessible by Foot or Air.	UNR
8	RM Manning Pump House	NPS	0000001	Utility	Other	No	1/30/13	Unknown	95	High	Not Designated	Facility only accessible by foot or Air.	UNR
9	RM Manning Water Tank	NPS	0000002	Utility	Admin	No	1/30/13	Unknown	119	High	Not Designated	Facility is only accessible by foot or Air	UNR
10	RM Spud Rock Campground Toilet	NPS	0000004	Toilet	Other	No	1/31/13	Unknown	96	High	Not Designated	Facility is an open toilet, Only Accessable by Foot or Air.	UNR



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

NPS Unit - Location: SAGU - Rincon Mountain - Backcountry

Label #	Facility/Community Name	Assessment Scale	Site Visit Type	Firewise Zone	Treatment	Treatment Description	Person Hours
2	Grass Shack vault toilet	Individual Facility	SiteVisit	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		2.0
		Individual Facility	SiteVisit	1	Remove dead or dying component of shrubs and trees	Light brush needed adjacent to restroom. Pull and scatter brush and dead fuels away from area.	2.0
		Individual Facility	SiteVisit	2	Open crown spacing 10 to 30 feet depending on slope	Open canopy spacing and reduce ladder fuels within zone 2.	6.0
		Individual Facility	SiteVisit	2	Remove dead or dying component of shrubs and trees	Remove adjacent snags and dead/dying fuels.	2.0
3	Manning Cabin Vault Toilet	Individual Facility	Initial	2	Open crown spacing 10 to 30 feet depending on slope	Remove clump of smaller PIPO adjacent to structure.	1.0
4	Mica Repeater	Individual Facility					
5	Rincon RAWS	Individual Facility					
6	RM Manning Cabin	Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		6.0



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

6	RM Manning Cabin	Individual Facility	Initial	1	Firewood should be moved at least 50 ft from the facility and 15 horizontal feet from tree canopies		6.0
		Individual Facility	Initial	1	Remove dead or dying component of shrubs and trees		6.0
		Individual Facility	Initial	2	Limb trees 6 to 15 feet above ground		12.0
		Individual Facility	Initial	2	Open crown spacing 10 to 30 feet depending on slope		18.0
		Individual Facility	Initial	3	Remove heavy ground fuels such as logs and stumps		12.0
7	RM Manning Camp Comfort Station	Individual Facility	Initial	1	Flammable ground cover such as leaf litter, woody debris or highly flammable vegetation should be removed		6.0
		Individual Facility	Initial	2	Flammable ground cover should be removed or isolated		12.0
		Individual Facility	Initial	2	Limb trees 6 to 15 feet above ground		12.0
		Individual Facility	Initial	3	Remove heavy ground fuels such as logs and stumps		18.0



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

8	RM Manning Pump House	Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		0.0
		Individual Facility	Initial	1	Flammable ground cover such as leaf litter, woody debris or highly flammable vegetation should be removed		6.0
		Individual Facility	Initial	2	Flammable ground cover should be removed or isolated		6.0
		Individual Facility	Initial	2	Open crown spacing 10 to 30 feet depending on slope		6.0
		Individual Facility	Initial	3	Remove heavy ground fuels such as logs and stumps		6.0
9	RM Manning Water Tank	Individual Facility	Initial	1	Flammable ground cover such as leaf litter, woody debris or highly flammable vegetation should be removed	Remove adjacent heavy dead and down, rake needles and disperse.	3.0
		Individual Facility	Initial	2	Flammable ground cover should be removed or isolated		6.0
		Individual Facility	Initial	2	Limb trees 6 to 15 feet above ground		6.0
		Individual Facility	Initial	2	Open crown spacing 10 to 30 feet depending on slope		30.0



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

9	RM Manning Water Tank	Individual Facility	Initial	3	Remove heavy ground fuels such as logs and stumps	Area to be treated approx 2 Acres	12.0
		Individual Facility	Initial	3	Remove standing dead or dying trees or limb 6 to 15 feet above ground		6.0
10	RM Spud Rock Campground Toilet	Individual Facility		1			



NPS Wildand Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: **Saguaro National Park - Rincon Mountain - Backcountry**

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
Grass Shack vault toilet	Individual Facility		Fuels reduction - Reduce live and dead fuel loading within proximity to restroom facility. Reduce snags (1) within campground area.	8.0	-	
Manning Cabin Vault Toilet	Individual Facility	PrepHold	Structure wrap - Wrap.	4.0	-	
			Fuels reduction - Remove heavier accumulations of dead and down material away from 30 ft zone.	3.0	-	
Mica Repeater	Individual Facility	PrepLeave	-		-	
Rincon RAWS	Individual Facility	PrepLeave	-		-	
RM Manning Cabin	Individual Facility	PrepHold	Fuels reduction -	18.0	-	
			Remove flammable materials -	6.0	-	
			Structure wrap - Wrap is staged and located in rafters of dog run. Other supplies (tape, staples stapler) will be needed, ladder on site.	48.0	-	
RM Manning Camp Comfort Station	Individual Facility	PrepHold	Burnout, no line construction necessary -	6.0	-	
			Fuels reduction -	30.0	-	
RM Manning Pump House	Individual Facility	PrepHold	Structure wrap -	12.0	-	
			Fuels reduction -	6.0	-	
RM Manning Water Tank	Individual Facility	PrepHold	Handline - Install HL and fire off of HL at appropriate time.	6.0	-	
			Fuels reduction -	42.0	-	



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
RM Spud Rock Campground Toilet	Individual Facility		Structure wrap -	6.0	-	
			Handline - Handling and burnout.. best option. Structure wrap it light it and go	6.0	-	



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Grass Shack vault toilet

Unit - Location: SAGU - Rincon Mountain - Backcountry

FMSS ID:

Structure Type: Other

Structure Use: Public

Owner: NPS

Field Crew: SAGU

Last Site Visit Date: 2/1/2013

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 32° 11.0294' Long(WGS84): -110° 35.5347'

Primary Access: Foot

Ingress/Egress: N/A, access by foot, boat or air only

Access Width: N/A, access by foot, boat or air only

Access Condition: N/A, access by foot, boat or air only

Bridge Condition: None/nonflammable, load limit will not limit response

Access & Turnarounds: N/A, access by foot, boat, or air only

Facility Number/Sign: None or not clearly visible

Defensible Space: No defensible space

Fuel Load (w/in 300 ft): Heavy

Fuel Type (w/in 300ft): Grass, shrub, hardwood litter

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Vinyl

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat: NA

Assessment Comments: 1

Score: 89
Rating: High

Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Manning Cabin Vault Toilet

Unit - Location: SAGU - Rincon Mountain - Backcountry
FMSS ID: 0000003
Structure Type: Toilet
Structure Use: Admin
Owner: NPS
Field Crew: SAGU
Last Site Visit Date: 1/30/2013

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community?
Lat(WGS84): 32° 12.4293' **Long(WGS84):** -110° 33.2854'


Primary Access: Foot
Ingress/Egress: N/A, access by foot, boat or air only
Access Width: N/A, access by foot, boat or air only
Access Condition: N/A, access by foot, boat or air only
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: N/A,access by foot,boat,or air only
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Heavy
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Vinyl
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments: Facility only accessible by Foot or Air

Score: 93
Rating: High

Asset Priority Index
(API):
N/A



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Mica Repeater

Unit - Location: SAGU - Rincon Mountain - Backcountry

FMSS ID:

Structure Type: CommSite

Structure Use: Admin

Owner: NPS

Field Crew: SAGUWFM JY

Last Site Visit Date: 4/21/2021

Rating: High

Protection Level : Critical

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 32° 13.1988' **Long(WGS84):** -110° 32.6235'

Primary Access: Foot

Ingress/Egress: N/A, access by foot, boat or air only

Access Width: N/A, access by foot, boat or air only

Access Condition: N/A, access by foot, boat or air only

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: N/A,access by foot,boat,or air only

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Not applicable

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat: Unknown

Assessment Comments:




2021_SAGU__Mica Repeater_P.jpg

Score: 82
Rating: High

Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Rincon RAWS

Unit - Location: SAGU - Rincon Mountain - Backcountry

FMSS ID:

Structure Type: RAWS

Structure Use: Admin

Owner: BLM

Field Crew: SAGUWFM JY

Last Site Visit Date: 4/21/2021

Rating: High

Protection Level : Unknown

Resources of Concern Present? No

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 32° 12.3959' **Long(WGS84):** -110° 32.9186'

Primary Access: Foot

Ingress/Egress: N/A, access by foot, boat or air only

Access Width: N/A, access by foot, boat or air only

Access Condition: N/A, access by foot, boat or air only

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: N/A,access by foot,boat,or air only

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Not applicable

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat: Battery

Assessment Comments: QHVA3. WIMS ID 21207



2021_SAGU__Rincon RAWS_P.jpg


Score: 70
Rating: High



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RM Manning Cabin

Unit - Location: SAGU - Rincon Mountain - Backcountry
FMSS ID: 79293
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: SAGU
Last Site Visit Date: 1/30/2013

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community?
Lat(WGS84): 32° 12.4355' **Long(WGS84):** -110° 33.2772'

Primary Access: Foot
Ingress/Egress: N/A, access by foot, boat or air only
Access Width: N/A, access by foot, boat or air only
Access Condition: N/A, access by foot, boat or air only
Bridge Condition: None/nonflammable, load limit will not limit response
Access & Turnarounds: N/A, access by foot, boat, or air only
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: Adjacent to/under deck of facility
Propane Tanks: Present and fuels clearance
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: No safety zone(s) in area
Additional Obstacles: Hazmat, UXO, etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane, flammable materials in Flam locker.
Assessment Comments: Facility only accessible by foot or air.



2013_SAGU_79293_RM Manning Cabin_Front.jpg


Score: 72
Rating: High




Asset Priority Index (API): 44



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RM Manning Camp Comfort Station

Unit - Location: SAGU - Rincon Mountain - Backcountry

FMSS ID: 97712

Structure Type: Toilet

Structure Use: Public

Owner: NPS

Field Crew: SAGU

Last Site Visit Date: 1/30/2013

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community?

Lat(WGS84): 32° 12.3773' Long(WGS84): -110° 33.3263'

Primary Access: Foot

Ingress/Egress: N/A, access by foot, boat or air only

Access Width: N/A, access by foot, boat or air only

Access Condition: N/A, access by foot, boat or air only

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: N/A,access by foot,boat,or air only

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 31% to 40%

Roof Material: Noncombustible or not applicable

Siding Material: Vinyl

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat:

Assessment Comments: Facility is only accessible by Foot or Air.



2013_SAGU_97712_RM Manning Camp Comfort Station_Front.jpg




Score: 89
Rating: High



Asset Priority Index
(API):
31



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RM Manning Pump House

Unit - Location: SAGU - Rincon Mountain - Backcountry

FMSS ID: 0000001

Structure Type: Utility

Structure Use: Other

Owner: NPS

Field Crew: SAGU

Last Site Visit Date: 1/30/2013

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community?

Lat(WGS84): 32° 12.4595' Long(WGS84): -110° 33.2227'

Primary Access: Other

Ingress/Egress: N/A, access by foot, boat or air only

Access Width: N/A, access by foot, boat or air only

Access Condition: N/A, access by foot, boat or air only

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: N/A,access by foot,boat,or air only

Facility Number/Sign: None or not clearly visible

Defensible Space: No defensible space

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat: Sodium Hypochlorite,spray paint , spray adhesive, PVC cement and Primer.

Assessment Comments: Facility only accessible by foot or Air.



2013_SAGU_0000001_RM Manning Pump House_Front.jpg




Score: 95
Rating: High



Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RM Manning Water Tank

Unit - Location: SAGU - Rincon Mountain - Backcountry

FMSS ID: 0000002

Structure Type: Utility

Structure Use: Admin

Owner: NPS

Field Crew: SAGU

Last Site Visit Date: 1/30/2013

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community?

Lat(WGS84): 32° 12.4964' Long(WGS84): -110° 33.3213'

Primary Access: Foot

Ingress/Egress: N/A, access by foot, boat or air only

Access Width: N/A, access by foot, boat or air only

Access Condition: N/A, access by foot, boat or air only

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: N/A,access by foot,boat,or air only

Facility Number/Sign: None or not clearly visible

Defensible Space: No defensible space

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 31% to 40%

Roof Material: Combustible or no roof

Siding Material: Vinyl

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat:

Assessment Comments: Facility is only accessible by foot or Air



2013_SAGU_0000002_RM Manning Water Tank_Front.jpg


Score: 119
Rating: High




Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RM Spud Rock Campground Toilet

Unit - Location: SAGU - Rincon Mountain - Backcountry

FMSS ID: 0000004

Structure Type: Toilet

Structure Use: Other

Owner: NPS

Field Crew: SAGU

Last Site Visit Date: 1/31/2013

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community?

Lat(WGS84): 32° 12.2636' Long(WGS84): -110° 31.8708'

Primary Access: Foot

Ingress/Egress: N/A, access by foot, boat or air only

Access Width: N/A, access by foot, boat or air only

Access Condition: N/A, access by foot, boat or air only

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: N/A,access by foot,boat,or air only

Facility Number/Sign: None or not clearly visible

Defensible Space: No defensible space

Fuel Load (w/in 300 ft): Heavy

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Not applicable

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat:

Assessment Comments: Facility is an open toilet, Only Accessable by Foot or Air.



2013_SAGU_0000004_RM Spud Rock Campground Toilet_P.jpg




Score: 96
Rating: High



Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary