


NPS Wildfire Risk Assessments

Assessment Locations

Tumacacori National Historic Monument


National Park Service
U.S. Department of the Interior



Calabazas

NPS Wildfire Risk Assessments

National Park Service
U.S. Department of the Interior



Rating

 Moderate

Map Label	FMSS ID	Common Name
1	53829	Ruins
2	58889	Shelter



0 0.25 Miles

Author: sszturm
1/20/2022 10:40 AM

Intermountain Region Geographic Resources Division
March 2018
Data Sources: ESRI Basedata, NPS Park Data
NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: TUMA - Calabazas

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
1	Ruins	NPS	53829	CulturalR esource	Public	N	3/17/18	Unknown	56	Moderate	Not Designated	Not surveyed in 2021 - spoke to park staff and was told that the ruins/shelter are not made of flammable materials and 30ft defensible space is maintained.	UNR
2	Shelter	NPS	58889	Other	Admin	N	3/17/18	Yes	59	Moderate	Not Designated		UNR



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

NPS Unit - Location: TUMA - Calabazas

Label #	Facility/Community Name	Assessment Scale	Site Visit Type	Firewise Zone	Treatment	Treatment Description	Person Hours
1	Ruins	Individual Facility					
2	Shelter	Individual Facility					



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: Tumacácori National Historical Park - Calabazas

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
Ruins	Individual Facility	PrepLeave	-		-	
Shelter	Individual Facility	PrepLeave	-		-	



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Ruins

Unit - Location: TUMA - Calabazas

FMSS ID: 53829

Structure Type: CulturalResource

Structure Use: Public

Owner: NPS

Field Crew: Vaughn

Last Site Visit Date: 3/17/2018

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 31° 27.1547' **Long(WGS84):** -110° 57.5666'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Other than all season

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300ft from facility w/o turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:

Assessment Comments: Not surveyed in 2021 - spoke to park staff and was told that the ruins/shelter are not made of flammable materials and 30ft defensible space is maintained.




2018_TUMA__Ruins and Shelter_Front.jpg

Score: 56
Rating: Moderate

Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Shelter

Unit - Location: TUMA - Calabazas

FMSS ID: 58889

Structure Type: Other

Structure Use: Admin

Owner: NPS

Field Crew: Vaughn

Last Site Visit Date: 3/17/2018

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Yes, contact unit staff before engaging.

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 31° 27.1275' **Long(WGS84):** -110° 57.517'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Other than all season

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300ft from facility w/o turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Not applicable

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments:

Score: 59
Rating: Moderate

Asset Priority Index
(API):
63



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection