


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior




Little River National Preserve - Overview



Falls Area

LIRI - Little River Canyon National Preserve

National Park Service
U.S. Department of the Interior



Rating

Rating  Moderate

 Low



Author: sszturm
1/24/2024 9:50 AM

0 0.25 0.5 0.75 Miles

Scale: 1:18,000

NPS Wildfire Risk Assessments
NPS Fire GIS
January 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



Canyon Mouth

LIRI - Little River Canyon National Preserve

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
6	66396	CMP Multi-Use Facility
3	not found	Cinder Block Utility Building
4	227444	CMP Storage Building
5	111682	CMDUA Fee Booth
7	not found	USGS Stream Gaging Station
1	66397	CM Workshop



Author: sszturm
1/24/2024 9:47 AM

0 0.5 Miles

Scale: 1:12,000

NPS Wildfire Risk Assessments
NPS Fire GIS
January 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



Map Label	FMSS ID	Common Name
8	66417	Eberhart Comfort Station



Rating

Rating

Low



Author: sszturm
1/24/2024 9:45 AM



NPS Wildfire Risk Assessments
NPS Fire GIS
January 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CM Workshop

Unit - Location: LIRI - LIRI

FMSS ID: 66397

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 3/23/2022

Rating: Low

Protection Level : Unknown

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 17.2615' Long(WGS84): -85° 40.9137'

Primary Access: Foot

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments: attached to multi use building see for pictures

Score: 38
Rating: Low

Asset Priority Index
(API):
19



Factors Driving the Ratings



Access
Environment
Structure
Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Cinder Block Utility Building

Unit - Location: LIRI - LIRI

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 3/23/2022

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 17.1836' Long(WGS84): -85° 40.9996'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/o turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: No defensible space

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: None visible

Assessment Comments:



2022_LIRI_not found_Cinder Block Utility Building_Front.jpg


Score: 69
Rating: High




Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CMP Storage Building

Unit - Location: LIRI - LIRI

FMSS ID: 227444

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: MRZ Vick,Lewis

Last Site Visit Date: 8/28/2022

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 17.1862' Long(WGS84): -85° 40.9832'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/o turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat: None visible



Assessment Comments:




2022_LIRI_227444_CMP Storage Building_Front.jpg

Score: 56
Rating: Moderate

Asset Priority Index
(API):
7



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CMDUA Fee Booth

Unit - Location: LIRI - LIRI

FMSS ID: 111682

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 3/23/2022

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 34° 17.2217' Long(WGS84): -85° 40.9513'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: Flammable, load limit will limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible but separated from facility

Firewood: None

Propane Tanks: None

Water Supply: Limited or dependent on electricity

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat: None visible


Assessment Comments:




2016 LIRI_111682_CMDUA Fee Booth_Front.jpg

Score: 48
Rating: Moderate

Asset Priority Index
(API):
67



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CMP Multi-Use Facility

Unit - Location: LIRI - LIRI

FMSS ID: 66396

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 3/23/2022

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 17.2724' Long(WGS84): -85° 40.9184'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: Nonflammable, load limit will limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Limited or dependent on electricity

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: None visible

Assessment Comments:




2022_LIRI_66396_CMP Multi-Use Facility_Front.jpg


Score: 45
Rating: Moderate




Asset Priority Index
(API):
77



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: USGS Stream Gaging Station

Unit - Location: LIRI - LIRI

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: Unknown

Field Crew: castillo

Last Site Visit Date: 3/23/2022

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 34° 17.2805' **Long(WGS84):** -85° 40.8833'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/o turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Open or deck

Fences/Decks: Combustible but separated from facility

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: None visible

Assessment Comments:




2022_LIRI_not found_USGS Stream Gaging Station_Front.jpg


Score: 63
Rating: High




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Eberhart Comfort Station

Unit - Location: LIRI - LIRI

FMSS ID: 66417

Structure Type: Toilet

Structure Use: Public

Owner: NPS

Field Crew: MRZ Vick

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 34° 21.1522' Long(WGS84): -85° 40.587'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: None visible

Assessment Comments:




2022_LIRI_66417_Eberhart Comfort Station_Front.jpg


Score: 37
Rating: Low




Asset Priority Index
(API):
57



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: LIRI Visitor Center

Unit - Location: LIRI - LIRI

FMSS ID: 115757

Structure Type: Building

Structure Use: Public

Owner: State

Field Crew: MRZ Vick

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 23.9296' Long(WGS84): -85° 38.0437'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: Adjacent to/under deck of facility

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: Hazmat Storage

Assessment Comments:




2022_LIRI_115757_LIRI Visitor Center_Front.jpg


Score: 26
Rating: Low




Asset Priority Index
(API):
61



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: LIRI Amphitheatre

Unit - Location: LIRI - LIRI

FMSS ID: not found

Structure Type: Shade

Structure Use: Public

Owner: State

Field Crew: MRZ Vick

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 23.9604' Long(WGS84): -85° 38.02'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: Hazmat Storage

Assessment Comments: Please assess. Not owned by NPS. JMS 3/3/2022



2022_LIRI_not found_LIRI Amphitheatre_Front.jpg


Score: 27
Rating: Low




Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Falls Comfort Station

Unit - Location: LIRI - LIRI

FMSS ID: 66404

Structure Type: Toilet

Structure Use: Public

Owner: NPS

Field Crew: MRZ Vick

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 34° 23.7283' Long(WGS84): -85° 37.5579'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: None visible

Assessment Comments:




2022_LIRI_66404_Falls Comfort Station_Front.jpg


Score: 25
Rating: Low



Asset Priority Index
(API):
77



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Little River Canyon Shade Structure

Unit - Location: LIRI - LIRI

FMSS ID: not found

Structure Type: Shade

Structure Use: Private

Owner: Unknown

Field Crew: castillo

Last Site Visit Date: 3/23/2022

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 34° 23.7072' Long(WGS84): -85° 37.5557'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: Combustible but separated from facility

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat: None visible



Assessment Comments:




2022_LIRI_not found_Little River Canyon Shade Structure_Front.jpg

Score: 52
Rating: Moderate


Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Deer Check Station

Unit - Location: LIRI - LIRI

FMSS ID: 000000

Structure Type: SurveyNotRequired

Structure Use: Admin

Owner: State

Field Crew: MRZ Vick

Last Site Visit Date: 8/28/2022

Rating: SRVNotRequired

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes

Lat(WGS84): 34° 23.4871' Long(WGS84): -85° 36.6613'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Open or deck

Fences/Decks: Combustible but separated from facility

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: None visible

Assessment Comments: Owned and operated by Alabama Dept of NR. No survey necessary. (JMS 3/2/2022)




2016 LIRI__Deer Check Station_Front.jpg


Score: 53
Rating:
SRVNotRequired




Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: LIRI Fire Building & Gym

Unit - Location: LIRI - LIRI

FMSS ID: 104050

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: MRZ Lewis

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes

Lat(WGS84): 34° 23.5494' Long(WGS84): -85° 36.6288'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: None visible

Assessment Comments:




2022_LIRI_104050_LIRI Fire Building & Gym_Front.jpg


Score: 30
Rating: Low




Asset Priority Index
(API):
30



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Maint Flammable Storage Building

Unit - Location: LIRI - LIRI

FMSS ID: 97579

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: MRZ Vick

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes

Lat(WGS84): 34° 23.5456' Long(WGS84): -85° 36.6252'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat: Flammables storage and propane


Assessment Comments:




2022_LIRI_97579_Maint Flammable Storage Building_Front.jpg




Score: 28
Rating: Low



Asset Priority Index
(API):
40



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RT and Fire Building

Unit - Location: LIRI - LIRI

FMSS ID: 97577

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: MRZ Lewis

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes

Lat(WGS84): 34° 23.5412' **Long(WGS84):** -85° 36.622'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: Hazmat Storage

Assessment Comments:




2022_LIRI_97577_RT and Fire Building_Front.jpg


Score: 30
Rating: Low





Asset Priority Index (API): 30



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Maintenance Building

Unit - Location: LIRI - LIRI

FMSS ID: 66409

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: MRZ Vick

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes

Lat(WGS84): 34° 23.5333' Long(WGS84): -85° 36.602'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: Flammables storage

Assessment Comments:




2022_LIRI_66409_Maintenance Building_Front.jpg




Score: 30
Rating: Low



Asset Priority Index
(API):
53



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: State Wildlife Building

Unit - Location: LIRI - LIRI

FMSS ID: 00000

Structure Type: Building

Structure Use: Admin

Owner: State

Field Crew: MRZ Vick

Last Site Visit Date: 8/28/2022

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? No

Occupied? No

Local ID: [Local ID]

In a Community? Yes - Maintenance

Lat(WGS84): 34° 23.5646' Long(WGS84): -85° 36.5996'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: Hazmat Storage

Assessment Comments:



2022_LIRI_00000_State Wildlife Building_Front.jpg


Score: 26
Rating: Low




Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary