


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



DEVA - Death Valley National Park - Overview




NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



DEVA - Eureka Valley - Overview



Structure Groups

Location

 Eureka Valley



Author: sszturm
2/27/2024 2:26 PM

NPS Wildfire Risk Assessments
NPS Fire GIS
February 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project


Jackass Flats Tarpaper Cabin

DEVA - Death Valley National Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
198	NA	Jackass Flats Tarpaper Cabin



Rating
Rating
 High



Author: sszturm
2/27/2024 1:50 PM


0 500 1,000 1,500 Feet
Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
February 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

Marble Canyon

DEVA - Death Valley National Park

National Park Service
U.S. Department of the Interior



Rating
Facility
High



Author: sszturm
2/27/2024 2:08 PM

0

4 Miles


Scale: 1:50,000

NPS Wildfire Risk Assessments
NPS Fire GIS
February 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

Rebecca Mine Cabin
DEVA - Death Valley National Park



Map Label	FMSS ID	Common Name
201	not found	Rebecca Mine Cabin
200	not found	Up and Down Mine Cabin



Author: sszturm
2/27/2024 2:17 PM

0 0.5 Miles

Scale: 1:12,000



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Marble Canyon Cabin 2

Unit - Location: DEVA - Eureka Valley

FMSS ID: , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: K Hansen Remote, May 8, 2013

Coordinates (DDM): 37° 05.49033882' N 117° 57.96344796' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 191

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Easy Pickings Cabin

Unit - Location: DEVA - Eureka Valley

FMSS ID: , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: K Hansen Remote, April 7, 2012

Coordinates (DDM): 37° 05.43843234' N 117° 56.34588816' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 196

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Easy Pickings Shed

Unit - Location: DEVA - Eureka Valley

FMSS ID: , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: K Hansen Remote, May 8, 2013

Coordinates (DDM): 37° 05.44385088' N 117° 56.34460482' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 197

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combination of fire resitant and combustible

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Jackass Flats Tarpaper Cabin

Unit - Location: DEVA - Eureka Valley

FMSS ID: , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: K Hansen Remote, April 6, 2012

Coordinates (DDM): 37° 00.87066048' N 117° 54.65882658' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 198

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combination of fire resitant and combustible

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Marble Canyon Cabin 1

Unit - Location: DEVA - Eureka Valley

FMSS ID: not found , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: L. Catlin , February 27, 2021

Coordinates (DDM): 37° 05.49508068' N 117° 58.04519802' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 189

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Marble Canyon Headframe 1

Unit - Location: DEVA - Eureka Valley

FMSS ID: not found , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: L. Catlin , February 27, 2021

Coordinates (DDM): 37° 05.56383024' N 117° 57.57145344' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 194

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with no turnaround

Access and Turnarounds: Less than 300 ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource. 4x4 and high clearance necessary for access





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Marble Canyon Headframe 2

Unit - Location: DEVA - Eureka Valley

FMSS ID: not found , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: L. Catlin , February 27, 2021

Coordinates (DDM): 37° 05.50632018' N 117° 57.99335634' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 190

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Rebecca Mine Cabin

Unit - Location: DEVA - Eureka Valley

FMSS ID: not found , **Local ID:**

Structure Type, Use: No Wildland Risk, Other

Owner: National Park Service

Field Crew, Visit Date: K Hansen Remote, October 24, 2012

Coordinates (DDM): 37° 11.66285250' N 117° 42.41457906' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 20 yrs

Map Label: 201

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource. 4x4 and high clearance necessary to access





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Up and Down Mine Cabin

Unit - Location: DEVA - Eureka Valley

FMSS ID: not found , **Local ID:**

Structure Type, Use: No Wildland Risk, Other

Owner: National Park Service

Field Crew, Visit Date: K Hansen Remote, March 29, 2015

Coordinates (DDM): 37° 11.30214138' N 117° 43.03989240' W

Rating: No Wildland Risk

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 20 yrs

Map Label: 200

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource. 4x4 and high clearance necessary to access





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Whippoorwill Cabin 1

Unit - Location: DEVA - Eureka Valley

FMSS ID: not found , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: L. Catlin , February 27, 2021

Coordinates (DDM): 37° 02.25334914' N 117° 57.63905988' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 192

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Other than all season

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Fire resistant- tar, rubberized

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource. 4x4 and high clearance necessary to access





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Whippoorwill Cabin 2

Unit - Location: DEVA - Eureka Valley

FMSS ID: not found , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: L. Catlin , February 27, 2021

Coordinates (DDM): 37° 02.15640072' N 117° 57.58926510' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 193

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Other than all season

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource. 4x4 and high clearance necessary for access





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Whippoorwill Cabin 3

Unit - Location: DEVA - Eureka Valley

FMSS ID: not found , **Local ID:**

Structure Type, Use: Cultural Resource, Other

Owner: National Park Service

Field Crew, Visit Date: L. Catlin , February 27, 2021

Coordinates (DDM): 37° 02.22332076' N 117° 57.33914136' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 195

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Other than all season

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Backcountry cultural resource. 4x4 and high clearance necessary to access

