


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior




Organ Pipe Cactus National Monument - Overview



Structure Groups

Location	
 Bates Well Road	 East
 E Fenceline Road	 Monument Headquarters
 Puerto Blanco Drive	



Author: sszturm
3/4/2024 10:40 AM

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project


Puerto Blanco Drive

ORPI - Organ Pipe Cactus National Monument

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
88	74398	Bonita Well Restroom
89	not found	CBP Observation Tower



Author: sszturm
3/4/2024 2:53 PM

0

4 Miles

Scale: 1:50,000

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Bonita Well Restroom

Unit - Location: ORPI - Puerto Blanco Drive

FMSS ID: 74398, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: L. Catlin, January 14, 2021

Coordinates (DDM): 32° 00.56360400' N 112° 58.49849400' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 5 yrs

Map Label: 88

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Drug smuggling presence in the area.






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: CBP Observation Tower
Unit - Location: ORPI - Puerto Blanco Drive
FMSS ID: not found , **Local ID:**
Structure Type, Use: Communications Site, Administrative
Owner: Other Federal Government
Field Crew, Visit Date: L. Catlin, January 14, 2021
Coordinates (DDM): 31° 58.68374904' N 112° 59.96359272' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 89

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards
Comments: drug smuggling in area





NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: ORPI - Puerto Blanco Drive

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
88	Bonita Well Restroom	NPS	74398	Building	Public	N	1/14/21	Unknown	35	Low	Not Designated	Drug smuggling presence in the area.	UNR
89	CBP Observation Tower	OtherFedGov	not found	CommSite	Admin	N	1/14/21	Unknown	29	Low	Not Designated	drug smuggling in area	UNR



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

NPS Unit - Location: ORPI - Puerto Blanco Drive

Label #	Facility/Community Name	Assessment Scale	Site Visit Type	Firewise Zone	Treatment	Treatment Description	Person Hours
88	Bonita Well Restroom	Individual Facility	SiteVisit	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		3.0
89	CBP Observation Tower	Individual Facility	Initial	1	Flammable ground cover such as leaf litter, woody debris or highly flammable vegetation should be removed		3.0



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: Organ Pipe Cactus National Monument - Puerto Blanco Drive

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
Bonita Well Restroom	Individual Facility	Standalone	Other, please describe. - none necessary. sparse fuel load and flat terrain		-	
CBP Observation Tower	Individual Facility	Standalone	Other, please describe. - none necessary. sparse fuels and flat terrain		-	