


Rainbow Bridge

RABR - Rainbow Bridge National Monument

National Park Service
U.S. Department of the Interior



Author: sszturm
5/7/2024 7:18 AM

0 4 Miles

Scale: 1:50,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RB (Rainbow Bridge) B001 Comfort Station (Floating)

Unit - Location: RABR - Rainbow Bridge

FMSS ID: 44461

Structure Type: No Wildland Risk

Structure Use: Public

Owner: NPS

Field Crew: ZION WFM

Last Site Visit Date: 7/1/2012

Rating: NoWildlandRisk

Protection Level : Unknown

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community?

Lat(WGS84): 37° 4.887' Long(WGS84): -110° 58.282'

Primary Access: Road

Ingress/Egress:

Access Width:

Access Condition:

Bridge Condition:

Access & Turnarounds:

Facility Number/Sign:

Defensible Space:

Fuel Load (w/in 300 ft):

Fuel Type (w/in 300ft):

Topography (w/in 300ft):

Roof Material:

Siding Material:

Foundation:

Fences/Decks:

Firewood:

Propane Tanks:

Water Supply:

Overhead Hazards:

Safety Zones:

Additional Obstacles:

Triage Category:


Hazmat:

Assessment Comments: N/A: Building is floating in a canyon on the water




2012_RABR_44461_RB (Rainbow Bridge) B001 Comfort Station (Floating)_Front.jpg


Score:
Rating:
NoWildlandRisk



Asset Priority Index
(API):
88



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RB (Rainbow Bridge) Shade Structure #1


Unit - Location: RABR - Rainbow Bridge
FMSS ID: GLCA RB Shade Sturcuture #1
Structure Type: Other
Structure Use: Unknown
Owner: NPS
Field Crew: ZION WFM
Last Site Visit Date: 7/1/2012

Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community?
Lat(WGS84): 37° 7.743' **Long(WGS84):** -110° 57.954'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments: Road Width: By Boat. Water Supply: Lake Powell.
Treatment: None. Very sparse fuels. It is in a canyon only accessible by water.




2012_RABR_GLCA RB Shade Sturcuture #1_RB (Rainbow Bridge) Shade Structure #1_Front.jpg




Score: 56
Rating: Moderate



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: RB (Rainbow Bridge) Shade Structure #2

Unit - Location: RABR - Rainbow Bridge
FMSS ID: GLCA RB Shade Sturcuture #2
Structure Type: Other
Structure Use: Unknown
Owner: NPS
Field Crew: ZION WFM
Last Site Visit Date: 7/1/2012

Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community?
Lat(WGS84): 37° 4.697' **Long(WGS84):** -110° 57.856'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: No safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments: Road Width: By Boat. Water Supply: Lake Powell.
Treatment: None. Wooden structure has some accumulation of fuels around it but it is remotely located and culturally sensitive to do any work to this area.




2012_RABR_GLCA RB Shade Sturcuture #2_RB (Rainbow Bridge) Shade Structure #2_Front.jpg




Score: 59
Rating: Moderate




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary