


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



Canyon De Chelly National Monument - Overview



Structure Groups

Location	●	Headquarters
	●	Canyons



Author: sszturm
5/7/2024 12:26 PM



NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



Canyon De Chelly National Monument - Headquarters - Overview



Author: sszturm
5/7/2024 11:47 AM

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project


Visitors Center

CACH - Canyon De Chelly National Monument

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
12	68898	Comfort Station Loop 2
17	68896	Comfort Station Loop 1
21	108512	Campground Kiosk
32	97868	Headquarters Picnic Area Comfort Station
4	68891	CACH Visitor Center
23	100254	Concessions Maintenance and Laundry
38	72992	Ampatheatre
18	68899	Comfort Station Loop 3



Author: sszturm
5/7/2024 10:34 AM

0 500 1,000 1,500 Feet


Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project


Concessions
CACH - Canyon De Chelly National Monument



Map Label	FMSS ID	Common Name
46	68919	Headquarters Residence # 25
48	68917	Headquarters Residence # 24
49	68916	Headquarters Residence #23
10	68906	Maintenance Lumber Warehouse
7	68904	Maintenance Shop
45	68919	Headquarters Duplex #29 and #30
40	68925	Headquarters Duplex #31 and #32
47	68925	Headquarter Duplex #33 and #34
39	85510	Headquarters Duplex Trailor A1, A2
34	85511	Headquarters Bunkhouse B2
29	68922	Headquarters Residence # 39
5	68912	Ranger Office
8	230072	Resource Management Facility
6	228040	Ranger Office Garage
51	233978	Water Supply Wellhouse
36	85523	Concession Cafeteria
15	100253	Concession Managers Residence
11	106569	Concessions (Food Storage Warehouse)
9	100360	Concession Tour Truck Storage Shelter
27	85514	Concessions Maintenance Building
28	80661	Concession Thunderbird Storage Barn
22	85524	Concessions Motel Units (42 rooms)
19	100357	Concession Residence House 2
20	100252	Concession Residence House 1
16	100358	Concession Residence House 3
31	106566	Concession Pump House
14	100359	Concession Thunderbird Garages & Repair Shop
42	85522	Concession Office and Curio Shop
50	100255	Concession Passenger Loading Shelter
41	85515	Concessions Lodge Rooms
37	85517	Concessions Lodge Rooms 6 and 8
33	85518	Concession Lodge Room 9
25	85519	Concessions Lodge Rooms 10 and 11
44	85520	Concession Motel Units 14-23
35	85521	Concession Motel Units 24-35
30	85512	Concessions (Linen and Storage Shed)
26	80659	Concession Motel Office



Author: sszturm
5/7/2024 11:22 AM





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concessions Motel Units (42 rooms)

Unit - Location: CACH - Headquarters

FMSS ID: 85524, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.82191454' N 109° 32.36867724' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 22

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments: motel built into hill. no photo b,c,d





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Residence # 24

Unit - Location: CACH - Headquarters

FMSS ID: 68917, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.70229572' N 109° 32.29073922' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 48

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: 5ft to 30ft from facility



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Residence House 1

Unit - Location: CACH - Headquarters

FMSS ID: 100252, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.86575378' N 109° 32.38996854' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 20

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Passenger Loading Shelter

Unit - Location: CACH - Headquarters

FMSS ID: 100255, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.81959770' N 109° 32.28114060' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 50

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Thunderbird Storage Barn

Unit - Location: CACH - Headquarters

FMSS ID: 80661, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.82358434' N 109° 32.35051896' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 28

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Ranger Office

Unit - Location: CACH - Headquarters

FMSS ID: 68912, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.85637098' N 109° 32.51516118' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 5

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Residence House 2

Unit - Location: CACH - Headquarters

FMSS ID: 100357, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.86059474' N 109° 32.40240402' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 19

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Duplex #31 and #32

Unit - Location: CACH - Headquarters

FMSS ID: 68925, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.64343152' N 109° 32.31223740' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 40

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concessions Maintenance and Laundry

Unit - Location: CACH - Headquarters

FMSS ID: 100254, **Local ID:**

Structure Type, Use: Utility Site (Water, Gas, Elec), Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.88382236' N 109° 32.36254080' W

Rating: Low

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 23

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30 in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Lodge Room 9

Unit - Location: CACH - Headquarters

FMSS ID: 85518, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.81624088' N 109° 32.32967718' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 33

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: CACH Visitor Center

Unit - Location: CACH - Headquarters

FMSS ID: 68891, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 09.18873354' N 109° 32.34207804' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: No,

Revisit Interval: 10 yrs

Map Label: 4

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Motel Units 24-35

Unit - Location: CACH - Headquarters

FMSS ID: 85521, **Local ID:**

Structure Type, Use: Building, Visitor Lodging

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.85183570' N 109° 32.32774308' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 35

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Campground Kiosk

Unit - Location: CACH - Headquarters

FMSS ID: 108512, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.91524406' N 109° 32.36895258' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 21

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with no turnaround

Access and Turnarounds: Less than 300 ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Maintenance Lumber Warehouse

Unit - Location: CACH - Headquarters

FMSS ID: 68906, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.84049672' N 109° 32.46536256' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 10

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: Present and fuels clearance

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Residence #23

Unit - Location: CACH - Headquarters

FMSS ID: 68916, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.72118180' N 109° 32.28346626' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 49

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: 5ft to 30ft from facility



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Resource Management Facility

Unit - Location: CACH - Headquarters

FMSS ID: 230072, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.86929486' N 109° 32.47955904' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 8

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed

Firewood: None



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Managers Residence

Unit - Location: CACH - Headquarters

FMSS ID: 100253, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.81632938' N 109° 32.41621842' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 15

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Greater than 300 ft with turnaround

Access and Turnarounds: Greater than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concessions Lodge Rooms 6 and 8

Unit - Location: CACH - Headquarters

FMSS ID: 85517, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.82420396' N 109° 32.32135602' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 37

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Motel Units 14-23

Unit - Location: CACH - Headquarters

FMSS ID: 85520, **Local ID:**

Structure Type, Use: Building, Visitor Lodging

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.84161560' N 109° 32.30759970' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 44

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Residence # 39

Unit - Location: CACH - Headquarters

FMSS ID: 68922, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.60987346' N 109° 32.35015686' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 29

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, 6in to 30in masonry exposed

Firewood: None



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Maintenance Shop

Unit - Location: CACH - Headquarters

FMSS ID: 68904, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.82768558' N 109° 32.49352758' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 7

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: Present and fuels clearance

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Comfort Station Loop 3

Unit - Location: CACH - Headquarters

FMSS ID: 68899, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 09.02853198' N 109° 32.40997128' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 18

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with no turnaround

Access and Turnarounds: Less than 300 ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Office and Curio Shop

Unit - Location: CACH - Headquarters

FMSS ID: 85522, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.81752488' N 109° 32.31165870' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 42

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, 6in to 30in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concessions Lodge Rooms 10 and 11

Unit - Location: CACH - Headquarters

FMSS ID: 85519, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.80912410' N 109° 32.35276536' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 25

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Duplex Trailor A1, A2

Unit - Location: CACH - Headquarters

FMSS ID: 85510, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.61125538' N 109° 32.31581682' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 39

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed

Firewood: None



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Water Supply Wellhouse

Unit - Location: CACH - Headquarters

FMSS ID: 233978, **Local ID:**

Structure Type, Use: Utility Site (Water, Gas, Elec), Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.78574636' N 109° 32.26946784' W

Rating: Low

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 51

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarter Duplex #33 and #34

Unit - Location: CACH - Headquarters

FMSS ID: 68925, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.62362378' N 109° 32.29284270' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 47

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Thunderbird Garages and Repair Shop
Unit - Location: CACH - Headquarters
FMSS ID: 100359, **Local ID:**
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: shawn Castillo, March 15, 2021
Coordinates (DDM): 36° 08.82440736' N 109° 32.42888766' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Park Headquarters
Revisit Interval: 10 yrs
Map Label: 14

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concessions (Linen and Storage Shed)

Unit - Location: CACH - Headquarters

FMSS ID: 85512, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.83128834' N 109° 32.33990898' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 30

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concessions Lodge Rooms

Unit - Location: CACH - Headquarters

FMSS ID: 85515, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.82869508' N 109° 32.31194388' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 41

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Moderate

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concessions Maintenance Building

Unit - Location: CACH - Headquarters

FMSS ID: 85514, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.83515756' N 109° 32.35126050' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 27

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Pump House

Unit - Location: CACH - Headquarters

FMSS ID: 106566, **Local ID:**

Structure Type, Use: Utility Site (Water, Gas, Elec), Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.82155154' N 109° 32.33741898' W

Rating: Low

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 31

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Comfort Station Loop 2

Unit - Location: CACH - Headquarters

FMSS ID: 68898, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.96384514' N 109° 32.43574764' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 12

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with no turnaround

Access and Turnarounds: Less than 300 ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Duplex #29 and #30

Unit - Location: CACH - Headquarters

FMSS ID: 68919, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.66070564' N 109° 32.30082870' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 45

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Ranger Office Garage

Unit - Location: CACH - Headquarters

FMSS ID: 228040, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.84893290' N 109° 32.51320596' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 6

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Comfort Station Loop 1

Unit - Location: CACH - Headquarters

FMSS ID: 68896, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.92625280' N 109° 32.41126428' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 17

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with no turnaround

Access and Turnarounds: Less than 300 ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Cafeteria

Unit - Location: CACH - Headquarters

FMSS ID: 85523, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.79755880' N 109° 32.32437900' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 36

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Motel Office

Unit - Location: CACH - Headquarters

FMSS ID: 80659, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.77606818' N 109° 32.35158888' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 26

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Residence # 25

Unit - Location: CACH - Headquarters

FMSS ID: 68919, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.68398534' N 109° 32.29430442' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 46

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: 5ft to 30ft from facility



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Residence House 3

Unit - Location: CACH - Headquarters

FMSS ID: 100358, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.85442242' N 109° 32.41301400' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 16

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concessions (Food Storage Warehouse)

Unit - Location: CACH - Headquarters

FMSS ID: 106569, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.78880684' N 109° 32.44117476' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 11

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Picnic Area Comfort Station

Unit - Location: CACH - Headquarters

FMSS ID: 97868, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.94078522' N 109° 32.33680158' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 32

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Ampatheatre

Unit - Location: CACH - Headquarters

FMSS ID: 72992, **Local ID:**

Structure Type, Use: Other, Unknown

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.97443058' N 109° 32.32001430' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied:

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 38

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Bunkhouse B2

Unit - Location: CACH - Headquarters

FMSS ID: 85511, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.60489850' N 109° 32.32962126' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 34

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed

Firewood: None



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Concession Tour Truck Storage Shelter

Unit - Location: CACH - Headquarters

FMSS ID: 100360, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: shawn Castillo, March 15, 2021

Coordinates (DDM): 36° 08.80895940' N 109° 32.46855546' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 10 yrs

Map Label: 9

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:

