


NPS Wildfire Risk Assessments Assessment Locations

Tuzigoot National Monument

National Park Service
U.S. Department of the Interior



Structure Locations

● Tuzigoot National Monument (12)



0

1

Miles

Author: sszturm
1/27/2022 3:47 PM


Intermountain Region Geographic Resources Division
December 2020
Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project

Tuzigoot National Monument

NPS Wildfire Risk Assessments

National Park Service
U.S. Department of the Interior



0

0.5
Miles

Author: sszturm
1/27/2022 3:46 PM

Intermountain Region Geographic Resources Division
December 2020
Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: TUZI - Tuzigoot National Monument

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
1	Fire Pump Building	NPS	74442	None Found	Admin	N	12/21/20	Unknown	40	None	Unknown		UNR
2	Quarters 5	NPS	13713	Building	Residence	Y	12/21/20	Unknown	39	Low	Not Designated		UNR
3	Quarters 7	NPS	13716	Building	Residence	Y	12/21/20	Unknown	49	Moderate	Not Designated		UNR
4	Resource Center	NPS	13711	Building	Admin	Y	12/21/20	Unknown	39	Low	Not Designated		UNR
5	Storage Building	NPS	26621	Building	Admin	N	12/21/20	Unknown	52	Moderate	Not Designated		UNR
6	Storage Shed	NPS	search not found	Building	Admin	N	12/21/20	Unknown	53	Moderate	Not Designated		UNR
7	Storage Shed	NPS	search not found	Building	Admin	N	12/21/20	Unknown	37	Low	Not Designated		UNR
8	Generator Building	NPS	26622	Utility	Admin	N	12/21/20	Unknown	55	Moderate	Unknown		UNR
9	Old Shop Building HB	NPS	13719	Building	Admin	N	12/21/20	Unknown	59	Moderate	Unknown		UNR
10	Restrooms	NPS	13704	Building	Public	N	12/21/20	Unknown	35	Low	Unknown		UNR
11	Visitor Center	NPS	13702	Building	Public	Y	12/21/20	Unknown	41	Low	Unknown		UNR
12	Well Pump House	NPS	26620	Utility	Admin	N	12/21/20	Unknown	59	Moderate	Unknown		UNR



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

NPS Unit - Location: TUZI - Tuzigoot National Monument

Label #	Facility/Community Name	Assessment Scale	Site Visit Type	Firewise Zone	Treatment	Treatment Description	Person Hours
1	Fire Pump Building	Facility In Community (Tuzigoot)					
2	Quarters 5	Individual Facility	Initial	1	Remove dead or dying component of shrubs and trees	May need to mow grass around the building w/ weed eaters or a lawn mower.	0.5
		Individual Facility	Initial	2	Flammable ground cover should be removed or isolated	Fuels need to be limbed, brushed, and mowed. The equipment needed to properly thin this zone would be chainsaws, brush cutters, and weed eaters. Would recommend clearing wood debris from outbuilding in the backyard. Would recommend clearing wood table and removing wood gate from alpha side of house.	2.0
		Individual Facility	Initial	3	Remove standing dead or dying trees or limb 6 to 15 feet above ground	Fuels need to be limbed and cut with chainsaws and brush cutters.	3.0
3	Quarters 7	Individual Facility	Initial	1	Remove dead or dying component of shrubs and trees	May need to mow grass around the building w/ weed eaters or a lawn mower.	0.5
		Individual Facility	Initial	2	Flammable ground cover should be removed or isolated	Fuels need to be limbed, brushed, and mowed. The equipment needed to properly thin this zone would be chainsaws, brush cutters, and weed eaters. Would recommend clearing wood debris from outbuilding in the backyard. Would recommend clearing wood table and removing wood gate from alpha side of house.	2.0
		Individual Facility	Initial	3	Remove standing dead or dying trees or limb 6 to 15 feet above ground	Fuels need to be limbed and cut with chainsaws and brush cutters.	3.0
4	Resource Center	Individual Facility	Initial	1	Remove dead or dying component of shrubs and trees	May need to mow grass around the building w/ weed eaters or a lawn mower.	0.5



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

4	Resource Center	Individual Facility	Initial	2	Flammable ground cover should be removed or isolated	Fuels need to be limbed, brushed, and mowed. The equipment needed to properly thin this zone would be chainsaws, brush cutters, and weed eaters. Would recommend clearing wood debris from outbuilding in the backyard. Would recommend clearing wood table and removing wood gate from alpha side of house.	2.0
		Individual Facility	Initial	3	Remove standing dead or dying trees or limb 6 to 15 feet above ground	Fuels need to be limbed and cut with chainsaws and brush cutters.	3.0
5	Storage Building	Individual Facility	Initial	1	Open crown spacing 10 to 30 feet depending on slope	Create adequate crown spacing in brush.	2.0
		Individual Facility	Initial	2	Open crown spacing 10 to 30 feet depending on slope	Create adequate crown spacing in brush.	2.0
		Individual Facility	Initial	2	Remove dead or dying component of shrubs and trees		1.0
7	Storage Shed	Individual Facility	Initial	2	Limb trees 6 to 15 feet above ground		1.0
		Individual Facility	Initial	2	Remove dead or dying component of shrubs and trees		1.0
		Individual Facility	Initial	1	Limb trees 6 to 15 feet above ground		1.0
		Individual Facility	Initial	2	Remove dead or dying component of shrubs and trees		1.0
8	Generator Building	Facility In Community (Tuzigoot)					



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

9	Old Shop Building HB	Facility In Community (Tuzigoot)	Initial	1	Flammable ground cover such as leaf litter, woody debris or highly flammable vegetation should be removed	Trim ground cover near structure.	1.5
		Facility In Community (Tuzigoot)	Initial	2	Flammable ground cover should be removed or isolated	Trim dead/dying grass to less than 4 inches and flammable ground cover to less than 18 inches on bravo, charlie and delta sides.	1.0
		Facility In Community (Tuzigoot)	Initial	2	Limb trees 6 to 15 feet above ground	Limb trees/shrubs 6 to 15 ft above vegetation.	2.0
		Facility In Community (Tuzigoot)	Initial	2	Open crown spacing 10 to 30 feet depending on slope	Create adequate horizontal spacing taking into consideration height and slope on all sides of structures.	1.5
		Facility In Community (Tuzigoot)	Initial	3	Remove standing dead or dying trees or limb 6 to 15 feet above ground	Limb dead/dying trees/branches 6 to 15 ft above ground fuels.	1.5
10	Restrooms	Facility In Community (Tuzigoot)					
		Facility In Community (Tuzigoot)				Clear roof and gutters of debris.	
		Facility In Community (Tuzigoot)				Trim dead or dying grass to less than 4 inches and flammable ground cover to less than 18 inches.	
11	Visitor Center	Facility In Community (Tuzigoot)	Initial	1	Roof and gutters should be cleared of vegetative debris	Clear roof and gutters of debris.	0.5
		Facility In Community (Tuzigoot)	Initial	2	Flammable ground cover should be removed or isolated	Trim dead or dying grass to less than 4 inches and flammable ground cover to less than 18 inches.	1.0



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

11	Visitor Center	Facility In Community (Tuzigoot)	Initial	2	Limb trees 6 to 15 feet above ground	Limb trees/shrubs 6 to 15 ft above vegetation.	2.0
		Facility In Community (Tuzigoot)	Initial	2	Open crown spacing 10 to 30 feet depending on slope	Create adequate horizontal spacing taking into consideration height and slope on all sides of structures.	1.5
		Facility In Community (Tuzigoot)	Initial	3	Remove standing dead or dying trees or limb 6 to 15 feet above ground	Limb dead or dying trees/limbs 6 to 15 ft above the ground.	1.5
12	Well Pump House	Facility In Community (Tuzigoot)	Initial	1	Roof and gutters should be cleared of vegetative debris	Clear roof and gutters of debris.	0.5
		Facility In Community (Tuzigoot)	Initial	2	Flammable ground cover should be removed or isolated	Trim dead or dying grass to less than 4 inches and flammable ground cover to less than 18 inches.	1.0
		Facility In Community (Tuzigoot)	Initial	2	Limb trees 6 to 15 feet above ground	Limb trees/shrubs 6 to 15 ft above vegetation.	2.0
		Facility In Community (Tuzigoot)	Initial	2	Open crown spacing 10 to 30 feet depending on slope	Create adequate horizontal spacing taking into consideration height and slope on all sides of structures.	1.5
		Facility In Community (Tuzigoot)	Initial	3	Remove standing dead or dying trees or limb 6 to 15 feet above ground	Limb dead or dying trees/limbs 6 to 15 ft above the ground.	1.5



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: Tuzigoot National Monument - Tuzigoot National Monument

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
Fire Pump Building	Facility In Community (Tuzigoot)		-		-	
Generator Building	Facility In Community (Tuzigoot)	PrepLeave	-		-	
Old Shop Building HB	Facility In Community (Tuzigoot)	PrepLeave	Fuels reduction - Zones 2 and 3 need treated to FireWise standards.	9.0	-	
Quarters 5	Individual Facility	PrepHold	Engine on scene - Engine should be on scene during fire event. Would recommend cutting grass and brush w/ a potential threat to the structure. Would recommend an engine on scene (A hydrant is on the Alpha side of the building, which is fed from a 50,000 gal. tank for drafting). Would recommend a sprinkler kit w/ pump to help protect the structure.	6.0	-	
			Fuels reduction - Fuels in zones 2 and 3 need treated to FireWise standards. Would recommend cutting grass and brush w/ a potential threat to the structure. Would recommend an engine on scene (A hydrant is on the Alpha side of the building, which is fed from a 50,000 gal. tank for drafting). Would recommend a sprinkler kit w/ pump to help protect the structure.	12.0	-	



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
Quarters 7	Individual Facility	PrepHold	Fuels reduction - Fuels in zones 2 and 3 need treated to FireWise standards. Flammable materials should be moved away from outbuilding. Would recommend cutting grass and brush w/ a potential threat to the structure. Would recommend an engine on scene (A hydrant is on the Alpha side of the building, which is fed from a 50,000 gal. tank for drafting). Would recommend a sprinkler kit w/ pump to help protect the structure.	12.0	-	
			Engine on scene - Engine should be on scene during fire event. Would recommend cutting grass and brush w/ a potential threat to the structure. Would recommend an engine on scene (A hydrant is on the Alpha side of the building, which is fed from a 50,000 gal. tank for drafting). Would recommend a sprinkler kit w/ pump to help protect the structure.	3.0	-	
Resource Center	Individual Facility	PrepHold	Engine on scene - (A hydrant is on the Alpha side of the building, which is fed from a 50,000 gal. tank for drafting). Would recommend a sprinkler kit w/ pump to help protect the structure.	6.0	-	
			Fuels reduction - Fuels in zones 2 and 3 need treated to FireWise standards. Would recommend cutting grass and brush w/ a potential threat to the structure.	12.0	-	
Restrooms	Facility In Community (Tuzigoot)	PrepHold	-		-	



NPS Wildand Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
Storage Building	Individual Facility	PrepLeave	Other, please describe. - Building is currently safe with no protection action needed during fire event. The fuels in Zone 1 need to be periodically maintained (brushing) to remain at this safety level.		-	
Storage Shed	Individual Facility	PrepLeave	Engine on scene - This shed is located in the backyard of the quarters, could be monitored as the larger buildings are main focus		-	
Storage Shed	Individual Facility	PrepLeave	Other, please describe. - If nearby trees are limbed, no tactics necessary in event of fire		-	
Visitor Center	Facility In Community (Tuzigoot)	PrepHold	Engine on scene - Recommend sprinklers be installed on C side, and engine on scene during fire event.	6.0	-	
			Install sprinkler system - Recommend sprinklers be installed on C side, and engine on scene during fire event.	6.0	-	
Well Pump House	Facility In Community (Tuzigoot)	PrepLeave	-		-	



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Fire Pump Building

Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 74442
Structure Type: None Found
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020


Rating: None
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Tuzigoot
Lat(WGS84): 34° 46.2339' **Long(WGS84):** -112° 1.55842'

Primary Access: Road
Ingress/Egress: Two or more roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:



2018_TUZI_74442_Fire Pump Building_D.jpg




Score: 40
Rating: None



Asset Priority Index (API):
N/A



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 5

Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 13713
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 34° 46.3399' **Long(WGS84):** -112° 1.56668'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1 lane (<18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:




2020_TUFrontL_13713_Quarters 5_Front


Score: 39
Rating: Low




Asset Priority Index (API): 30



Factors Driving the Ratings



■ Access
 ■ Environment
 ■ Structure
 ■ Protection



● Facility
 ■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 7


Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 13716
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 34° 46.3424' **Long(WGS84):** -112° 1.57406'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1 lane (<18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:




2020_TUFrontL_13716_Quarters 7_Front



Score: 49
Rating: Moderate
Asset Priority Index (API): 20



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Resource Center

Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 13711
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local ID]
In a Community? No
Lat(WGS84): 34° 46.3516' **Long(WGS84):** -112° 1.56097'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1 lane (<18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:



2020_TUFrontI_13711_Resource Center_Front


Score: 39
Rating: Low




Asset Priority Index (API): 42



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Storage Building


Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 26621
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 34° 46.3743' **Long(WGS84):** -112° 1.59081'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1 lane (<18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: fuel storage locker on D side
Assessment Comments:




2020_TUFrontI_26621_Storage Building_Front



Score: 52
Rating: Moderate
Asset Priority Index (API): 32



Factors Driving the Ratings



● Facility
 ■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Storage Shed

Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: search not found
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020


Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 34° 46.3696' **Long(WGS84):** -112° 1.59177'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1 lane (<18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Vinyl
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:



2020_TUFrontI_search not found _Storage Shed_Front


Score: 53
Rating: Moderate



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Storage Shed

Unit - Location: TUZI - Tuzigoot National Monument

FMSS ID: search not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 12/21/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 46.3407' **Long(WGS84):** -112° 1.58491'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: Present and fuels clearance

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2020_TUFrontI_search not found _Storage Shed_Front


Score: 37
Rating: Low



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Generator Building


Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 26622
Structure Type: Utility
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020

Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Tuzigoot
Lat(WGS84): 34° 46.2331' **Long(WGS84):** -112° 1.55535'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade>5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope >40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:



Photo 1.jpg




Score: 55
Rating: Moderate



Asset Priority Index (API): 20



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Old Shop Building HB

Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 13719
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020


Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Tuzigoot
Lat(WGS84): 34° 46.1909' **Long(WGS84):** -112° 1.57768'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade>5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope >40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:





2020_TUFrontL_13719_Old Shop Building HB_Front

Score: 59
Rating: Moderate
Asset Priority Index (API): 55



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Restrooms

Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 13704
Structure Type: Building
Structure Use: Public
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020


Rating: Low
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Tuzigoot
Lat(WGS84): 34° 46.2216' **Long(WGS84):** -112° 1.57524'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade>5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:




2020_TUFrontL_13704_Restrooms_Front


Score: 35
Rating: Low




Asset Priority Index (API): 67



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Visitor Center

Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 13702
Structure Type: Building
Structure Use: Public
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020


Rating: Low
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Tuzigoot
Lat(WGS84): 34° 46.2132' **Long(WGS84):** -112° 1.58096'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade>5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 21% to 30%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:



2020_TUFrontL_13702_Visitor Center_Front



Score: 41
Rating: Low



Asset Priority Index (API): 90



Factors Driving the Ratings



● Facility
 ■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Well Pump House

Unit - Location: TUZI - Tuzigoot National Monument
FMSS ID: 26620
Structure Type: Utility
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 12/21/2020


Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Tuzigoot
Lat(WGS84): 34° 46.2153' **Long(WGS84):** -112° 1.5646'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade>5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope >40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:




2020_TUFrontI_26620_Well Pump House_Front



Score: 59
Rating: Moderate



Asset Priority Index (API): 55



Factors Driving the Ratings



● Facility
■ NPS Boundary