


NPS Wildfire Risk Assessments

Assessment Locations

Sunset Crater Volcano National Monument

National Park Service
U.S. Department of the Interior



Sunset Crater 1

SUCR - Sunset Crater Volcano National Monument

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
3	not found	Shed
12	113349	SUCR Mod # 12 Detached Garage
1	Not found	Fuel Pumps / Tanks
6	113348	SUCR Apt 18B Detached Garage (being used as a Fire Cache)
17	48439	SUCR Pump House Building
4	not found	Shed
11	48441	SUCR Maintenance Office (Formerly Mod # 12)
14	113350	SUCR Mod # 2 Detached Garage
18	48424	SUCR Visitor Center
15	82933	SUCR Mod # 7
7	52742	SUCR Apt Building
13	48526	SUCR Mod # 2 (closest to gas pumps)
2	not found	Shed
8	48425	SUCR Entrance Station
16	82933	SUCR Mod # 7 Garage
5	113344	SUCR Apt 18A - Detached Garage

Rating		
Rating		Low
	High	
	Moderate	



Author: scastillo
5/9/2024 4:42 PM

0 500 Feet
Scale: 1:3,840


NPS Wildfire Risk Assessments
NPS Fire GIS
April 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

Sunset Crater 2

SUCR - Sunset Crater Volcano National Monument



Map Label	FMSS ID	Common Name
10	48429	SUCR Lava Flow Rest Room
9	48433	SUCR Lava Flow Interpretive Kiosk



Rating

Rating

Low

Not Found



Author: scastillo
5/9/2024 4:38 PM

0 500 Feet
Scale: 1:3,840



NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: SUCR - Sunset Crater

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
1	Fuel Pumps / Tanks	NPS	Not found	Building	Admin	Y	12/20/20	Unknown	45	Moderate	Not Designated		UNR
2	Shed	NPS	not found	Building	Admin	N	12/20/20	Unknown	52	Moderate	Not Designated		UNR
3	Shed	NPS	not found	Building	Admin	Y	12/20/20	Unknown	48	Moderate	Not Designated		UNR
4	Shed	NPS	not found	Building	Admin	Y	12/20/20	Unknown	69	High	Not Designated		UNR
5	SUCR Apt 18A - Detached Garage	NPS	113344	Building	Admin	Y	12/20/20	Unknown	49	Moderate	Not Designated		UNR
6	SUCR Apt 18B Detached Garage (being used as a Fire Cache)	NPS	113348	Building	Admin	Y	12/20/20	Unknown	51	Moderate	Not Designated		UNR
7	SUCR Apt Building	NPS	52742	Building	Admin	Y	12/20/20	Unknown	69	High	Not Designated		UNR
8	SUCR Entrance Station	NPS	48425	Building	Admin	Y	12/20/20	Unknown	76	High	Not Designated		UNR
9	SUCR Lava Flow Interpretive Kiosk	NPS	48433	None Found	Admin	N	12/20/20	Unknown	48	None	Not Designated		UNR
10	SUCR Lava Flow Rest Room	NPS	48429	Building	Public	N	12/20/20	Unknown	33	Low	Not Designated		UNR
11	SUCR Maintenance Office (Formerly Mod # 12)	NPS	48441	Building	Admin	Y	12/20/20	Unknown	32	Low	Not Designated		UNR
12	SUCR Mod # 12 Detached Garage	NPS	113349	Building	Admin	Y	12/20/20	Unknown	24	Low	Not Designated		UNR



NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: SUCR - Sunset Crater

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
13	SUCR Mod # 2 (closest to gas pumps)	NPS	48526	Building	Admin	Y	12/20/20	Unknown	36	Low	Not Designated	Spatial data comes from the FRPP section of FMSS. Each point was verified for positional accuracy.	UNR
14	SUCR Mod # 2 Detached Garage	NPS	113350	Building	Admin	Y	12/20/20	Unknown	27	Low	Not Designated		UNR
15	SUCR Mod # 7	NPS	82933	Building	Admin	Y	12/20/20	Unknown	30	Low	Not Designated	Spatial data comes from the FRPP section of FMSS. Each point was verified for positional accuracy.	UNR
16	SUCR Mod # 7 Garage	NPS	82933	Building	Admin	Y	12/20/20	Unknown	21	Low	Not Designated		UNR
17	SUCR Pump House Building	NPS	48439	Utility	Admin	N	12/20/20	Unknown	50	Moderate	Not Designated		UNR



NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: SUCR - Sunset Crater

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
18	SUCR Visitor Center	NPS	48424	Building	Admin	Y	12/20/20	Unknown	66	High	Not Designated	Spatial data comes from the FRPP section of FMSS. Each point was verified for positional accuracy.	UNR



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

NPS Unit - Location: SUCR - Sunset Crater

Label #	Facility/Community Name	Assessment Scale	Site Visit Type	Firewise Zone	Treatment	Treatment Description	Person Hours
1	Fuel Pumps / Tanks	Individual Facility					
		Individual Facility	Initial	1	Flammable ground cover such as leaf litter, woody debris or highly flammable vegetation should be removed	clear pine needles.	2.0
4	Shed	Individual Facility					
		Individual Facility	Initial	2	Limb trees 6 to 15 feet above ground		2.0
		Individual Facility					
		Individual Facility	Initial				
		Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		1.0
		Individual Facility					
		Individual Facility	Initial	0			



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

5	SUCR Apt 18A - Detached Garage	Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		2.0
		Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0
		Individual Facility	Initial	2	Remove dead or dying component of shrubs and trees		1.0
6	SUCR Apt 18B Detached Garage (being used as a Fire Cache)	Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		3.0
		Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0
7	SUCR Apt Building	Individual Facility					
		Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		2.0
		Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

8	SUCR Entrance Station	Individual Facility					
		Individual Facility	Initial	0			
9	SUCR Lava Flow Interpretive Kiosk	Individual Facility	Initial	1	Remove dead or dying component of shrubs and trees		8.0
10	SUCR Lava Flow Rest Room	Individual Facility					
		Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		0.5
11	SUCR Maintenance Office (Formerly Mod # 12)	Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0
		Individual Facility	Initial	2	Remove dead or dying component of shrubs and trees		6.0
12	SUCR Mod # 12 Detached Garage	Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		2.0
		Individual Facility	Initial	1	Mow dead/dying grass to less than 4 inches		1.0
		Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

13	SUCR Mod # 2 (closest to gas pumps)	Individual Facility					
		Individual Facility	Initial	1	Mow dead/dying grass to less than 4 inches		1.0
		Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0
14	SUCR Mod # 2 Detached Garage	Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0
		Individual Facility	Initial	2	Remove dead or dying component of shrubs and trees		5.0
15	SUCR Mod # 7	Individual Facility					
		Individual Facility	Initial	1	Mow dead/dying grass to less than 4 inches		1.0
		Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0
16	SUCR Mod # 7 Garage	Individual Facility	Initial	1	Limb trees 6 to 15 feet above ground		2.0
		Individual Facility	Initial	1	Mow dead/dying grass to less than 4 inches		1.0
		Individual Facility	Initial	1	Open crown spacing 10 to 30 feet depending on slope		8.0
		Individual Facility	Initial	1	Roof and gutters should be cleared of vegetative debris		1.0
17	SUCR Pump House Building	Individual Facility					



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

17	SUCR Pump House Building	Individual Facility	Initial	1	Limb trees 6 to 15 feet above ground		1.0
18	SUCR Visitor Center	Individual Facility	Initial	1	Clear adjacent and overhanging fuels to create 10 feet spacing between canopy and structure or chimney openings		4.0
		Individual Facility	Initial	1	Mow dead/dying grass to less than 4 inches		1.0
		Individual Facility	Initial	2	Open crown spacing 10 to 30 feet depending on slope		24.0



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: Sunset Crater Volcano National Monument - Sunset Crater

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
Fuel Pumps / Tanks	Individual Facility	PrepHold	Install sprinkler system -	1.0	-	
			Engine on scene -		-	
			Handline -	1.0	-	
Shed	Individual Facility	PrepHold	Install sprinkler system -	2.0	-	
			Engine on scene -		-	
Shed	Individual Facility	PrepHold	Install sprinkler system -	2.0	-	
			Engine on scene -		-	
Shed	Individual Facility	PrepHold	Engine on scene -		-	
			Install sprinkler system -	1.0	-	
SUCR Apt 18A - Detached Garage	Individual Facility	PrepHold	Install sprinkler system -	1.0	-	
			Engine on scene -		-	
SUCR Apt 18B Detached Garage (being used as a Fire Cache)	Individual Facility	PrepHold	Install sprinkler system -	2.0	-	
			Engine on scene -		-	
SUCR Apt Building	Individual Facility	PrepHold	Engine on scene -		-	
			Install sprinkler system -	4.0	-	
SUCR Entrance Station	Individual Facility	PrepHold	-		-	



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
SUCR Entrance Station	Individual Facility	PrepHold	Structure wrap -	2.0	-	
			-		-	
SUCR Lava Flow Interpretive Kiosk	Individual Facility		Engine on scene -		-	
SUCR Lava Flow Rest Room	Individual Facility	Standalone	Other, please describe. - no tactics necessary		-	
			-		-	
			-		-	
SUCR Maintenance Office (Formerly Mod # 12)	Individual Facility	PrepHold	Engine on scene -		-	
			Install sprinkler system -	3.0	-	
SUCR Mod # 12 Detached Garage	Individual Facility	PrepHold	Install sprinkler system -	1.0	-	
			Engine on scene -		-	
SUCR Mod # 2 (closest to gas pumps)	Individual Facility	PrepHold	-		-	
			-		-	
			Engine on scene -		-	
			Install sprinkler system -	4.0	-	
SUCR Mod # 2 Detached Garage	Individual Facility	PrepHold	-		-	
			Install sprinkler system -	1.0	-	
			Engine on scene -		-	



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
SUCR Mod # 2 Detached Garage	Individual Facility	PrepHold	-		-	
SUCR Mod # 7	Individual Facility	PrepHold	Engine on scene -		-	
			Install sprinkler system -	3.0	-	
SUCR Mod # 7 Garage	Individual Facility	PrepHold	Engine on scene -		-	
			Install sprinkler system -	2.0	-	
SUCR Pump House Building	Individual Facility	PrepHold	-		-	
			Engine on scene -		-	
SUCR Visitor Center	Individual Facility	PrepHold	Install sprinkler system -	10.0	-	
			Engine on scene -		-	



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Fuel Pumps / Tanks

Unit - Location: SUCR - Sunset Crater

FMSS ID: Not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: Castillo

Last Site Visit Date: 12/20/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.0832' **Long(WGS84):** -111° 32.582'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Heavy

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments:




2020_SUCR_Not found_Fuel Pumps / Tanks_Front.jpg

Score: 45
Rating: Moderate


Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Shed

Unit - Location: SUCR - Sunset Crater

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.0019' **Long(WGS84):** -111° 32.6472'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: 5ft to 30ft from facility

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:




2020_SUCR_not found _Shed_Z.jpg


Score: 52
Rating: Moderate




Asset Priority Index (API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Shed

Unit - Location: SUCR - Sunset Crater

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.1309' **Long(WGS84):** -111° 32.5969'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments:




2020_SUCR_not found_Shed_Z.jpg

Score: 48
Rating: Moderate


Asset Priority Index (API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Shed

Unit - Location: SUCR - Sunset Crater

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.1218' **Long(WGS84):** -111° 32.6069'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: Diesel and gas in open bay.

Assessment Comments:



2020_SUCR_not found_Shed_Z.jpg


Score: 69
Rating: High




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Apt 18A - Detached Garage

Unit - Location: SUCR - Sunset Crater

FMSS ID: 113344

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.1158' Long(WGS84): -111° 32.6329'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments:




2020_SUCR_113344_SUCR Apt 18A - Detached Garage_Z.jpg




Score: 49
Rating: Moderate




Asset Priority Index
(API):
19



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: *SUCR Apt 18B Detached Garage (being used as a Fire Cache)*

Unit - Location: SUCR - Sunset Crater
FMSS ID: 113348
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo
Last Site Visit Date: 12/20/2020


Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 35° 22.1068' **Long(WGS84):** -111° 32.6167'

Primary Access: Road
Ingress/Egress: Two or more roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope <5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: 5ft to 30ft from facility
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:



2020_SUCR_113348_SUCR Apt 18B Detached Garage (being used as a Fire Cache)_Z.jpg


Score: 51
Rating: Moderate




Asset Priority Index (API): 19



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Apt Building

Unit - Location: SUCR - Sunset Crater

FMSS ID: 52742

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 35° 22.1155' Long(WGS84): -111° 32.6203'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: Adjacent to/under deck of facility

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2020_SUCR_52742_SUCR Apt Building_Z.jpg


Score: 69
Rating: High




Asset Priority Index
(API):
43



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Entrance Station

Unit - Location: SUCR - Sunset Crater

FMSS ID: 48425

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 12/20/2020

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.187' Long(WGS84): -111° 32.6367'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Heavy

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2020_SUCR_48425_SUCR Entrance Station_P.jpg


Score: 76
Rating: High




Asset Priority Index
(API):
30



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Lava Flow Interpretive Kiosk

Unit - Location: SUCR - Sunset Crater

FMSS ID: 48433

Structure Type: None Found

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 12/20/2020

Rating: None

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 21.7957' **Long(WGS84):** -111° 31.0823'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Vinyl

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



SUCR-48433-SUCR Lava Flow Interpretive Kiosk-Front.jpg


Score: 48
Rating: None




Asset Priority Index (API):
0



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Lava Flow Rest Room

Unit - Location: SUCR - Sunset Crater

FMSS ID: 48429

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 12/20/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 35° 21.7986' Long(WGS84): -111° 31.1058'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Vinyl

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:




2020_SUCR_48429_SUCR Lava Flow Rest Room_Z.jpg


Score: 33
Rating: Low




Asset Priority Index
(API):
47




Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Maintenance Office (Formerly Mod # 12)

Unit - Location: SUCR - Sunset Crater

FMSS ID: 48441

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.1076' Long(WGS84): -111° 32.6611'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Vinyl

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:




2020_SUCR_48441_SUCR Maintenance Office (Formerly Mod # 12)_Z.jpg


Score: 32
Rating: Low



Asset Priority Index
(API):
32



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Mod # 12 Detached Garage

Unit - Location: SUCR - Sunset Crater

FMSS ID: 113349

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.1' Long(WGS84): -111° 32.6616'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2020_SUCR_113349_SUCR Mod # 12 Detached Garage_Z.jpg


Score: 24
Rating: Low




Asset Priority Index
(API):
7



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Mod # 2 (closest to gas pumps)

Unit - Location: SUCR - Sunset Crater

FMSS ID: 48526

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.0859' **Long(WGS84):** -111° 32.6298'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible,adjacent,no veg/debris clearance

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: Spatial data comes from the FRPP section of FMSS. Each point was verified for positional accuracy.



2020_SUCR_48526_SUCR Mod # 2 (closest to gas pumps)_Z.jpg


Score: 36
Rating: Low




Asset Priority Index (API): 13



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Mod # 2 Detached Garage

Unit - Location: SUCR - Sunset Crater

FMSS ID: 113350

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.0932' Long(WGS84): -111° 32.6257'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2020_SUCR_113350_SUCR Mod # 2 Detached Garage_Front.jpg


Score: 27
Rating: Low




Asset Priority Index
(API):
7



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Mod # 7

Unit - Location: SUCR - Sunset Crater

FMSS ID: 82933

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.0882' Long(WGS84): -111° 32.6469'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: Spatial data comes from the FRPP section of FMSS.
Each point was verified for positional accuracy.



2020_SUCR_82933_SUCR Mod # 7_Z.jpg


Score: 30
Rating: Low




Asset Priority Index
(API):
20



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Mod # 7 Garage

Unit - Location: SUCR - Sunset Crater

FMSS ID: 82933

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.0934' Long(WGS84): -111° 32.6535'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Vinyl

Foundation: Closed, 6in to 30in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2020_SUCR_82933_SUCR Mod # 7 Garage_Z.jpg


Score: 21
Rating: Low




Asset Priority Index
(API):
20



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Pump House Building

Unit - Location: SUCR - Sunset Crater

FMSS ID: 48439

Structure Type: Utility

Structure Use: Admin

Owner: NPS

Field Crew: castillo

Last Site Visit Date: 12/20/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 21.9981' Long(WGS84): -111° 32.6361'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Non-surfaced- gravel,dirt,grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2020_SUCR_48439_SUCR Pump House Building_Z.jpg


Score: 50
Rating: Moderate




Asset Priority Index
(API):
63



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: SUCR Visitor Center

Unit - Location: SUCR - Sunset Crater

FMSS ID: 48424

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: Castillo

Last Site Visit Date: 12/20/2020

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 22.1406' Long(WGS84): -111° 32.6148'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: Spatial data comes from the FRPP section of FMSS.

Each point was verified for positional accuracy.




2020_SUCR_48424_SUCR Visitor Center_Front.jpg


Score: 66
Rating: High




Asset Priority Index
(API):
78



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary

