


Capulin Volcano

CAVO - Capulin Volcano National Monument

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
10	92379	Covered Storage Shed
6	245920	Tan yurt
12	33572	Cavo Maintenance Shop
4	68760	Cavo Rim Parking Lot Romtech Vault Toilet
11	33564	Cavo Visitor Center & Administration Offices
5	33568	Cavo Residence #9 Bldg.#52
1	33585	Cavo Pump House
7	33566	Cavo Residence #3 Bldg.#50
2	92377	Historical Rock House
8	33565	Cavo Residence #2 Bldg. #48
3	69177	Cavo Comfort Station
9	92380	Metal Skid Storage Building



Author: sszturm
5/16/2024 11:29 AM

0 0.5 Miles

Scale: 1:12,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Source: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Cavo Residence #9 Bldg.#52

Unit - Location:

FMSS ID: 33568, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Castillo ,

Coordinates (DDM): 36° 46.70556420' N 103° 58.86237624' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes,

Revisit Interval: 10 yrs

Map Label: 5

Primary Access:

Ingress Egress:

Access Width:

Access Condition:

Bridge Condition:

Access and Turnarounds:

Facility Number or Sign:

Fuel Type:

Fuel Load:

Defensible Space:

Topography:

Roof Material:

Siding Material:

Foundation:



Firewood:

Water Supply:

Propane:

Overhead Hazards:

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Historical Rock House

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 92377, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo, February 17, 2021

Coordinates (DDM): 36° 46.71461340' N 103° 58.65515118' W

Rating: Low

Protection Level: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 2

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Other than all season

Bridge Condition: Greater than 300 ft with turnaround

Access and Turnarounds: Greater than 300 ft with turnaround

Facility Number or Sign:

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material:

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None



Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Covered Storage Shed

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 92379, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , February 17, 2021

Coordinates (DDM): 36° 46.63654158' N 103° 58.80836070' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Headquarters and Maintenance Area

Revisit Interval: 10 yrs

Map Label: 10

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: 5ft to 30ft from facility

Water Supply: Limited or dependent on electricity



Propane: None

Overhead Hazards: No overhead hazards

Comments: Hydrants are gravity fed, not fully pressurized.

Propane tanks near south end of Visitor Center parking lot.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Cavo Comfort Station

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 69177, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo, February 17, 2021

Coordinates (DDM): 36° 46.77778284' N 103° 58.61234400' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 3

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Greater than 300 ft with turnaround

Access and Turnarounds: Greater than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: no water due to a burst in a water line





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Cavo Residence #2 Bldg. #48

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 33565, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Castillo , February 17, 2021

Coordinates (DDM): 36° 46.70042454' N 103° 58.81526292' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Headquarters and Maintenance Area

Revisit Interval: 10 yrs

Map Label: 8

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Hydrants are gravity fed, not fully pressurized.
Propane tanks near south end of Visitor Center parking lot.
no water due to water line leak





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Cavo Rim Parking Lot Romtech Vault Toilet

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 68760, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , February 17, 2021

Coordinates (DDM): 36° 46.94084550' N 103° 58.34390004' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 4

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: all water shut off due to pipe burst





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Cavo Residence #3 Bldg.#50

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 33566, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Castillo , February 17, 2021

Coordinates (DDM): 36° 46.70156670' N 103° 58.83582150' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Headquarters and Maintenance Area

Revisit Interval: 10 yrs

Map Label: 7

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None

Water Supply: Limited or dependent on electricity



Propane: None

Overhead Hazards: No overhead hazards

Comments: Hydrants are gravity fed, not fully pressurized.

Propane tanks near south end of Visitor Center parking lot.

no water due to water line leak





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Cavo Visitor Center and Administration Offices

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 33564, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo, February 17, 2021

Coordinates (DDM): 36° 46.72298184' N 103° 58.80041508' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Headquarters and Maintenance Area

Revisit Interval: 10 yrs

Map Label: 11

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None

Water Supply: No reliable water source nearby



Propane: Present and fuels clearance

Overhead Hazards: No overhead hazards

Comments: Hydrants are gravity fed, not fully pressurized.

Propane tanks near south end of Visitor Center parking lot.

water line leak no water







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Tan yurt
Unit - Location: CAVO - Capulin Volcano
FMSS ID: 245920, **Local ID:**
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: Castillo , February 17, 2021
Coordinates (DDM): 36° 46.71706254' N 103° 58.85333250' W

Rating: Low
Protection Level: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Headquarters and Maintenance Area
Revisit Interval: 10 yrs
Map Label: 6

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, grade Less than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra, northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar, rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Limited or dependent on electricity
Propane: None
Overhead Hazards: No overhead hazards
Comments: "Not Ready" per FMSS. Hydrants are gravity fed, not fully pressurized. Propane tanks near south end of Visitor Center parking lot.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Cavo Pump House

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 33585, **Local ID:**

Structure Type, Use: Utility Site, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , February 17, 2021

Coordinates (DDM): 36° 46.85592726' N 103° 58.76847858' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied:

In Community: No,

Revisit Interval: 10 yrs

Map Label: 1

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Other than all season

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar, rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Cavo Maintenance Shop

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 33572, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , February 17, 2021

Coordinates (DDM): 36° 46.63389480' N 103° 58.79356224' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Headquarters and Maintenance Area

Revisit Interval: 10 yrs

Map Label: 12

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Limited or dependent on electricity

Propane: Present and fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Metal Skid Storage Building

Unit - Location: CAVO - Capulin Volcano

FMSS ID: 92380, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , February 17, 2021

Coordinates (DDM): 36° 46.62269310' N 103° 58.80893178' W

Rating: Moderate

Protection Level: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Headquarters and Maintenance Area

Revisit Interval: 10 yrs

Map Label: 9

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Hydrants are gravity fed, not fully pressurized.

Propane tanks near south end of Visitor Center parking lot.

