


NPS Wildfire Risk Assessments Assessment Locations

CURE- Curecanti National Recreation Area Overview

National Park Service
U.S. Department of the Interior



0 10 20 Miles

Author: sszturm
1/9/2023 1:56 PM

Intermountain Region Geographic Resources Division

May 2021

Data Sources: ESRI Basedata, NPS Park Data


NPS Wildfire Risk Assessment Project

NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



Curecanti National Recreation Area - Steven's Creek - Overview



Structure Groups

Location

● Stevens Creek



0


1

2


Miles

Author: sszturm
5/20/2024 11:29 AM

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



Author: sszturm
5/20/2024 11:14 AM



NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

Rating


Rating

Low

Stevens Creek

CURE - Curecanti National Recreation Area

National Park Service
U.S. Department of the Interior





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: North Willow Comfort Station

Unit - Location: CURE - Stevens Creek

FMSS ID: 75468

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: Castillo, Gallagher

Last Site Visit Date: 10/29/2020

Rating: Low

Protection Level : Unknown

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 28.8167' Long(WGS84): -107° 6.59333'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Non-surfaced- gravel,dirt,grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: Reliable water source near by is the lake.




CURE_75468_North Willow Comfort Station_Front.jpg


Score: 22
Rating: Low





Asset Priority Index
(API):
20



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Old Stevens Comfort Station

Unit - Location: CURE - Stevens Creek

FMSS ID: 75471

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: Castillo, Gallagher

Last Site Visit Date: 10/29/2020

Rating: Low

Protection Level : Unknown

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 29.1027' Long(WGS84): -107° 5.87066'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:




CURE_75471_Old Stevens Comfort Station_Front.jpg


Score: 39
Rating: Low




Asset Priority Index
(API):
20



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Stevens Creek Loop C Comfort Station

Unit - Location: CURE - Stevens Creek

FMSS ID: 75010

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: Castillo, Gallagher

Last Site Visit Date: 10/29/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 29.1931' **Long(WGS84):** -107° 5.62652'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Limited or dependent on electricity

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:



Assessment Comments: all treatments and tactics will be the same as water craft inspection facility




CURE_75010_Stevens Creek Loop C Comfort Station_Front.jpg

Score: 46
Rating: Moderate


Asset Priority Index (API): 37



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Stevens Creek Pumphouse

Unit - Location: CURE - Stevens Creek

FMSS ID: 75019

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: Castillo, Gallagher

Last Site Visit Date: 10/29/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 29.2193' **Long(WGS84):** -107° 5.57295'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Limited or dependent on electricity

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: create community / all treatments and tactics will be the same as water craft inspection facility




CURE_75019_Stevens Creek Pumphouse_Front.jpg

Score: 45
Rating: Moderate


Asset Priority Index (API): 13



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Stevens Creek Ampitheatre

Unit - Location: CURE - Stevens Creek

FMSS ID:

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: Skip Shawn Craig

Last Site Visit Date: 10/29/2020

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 29.1894' **Long(WGS84):** -107° 5.54169'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: No defensible space

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Combination of fire resisitant and combustible

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: create a community for this area. treatments and tactics at watercraft inspection station.




CURE__Stevens Creek Ampitheatre_Front.jpg


Score: 72
Rating: High




Asset Priority Index (API):
N/A




Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



1:24,000



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Stevens Creek Watercraft Inspection Station

Unit - Location: CURE - Stevens Creek

FMSS ID:

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: Castillo, Gallagher

Last Site Visit Date: 10/29/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 29.2312' Long(WGS84): -107° 5.51515'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Limited or dependent on electricity

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:




CURE_Stevens Creek Watercraft Inspection Station_Front.jpg


Score: 36
Rating: Low





Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Stevens Creek Fish Cleaning Station

Unit - Location: CURE - Stevens Creek

FMSS ID: 75013

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: Castillo, Gallagher

Last Site Visit Date: 10/29/2020

Rating: Low

Protection Level : Unknown

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 29.208' **Long(WGS84):** -107° 5.50404'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:




2015_CURE_75013_Stevens Creek Fish Cleaning Station_Z.jpg




Score: 39
Rating: Low



Asset Priority Index (API): 39



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Stevens Creek Loop B Comfort Station

Unit - Location: CURE - Stevens Creek

FMSS ID: 75001

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: Castillo, Gallagher

Last Site Visit Date: 10/29/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 29.1845' **Long(WGS84):** -107° 5.43529'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Limited or dependent on electricity

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:

Assessment Comments:




CURE_75001_Stevens Creek Loop B Comfort Station_Front.jpg




Score: 46
Rating: Moderate

Asset Priority Index (API): 37



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Stevens Creek Loop A Comfort Station

Unit - Location: CURE - Stevens Creek

FMSS ID: 74991

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: Castillo, Gallagher

Last Site Visit Date: 10/29/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 38° 29.2461' **Long(WGS84):** -107° 5.433'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is >300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Limited or dependent on electricity

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:

Assessment Comments:





CURE_74991_Stevens Creek Loop A Comfort Station_Front.jpg




Score: 54
Rating: Moderate


Asset Priority Index (API): 44



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary