


NPS Wildfire Risk Assessments Assessment Locations

Amistad National Recreation Area

National Park Service
U.S. Department of the Interior



Structure Locations

- | | |
|---------------------------|--------------------|
| ● AMIS - Headquarters (1) | ● Pecos (5) |
| ● Box Canyon (1) | ● Rough Canyon (3) |
| ● Diablo East (18) | ● San Pedro (6) |
| ● Governors Landing (7) | ● Spur 406 (2) |
| ● HWY 227 (4) | ● Sunrise (4) |



0

25
Miles

Author: sszturm
2/2/2022 10:26 AM

Intermountain Region Geographic Resources Division
May 2021

Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project


NPS Wildfire Risk Assessments

Assessment Locations

National Park Service
U.S. Department of the Interior



AMIS Headquarters- Overview



0 1 2 Miles


Author: scastillo
5/16/2024 2:36 PM

NPS Wildfire Risk Assessments
NPS Fire GIS
April 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

AMIS Headquarters

NPS Wildfire Risk Assessments

National Park Service
U.S. Department of the Interior



Rating
Low

Map Label	FMSS ID	Common Name
2	99070	Museum Storage Facility



0 1 Miles

Author: sszturm
2/2/2022 11:31 AM

Intermountain Region Geographic Resources Division
May 2021

Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Museum Storage Facility

Unit - Location: AMIS - AMIS - Headquarters

FMSS ID: 99070

Structure Type: Toilet

Structure Use: Public

Owner: NPS

Field Crew: Castillo

Last Site Visit Date: 5/8/2021

Rating: Low

Protection Level : Unknown

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 29° 25.202' Long(WGS84): -100° 54.3219'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments:




2021_AMIS_99070_Museum Storage Facility_Front.jpg




Score: 14
Rating: Low



Asset Priority Index
(API):
68



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary