


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



CHAM - Chamizal National Memorial Overview



0 0.5 1 Miles

Author: sszturm
12/13/2022 8:57 AM


Intermountain Region Geographic Resources Division
May 2021
Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project

Chamizal National Memorial

CHAM - Chamizal National Memorial

National Park Service
U.S. Department of the Interior



Author: sszturm
12/13/2022 8:41 AM

0 500 1,000 1,500 Feet
Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
August 2022
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: AMPHITHEATRE



Unit - Location: CHAM - Chamizal National Memorial
FMSS ID: 73768
Structure Type: Toilet
Structure Use: Public
Owner: NPS
Field Crew: SAGU
Last Site Visit Date: 5/13/2013

Rating: Low
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 31° 45.9897' **Long(WGS84):** -106° 27.3237'


Primary Access: Road
Ingress/Egress: Two or more roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is >300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: >100ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:

Score: 12
Rating: Low



Asset Priority Index
(API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: COMFORT STATION



Unit - Location: CHAM - Chamizal National Memorial
FMSS ID: 72863
Structure Type: Toilet
Structure Use: Public
Owner: NPS
Field Crew: SAGU
Last Site Visit Date: 5/13/2013

Rating: Low
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 31° 45.9696' **Long(WGS84):** -106° 27.2831'


Primary Access: Road
Ingress/Egress: Two or more roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is >300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: >100ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:

Score: 12
Rating: Low


Asset Priority Index
(API):
29



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Los Paisanos Gallery and Administration Building


Unit - Location: CHAM - Chamizal National Memorial
FMSS ID: 112904
Structure Type: No Wildland Risk
Structure Use: Admin
Owner: NPS
Field Crew: SAGU Spannuth
Last Site Visit Date: 5/13/2013

Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 31° 46.0624' Long(WGS84): -106° 27.2746'



Primary Access:
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space: >100ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass, shrub, hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar, rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat:
Assessment Comments:

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
82



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>


Facility: Chamizal Maintenance Shop

Unit - Location: CHAM - Chamizal National Memorial
FMSS ID: 72861
Structure Type: No Wildland Risk
Structure Use: Admin
Owner: NPS
Field Crew: SAGU Spannuth
Last Site Visit Date: 5/13/2013



Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 31° 46.0984' **Long(WGS84):** -106° 27.2376'

Primary Access:
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space: >100ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass, shrub, hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar, rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat: plant and general maintenance materials.
Assessment Comments:

Score:
Rating: NoWildlandRisk
Asset Priority Index (API): 30



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>


Facility: Chamizal Visitor Center

Unit - Location: CHAM - Chamizal National Memorial
FMSS ID: 72622
Structure Type: No Wildland Risk
Structure Use: Admin
Owner: NPS
Field Crew: SAGU Spannuth
Last Site Visit Date: 5/13/2013

Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 31° 46.0641' **Long(WGS84):** -106° 27.2358'

Primary Access:
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space: >100ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass, shrub, hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar, rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat:
Assessment Comments:

Score:
Rating: NoWildlandRisk
Asset Priority Index (API): 67



Factors Driving the Ratings

