


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



Bandelier Nation Park-Overview



Bandelier National Monument - Entrance Area - Entrance Road

National Park Service
U.S. Department of the Interior



NPS Wildfire Risk Assessments


Map Label	FMSS ID	Common Name
1	91182	B 58 Amphitheater AV Building / Speaker house
10	31585	Quarters 56
11	31586	Quarters 102
12	97526	FEMOOFFICEMH128
13	97527	Quarters MH-127 , 00000127
14	31583	Quarters 54
15	31584	Quarters 55
16	31587	Quarters 103
17	31582	Quarters 53
18	31581	Quarters 52
19		LAUNDRY QUARTERS 103
2	searched not found	ENTRANCE STATION RESTROOM
20	31592	Quarters MH-126 , 00000126
21	108464	EQUIPMENTSTORAGEBUILDING
22		MAINT OFFICE
23		MAINT SHED
24	116885	B133EQUIPMENTBUILDING
3	31479	HB26 ENTRANCE STATION
5	31641	B-67 Comfort Station
6	31622	AMPHITHEATER
7	5324	B-66 Comfort Station
8	5323	B-65 Comfort Station
9	103786	FUMOOFFICEMH129

Rating

High

Moderate

Low



0 500 1,000 1,500 2,000 2,500 US Feet

Author: SHartsburg
5/1/2022 10:25 AM

Intermountain Region Geographic Resources Division
February 2018
Data Sources: ESRI Basedata, NPS Park Data
NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: BAND - Entrance Area/Road

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
1	B 58 Amphitheater AV Building / Speaker house	NPS	91182	Building	Admin	N	12/7/20	Unknown	53	Moderate	Not Designated		UNR
2	ENTRANCE STATION RESTROOM	NPS	searched not found	Building	Admin	Y	12/7/20	Unknown	42	Low	Not Designated	no treatment needed stand alone	UNR
3	HB26 ENTRANCE STATION	NPS	31479	Building	Admin	Y	12/7/20	Unknown	34	Low	Not Designated	no treatment needed stand alone	UNR
4	HB-30FIRETOWER	NPS	31646	Building	Admin	Y	12/7/20	Unknown	52	Moderate	Not Designated		UNR
5	B-67 Comfort Station	NPS	31641	Toilet	Public	N	12/7/20	Unknown	67	High	Not Designated		UNR
6	AMPHITHEATER	NPS	31622	Other	Admin	N	12/7/20	Unknown	58	Moderate	Unknown		UNR
7	B-66 Comfort Station	NPS	5324	Toilet	Public	N	12/7/20	Unknown	68	High	Not Designated		UNR
8	B-65 Comfort Station	NPS	5323	Toilet	Public	N	12/7/20	Unknown	68	High	Not Designated		UNR
9	FUMOOFFICEMH 129	NPS	103786	Building	Admin	N	12/7/20	Unknown	68	High	Not Designated		UNR
10	Quarters 56	NPS	31585	Building	Residence	Y	12/7/20	Unknown	59	Moderate	Unknown		UNR
11	Quarters 102	NPS	31586	Building	Residence	Y	12/7/20	Unknown	35	Low	Unknown		UNR
12	FEMOOFFICEMH1 28	NPS	97526	Building	Admin	N	12/7/20	Unknown	61	Moderate	Not Designated		UNR
13	Quarters MH-127 , 00000127	NPS	97527	Building	Residence	Y	12/7/20	Unknown	53	Moderate	Not Designated		UNR
14	Quarters 54	NPS	31583	Building	Residence	Y	12/7/20	Unknown	60	Moderate	Not Designated		UNR



NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: BAND - Entrance Area/Road

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
15	Quarters 55	NPS	31584	Building	Residence	Y	12/7/20	Unknown	47	Moderate	Not Designated		UNR
16	Quarters 103	NPS	31587	Building	Residence	Y	12/7/20	Unknown	47	Moderate	Unknown		UNR
17	Quarters 53	NPS	31582	Building	Residence	Y	12/7/20	Unknown	46	Moderate	Unknown		UNR
18	Quarters 52	NPS	31581	Building	Residence	Y	12/7/20	Unknown	55	Moderate	Unknown		UNR
19	LAUNDRY QUARTERS 103	NPS		Building	Public	N	12/7/20	Unknown	39	Low	Not Designated		UNR
20	Quarters MH-126 , 00000126	NPS	31592	Building	Admin	Y	12/7/20	Unknown	64	High	Not Designated		UNR
21	EQUIPMENTSTOR AGEBUILDING	NPS	108464	Building	Admin	N	12/7/20	Unknown	50	Moderate	Not Designated		UNR
22	MAINT OFFICE	NPS		Building	Admin	Y	12/7/20	Unknown	44	Low	Not Designated		UNR
23	MAINT SHED	NPS		Building	Admin	N	12/7/20	Unknown	44	Low	Not Designated		UNR
24	B133EQUIPMENT BUILDING	NPS	116885	Building	Admin	Y	12/7/20	Unknown	43	Low	Not Designated		UNR
25	B- 100RADIOTOWER BUILDING	NPS	46920	Building	Admin	Y	12/7/20	Unknown	52	Moderate	Not Designated		UNR



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

NPS Unit - Location: BAND - Entrance Area/Road

Label #	Facility/Community Name	Assessment Scale	Site Visit Type	Firewise Zone	Treatment	Treatment Description	Person Hours	Date
0	Mesa Top	Community	Initial	1	Limb trees 6 to 15 feet above ground		20.0	12/18/20
		Community	Initial	2	Remove dead or dying component of shrubs and trees		40.0	12/18/20
1	B 58 Amphitheater AV Building / Speaker house	Individual Facility						
10	Quarters 56	Facility In Community (Mesa Top)						
11	Quarters 102	Facility In Community (Mesa Top)						
12	FEMOOFFICEMH128	Facility In Community (Mesa Top)						
13	Quarters MH-127 , 00000127	Facility In Community (Mesa Top)						
14	Quarters 54	Facility In Community (Mesa Top)						
15	Quarters 55	Facility In Community (Mesa Top)						
16	Quarters 103	Facility In Community (Mesa Top)						



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

17	Quarters 53	Facility In Community (Mesa Top)						
18	Quarters 52	Facility In Community (Mesa Top)						
19	LAUNDRY QUARTERS 103	Facility In Community (Mesa Top)						
2	ENTRANCE STATION RESTROOM	Individual Facility		1	Flammable ground cover such as leaf litter, woody debris or highly flammable vegetation should be removed		5.0	3/18/17
		Individual Facility		1	Flammable ground cover such as leaf litter, woody debris or highly flammable vegetation should be removed		5.0	12/16/20
		Individual Facility		2	Flammable ground cover should be removed or isolated		5.0	3/18/17
		Individual Facility		2	Flammable ground cover should be removed or isolated		5.0	12/16/20
20	Quarters MH-126 , 00000126	Facility In Community (Mesa Top)						
21	EQUIPMENTSTORAGEBUILDING	Facility In Community (Mesa Top)						



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

22	MAINT OFFICE	Facility In Community (Mesa Top)						
23	MAINT SHED	Facility In Community (Mesa Top)						
24	B133EQUIPMENTBUILDING	Facility In Community (Mesa Top)						
25	B-100RADIOTOWERBUILDING	Facility In Community (Frijoles Canyon)	Initial	2	Flammable ground cover should be removed or isolated		5.0	3/18/17
		Facility In Community (Frijoles Canyon)	Initial	2	Flammable ground cover should be removed or isolated		5.0	12/16/20
		Facility In Community (Frijoles Canyon)	Initial	2	Limb trees 6 to 15 feet above ground		5.0	3/18/17
		Facility In Community (Frijoles Canyon)	Initial	2	Limb trees 6 to 15 feet above ground		5.0	12/16/20
3	HB26 ENTRANCE STATION	Individual Facility		1	Roof and gutters should be cleared of vegetative debris		1.0	3/18/17
		Individual Facility		1	Roof and gutters should be cleared of vegetative debris		1.0	12/16/20



NPS Wildand Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

3	HB26 ENTRANCE STATION	Individual Facility		2	Flammable ground cover should be removed or isolated		5.0	3/18/17
		Individual Facility		2	Flammable ground cover should be removed or isolated		5.0	12/16/20
4	HB-30FIRETOWER	Individual Facility	Initial	2	Flammable ground cover should be removed or isolated		5.0	3/18/17
		Individual Facility	Initial	2	Flammable ground cover should be removed or isolated		5.0	12/16/20
		Individual Facility	Initial	2	Limb trees 6 to 15 feet above ground		5.0	3/18/17
		Individual Facility	Initial	2	Limb trees 6 to 15 feet above ground		5.0	12/16/20
5	B-67 Comfort Station	Facility In Community (Mesa Top)						
6	AMPHITHEATER	Facility In Community (Mesa Top)						
7	B-66 Comfort Station	Facility In Community (Mesa Top)						
8	B-65 Comfort Station	Facility In Community (Mesa Top)						
9	FUMOOFFICEMH129	Facility In Community (Mesa Top)						



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: B 58 Amphitheater AV Building / Speaker house

Unit - Location: BAND - Entrance Area/Road

FMSS ID: 91182

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: shawn castillo

Last Site Visit Date: 12/7/2020

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Mesa Top

Lat(WGS84): 35° 47.7666' Long(WGS84): -106° 16.9289'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, 6in to 30in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: No safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat:

Assessment Comments:



2020_BAND_91182_B 58 Amphitheater AV Building / Speaker house_Front




Score: 53
Rating: Moderate

Asset Priority Index
(API):
34



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: ENTRANCE STATION RESTROOM

Unit - Location: BAND - Entrance Area/Road

FMSS ID: searched not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: shawn castillo

Last Site Visit Date: 12/7/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 47.6969' Long(WGS84): -106° 16.5434'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:

Assessment Comments: no treatment needed stand alone




2020_BAND_searched not found_ENTRANCE STATION RESTROOM_Front

Score: 42
Rating: Low

Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: HB26 ENTRANCE STATION

Unit - Location: BAND - Entrance Area/Road

FMSS ID: 31479

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: shawn castillo

Last Site Visit Date: 12/7/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 47.7089' Long(WGS84): -106° 16.5349'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade>5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:

Assessment Comments: no treatment needed stand alone



Photo 1.jpg




Score: 34
Rating: Low



Asset Priority Index
(API):
90



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: HB-30FIRETOWER

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31646
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 35° 46.7711' **Long(WGS84):** -106° 15.9518'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1 lane (<18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 21% to 30%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:




2020_BAND_31646_HB-30FIRETOWER_Front



Score: 52 **Asset Priority Index (API): 76**
Rating: Moderate



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: B-67 Comfort Station

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31641
Structure Type: Toilet
Structure Use: Public
Owner: NPS
Field Crew: shawn castillo
Last Site Visit Date: 12/7/2020

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.7647' **Long(WGS84):** -106° 17.0499'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: No safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:

Score: 67
Rating: High

Asset Priority Index
(API):
44



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: AMPHITHEATER

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31622
Structure Type: Other
Structure Use: Admin
Owner: NPS
Field Crew: shawn castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.7744' **Long(WGS84):** -106° 16.9369'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Not applicable
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: No safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:



2020_BAND_31622_AMPHITHEATER_Front



Score: 58
Rating: Moderate
Asset Priority Index (API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: B-66 Comfort Station

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 5324
Structure Type: Toilet
Structure Use: Public
Owner: NPS
Field Crew: shawn castillo
Last Site Visit Date: 12/7/2020

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.7621' **Long(WGS84):** -106° 16.8426'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: No safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:



2020_BAND_5324_B-66 Comfort Station_Front




Score: 68
Rating: High



Asset Priority Index (API): 44



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: B-65 Comfort Station

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 5323
Structure Type: Toilet
Structure Use: Public
Owner: NPS
Field Crew: shawn castillo
Last Site Visit Date: 12/7/2020

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.7988' **Long(WGS84):** -106° 16.8027'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: No safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:



2020_BAND_5323_B-65 Comfort Station_Front


Score: 68
Rating: High



Asset Priority Index (API): 44



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: FUMOOFFICEMH129

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 103786
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.5881' **Long(WGS84):** -106° 16.8008'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: FUELS
Assessment Comments:



2020_BAND_103786_FUMOOFFICEMH129_Front




Score: 68
Rating: High



Asset Priority Index (API):
0



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 56

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31585
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.6811' **Long(WGS84):** -106° 16.7868'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: 5ft to 30ft from facility
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: NULL
Assessment Comments:




2020_BAND_31585_Quarters 56_Front



Score: 59
Rating: Moderate
Asset Priority Index (API): 40



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 102

Unit - Location: BAND - Entrance Area/Road

FMSS ID: 31586

Structure Type: Building

Structure Use: Residence

Owner: NPS

Field Crew: Castillo

Last Site Visit Date: 12/7/2020

Rating: Low

Protection Level : Unknown

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Mesa Top

Lat(WGS84): 35° 47.6097' Long(WGS84): -106° 16.7829'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: UNKNOWN

Assessment Comments:



2020_BAND_31586_Quarters 102_Front




Score: 35
Rating: Low



Asset Priority Index
(API):
40



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: FEMOOFFICEMH128

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 97526
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.5684' **Long(WGS84):** -106° 16.782'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:




2020_BAND_97526_FEMOOFFICEMH128_Front

Score: 61
Rating: Moderate
Asset Priority Index (API):
0



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters MH-127 , 00000127

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 97527
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.5731' **Long(WGS84):** -106° 16.7621'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: 5ft to 30ft from facility
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:




2020_BAND_97527_Quarters MH-127 , 00000127_Front



Score: 53
Rating: Moderate
Asset Priority Index (API):
0



Factors Driving the Ratings



● Facility
 ■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 54

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31583
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.6572' **Long(WGS84):** -106° 16.7619'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: 5ft to 30ft from facility
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:




2020_BAND_31583_Quarters 54_Front



Score: 60
Rating: Moderate
Asset Priority Index (API): 40



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 55

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31584
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020


Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.6233' **Long(WGS84):** -106° 16.7502'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: Adjacent to/under deck of facility
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:





2020_BAND_31584_Quarters 55_Front

Score: 47
Rating: Moderate
Asset Priority Index (API): 40



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 103

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31587
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020


Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.5969' **Long(WGS84):** -106° 16.7461'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: NONE
Assessment Comments:




2020_BAND_31587_Quarters 103_Front

Score: 47
Rating: Moderate
Asset Priority Index (API): 23



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 53

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31582
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020


Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.6485' **Long(WGS84):** -106° 16.7427'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: 5ft to 30ft from facility
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: NULL
Assessment Comments:




2020_BAND_31582_Quarters 53_Front

Score: 46
Rating: Moderate
Asset Priority Index (API): 40



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters 52

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31581
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Unknown
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.6477' **Long(WGS84):** -106° 16.7206'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: >30 ft from facility
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments:




2020_BAND_31581_Quarters 52_Front



Score: 55
Rating: Moderate
Asset Priority Index (API): 40



Factors Driving the Ratings



● Facility
 ■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: LAUNDRY QUARTERS 103

Unit - Location: BAND - Entrance Area/Road

FMSS ID:

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: Castillo

Last Site Visit Date: 12/7/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Mesa Top

Lat(WGS84): 35° 47.6064' Long(WGS84): -106° 16.6943'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: NONE

Assessment Comments:



2020_BAND__LAUNDRY QUARTERS 103_Front




Score: 39
Rating: Low



Asset Priority Index
(API):
N/A



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Quarters MH-126 , 00000126

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 31592
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.5804' **Long(WGS84):** -106° 16.6923'




Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: NONE
Assessment Comments:

Score: 64
Rating: High

Asset Priority Index (API):
0



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: EQUIPMENTSTORAGEBUILDING

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 108464
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.4118' **Long(WGS84):** -106° 16.6613'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: FUEL PUMPS
Assessment Comments:




2020_BAND_108464_EQUIPMENTSTORAGEBUILDING_Front



Score: 50
Rating: Moderate
Asset Priority Index (API): 30



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: MAINT OFFICE

Unit - Location: BAND - Entrance Area/Road

FMSS ID:

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: Castillo

Last Site Visit Date: 12/7/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Mesa Top

Lat(WGS84): 35° 47.4242' Long(WGS84): -106° 16.6546'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: FUEL ADJACENT

Assessment Comments:




2020_BAND__MAINT OFFICE_Front

Score: 44
Rating: Low

Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: MAINT SHED

Unit - Location: BAND - Entrance Area/Road

FMSS ID:

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: Castillo

Last Site Visit Date: 12/7/2020

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? Yes - Mesa Top

Lat(WGS84): 35° 47.3917' Long(WGS84): -106° 16.6531'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: No reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: PROPANE

Assessment Comments:



2020_BAND__MAINT SHED_Front




Score: 44
Rating: Low

Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: B133EQUIPMENTBUILDING

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 116885
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Mesa Top
Lat(WGS84): 35° 47.4073' **Long(WGS84):** -106° 16.6483'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: FUEL PUMP
Assessment Comments:



2020_BAND_116885_B133EQUIPMENTBUILDING_Front




Score: 43
Rating: Low



Asset Priority Index (API): 42



Factors Driving the Ratings



● Facility
 ■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: B-100RADIOTOWERBUILDING

Unit - Location: BAND - Entrance Area/Road
FMSS ID: 46920
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: Castillo
Last Site Visit Date: 12/7/2020

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Frijoles Canyon
Lat(WGS84): 35° 46.7675' **Long(WGS84):** -106° 15.9519'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1 lane (<18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: No reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:




2020_BAND_46920_B-100RADIOTOWERBUILDING_Front



Score: 52
Rating: Moderate
Asset Priority Index (API): 0



Factors Driving the Ratings



● Facility
■ NPS Boundary