


NPS Wildfire Risk Assessments Assessment Locations

CRLA -Crater Lake National Park - Overview

National Park Service
U.S. Department of the Interior




NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



CRLA - Headquarters - Overview



Steel Circle


CRLA - Crater Lake National Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
47	61626	Qtrs. 18 Steel Circle
49	61616	Qtrs. 15 Steel Circle
56	62896	Qtrs. 227 Steel Circle
55		tennis court
48	61631	Qtrs. 26 Steel Circle
51	61618	Qtrs. 17 Steel Circle
13	NA	Munson Flow Mon. Sta.
52	61585	Community Bldg. #222
54	61587	Fitness Center #504
53	62894	Qtrs. 221 Steel Circle
50	62893	Qtrs. 219 Steel Circle
57	62895	Qtrs. 226 Steel Circle
47	NA	Shed
47	NA	Shed 2

Rating	
Facility	Moderate
High	



Author: sszturm
7/19/2024 9:58 AM


0 500 1,000 1,500 Feet
Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
July 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

Stone House and Sleepy Hallow

CRLA - Crater Lake National Park

National Park Service
U.S. Department of the Interior



Rating	
Facility	Moderate
	High

Map Label	FMSS ID	Common Name
28	61628	Qtrs. 20 Stone House
27	61593	Open Storage Bldg. #10
31	61591	Open Storage Bldg. #7
46	61584	Administration Bldg. #1
38	61636	Qtrs. 34 House (Historic Hospital)
43	61598	Trails Shop Bldg. #37
21	61637	Qtrs. 83 Sleepy Hollow
18	61641	Qtrs. 87 Sleepy Hollow
20	62883	Qtrs. 88 Sleepy Hollow
25	61589	Maintenance Bldg. #14
17	NA	Headquarters Water tank
24	61612	Science and Learning Center #19
35	61594	Ranger Station Bldg. #3
29	61605	Warehouse Bldg. #4
39	61588	Garage #33
44	62897	Storage Bldg. #36 (old phone)
23	62890	Qtrs. 90 Sleepy Hollow
22	62887	Qtrs. 89 Sleepy Hollow
15	61640	Qtrs. 86 Sleepy Hollow
36	61630	Qtrs. 25 Stone House
34	80602	Garage 24A
33	61629	Qtrs. 24 Stone House
37	61632	Qtrs. 28 Stone House
42	61633	Qtrs. 30 Stone House
41	61634	Qtrs. 31 Stone House
40	61635	Qtrs. 32 Stone House
45	61603	Visitor Center Bldg. #2
19	61638	Qtrs. 84 Sleepy Hollow
16	61639	Qtrs. 85 Sleepy Hollow
14	61590	Nine Stall Bldg. #40
30	61595	Rat Hall Bldg. #5
32	61602	Trails Cache Bldg. #13
14	NA	Storage shed



Author: sszturm
7/19/2024 9:43 AM

0 500 1,000 1,500 Feet
Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
July 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 20 Stone House

Unit - Location: CRLA - Headquarters

FMSS ID: 61628, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.97314946' N 122° 08.15744388' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 28

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30 in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Open Storage Bldg.#10

Unit - Location: CRLA - Headquarters

FMSS ID: 61593, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm , July 21, 2022

Coordinates (DDM): 42° 53.81083254' N 122° 08.16780186' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 27

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Open Storage Bldg.#7

Unit - Location: CRLA - Headquarters

FMSS ID: 61591, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm , July 21, 2022

Coordinates (DDM): 42° 53.81338314' N 122° 08.15427594' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 31

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 18 Steel Circle

Unit - Location: CRLA - Headquarters

FMSS ID: 61626, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 20, 2022

Coordinates (DDM): 42° 53.59950828' N 122° 08.19385818' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qtrs

Revisit Interval: 5 yrs

Map Label: 47

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 15 Steel Circle

Unit - Location: CRLA - Headquarters

FMSS ID: 61616, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 20, 2022

Coordinates (DDM): 42° 53.52021180' N 122° 08.13985686' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qtrs

Revisit Interval: 5 yrs

Map Label: 49

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Administration Bldg. #1

Unit - Location: CRLA - Headquarters

FMSS ID: 61584, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.83244280' N 122° 08.02424406' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 46

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 34 House (Historic Hospital)

Unit - Location: CRLA - Headquarters

FMSS ID: 61636, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.82571920' N 122° 08.09797104' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 38

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Trails Shop Bldg. #37

Unit - Location: CRLA - Headquarters

FMSS ID: 61598, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.77069344' N 122° 08.08017432' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 43

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 227 Steel Circle

Unit - Location: CRLA - Headquarters

FMSS ID: 62896, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 20, 2022

Coordinates (DDM): 42° 53.50771500' N 122° 08.08363476' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qtrs

Revisit Interval: 5 yrs

Map Label: 56

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD. This building is also used as an archives storage facility.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: tennis court

Unit - Location: CRLA - Headquarters

FMSS ID: , **Local ID:**

Structure Type, Use: Other, Other

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 20, 2022

Coordinates (DDM): 42° 53.52896676' N 122° 08.08478124' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Steel Circle - Qrts

Revisit Interval: 5 yrs

Map Label: 55

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Not applicable

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD. Asphalt tennis court.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 83 Sleepy Hollow

Unit - Location: CRLA - Headquarters

FMSS ID: 61637, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 22, 2022

Coordinates (DDM): 42° 53.70501660' N 122° 08.33435604' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 21

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 87 Sleepy Hollow

Unit - Location: CRLA - Headquarters

FMSS ID: 61641, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 22, 2022

Coordinates (DDM): 42° 53.67177540' N 122° 08.37838068' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 18

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6 in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 88 Sleepy Hollow

Unit - Location: CRLA - Headquarters

FMSS ID: 62883, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 22, 2022

Coordinates (DDM): 42° 53.68292496' N 122° 08.35555758' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 20

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Maintenance Bldg. #14

Unit - Location: CRLA - Headquarters

FMSS ID: 61589, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 22, 2022

Coordinates (DDM): 42° 53.72226600' N 122° 08.19251796' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 25

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Headquarters Water tank

Unit - Location: CRLA - Headquarters

FMSS ID: NA, **Local ID:**

Structure Type, Use: Utility Site (Water, Gas, Elec), Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 54.00631872' N 122° 08.38356654' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 17

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Non-surfaced- gravel, dirt, grade Greater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 31% to 40%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Science and Learning Center #19

Unit - Location: CRLA - Headquarters

FMSS ID: 61612, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 54.01163316' N 122° 08.24745126' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 24

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Ranger Station Bldg. #3

Unit - Location: CRLA - Headquarters

FMSS ID: 61594, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.79093492' N 122° 08.11694328' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 35

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30 in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Warehouse Bldg. #4

Unit - Location: CRLA - Headquarters

FMSS ID: 61605, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.78865660' N 122° 08.15645484' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 29

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 26 Steel Circle

Unit - Location: CRLA - Headquarters

FMSS ID: 61631, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 20, 2022

Coordinates (DDM): 42° 53.55221004' N 122° 08.17970730' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qtrs

Revisit Interval: 5 yrs

Map Label: 48

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 17 Steel Circle

Unit - Location: CRLA - Headquarters

FMSS ID: 61618, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.51225334' N 122° 08.11134510' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qtrs

Revisit Interval: 5 yrs

Map Label: 51

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Garage #33

Unit - Location: CRLA - Headquarters

FMSS ID: 61588, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.84166666' N 122° 08.09448744' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 39

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 31% to 40%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Storage Bldg. #36 (old phone)

Unit - Location: CRLA - Headquarters

FMSS ID: 62897, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.78608254' N 122° 08.07929742' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 44

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 90 Sleepy Hollow

Unit - Location: CRLA - Headquarters

FMSS ID: 62890, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 25, 2022

Coordinates (DDM): 42° 53.69203032' N 122° 08.29179840' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 23

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6 in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 89 Sleepy Hollow

Unit - Location: CRLA - Headquarters

FMSS ID: 62887, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 25, 2022

Coordinates (DDM): 42° 53.69139204' N 122° 08.32176528' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 22

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 86 Sleepy Hollow

Unit - Location: CRLA - Headquarters

FMSS ID: 61640, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 22, 2022

Coordinates (DDM): 42° 53.67136920' N 122° 08.40344460' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 15

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6 in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Munson Flow Mon. Sta.

Unit - Location: CRLA - Headquarters

FMSS ID: NA, **Local ID:**

Structure Type, Use: Utility Site (Water, Gas, Elec), Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.25131658' N 122° 08.19447780' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 5 yrs

Map Label: 13

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel, dirt, grade Greater than 5%

Bridge Condition: Less than 300 ft with no turnaround

Access and Turnarounds: Less than 300 ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 25 Stone House

Unit - Location: CRLA - Headquarters

FMSS ID: 61630, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.88061818' N 122° 08.11192848' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 36

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Garage 24A

Unit - Location: CRLA - Headquarters

FMSS ID: 80602, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.88873444' N 122° 08.11872474' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 34

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Combination of fire resisitant and combustible

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 24 Stone House

Unit - Location: CRLA - Headquarters

FMSS ID: 61629, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.89604256' N 122° 08.12223510' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 33

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 28 Stone House

Unit - Location: CRLA - Headquarters

FMSS ID: 61632, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.90729256' N 122° 08.11102218' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 37

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30 in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Community Bldg. #222

Unit - Location: CRLA - Headquarters

FMSS ID: 61585, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.56256778' N 122° 08.11041864' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Steel Circle - Qrts

Revisit Interval: 5 yrs

Map Label: 52

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Fitness Center #504

Unit - Location: CRLA - Headquarters

FMSS ID: 61587, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.58007644' N 122° 08.09521830' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qrts

Revisit Interval: 5 yrs

Map Label: 54

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Vinyl

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 221 Steel Circle

Unit - Location: CRLA - Headquarters

FMSS ID: 62894, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 20, 2022

Coordinates (DDM): 42° 53.60193126' N 122° 08.10733938' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qtrs

Revisit Interval: 5 yrs

Map Label: 53

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 219 Steel Circle

Unit - Location: CRLA - Headquarters

FMSS ID: 62893, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 20, 2022

Coordinates (DDM): 42° 53.62182318' N 122° 08.13283338' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qtrs

Revisit Interval: 5 yrs

Map Label: 50

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 30 Stone House

Unit - Location: CRLA - Headquarters

FMSS ID: 61633, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, August 11, 2022

Coordinates (DDM): 42° 53.87112318' N 122° 08.08851828' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 42

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 31 Stone House

Unit - Location: CRLA - Headquarters

FMSS ID: 61634, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, August 11, 2022

Coordinates (DDM): 42° 53.86145178' N 122° 08.08967022' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 41

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 32 Stone House

Unit - Location: CRLA - Headquarters

FMSS ID: 61635, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, August 11, 2022

Coordinates (DDM): 42° 53.85161928' N 122° 08.09129388' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 40

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Visitor Center Bldg. #2

Unit - Location: CRLA - Headquarters

FMSS ID: 61603, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.81744604' N 122° 08.05825146' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 45

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 226 Steel Circle

Unit - Location: CRLA - Headquarters

FMSS ID: 62895, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 20, 2022

Coordinates (DDM): 42° 53.53486944' N 122° 08.04272004' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qtrs

Revisit Interval: 5 yrs

Map Label: 57

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 84 Sleepy Hollow

Unit - Location: CRLA - Headquarters

FMSS ID: 61638, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 22, 2022

Coordinates (DDM): 42° 53.71099956' N 122° 08.37208596' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 19

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6 in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Qtrs. 85 Sleepy Hollow

Unit - Location: CRLA - Headquarters

FMSS ID: 61639, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, January 22, 2022

Coordinates (DDM): 42° 53.70970728' N 122° 08.39593248' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 16

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6 in masonry exposed


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Nine Stall Bldg. #40

Unit - Location: CRLA - Headquarters

FMSS ID: 61590, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.69705100' N 122° 08.40825732' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 14

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Fire resistant- tar, rubberized

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed


Firewood: 5ft to 30ft from facility

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Rat Hall Bldg. #5

Unit - Location: CRLA - Headquarters

FMSS ID: 61595, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.75443002' N 122° 08.15637168' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 30

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Trails Cache Bldg. #13

Unit - Location: CRLA - Headquarters

FMSS ID: 61602, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.81000676' N 122° 08.12777442' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 32

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Storage shed

Unit - Location: CRLA - Headquarters

FMSS ID: NA, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.71255002' N 122° 08.38449528' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Park Headquarters

Revisit Interval: 5 yrs

Map Label: 14

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Fire resistant- tar, rubberized

Siding Material: Wood or open sided

Foundation: Closed, 6 in to 30 in masonry exposed

Firewood: None


Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Shed

Unit - Location: CRLA - Headquarters

FMSS ID: NA, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.56195638' N 122° 08.18404260' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qrts

Revisit Interval: 5 yrs

Map Label: 47

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Shed 2

Unit - Location: CRLA - Headquarters

FMSS ID: NA, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Szturm, July 21, 2022

Coordinates (DDM): 42° 53.55102756' N 122° 08.07284832' W

Rating: Moderate

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Steel Circle - Qrts

Revisit Interval: 5 yrs

Map Label: 47

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, grade Less than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments: Created by RISD.

