


NPS Wildfire Risk Assessments Assessment Locations

Craters of the Moon National Monument

National Park Service
U.S. Department of the Interior



Structure Groups

Facility

Location

● CRMO



0 3 6 Miles

Author: scastillo
9/27/2023 12:10 PM

Intermountain Region Geographic Resources Division
September 2023
Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project


Craters of the Moon 2

CRMP - Craters Of The Moon National Monument and Preserve

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
1		Vault Toilet
10	NA	Solar Panels
11	586493	BLDG 22 A&B
12	69436	BLDG 20
13	69433	BLDG 19 Shed
14	69433	BLDG 19
15	71040	Ampitheatre
16	69453	BLDG Log Restroom
17	84429	BLDG Vault Toilet Lava Campground
18	69458	BLDG Entrance Kiosk
19	69439	BLDG Log Storage
2	69460	BLDG North End Vault Toilet
20	69459	BLDG Air Quality Monitoring Station
21	NA	Roads Maintenance
22	69465	BLDG Tree Molds Vault Toilet
23	69463	BLDG Devils Orchard Mens Vault Toilet
24		Yurt
25	69457	BLDG Well Control
26	69438	BLDG 21 Shed
27	69438	BLDG 21
28	110486	BLDG 20 Support Building (Shed)
29	69455	BLDG Brick Restroom
3	69456	BLDG Chlorinator
30	69464	BLDG Devils Orchard Womens Vault Toilet
31	69467	BLDG Caves Womens Vault Toilet
32	69466	BLDG Caves Mens Vault Toilet
4	69424	BLDG Visitors Center
5	NA	Shed (Recycle / Paper)
6	114102	BLDG Shed (NHA storage)
7	69428	BLDG Maintenance Shop
8	69429	BLDG 23 ABCD
9	110488	BLDG 22A&B Support Building (Shed)



Author: scastillo
9/27/2023 11:52 AM

0 1 2 Miles
Scale: 1:50,000

NPS Wildfire Risk Assessments
NPS Fire GIS
August 2023
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project


Craters Of the Moon 1

CRMP - Craters Of The Moon National Monument and Preserve

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
22	69465	BLDG Tree Molds Vault Toilet
31	69467	BLDG Caves Womens Vault Toilet
32	69466	BLDG Caves Mens Vault Toilet



Rating	
Rating	
	Moderate



Author: scastillo
9/27/2023 11:59 AM

0 0.25 0.5 0.75 1 Miles
Scale: 1:24,000

NPS Wildfire Risk Assessments
NPS Fire GIS
August 2023
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Vault Toilet Lava Campground
Unit - Location: CRMO - CRMO
FMSS ID: 84429, **Local ID:**
Structure Type, Use: Toilet, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , July 23, 2023
Coordinates (DDM): 43° 27.675' N 113° 33.441' W

Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Lava Flow Campground Area
Revisit Interval: 5 yrs
Map Label: 17

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, grade Greater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Shed (NHA storage)

Unit - Location: CRMO - CRMO

FMSS ID: 114102, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 26, 2017

Coordinates (DDM): 43° 27.737' N 113° 33.695' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 6

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 20 Support Building (Shed)

Unit - Location: CRMO - CRMO

FMSS ID: 110486, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 27.76496226' N 113° 33.57097116' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 28

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Chlorinator

Unit - Location: CRMO - CRMO

FMSS ID: 69456, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 28.38421158' N 113° 33.93051204' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 3

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Greater than 300 ft with turnaround

Access and Turnarounds: Greater than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Entrance Kiosk

Unit - Location: CRMO - CRMO

FMSS ID: 69458, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.670' N 113° 33.403' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Lava Flow Campground Area

Revisit Interval: 5 yrs

Map Label: 18

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, grade Greater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Log Storage

Unit - Location: CRMO - CRMO

FMSS ID: 69439, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.565' N 113° 33.325' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Lava Flow Campground Area

Revisit Interval: 5 yrs

Map Label: 19

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Log construction

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Shed (Recycle / Paper)

Unit - Location: CRMO - CRMO

FMSS ID: NA, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 26, 2017

Coordinates (DDM): 43° 27.743' N 113° 33.695' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 5

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Caves Womens Vault Toilet

Unit - Location: CRMO - CRMO

FMSS ID: 69467, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 26.740' N 113° 32.106' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 5 yrs

Map Label: 31

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, grade Greater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 20

Unit - Location: CRMO - CRMO

FMSS ID: 69436, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 27.75854682' N 113° 33.56813856' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 12

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 19

Unit - Location: CRMO - CRMO

FMSS ID: 69433, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 27.74809488' N 113° 33.54887322' W

Rating: Not Surveyed

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 14

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply:

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Devils Orchard Womens Vault Toilet

Unit - Location: CRMO - CRMO

FMSS ID: 69464, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.075' N 113° 32.335' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 5 yrs

Map Label: 30

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 19 Shed

Unit - Location: CRMO - CRMO

FMSS ID: 69433, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 27.75505824' N 113° 33.54939246' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 13

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: Adjacent to/under deck of facility

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 22 AandB

Unit - Location: CRMO - CRMO

FMSS ID: 586493, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.762' N 113° 33.620' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 11

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 21

Unit - Location: CRMO - CRMO

FMSS ID: 69438, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 27.76403280' N 113° 33.59022942' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 27

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Air Quality Monitoring Station

Unit - Location: CRMO - CRMO

FMSS ID: 69459, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 27.63119706' N 113° 33.30056088' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Lava Flow Campground Area

Revisit Interval: 5 yrs

Map Label: 20

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, grade Greater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: No defensible space

Topography: Slope Greater than 40%

Roof Material: Fire resistant- tar, rubberized

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Brick Restroom

Unit - Location: CRMO - CRMO

FMSS ID: 69455, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.634' N 113° 33.535' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Lava Flow Campground Area

Revisit Interval: 5 yrs

Map Label: 29

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, grade Greater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Devils Orchard Mens Vault Toilet

Unit - Location: CRMO - CRMO

FMSS ID: 69463, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.076' N 113° 32.338' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 5 yrs

Map Label: 23

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 21 Shed

Unit - Location: CRMO - CRMO

FMSS ID: 69438, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 27.76953594' N 113° 33.59615862' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 26

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 23 ABCD

Unit - Location: CRMO - CRMO

FMSS ID: 69429, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 27.74770308' N 113° 33.64415520' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 8

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Caves Mens Vault Toilet

Unit - Location: CRMO - CRMO

FMSS ID: 69466, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 26.738' N 113° 32.103' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 5 yrs

Map Label: 32

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, grade Greater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Visitors Center

Unit - Location: CRMO - CRMO

FMSS ID: 69424, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.723' N 113° 33.704' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 4

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Well Control

Unit - Location: CRMO - CRMO

FMSS ID: 69457, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 28.61738490' N 113° 35.23963716' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 25

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: No defensible space

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Ampitheatre

Unit - Location: CRMO - CRMO

FMSS ID: 71040, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.587' N 113° 33.507' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Lava Flow Campground Area

Revisit Interval: 5 yrs

Map Label: 15

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, grade Greater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Limited or dependent on electricity

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments: This is the center point for the screen building, not including the stage and seating area.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Maintenance Shop

Unit - Location: CRMO - CRMO

FMSS ID: 69428, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 26, 2017

Coordinates (DDM): 43° 27.743' N 113° 33.679' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 7

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: Adjacent to/under deck of facility

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG 22AandB Support Building (Shed)

Unit - Location: CRMO - CRMO

FMSS ID: 110488, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.769' N 113° 33.622' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 9

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG North End Vault Toilet

Unit - Location: CRMO - CRMO

FMSS ID: 69460, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 28.38052074' N 113° 34.00665876' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 2

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Greater than 300 ft with turnaround

Access and Turnarounds: Greater than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Treatments and tactics include adjacent campground area.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Log Restroom

Unit - Location: CRMO - CRMO

FMSS ID: 69453, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.659' N 113° 33.469' W

Rating: Low

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Lava Flow Campground Area

Revisit Interval: 5 yrs

Map Label: 16

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Log construction

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: BLDG Tree Molds Vault Toilet

Unit - Location: CRMO - CRMO

FMSS ID: 69465, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 25.70365164' N 113° 32.92057872' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 22

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1.5 lanes (Greater than 18')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Yurt

Unit - Location: CRMO - CRMO

FMSS ID: , **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 28.57564152' N 113° 35.40171576' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: No,

Revisit Interval: yrs

Map Label: 24

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: 5ft to 30ft from facility

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Vault Toilet

Unit - Location: CRMO - CRMO

FMSS ID: , **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Vaughn, July 26, 2017

Coordinates (DDM): 43° 28.58529120' N 113° 35.37152856' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 1

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Roads Maintenance

Unit - Location: CRMO - CRMO

FMSS ID: NA, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.602' N 113° 33.202' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Lava Flow Campground Area

Revisit Interval: 5 yrs

Map Label: 21

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Solar Panels

Unit - Location: CRMO - CRMO

FMSS ID: NA, **Local ID:**

Structure Type, Use: Utility Site (Water, Gas, Elec), Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , July 23, 2023

Coordinates (DDM): 43° 27.780' N 113° 33.621' W

Rating: High

Protection Level: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Visitor Center

Revisit Interval: 5 yrs

Map Label: 10

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel, dirt, grade Greater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:

