


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



GLAC - Glacier National Park - Overview




NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



GLAC - Hwy 2-North - Overview




Lincoln Creek Patrol Cabin

GLAC - Glacier National Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
758	80394	WLD Middle Fork Building 617 Lincoln Creek Patrol Cabin
759		WLD Dudy Homestead Cabin
760		WLD Harrison Creek Dooty Homestead Pit Toilet



Author: sszturm
8/1/2024 5:14 AM

0 0.25 0.5 0.75 1 Miles

Scale: 1:24,000

Rating

Rating

 High

NPS Wildfire Risk Assessments
NPS Fire GIS
August 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project


Nyack Barn

GLAC - Glacier National Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
761	61152	WLD Middle Fork Building 369 Nyack Barn
762	80407	WLD Middle Fork Building 375 Nyack Fire Cache



Rating

Facility

 High



Author: sszturm
8/1/2024 5:11 AM



NPS Wildfire Risk Assessments
NPS Fire GIS
August 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: WLD Middle Fork Building 369 Nyack Barn

Unit - Location: GLAC - Hwy 2-North

FMSS ID: 61152, **Local ID:**

Structure Type, Use: Building, No known use

Owner: National Park Service

Field Crew, Visit Date: Fire Effects Crew, August 27, 2014

Coordinates (DDM): 48° 26.41714524' N 113° 47.79370962' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 761

Primary Access: Foot

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Heavy

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Log construction

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: Structure is deteriorating and is no longer being used.






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: WLD Middle Fork Building 375 Nyack Fire Cache
Unit - Location: GLAC - Hwy 2-North
FMSS ID: 80407, **Local ID:**
Structure Type, Use: Building, No known use
Owner: National Park Service
Field Crew, Visit Date: Fire Effects Crew, August 27, 2014
Coordinates (DDM): 48° 26.40183912' N 113° 47.79249102' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 762

Primary Access: Foot
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Heavy
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Log construction
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments: Structure is deteriorating and no longer used.





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: WLD Middle Fork Building 617 Lincoln Creek Patrol Cabin

Unit - Location: GLAC - Hwy 2-North

FMSS ID: 80394, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: K Weidman, September 15, 2014

Coordinates (DDM): 48° 29.87072436' N 113° 52.86634602' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 758

Primary Access: Foot

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Log construction

Foundation: Open or deck

Firewood: Greater than 30 ft from facility

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: WLD Harrison Creek Dooty Homestead Pit Toilet
Unit - Location: GLAC - Hwy 2-North
FMSS ID: , **Local ID:**
Structure Type, Use: Toilet, Administrative
Owner: National Park Service
Field Crew, Visit Date: K Kaszuba, September 2, 2014
Coordinates (DDM): 48° 29.67188880' N 113° 50.92341096' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 760

Primary Access: Foot
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: No defensible space
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: WLD Dudy Homestead Cabin

Unit - Location: GLAC - Hwy 2-North

FMSS ID: , **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: K Weidman, September 2, 2014

Coordinates (DDM): 48° 29.66835480' N 113° 50.96496288' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 759

Primary Access: Foot

Ingress Egress: N/A,access by foot,boat,or air only

Access Width: N/A,access by foot,boat,or air only

Access Condition: N/A,access by foot,boat,or air only

Bridge Condition: N/A,access by foot,boat,or air only

Access and Turnarounds: N/A,access by foot,boat,or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Heavy

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: Adjacent to/under deck of facility

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:

