



NPS Wildfire Risk Assessments Assessment Locations

Castillo De San Marcos National Monument-Overview

National Park Service
U.S. Department of the Interior




Author: scastillo
9/18/2024 4:33 PM

NPS Wildfire Risk Assessments
NPS Fire GIS
April 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

Castillo De San Marcos
CASA - Castillo De San Marcos National Monument



Map Label	FMSS ID	Common Name
1		Castillo de San Marcos
10	13654	CASA Gas Shed
11	32798	Chief of Maintenance Office
2	13593	CASA Fee Booth
3	31710	CASA Gift Shop Eastern National Park & Monument
4	13648	CASA Restrooms
5	13649	CASA Ranger Offices
6		Reconstructed Cubo Line
7		City Gate Pillars
8	13650	CASA Administration Building
9	13655	CASA Maintenance Bay Storage





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Castillo de San Marcos

Unit - Location: CASA - CASA

FMSS ID:

Structure Type: No Wildland Risk

Structure Use: Unknown

Owner: NPS

Field Crew: Vaughn

Last Site Visit Date: 5/1/2017

Rating: NoWildlandRisk

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community? Yes - CASA Buildings

Lat(WGS84): 29° 53.8713' Long(WGS84): -81° 18.6912'

Primary Access: Road

Ingress/Egress:

Access Width:

Access Condition:

Bridge Condition:

Access & Turnarounds:

Facility Number/Sign:

Defensible Space:

Fuel Load (w/in 300 ft):

Fuel Type (w/in 300ft):

Topography (w/in 300ft):

Roof Material:

Siding Material:

Foundation:

Fences/Decks:

Firewood:

Propane Tanks:

Water Supply:

Overhead Hazards:

Safety Zones:

Additional Obstacles:



Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE:

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
N/A



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CASA Fee Booth

Unit - Location: CASA - CASA
FMSS ID: 13593
Structure Type: No Wildland Risk
Structure Use: Unknown
Owner: NPS
Field Crew: Vaughn
Last Site Visit Date: 5/1/2017


Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community? Yes - CASA Buildings
Lat(WGS84): 29° 53.8384' Long(WGS84): -81° 18.6779'

Primary Access: Road
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space:
Fuel Load (w/in 300 ft):
Fuel Type (w/in 300ft):
Topography (w/in 300ft):
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor
Cont Stat (GSF)

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
45



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CASA Gift Shop Eastern National Park & Monument

Unit - Location: CASA - CASA
FMSS ID: 31710
Structure Type: No Wildland Risk
Structure Use: Unknown
Owner: NPS
Field Crew: Vaughn
Last Site Visit Date: 5/1/2017


Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community? Yes - CASA Buildings
Lat(WGS84): 29° 53.8601' Long(WGS84): -81° 18.6917'

Primary Access: Road
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space:
Fuel Load (w/in 300 ft):
Fuel Type (w/in 300ft):
Topography (w/in 300ft):
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Center (GSF)

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
55



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CASA Restrooms

Unit - Location: CASA - CASA
FMSS ID: 13648
Structure Type: No Wildland Risk
Structure Use: Unknown
Owner: NPS
Field Crew: Vaughn
Last Site Visit Date: 5/1/2017


Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community? Yes - CASA Buildings
Lat(WGS84): 29° 53.8655' Long(WGS84): -81° 18.6796'

Primary Access: Road
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space:
Fuel Load (w/in 300 ft):
Fuel Type (w/in 300ft):
Topography (w/in 300ft):
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
78



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CASA Ranger Offices

Unit - Location: CASA - CASA
FMSS ID: 13649
Structure Type: No Wildland Risk
Structure Use: Unknown
Owner: NPS
Field Crew: Vaughn
Last Site Visit Date: 5/1/2017


Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community? Yes - CASA Buildings
Lat(WGS84): 29° 53.874' Long(WGS84): -81° 18.6787'

Primary Access: Road
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space:
Fuel Load (w/in 300 ft):
Fuel Type (w/in 300ft):
Topography (w/in 300ft):
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
53



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Reconstructed Cubo Line

Unit - Location: CASA - CASA

FMSS ID:

Structure Type: No Wildland Risk

Structure Use: NotApplicable

Owner: NPS

Field Crew: Vaughn

Last Site Visit Date: 5/1/2017

Rating: NoWildlandRisk

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community? Yes - CASA Buildings

Lat(WGS84): 29° 53.8762' Long(WGS84): -81° 18.7611'

Primary Access: Road

Ingress/Egress:

Access Width:

Access Condition:

Bridge Condition:

Access & Turnarounds:

Facility Number/Sign:

Defensible Space:

Fuel Load (w/in 300 ft):

Fuel Type (w/in 300ft):

Topography (w/in 300ft):

Roof Material:

Siding Material:

Foundation:

Fences/Decks:

Firewood:

Propane Tanks:

Water Supply:

Overhead Hazards:

Safety Zones:

Additional Obstacles:


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE:

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
N/A



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: City Gate Pillars

Unit - Location: CASA - CASA

FMSS ID:

Structure Type: No Wildland Risk

Structure Use: NotApplicable

Owner: NPS

Field Crew: Vaughn

Last Site Visit Date: 5/1/2017

Rating: NoWildlandRisk

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community? Yes - CASA Buildings

Lat(WGS84): 29° 53.872' Long(WGS84): -81° 18.8154'

Primary Access: Road

Ingress/Egress:

Access Width:

Access Condition:

Bridge Condition:

Access & Turnarounds:

Facility Number/Sign:

Defensible Space:

Fuel Load (w/in 300 ft):

Fuel Type (w/in 300ft):

Topography (w/in 300ft):

Roof Material:

Siding Material:

Foundation:

Fences/Decks:

Firewood:

Propane Tanks:

Water Supply:

Overhead Hazards:

Safety Zones:

Additional Obstacles:


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE:

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
N/A



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CASA Administration Building

Unit - Location: CASA - CASA
FMSS ID: 13650
Structure Type: No Wildland Risk
Structure Use: Unknown
Owner: NPS
Field Crew: Vaughn
Last Site Visit Date: 5/1/2017


Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community? Yes - CASA Buildings
Lat(WGS84): 29° 53.9439' Long(WGS84): -81° 18.8258'

Primary Access: Road
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space:
Fuel Load (w/in 300 ft):
Fuel Type (w/in 300ft):
Topography (w/in 300ft):
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:

Hazmat:
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
70



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CASA Maintenance Bay Storage

Unit - Location: CASA - CASA
FMSS ID: 13655
Structure Type: No Wildland Risk
Structure Use: Unknown
Owner: NPS
Field Crew: Vaughn
Last Site Visit Date: 5/1/2017


Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local ID]
In a Community? Yes - CASA Buildings
Lat(WGS84): 29° 53.9467' Long(WGS84): -81° 18.8011'

Primary Access: Road
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space:
Fuel Load (w/in 300 ft):
Fuel Type (w/in 300ft):
Topography (w/in 300ft):
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg.
Warehouse (GSF)

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
30



Factors Driving the Ratings



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CASA Gas Shed

Unit - Location: CASA - CASA
FMSS ID: 13654
Structure Type: No Wildland Risk
Structure Use: Unknown
Owner: NPS
Field Crew: Vaughn
Last Site Visit Date: 5/1/2017


Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community? Yes - CASA Buildings
Lat(WGS84): 29° 53.9431' Long(WGS84): -81° 18.8079'

Primary Access: Road
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space:
Fuel Load (w/in 300 ft):
Fuel Type (w/in 300ft):
Topography (w/in 300ft):
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:
Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
30



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Chief of Maintenance Office

Unit - Location: CASA - CASA
FMSS ID: 32798
Structure Type: No Wildland Risk
Structure Use: Unknown
Owner: NPS
Field Crew: Vaughn
Last Site Visit Date: 5/1/2017


Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community? Yes - CASA Buildings
Lat(WGS84): 29° 53.9395' Long(WGS84): -81° 18.8155'

Primary Access: Road
Ingress/Egress:
Access Width:
Access Condition:
Bridge Condition:
Access & Turnarounds:
Facility Number/Sign:
Defensible Space:
Fuel Load (w/in 300 ft):
Fuel Type (w/in 300ft):
Topography (w/in 300ft):
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply:
Overhead Hazards:
Safety Zones:
Additional Obstacles:
Triage Category:

Hazmat:
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)

Score:
Rating:
NoWildlandRisk

Asset Priority Index
(API):
20



Factors Driving the Ratings

