



NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



MORR - Morristown National Historic Park - Overview



Author: sszturm
9/18/2024 1:36 PM


NPS Wildfire Risk Assessments
NPS Fire GIS
September 2024
Data Sources: ESRI Basedata, NPS Park Data

Washington's Headquarters
MORR - Morristown National Historical Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
23	62628	Museum
24	62663	Ford Mansion
25	62664	Caretakers Cottage
26	69628	Quarters # 47



Rating

Rating

 Low



Author: sszturm
9/18/2024 2:11 PM

0 500 Feet
Scale: 1:3,000

NPS Wildfire Risk Assessments
NPS Fire
September 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Caretakers Cottage

Unit - Location: MORR - MORR - Washington's Headquarters

FMSS ID: 62664, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo, November 21, 2021

Coordinates (DDM): 40° 47.79735234' N 074° 27.98578182' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Ford Mansion / Museum

Revisit Interval: 6 yrs

Map Label: 25

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Museum

Unit - Location: MORR - MORR - Washington's Headquarters

FMSS ID: 62628, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo, November 21, 2021

Coordinates (DDM): 40° 47.84274726' N 074° 28.02613614' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Ford Mansion / Museum

Revisit Interval: 6 yrs

Map Label: 23

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None



Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE:

Bldg. Museum Repository (GSF)





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Quarters # 47

Unit - Location: MORR - MORR - Washington's Headquarters

FMSS ID: 69628, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Castillo, November 21, 2021

Coordinates (DDM): 40° 47.83525938' N 074° 27.97761840' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Ford Mansion / Museum

Revisit Interval: 6 yrs

Map Label: 26

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A

Firewood: None


Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE:

Bldg. Housing, Support (GSF)





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Ford Mansion

Unit - Location: MORR - MORR - Washington's Headquarters

FMSS ID: 62663, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo, November 21, 2021

Coordinates (DDM): 40° 47.78164458' N 074° 28.00434360' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Ford Mansion / Museum

Revisit Interval: 6 yrs

Map Label: 24

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 100 ft treated

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed

Firewood: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Propane: None

Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE:

Bldg. Museum Repository (GSF)

