


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



BRCA - Bryce Canyon National Park - Overview






Rating

Rating

High

Map Label	FMSS ID	Common Name
95	46431	Rainbow Dryhead North
96	46430	Rainbow Dryhead South
97	46424	Rainbow Comfort Station





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Rainbow Dryhead South
Unit - Location: BRCA - Rainbow Point
FMSS ID: 46430, **Local ID:**
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: Castillo, March 27, 2021
Coordinates (DDM): 37° 28.48900002' N 112° 14.44300002' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 8 yrs
Map Label: 96

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Heavy
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment



For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Rainbow Dryhead North
Unit - Location: BRCA - Rainbow Point
FMSS ID: 46431, **Local ID:**
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: Castillo, March 27, 2021
Coordinates (DDM): 37° 28.50300000' N 112° 14.44699998' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 8 yrs
Map Label: 95

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Heavy
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Rainbow Comfort Station

Unit - Location: BRCA - Rainbow Point

FMSS ID: 46424, **Local ID:**

Structure Type, Use: Building, Unknown

Owner: National Park Service

Field Crew, Visit Date: Castillo, March 27, 2021

Coordinates (DDM): 37° 28.49599998' N 112° 14.39299998' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 8 yrs

Map Label: 97

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope 21% to 30%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed

Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE

