


Cedar Breaks

CEBR - Cedar Breaks National Monument

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
1	46905	Pump House
3	52351	Ranger/Fee Office
4	47007	Visitor Center
5	47008	Visitor Center Restroom
6	47011	Fee Booth
7	47020	Maintenance Shed
8	47431	Apartments
9	52332	Campground RR
2	NA	Log Cabin



Rating	
	High
	Moderate
	Low



Author: sszturm
10/28/2024 9:07 AM

0 0.35 0.7 1.05 1.4 Miles

Scale: 1:34,000

NPS Wildfire Risk Assessments
NPS Fire GIS
October 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Campground RR

Unit - Location: CEBR - Cedar Breaks

FMSS ID: 52332, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo, March 27, 2021

Coordinates (DDM): 37° 36.62613324' N 112° 49.84657896' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 9

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and fuels clearance

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Pump House

Unit - Location: CEBR - Cedar Breaks

FMSS ID: 46905, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo, March 27, 2021

Coordinates (DDM): 37° 36.42594960' N 112° 50.78474262' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 1

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed

Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Ranger/Fee Office

Unit - Location: CEBR - Cedar Breaks

FMSS ID: 52351, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo, March 27, 2021

Coordinates (DDM): 37° 36.56493150' N 112° 50.25794052' W

Rating: Low

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: No,

Revisit Interval: 10 yrs

Map Label: 3

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Greater than 300 ft with turnaround

Access and Turnarounds: Greater than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Vistor Center

Unit - Location: CEBR - Cedar Breaks

FMSS ID: 47007, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo, March 27, 2021

Coordinates (DDM): 37° 36.77855010' N 112° 50.25098538' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: No,

Revisit Interval: 10 yrs

Map Label: 4

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Combination of fire resisitant and combustible

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Fee Booth
Unit - Location: CEBR - Cedar Breaks
FMSS ID: 47011, **Local ID:**
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo, March 27, 2021
Coordinates (DDM): 37° 36.74111196' N 112° 50.23458090' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 10 yrs
Map Label: 6

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Combination of fire resitant and combustible
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Apartments

Unit - Location: CEBR - Cedar Breaks

FMSS ID: 47431, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: Castillo, March 27, 2021

Coordinates (DDM): 37° 36.60632490' N 112° 50.15888820' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: No,

Revisit Interval: 10 yrs

Map Label: 8

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed


Firewood: 5ft to 30ft from facility

Water Supply: Reliable water source nearby

Propane: Present and little to no fuels clearance

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Maintenance Shed

Unit - Location: CEBR - Cedar Breaks

FMSS ID: 47020, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo, March 27, 2021

Coordinates (DDM): 37° 36.65093040' N 112° 50.15900244' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: No,

Revisit Interval: 10 yrs

Map Label: 7

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and little to no fuels clearance

Overhead Hazards: Overhead hazards will limit aircraft

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Visitor Center Restroom

Unit - Location: CEBR - Cedar Breaks

FMSS ID: 47008, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo, March 27, 2021

Coordinates (DDM): 37° 36.73766232' N 112° 50.24644452' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 10 yrs

Map Label: 5

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Log Cabin
Unit - Location: CEBR - Cedar Breaks
FMSS ID: , **Local ID:**
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: Castillo, March 27, 2021
Coordinates (DDM): 37° 36.54141858' N 112° 50.27717826' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 10 yrs
Map Label: 2

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Log construction
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:

NO PHOTO AVAILABLE

