


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



ROMO - Rocky Mountain National Park - Overview




Wild Basin

ROMO - Rocky Mountain National Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
254	23661	Q-0251-H S Wild Basin RS & Quarters 00000251
255	23683	B-1035-N Wild Basin Vault Toilet
259	Finch Lake	Finch Lake TH
261	Utility	Utility Panel Deerhaven
262	23681	B-0995-N Abandoned Light Plant - EXCESS
263	23675	B-0683-H Deerhaven T Cabin
264	23674	Q-0682-H S 2-bdr house, Deerhaven 00000682
265		INHOLDER STRUCTURE
266	not found	WILDBASIN LODGE CISTERN/PUMPHOUSE
267	98025	B-0987-N Pumphouse - new by Good house
268	23682	B-0996-N Sandbeach TrlHd Vault Toilet
269	23679	Q-0894-N S 3-Bdrm House (Good) 00000894
271	23684	B-1046-N Wild Basin Kiosk
272	23657	Q-0032-H S Wild Basin Seasonal Cabin 00000032
273	23677	B-0819-N Tackroom/Storage @ Ranger Station
275	98016	B-0851-N Pumphouse, Deer Haven
276	23673	Q-0681-H S Deerhaven Lodge 00000681
277	23676	B-0788-H Deerhaven Garage
278	not found	AIR INTAKE SHED
279	97844	B-0253-N Pumphouse by 0032, Wild Basin
280		INHOLDER STRUCTURE



Author: sszturm
12/2/2024 9:17 AM

0 0.25 0.5 0.75 Miles

Scale: 1:18,000

NPS Wildfire Risk Assessments
NPS Fire GIS
December 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-0819-N Tackroom/Storage @ Ranger Station

Unit - Location: ROMO - Wild Basin

FMSS ID: 23677, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 12.51860790' N 105° 33.98092308' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Wild Basin

Revisit Interval: 4 yrs

Map Label: 273

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed


Firewood: 5ft to 30ft from facility

Water Supply: Reliable water source nearby

Propane: Present and fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-1035-N Wild Basin Vault Toilet

Unit - Location: ROMO - Wild Basin

FMSS ID: 23683, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 12.49047762' N 105° 33.98516172' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Wild Basin

Revisit Interval: 4 yrs

Map Label: 255

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Q-0032-H S Wild Basin Seasonal Cabin 00000032

Unit - Location: ROMO - Wild Basin

FMSS ID: 23657, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 12.48267360' N 105° 34.04492280' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Wild Basin

Revisit Interval: 4 yrs

Map Label: 272

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed



Firewood: 5ft to 30ft from facility

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Q-0681-H S Deerhaven Lodge 00000681

Unit - Location: ROMO - Wild Basin

FMSS ID: 23673, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 12.70880736' N 105° 33.18847614' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Deerhaven

Revisit Interval: 4 yrs

Map Label: 276

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 31% to 40%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed


Firewood: 5ft to 30ft from facility

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-0683-H Deerhaven T Cabin

Unit - Location: ROMO - Wild Basin

FMSS ID: 23675, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 12.71481510' N 105° 33.16210068' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Deerhaven

Revisit Interval: 4 yrs

Map Label: 263

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 31% to 40%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: Adjacent to/under deck of facility

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-0788-H Deerhaven Garage

Unit - Location: ROMO - Wild Basin

FMSS ID: 23676, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 12.71738886' N 105° 33.17182632' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Deerhaven

Revisit Interval: 4 yrs

Map Label: 277

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 31% to 40%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: Adjacent to/under deck of facility

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Q-0682-H S 2-bdr house, Deerhaven 00000682
Unit - Location: ROMO - Wild Basin
FMSS ID: 23674, **Local ID:**
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , September 28, 2022
Coordinates (DDM): 40° 12.70962438' N 105° 33.14615304' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Deerhaven
Revisit Interval: 4 yrs
Map Label: 264

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: 5ft to 30ft from facility
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-0995-N Abandoned Light Plant - EXCESS

Unit - Location: ROMO - Wild Basin

FMSS ID: 23681, **Local ID:**

Structure Type, Use: Building, Unknown

Owner: National Park Service

Field Crew, Visit Date: ,

Coordinates (DDM): 40° 12.67710042' N 105° 33.17520084' W

Rating: Not Surveyed

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied:

In Community: Yes, Deerhaven

Revisit Interval: yrs

Map Label: 262

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 100 ft treated

Topography: Slope 21% to 30%

Roof Material:

Siding Material:

Foundation:

Firewood:


Water Supply: Reliable water source nearby

Propane:

Overhead Hazards: No overhead hazards

Comments: No longer exists in FMSS

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-0851-N Pumphouse, Deer Haven

Unit - Location: ROMO - Wild Basin

FMSS ID: 98016, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 12.70523448' N 105° 33.20014332' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Deerhaven

Revisit Interval: 4 yrs

Map Label: 275

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 31% to 40%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-0253-N Pumphouse by 0032, Wild Basin

Unit - Location: ROMO - Wild Basin

FMSS ID: 97844, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 12.48692202' N 105° 34.05428610' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Wild Basin

Revisit Interval: 4 yrs

Map Label: 279

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeGreater than 5%

Bridge Condition: Greater than 300ft with no turnaround

Access and Turnarounds: Greater than 300ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed



Firewood: 5ft to 30ft from facility

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: INHOLDER STRUCTURE

Unit - Location: ROMO - Wild Basin

FMSS ID: , **Local ID:**

Structure Type, Use: Building, Private

Owner: Individual or Private Corporation

Field Crew, Visit Date: , September 24, 2014

Coordinates (DDM): 40° 13.18877394' N 105° 32.14516392' W

Rating: Not Surveyed

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied:

In Community: Yes, Wild Basin Entrance Station

Revisit Interval: yrs

Map Label: 265

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope 31% to 40%

Roof Material:

Siding Material:

Foundation:

Firewood:



Water Supply: Reliable water source nearby

Propane: Adjacent to facility and no fuels clearance

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: INHOLDER STRUCTURE

Unit - Location: ROMO - Wild Basin

FMSS ID: , **Local ID:**

Structure Type, Use: Building, Private

Owner: Individual or Private Corporation

Field Crew, Visit Date: , September 24, 2014

Coordinates (DDM): 40° 13.18357332' N 105° 32.15471160' W

Rating: Not Surveyed

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied:

In Community: Yes, Wild Basin Entrance Station

Revisit Interval: yrs

Map Label: 280

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope 31% to 40%

Roof Material:

Siding Material:

Foundation:

Firewood:



Water Supply: Reliable water source nearby

Propane: Adjacent to facility and no fuels clearance

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Utility Panel Deerhaven
Unit - Location: ROMO - Wild Basin
FMSS ID: Utility Panel Deerhaven, **Local ID:**
Structure Type, Use: Utility Site (Water, Gas,Elec), Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , September 28, 2022
Coordinates (DDM): 40° 12.71188524' N 105° 33.19290084' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Deerhaven
Revisit Interval: 4 yrs
Map Label: 261

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Q-0251-H S Wild Basin RS and Quarters 00000251
Unit - Location: ROMO - Wild Basin
FMSS ID: 23661, **Local ID:**
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo, September 28, 2022
Coordinates (DDM): 40° 12.50884680' N 105° 33.98723142' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Wild Basin
Revisit Interval: 4 yrs
Map Label: 254

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: 5ft to 30ft from facility
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Finch Lake TH

Unit - Location: ROMO - Wild Basin

FMSS ID: Finch Lake TH, **Local ID:**

Structure Type, Use: Sign, Unknown

Owner: National Park Service

Field Crew, Visit Date: Jeff Singer, January 31, 2013

Coordinates (DDM): 40° 12.51047388' N 105° 33.65657328' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: yrs

Map Label: 259

Primary Access: Road

Ingress Egress: 2 or more roads in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Slash

Fuel Load: Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed

Firewood: None



Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-0996-N Sandbeach TrlHd Vault Toilet

Unit - Location: ROMO - Wild Basin

FMSS ID: 23682, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 13.18900962' N 105° 32.08247730' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Wild Basin Entrance Station

Revisit Interval: 5 yrs

Map Label: 268

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Reliable water source nearby

Propane: Adjacent to facility and no fuels clearance

Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Q-0894-N S 3-Bdrm House (Good) 00000894
Unit - Location: ROMO - Wild Basin
FMSS ID: 23679, **Local ID:**
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: Castillo , September 28, 2022
Coordinates (DDM): 40° 13.16728104' N 105° 32.07863202' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 4 yrs
Map Label: 269

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: 5ft to 30ft from facility
Water Supply: Limited or dependent on electricity
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-1046-N Wild Basin Kiosk

Unit - Location: ROMO - Wild Basin

FMSS ID: 23684, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 13.17557298' N 105° 32.06564580' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Wild Basin Entrance Station

Revisit Interval: 4 yrs

Map Label: 271

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Greater than 30in masonry exposed or N/A



Firewood: None

Water Supply: Reliable water source nearby

Propane: Adjacent to facility and no fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: B-0987-N Pumphouse - new by Good house

Unit - Location: ROMO - Wild Basin

FMSS ID: 98025, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 13.19869308' N 105° 32.09260218' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Wild Basin Entrance Station

Revisit Interval: 4 yrs

Map Label: 267

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Reliable water source nearby

Propane: Adjacent to facility and no fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: WILDBASIN LODGE CISTERN/PUMPHOUSE

Unit - Location: ROMO - Wild Basin

FMSS ID: not found, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 13.17246714' N 105° 32.09442342' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Wild Basin Entrance Station

Revisit Interval: 4 yrs

Map Label: 266

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Reliable water source nearby

Propane: Adjacent to facility and no fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: AIR INTAKE SHED

Unit - Location: ROMO - Wild Basin

FMSS ID: not found, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Castillo , September 28, 2022

Coordinates (DDM): 40° 13.19207574' N 105° 32.06229360' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Wild Basin Entrance Station

Revisit Interval: 4 yrs

Map Label: 278

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 2 lanes (Greater than 24')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: Marked and clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed

Firewood: None

Water Supply: Reliable water source nearby

Propane: Adjacent to facility and no fuels clearance

Overhead Hazards: No overhead hazards

Comments:

