


NPS Wildfire Risk Assessments

Assessment Locations

National Park Service
U.S. Department of the Interior




North Cascades National Park Overview



Structure Groups

Facility		Diablo Area	
Location		El Dorado Area	
	Bridge Creek Area		Meadow Cabin Area
	Copper Mountain Lookout		NOCA



Author: sszturm
8/29/2023 11:31 AM

Intermountain Region Geographic Resources Division
September 2023
Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project


Meadow Cabin Area

NOCA - North Cascades National Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
10	16682	TRL LCS Rock Cabin
7	18665	TRL LCS Meadow Cabin West
9	98705	TRL LCS Meadow Cabin East
8	NA	USGS Cabin



Author: sszturm
2/13/2025 10:22 AM

0 0.25 0.5 0.75 Miles

Scale: 1:18,000

NPS Wildfire Risk Assessments
NPS Fire GIS
January 2025
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: USGS Cabin

Unit - Location: NOCA - Meadow Cabin Area

FMSS ID: , **Local ID:**

Structure Type, Use: , Unknown

Owner: Unknown

Field Crew, Visit Date: Vaughn,

Coordinates (DDM): 48° 34.71919608' N 121° 01.51105938' W

Rating: Not Surveyed

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied:

In Community: No,

Revisit Interval: yrs

Map Label: 8

Primary Access:

Ingress Egress:

Access Width:

Access Condition:

Bridge Condition:

Access and Turnarounds:

Facility Number or Sign:

Fuel Type:

Fuel Load:

Defensible Space:

Topography:

Roof Material:

Siding Material:

Foundation:

Firewood:


Water Supply:

Propane:

Overhead Hazards:

Comments: Obscured by vegetation - approximate location

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: TRL LCS Meadow Cabin West

Unit - Location: NOCA - Meadow Cabin Area

FMSS ID: 18665, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: Vaughn,

Coordinates (DDM): 48° 34.69489794' N 121° 01.51271538' W

Rating: Not Surveyed

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied:

In Community: No,

Revisit Interval: yrs

Map Label: 7

Primary Access:

Ingress Egress:

Access Width:

Access Condition:

Bridge Condition:

Access and Turnarounds:

Facility Number or Sign:

Fuel Type:

Fuel Load:

Defensible Space:

Topography:

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation:

Firewood:


Water Supply:

Propane:

Overhead Hazards:

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: TRL LCS Rock Cabin

Unit - Location: NOCA - Meadow Cabin Area

FMSS ID: 16682, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Vaughn,

Coordinates (DDM): 48° 34.68638736' N 120° 59.86041786' W

Rating: Not Surveyed

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied:

In Community: No,

Revisit Interval: yrs

Map Label: 10

Primary Access:

Ingress Egress:

Access Width:

Access Condition:

Bridge Condition:

Access and Turnarounds:

Facility Number or Sign:

Fuel Type:

Fuel Load:

Defensible Space:

Topography:

Roof Material: Combustible or no roof

Siding Material: Log construction

Foundation:

Firewood:


Water Supply:

Propane:

Overhead Hazards:

Comments: Obscured by vegetation - approximate location

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: TRL LCS Meadow Cabin East

Unit - Location: NOCA - Meadow Cabin Area

FMSS ID: 98705, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: Vaughn,

Coordinates (DDM): 48° 34.70071980' N 121° 01.49312058' W

Rating: Not Surveyed

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied:

In Community: No,

Revisit Interval: yrs

Map Label: 9

Primary Access:

Ingress Egress:

Access Width:

Access Condition:

Bridge Condition:

Access and Turnarounds:

Facility Number or Sign:

Fuel Type:

Fuel Load:

Defensible Space:

Topography:

Roof Material:

Siding Material: Log construction

Foundation:

Firewood:

Water Supply:

Propane:

Overhead Hazards:

Comments:

NO PHOTO AVAILABLE

