



United States Department of the Interior

NATIONAL PARK SERVICE

Padre Island National Seashore
9405 South Padre Island Drive
Corpus Christi, Texas 78418



IN REPLY REFER TO:

L3025

September 29, 1993

Michael A. Grimm
Environmental Specialist
Amoco Production Company
P.O. Box 3092
Houston, TX 77253

Dear Mr. Grimm:

As a follow-up to recent conversations between yourself and Mr. Paul Eubank, Environmental Protection Specialist, we are requesting that Amoco Production Company submit an Action Plan regarding the hydrocarbon contamination at the South Sprint Gas Unit. This plan will be included in our records to document the incident and recovery efforts. The plan should include the following:

1. By whom and when was the contamination discovered?
2. What is the contamination, identification and concentration? Include a map or aerial photograph showing the location of the contamination.
3. How will the contamination be removed? What methods will be employed?
4. When will the work begin? Include an estimate on the time required to complete the clean-up process.
5. What adverse impacts are associated with the removal of the contamination, i.e., increased noise, surface disturbance, etc.?
6. What regulatory officials have been notified?

We look forward to working with Amoco Production Company in this project. If we can be of assistance, please call Mr. Paul Eubank at 512-949-8173.

Sincerely,

/s/

Charles R. Farabee
Superintendent

