



**Enron Oil & Gas
Company**

539 N. Carancahua, Suite 800
Corpus Christi, TX 78401
(512) 883-9231

May 14, 1999

Mr. Paul H. Eubank
Environmental Protection Specialist
National Park Service
Padre Island National Seashore
P. O. Box 181300
Corpus Christi, Texas 78480-1300

Dear Mr. Eubank:

In reference to your letter dated May 10, 1999 regarding issues that need to be addressed at the South Sprint Production Facility.

Sandblasting work had stopped back in October due to the weather conditions and the Land well loading up. We started swabbing the well and made a decision to change out the tubing, as the well does not flow consistently. The #1 well is being evaluated for production purposes and will not be converted into a SWD. The compressor will remain, the fencing will be replaced, and sand blasting and painting will resume this week. Arcadis, Geraghty & Miller have completed remediation study. The Houston office has reviewed the plan of action and a copy will be forwarded to you sometime next week.

Sincerely,

Tom Bradley
Production Superintendent

TB/man

cc: Steve Lipari
Marilyn Fish

M:\DOT\South Sprint Facility_PEubank.doc

