

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Upper Charley	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/13/2018	phone: (757) 824-7450	phone: (208) 387-5475
Operators	SOUSANES, K HILL	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather' -->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	Y	Presumed Damage 20171017
Longitude	Temp/RH	Y (HMP45)	
NESDIS ID	Solar Radiation	Y	Presumed Damage 20171017
Tx Time (mm:ss)	Wind Speed/Dir	N	
Tx Channel	Snow Depth	?	Condition unknown
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	
Antenna Elev. (Deg.)	Soil Temp 2	N	
Currently activated?	Soil Temp 3	N	
Currently transmitting?	Precipitation	N	
NWS Site ID	Datalogger	N	
Camera	Transmitter	Y	Add new TX 321
	Battery	N	
	Fence	Y	Condition unknown

Record Site Conditions

Time visit begins:	14:15	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	N	If no, comment:	11200X + 109 CABLES CHANGED
Power source ok? (Y/N)	Y	If no, comment:	BUT CONDUIT AT 921005004 WAS CHANGED
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	25	25	
ProgName	Ucharley_2017	UCHARLEY_2017	
StartTime	7/13/17 0:00	6/13/17 15:46	
12 V Battery Voltage	13.5	13.5	
Panel Temperature	12.1	12.1	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.4	3.5	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative			
SR50a height	80 in 2017		

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	4.06
RNIN before program update	4.06	WSM	9.3
SR50 height before	80	WDD	27.3
Upload new program	N	ATF	53.0
Re-enter RNIN after	NA	FTF	
Measure and re-enter SR50	N	RHP	42.7
Clean Rain Gage	N	BVV	13.5
Clean Temp Shield	N	WDDP	26.6
Level Solar sensor	N	WSMPH	14.8
OS Version updated?	N	SDI	80
Replace Desiccant	N	SRW	532

Tighten Guy Wires	N	STF	45.4	
Clean Battery Terminals	N	STF2	41.2	
Clean Snow Depth Area	N	STF3	39.1	
Brush Station Vicinity	N	STF4	—	
Tighten elements on YAGI	N (ad style)	ATF HMP	52.9	
Take Site Photos	N	ATF ThermX	53.0	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1	109	308903-13	109	308903-32		
Air Temperature 2						
Temp/RH	HMP45	X2410056	HMP45	F4010029		
Solar Radiation	Li200x	PY413204	Li200x	PY83323		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Datalogger						
Transmitter						

Comments

To do:

Swap HMP45 ☒ Swap Solar ☒ Assess SR50a and replace if needed LOOKS GOOD Assess general site damage MINOR DAMAGE; FENCE TAKEN DOWN BY SOMETHING; 2 CABLES CHANGED.
 Repair Fence ☒ Swap SD Card in Camera ☒ Assess condition of camera EXCELLENT MAYBE NEW TEETH MARKS ON BATTERY BOX, BUT COULD BE OLD ONES.

STRUNG NEW POLY WIRE AROUND FENCE.

Pre-visit notes: Station damaged Oct 17, 2017. Air Temp 109 and Solar sensor damaged.

Could be additional damage, but battery, wind, precip, RH, soil, and ThermX look okay as of May 4, 2018.

Need to call WFMI after site visit and un-Skip ATF, AT1L, AT1H, and SDI.

May be able to back-calculate snow depth values in Aquarius based on temperature correction from ThermX/HMP sensor?

LOOKS LIKE BEAR DAMAGE; FENCE WAS A MESS + CABLES WERE CHANGED ON THE 109 + SOLAR RAD SENSOR. ALL OTHER CABLES LOOK GOOD. SLIGHT DAMAGE TO POWER CABLE AT ENCLOSURE; USED MASTIC TO SECURE CONNECTION.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

COMMENTS CONT'D: SWAPPED THE TX312 FOR A TX320. TOOK GREEN POWER END OFF OF THE TX312 AND WIRED THE EXISTING MESH COILED POWER SUPPLY TO DIFFERENT STYLE BATTERY CONNECTION THAT FIT THE TX320. WATCHED A TX GO THROUGH. LOOKS OK.

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NW Towards	
3		W Towards	
4		SW Towards	
5		South Towards	
6		SE Towards	
7		E Towards	
8		NE Towards	
9		North Away	
10		NW Away	
11		W Away	
12		SW Away	
13		S Away	
14		SE Away	
15		E Away	
16		NE Away	
17		Enclosure	

CAKN Weather & Climate Monitoring
Site Visit Worksheet
Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Suspect Data

*RNIN (Since April?)
SR (out of level ~150,
unknown date)*

Site name Coal Creek
Date of this visit 6/14/2017
Operators SOUSANES + HILL

DCS - Sat. TX Check
phone: (757) 824-7450
24/7 technical support

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:		Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	65.304131	Temp	N	
Longitude	143.157011	Temp/RH	Y (HMP45)	
NESDIS ID	39605670	Solar Radiation	N	
Tx Time (mm:ss)	0:33:20	Wind Speed/Dir	N	
Tx Channel	172	Snow Depth	N	
Antenna Azimuth (Deg Mag)	171	Soil Temp 1	N	
Antenna Elev. (Deg.)	16	Soil Temp 2	N	
Currently activated?	Y	Soil Temp 3	N	
Currently transmitting?	Y	Precipitation	?	Precip near 100" - Apr 21???
NWS Site ID	CLCA2	Datalogger	N	
		Transmitter	Y	Add new TX321
		Battery	N	
		Fence	N/A	

Record Site Conditions

Time visit begins:	8:55	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	25	25	
ProgName	CoalCreek_2017	COALCREEK_2017	
StartTime	6/14/17 9:45	6/14/17 9:45	
12 V Battery Voltage	13.3	13.3	
Panel Temperature	16.3	16.3	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.4	3.4	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative			
SR50a height			

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
Download Hourly Data	Y	RNIN	0.00
RNIN before program update	95 +	WSM	0.9
SR50 height before	72.0	WDD	170
Upload new program	N	ATF	55.1
Re-enter RNIN after	0.00	FTF	
Measure and re-enter SR50	N	RHP	49.3
Clean Rain Gage	Y	BVV	13.2
Clean Temp Shield	Y	WDDP	59
Level Solar sensor	Y	WSMPH	1.9
OS Version updated?	Y	SDI	0.0
Replace Desiccant	Y	SRW	551

Tighten Guy Wires	OK	STF	38.2		TCOT	73.0
Clean Battery Terminals	N	STF2	31.5			
Clean Snow Depth Area	Y	STF3	31.3			
Brush Station Vicinity	N	STF4	—			
Tighten elements on YAGI	NA	ATF HMP	54.7			
Take Site Photos	Y	ATF ThermX	54.9			

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	X3410060	HMP45C	X3410061		
Solar Radiation						
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

To do:

Swap HMP45 ✓ ; Consider Adding Rubber Gasket to Tipping Bucket ✓ ; Assess Condition of Enclosure RE SURFACED
 ADDED TX321 - SWAPPED W/ TX312. SWAPPED GREEN POWER PLUG, LEFT REST OF POWER CABLE SET-UP.
 Cleaned, Inspected, and tested tipping bucket. Reset to 0.00, ADDED RUBBER GASKET.
 WIND / SOLAR CROSSBAR OUT OF LEVEL 15°. RELEVELLED, EVERYTHING SEEMED TIGHT, SO NOT SURE WHY IT WAS OUT OF LEVEL.
 To Do 2019: Paint Enclosure Brown? Add a sign to outside of Enclosure
 CLEANED, SANDED, & PAINTED ENCLOSED SURF.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name Ruth Glacier
 Date of this visit 6/20/18
 Operators SOUSANES + SIMMONS

DCS - Sat. TX Check
 phone: (757) 824-7450
 24/7 technical support

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:		Swap? (Y/N)		Recent error events (list)?	
Latitude	62 42.583	Sensors	Temp N		
Longitude	150 32.383	Temp/RH	Y (HMP45)		
NESDIS ID	3960157A	Solar Radiation	Y		
Tx Time (mm:ss)	0:32:40	Wind Speed/Dir	N	30' cable	
Tx Channel	172	Snow Depth	N		
Antenna Azimuth (Deg Mag)	143	Soil Temp 1	N		
Antenna Elev. (Deg.)	19	Soil Temp 2	N		
Currently activated?	Y	Soil Temp 3	N		
Currently transmitting?	Y	Precipitation	N		
NWS Site ID	RUGA2	Datalogger	N		
		Transmitter	N		
		Battery	N		
		Fence	Y	Bring fence parts	

Record Site Conditions

Time visit begins:	1:00	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26		
ProgName	Ruth2017		
StartTime	6/21/17 13:38		
12 V Battery Voltage	13.4		
Panel Temperature	14.2		
Watchdog Errors	2		Reset if >0
Lithium Batt Volt	3.4		Replace if <2.9
Low 12V Batt Count	119		Reset if >0
Skipped Scan	0		Reset if >0
RNIN Cumulative			
SR50a height			

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	6.78
RNIN before program update	6.78	WSM	4.25
SR50 height before	69	WDD	0.48
Upload new program	N	ATF	54.8
Re-enter RNIN after	1	FTF	—
Measure and re-enter SR50	Y	RHP	48.0
Clean Rain Gage	Y	BVV	13.4
Clean Temp Shield	Y	WDDP	39
Level Solar sensor	Y	WSMPH	5.7
OS Version updated?	Y	SDI	0
Replace Desiccant	Y	SRW	886
Tighten Guy Wires	Y	STF	50.2

Suspect Data
 Soil Temps (heaving)

Clean Battery Terminals	<u>Y</u>	STF2	<u>44.9</u>	
Clean Snow Depth Area	<u>Y</u>	STF3	<u>43.1</u>	
Brush Station Vicinity	<u>Y</u>	STF4	<u>—</u>	
Tighten elements on YAGI	<u>Y</u>	ATF HMP	<u>55.9</u>	
Take Site Photos	<u>Y</u>	ATF ThermX	<u>54.7</u>	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	E2630037	HMP45	D3670033		
Solar Radiation	<u>LI200X</u>	<u>63699</u>	<u>LI200X</u>	<u>PY 63677</u>		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

NOTE: SERIAL #
IS RUBBING OFF.
CHECK AGAINST
CALIBRATION
SHEET

Comments

To do:

Replace HMP45 sensor head ☒ Replaced Li200x Solar Radiation Sensor ☒
Repair Electric fence ☒ Assess condition of enclosure and enclosure collar Replace enclosure next year. collar is busted.

Notes from field:

Lots of little bugs in enclosure and on station in general.
Fence needed repair - replaced solar charger b/c mounting bracket was busted.
- Wind cable was sagging, but not damaged.

- HMP45C
cable end was
a bit corroded.
Replace next
year w/ CE181
- Watchdog errors
for low 12V
battery - solar
pad buried?
- Soil sensors
heaved a bit.
pushed them
back in holes

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name: Tana Knob
 Date of this visit: 7/10/2018
 Operators: Hill / SOUSANES

DCS - Sat. TX Check

phone: (757) 824-7450

24/7 technical support

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:		Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	60.908	Temp	?	
Longitude	142.901311	Temp/RH	Y (HMP45)	
NESDIS ID	3960709C	Solar Radiation	Y	
Tx Time (mm:ss)	0:33:40	Wind Speed/Dir	N	
Tx Channel	172	Snow Depth	N	
Antenna Azimuth (Deg Mag)	171	Soil Temp 1	N	
Antenna Elev. (Deg.)	21	Soil Temp 2	Y	Reading -99
Currently activated?	Y	Soil Temp 3	N	
Currently transmitting?	?	Precipitation	N	
NWS Site ID	TANA2	Datalogger	?	
		Transmitter	Y	Replace w/ 321. No Tx Dec - April
Camera	N	Battery	?	Power suspect; rain resets
		Fence	Y	

Suspect Data

- WD (station twisted unknown date)

- All data (intermittent due to bad battery cable, 2017-2018)

- STZ, cable severed

Record Site Conditions

Time visit begins:	1030	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	N	If no, comment:	STZ int. Reconnect?
Power source ok? (Y/N)	?	If no, comment:	10K 50K, but low 12V counts
Batteries ok? (Y/N)	?	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->Select 'Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26	OSVersion	26
ProgName	Tana - 2017	ProgName	TANA - 2018
StartTime	7/10/2018	StartTime	7/10/2018
12 V Battery Voltage	13.7	12 V Battery Voltage	13.8
Panel Temperature	9.8	Panel Temperature	7.6
Watchdog Errors	175	Watchdog Errors	0
Lithium Batt Volt	3.4	Lithium Batt Volt	3.4
Low 12V Batt Count	7542	Low 12V Batt Count	0
Skipped Scan	0	Skipped Scan	0

7:57 am. ???

12:47 PM

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	0
RNIN before program update	0.41	WSM	12.8
SR50 height before	103.5	WDD	15.2
Upload new program	Y	ATF	43.4
Re-enter RNIN after	Y	FTF	
Measure and re-enter SR50	Y	RHP	8.4
Clean Rain Gage	Y	BVV	12.7
Clean Temp Shield	Y	WDDP	10.4
Level Solar sensor	Y	WSMPH	14.2
OS Version updated?	Y	SDI	11.6
Replace Desiccant	Y	SRW	36.0
Tighten Guy Wires	Y	STF	53.1
Clean Battery Terminals	Y	STF2	47.3
Clean Snow Depth Area	Y	STF3	45.4
Brush Station Vicinity	Y	STF4	

Tighten elements on YAGI

Take Site Photos

ATF HMP

ATF ThermX

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	E263011	EE181	17121600004	4AB	
Solar Radiation	LI200x	100149	LI200x	100295		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2	107					
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

To do:

Replace TX3210 with TX321

Replace HMP45 with EE181

Swap LI200x

Repair Fence

Troubleshoot power/datalogger/timestamp/transmission issues (replace RS232 data cable?)

Repair/Replace ST2 Sensor

moved station mast from W to S facing.

GPS year 2022

Repaired guy wires

Battery voltage

Soil temp 2 cable covered + replaced

Battery cable was bad based on volt meter output. Replaced it. Station seems better.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

downloaded status table to desktop (Pam's tablet)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring
Site Visit Worksheet
Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name Tebay
Date of this visit 7/10/2018
Operators HILL SOUSANES

DCS - Sat. TX Check
phone: (757) 824-7450
24/7 technical support

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:		Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	61.18095	Temp	N	
Longitude	-144.3392	Temp/RH	Y (EE181)	
NESDIS ID	3960936E	Solar Radiation	N	
Tx Time (mm:ss)	0:34:00	Wind Speed/Dir	Y	Riming event mid-December
Tx Channel	172	Snow Depth	N	
Antenna Azimuth (Deg Mag)	169	Soil Temp 1	Y	Bad data in 2017; current tx ok? seems OK
Antenna Elev. (Deg.)	20	Soil Temp 2	N	
Currently activated?	Y	Soil Temp 3	N	
Currently transmitting?	Y	Precipitation	N	
NWS Site ID	TEBA2	Datalogger	N	
Camera	N	Transmitter	Y	Replace TX320 with TX321
		Battery	N	
		Fence	Y	

Record Site Conditions

Time visit begins:	2:10 PM	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	Soil cables pulled out of box
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26		
ProgName	Tebay_2017	TEBA2-2018	
StartTime	7/10/17 15:42	7/10/2018 15:22	
12 V Battery Voltage	13.4	13.3	
Panel Temperature	17.7	11.6	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.5	3.5	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	14.69
RNIN before program update	14.69	WSM	2.5
SR50 height before	93.6	WDD	290
Upload new program	Y	ATF	50.4
Re-enter RNIN after	Y	FTF	--
Measure and re-enter SR50	Y	RHP	92
Clean Rain Gage	N	BVV	13.3
Clean Temp Shield	N	WDDP	290
Level Solar sensor	N	WSMPH	312
OS Version updated?	N	SDI	
Replace Desiccant		SRW	487
Tighten Guy Wires	NA	STF	55.1

Clean Battery Terminals	N	STF2	54.4	
Clean Snow Depth Area	g	STF3	51.4	
Brush Station Vicinity	N	STF4		
Tighten elements on YAGI	NA	ATF HMP	181 51.1	
Take Site Photos		ATF ThermX	50.3	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	(ft)	(in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	X3140062	EE181	1710160000	4379	
Solar Radiation						
Wind Speed/Dir	5103	105722	5103	87973		
Snow depth						
Soil Temp 1		107				
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter	TX320		TX321			

Comments

To do:

Replace TX320 with TX321 ✓

Replace HMP45 with EE181 ✓

Swap 5103 ✓

Troubleshoot Parity errors SWAPPED TX Troubleshoot STF1 (requested skip in Sept. due to bad data, but current message looks ok)

Assess snow damage (~6 ft snowpack) YAGI ANTENNA WAS POINTING TOWARD GROUND. I BOULDER

ADJUSTMENT SHEARED OFF. TIGHTENED OTHER BOLT + ADDED CABLE TIE. SEEMS OK.
REPAIRED FENCE - REPLACED POLYUREA.
- LIGHTNING ROD SHEARED OFF - DID NOT REPAIR DUE TO RAINING AT THE SITE.
- SOIL CABLES PULLED OUT. THEY ARE IN CONDUIT + LOOK LIKE IT MIGHT HAVE BEEN SHOWN BY SNOW.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring
Site Visit Worksheet
Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name Chititu
Date of this visit 7/11/2018
Operators Ken Hill, Pam Sousanes

DCS - Sat. TX Check
phone: (757) 824-7450
24/7 technical support

RAWS HelpDesk:
phone: (208) 387-5475
Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather' -->'Select Station')

GOES Information:		Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	61.273589	Temp	N	
Longitude	-142.6209	Temp/RH	Y (EE181)	
NESDIS ID	396020E0	Solar Radiation	Y	
Tx Time (mm:ss)	0:32:50	Wind Speed/Dir	Y	
Tx Channel	172	Snow Depth	N	
Antenna Azimuth (Deg Mag)	171	Soil Temp 1	N	
Antenna Elev. (Deg.)	20	Soil Temp 2	N	
Currently activated?	Y	Soil Temp 3	N	
Currently transmitting?	Y	Precipitation	N	
NWS Site ID	CTUA2	Datalogger	N	
		Transmitter	Y	Replace TX320 with TX321
		Battery	N	
		Fence	N/A	

Elev 4609.2

Record Site Conditions

Time visit begins:	10:45	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	Took out one battery to bring to Tana

returned & reinstalled
7/12

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26	26	
ProgName	Chititu_2017	CHITITU_2018	
StartTime	7/12/17 19:39	7/11/2018 11:56am	
12 V Battery Voltage	13.7	13.6	
Panel Temperature	41.4	61.3	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.4	3.4	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0

Maintenance Checklist

	Completed? (Y/N)		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	5.42	
RNIN before program update	5.42	WSM		
SR50 height before	96.5	WDD		
Upload new program	Y	ATF	41.6	
Re-enter RNIN after	Y	FTF		
Measure and re-enter SR50	Y	RHP	69	
Clean Rain Gage	Y	BVV	13.5	
Clean Temp Shield	Y	WDDP		
Level Solar sensor	Y	WSMPH		
OS Version updated?	Y	SDI	0.02	
Replace Desiccant	Y	SRW	181	

Tighten Guy Wires	<u>Y</u>	STF	<u>45.2</u>	
Clean Battery Terminals	<u>Y</u>	STF2	<u>41.0</u>	
Clean Snow Depth Area	<u>N</u>	STF3	<u>35.7</u>	
Brush Station Vicinity	<u>N</u>	STF4	<u>23.0</u>	
Tighten elements on YAGI	<u>NA</u>	ATF HMP	<u>EE181 41.0</u>	<u>96.47</u>
Take Site Photos		ATF ThermX	<u>40.7</u>	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	(ft)	(in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	X3410042	EE181	1648160000	4190	
Solar Radiation	Li200x	0443026	Li200x	60173		
Wind Speed/Dir	5103	WM 132729	05103	58429		
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter	TX320		TX321			

Comments

To do:

Replace HMP45 with EE181 ☒ Replace TX320 with TX321 ☒ Swap 5103 ☒ Swap Li200x ☒

Confirm 2018 program has STF4 ☒

GPS YAGI FOR TX321 GPS ANTENNA = 7022 (?)

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Gates Glacier	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	7/11/2018	phone: (757) 824-7450	phone: (208) 387-5475
Operators	Hill, Sousanes	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather' -->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y (EE181)	
NESDIS ID	Solar Radiation	Y	
Tx Time (mm:ss)	Wind Speed/Dir	Y	
Tx Channel	Snow Depth	N	
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	
Antenna Elev. (Deg.)	Soil Temp 2	N	
Currently activated?	Soil Temp 3	N	
Currently transmitting?	Precipitation	N	
NWS Site ID	Datalogger	N	
Camera	Transmitter	Y	Replace TX320 with TX321
	Battery	?	Panel buried Dec.-May?
	Fence	N/A	

Record Site Conditions

Time visit begins:	15:30	Time visit ends:	17:15
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
 (Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:			After Maintenance:		
OSVersion	26		26		
ProgName	GatesGl_2017		GatesGl_2018		
StartTime	7/10/17 20:06		7/11/2018	16:54	
12 V Battery Voltage	13.4		13.4		
Panel Temperature	8.7		7.2		
Watchdog Errors	0	Reset if >0	0		Reset if >0
Lithium Batt Volt	3.5	Replace if <2.9	3.5		Replace if <2.9
Low 12V Batt Count	0	Reset if >0	0		Reset if >0
Skipped Scan	0	Reset if >0	0		Reset if >0

Maintenance Checklist

	Completed? (Y/N)		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	13.38	
RNIN before program update	13.38	WSM	7.7	
SR50 height before	103	WDD	344	
Upload new program	Y	ATF	40.7	
Re-enter RNIN after		FTF		
Measure and re-enter SR50		RHP	73	
Clean Rain Gage	checked-OK	BVV	13.5	
Clean Temp Shield	N	WDDP	344	
Level Solar sensor	OK	WSMPH	7.7	
OS Version updated?	N	SDI	0	
Replace Desiccant		SRW	215	
Tighten Guy Wires	Y	STF	52.6	
Clean Battery Terminals	N	STF2	49.2	
Clean Snow Depth Area	Y	STF3	44.1	
Brush Station Vicinity	N/A	STF4		

4

40.5

Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring
Site Visit Worksheet
Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name	Chicken Creek	DCS - Sat. TX Check	
Date of this visit	~~7/12/2017~~ 7/12/2018	phone: (757) 824-7450	
Operators	Hill, Sousanes	24/7 technical support	

Pre-Field Information

(Look up the station: www.nifc.blm.gov --> Login --> 'Weather' --> 'Select Station')

GOES Information:		Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	62.124019	Temp	N	
Longitude	141.847369	Temp/RH	Y (EE181)	
NESDIS ID	39603396	Solar Radiation	Y	
Tx Time (mm:ss)	0:33:00	Wind Speed/Dir	N	
Tx Channel	172	Snow Depth	N	
Antenna Azimuth (Deg Mag)	172	Soil Temp 1	N	
Antenna Elev. (Deg.)	19	Soil Temp 2	N	
Currently activated?	Y	Soil Temp 3	N	
Currently transmitting?	Y	Precipitation	N	
NWS Site ID	CREA2	Datalogger	N	
		Transmitter	Y	Replace TX320 with TX321
		Battery	N	
		Fence	N/A	

Record Site Conditions

Time visit begins:	12:15	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	looks like some cables may have been pulled from box, but no damage
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select Status' from Table Drop-Down Box)
(Laptop: Device config utility-->Select Datalogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26	26	
ProgName	Chicken_2017	CHICKEN_2018	
StartTime	7/11/17 0:00	7/12/2018 13:50	
12 V Battery Voltage	13.6	13.5	
Panel Temperature	7.5	8.4	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.4	3.4	Replace if <2.9
Low 12V Batt Count	6	0	Reset if >0
Skipped Scan	0	0	Reset if >0

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	7.93
RNIN before program update	7.93	WSM	8.4
SR50 height before	85.5	WDD	294
Upload new program	Y	ATF	45.6
Re-enter RNIN after	Y	FTF	—
Measure and re-enter SR50	Y	RHP	55
Clean Rain Gage	N	BVV	13.3
Clean Temp Shield	N	WDDP	281
Level Solar sensor	N	WSMPH	9.6
OS Version updated?	Y	SDI	0.2
Replace Desiccant	Y	SRW	400
Tighten Guy Wires	Y	STF	45.2
Clean Battery Terminals	N	STF2	43.4

85.5

Clean Snow Depth Area	Y	STF3	39.6	
Brush Station Vicinity	N	STF4	57.8	
Tighten elements on YAGI	NA	ATF_ThermX	44.5	
Take Site Photos	Y	ATF_HMP45	45.1	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	F4010022	EE181	17111160008	792A	
Solar Radiation	Li200x	60172	Li200x	64359		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter	TX320	1192	TX321			

Comments

To do:

Replace HMP45 with EE181 ✓

Swap Li200x ✓

Confirm program has STF4 ✓

Replace TX320 with TX321 ✓

Upload new program ✓

SIF U ASADWB 57.8.

ON JUNE 30 TEMP SENSORS CLIMBING FOR STF4. NOT SURE WHY - REPLACE NEXT YEAR. BUT MIGHT NOT FOR TX SWAP.

REPAIRING GROUND WIRE FROM ENCLOSURE TO MAST.
- CABLE FROM BATTERY TO ENCLOSURE IS SLIGHTLY DAMAGED (EXTERNAL) NEAR BATTERY END. THROTTLED
- CONSIDER REPLACING CABLE IS IN METAL CONDUIT. NEEDED MORE SLACK TO REACH CHARGE REGULATOR FOR TX SWAP.
- REPAIRING SNOW AND REMOVED CLIMBERS IN CENTER OF PLYWOOD UNDER SINKER.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Camera Image #	Direction	Comp. Image #
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

- dropped 6050 @ Eldorado Mine & Simmons @ stream site

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name	Stampede	DCS - Sat. TX Check	
Date of this visit	8/8/2017	phone: (757) 824-7450	
Operators	Sousanes Hill	24/7 technical support	

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y (HMP45)	replace shield
NESDIS ID	Solar Radiation	N	
Tx Time (mm:ss)	Wind Speed/Dir	Y	
Tx Channel	Snow Depth	N	
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	Depth Unknown
Antenna Elev. (Deg.)	Soil Temp 2	N	Depth Unknown
Currently activated?	Soil Temp 3	N	Depth Unknown
Currently transmitting?	Precipitation	?	No tips since December
NWS Site ID	Datalogger	N	
	Transmitter	N	check antenna, poor tx in winter
	Battery	N	
	Fence	N/A	

Record Site Conditions

Time visit begins:	1700	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	Rain gauge out of level
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:	After Maintenance:
OSVersion	27
ProgName	Stampede2017
StartTime	8/8/17 13:41
12 V Battery Voltage	13.3
Panel Temperature	7.7
Watchdog Errors	0
Lithium Batt Volt	3.5
Low 12V Batt Count	0
Skipped Scan	0
RNIN Cumulative	2.32
SR50a height	85.4

Maintenance Checklist

Completed? (Y/N)	Value	OK? (Y/N)
Download Hourly Data	Y	
RNIN before program update	2.32	
SR50 height before	85.4	85.4 inches 2017
Upload new program	N	
Re-enter RNIN after	2.32	
Measure and re-enter SR50	85.4	
Clean Rain Gage	Y	
Clean Temp Shield	N	
Level Solar sensor	N	
OS Version updated?	N	
Replace Desiccant	Y	
Tighten Guy Wires	OK	
Clean Battery Terminals	N	

Check transmitted values:

Value	OK? (Y/N)
RNIN	2.32
WSM	2.5
WDD	16.6
ATF	46.2
FTF	
RHP	91.6
BVV	13.6
WDDP	18.6
WSMPH	3.4
SDI	0.0
SRW	186.8
STF	52.2
STF2	52.6

Clean Snow Depth Area slywood
Brush Station Vicinity 4
Tighten elements on YAGI wedges
Take Site Photos 4

STF3 33.5
STF4 46.1
ATF HMP 43.9
ATF ThermX

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	D3620074	HMP45	B1240007		
Solar Radiation						
Wind Speed/Dir	5103	<u>58427</u>	5103	132717		
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Check soil probes - DEPTHS UNKNOWN ?? still unknown did not want to disturb record
Clear Site of brush Some. Needs more work. Possibly due to snow load.
Swap HMP 45 Sensor ✓ (430°)
Swap 05103 Wind Monitor ✓
Check Rain Gage (no tips since December) ✓ Out of level on arrival. Hose clamped straight to mounting pole; leveled, cleaned out bucket & funnel and re-tipped funnel. Brushed precip arm. Out of level due to snow loading (?).

To do: Request site clearing

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1	385		
2	386		
3	387		
4	388		
5	389		
6	390		
7	391		
8	392		
9	393		
10	394		
11	395		
12	396		
13	397		
14	398		
15	399		
16	400		
17	401		

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name Wigand
 Date of this visit 8/8/2017
 Operators SOUSANES, K.H.

DCS - Sat. TX Check
 phone: (757) 824-7450
 24/7 technical support

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather' -->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude 63.812081	Temp	N	
Longitude -150.049769	Temp/RH	Y (HMP45)	
NESDIS ID 3960060C	Solar Radiation	N	
Tx Time (mm:ss) 0:32:30	Wind Speed/Dir	N	
Tx Channel 172	Snow Depth	N	
Antenna Azimuth (Deg Mag) 141 (?)	Soil Temp 1	N	Seems cold. Too deep?
Antenna Elev. (Deg.) 18 (?)	Soil Temp 2	N	
Currently activated? Y	Soil Temp 3	N	
Currently transmitting? Y	Precipitation	N	
NWS Site ID WIGA2	Datalogger	N	
	Transmitter	N	
	Battery	N	
	Fence	Y	

Record Site Conditions

Time visit begins: 11:05	Time visit ends:
Station accessible? (Y/N) Y	If no, comment:
Cables intact? (Y/N) Y	If no, comment:
Power source ok? (Y/N) Y	If no, comment:
Batteries ok? (Y/N) Y	If no, comment:

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select' Status' from Table Drop-Down Box)
 (Laptop: Device config utility-->Select DataLogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:	After Maintenance:
OSVersion 26	26
ProgName Wigand2017	WIGAND2017
StartTime 8/8/17 15:06	8/8/17 15:06
12 V Battery Voltage 13.5	13.5
Panel Temperature 7.9	8.3
Watchdog Errors 0	0
Lithium Batt Volt 3.4	3.4
Low 12V Batt Count 0	0
Skipped Scan 0	0
RNIN Cumulative 8.32	
SR50a height 77.4	

Maintenance Checklist

Completed? (Y/N)	Value	OK? (Y/N)
Download Hourly Data Y	RNIN 8.33	
RNIN before program update 8.32	WSM 5.7	
SR50 height before 77.4	WDD 7.14	
Upload new program N	ATF 46.0	
Re-enter RNIN after 1	FTF -	
Measure and re-enter SR50 2	RHP 92	
Clean Rain Gage 2	BBV 13.5	
Clean Temp Shield 2	WDDP 2.14	
Level Solar sensor 2	WSMPH 8.7	
OS Version updated? 2	SDI 2.2	
Replace Desiccant 2	SRW 15.3	
Tighten Guy Wires Y	STF 41.9	

Clean Battery Terminals N
 Clean Snow Depth Area N
 Brush Station Vicinity N
 Tighten elements on YAGI N
 Take Site Photos N

STF2 41.0
 STF3 37.9
 STF4 —
 ATF HMP 46.0
 ATF ThermX 45.7

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2		<u>03620074</u>				
Temp/RH	HMP45	D3520027	HMP45	E3010021		
Solar Radiation						
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Swap HMP45 AT/RH Sensor ✓
 Repair Fence 6000 SHARE
 Take Trimble Coordinate NO
 Check ST1 Soil Depth ✓

STATION + FENCE LOOKED GREAT.
 TIGHTENED GUY WIRES (XTRA 3)
 TIGHTENED POLY ON FENCE
 SOIL TEMP 1 LOOKS OK, TUSsocky AREA SO 10CM IS RELATIVE.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			

CAKN Weather & Climate Monitoring
Site Visit Worksheet
Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name	Dunkle Hills	DCS - Sat. TX Check	
Date of this visit	8/8/2017	phone: (757) 824-7450	
Operators	Sousanes & Hill	24/7 technical support	

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude 63.300322	Temp	N	
Longitude -149.541531	Temp/RH	Y (HMP45)	
NESDIS ID 3960B582	Solar Radiation	N	
Tx Time (mm:ss) 0:34:20	Wind Speed/Dir	N	
Tx Channel 172	Snow Depth	N	
Antenna Azimuth (Deg Mag) 141 (?)	Soil Temp 1	N	
Antenna Elev. (Deg.) 18 (?)	Soil Temp 2	N	Depth Unknown now we know!
Currently activated? Y	Soil Temp 3	N	
Currently transmitting? Y	Precipitation	N	
NWS Site ID DKLA2	Datalogger	N	
	Transmitter	N	
Camera N	Battery	N	
	Fence	N/A	

Record Site Conditions

Time visit begins: 1:50 PM	Time visit ends:	
Station accessible? (Y/N) Y	If no, comment:	
Cables intact? (Y/N) Some	If no, comment:	Few had been chewed on. Coax, GPS & HMP45
Power source ok? (Y/N) Y	If no, comment:	
Batteries ok? (Y/N) Y	If no, comment:	

5. soils pulled out a bit but not chewed

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:	After Maintenance:
OSVersion 26	26
ProgName Dunkle2017	Dunkle2017
StartTime 8/8/17 11:24	8/8/17 11:24
12 V Battery Voltage 13.5	13.5
Panel Temperature 10.0	9.0
Watchdog Errors 0	0
Lithium Batt Volt 3.4	3.4
Low 12V Batt Count 0	0
Skipped Scan 0	0
RNIN Cumulative 7.63	
SR50a height 104	

Maintenance Checklist

Completed? (Y/N)	Value	OK? (Y/N)
Download Hourly Data Y	RNIN 7.63	
RNIN before program update 7.63	WSM 8.2	
SR50 height before 104	WDD 348	
Upload new program N	ATF 49.6	
Re-enter RNIN after NA	FTF -	
Measure and re-enter SR50 NA	RHP 55	
Clean Rain Gage N	BVV 13.5	
Clean Temp Shield N	WDDP 342	
Level Solar sensor N	WSMPH 12.7	
OS Version updated? N	SDI 0.2	
Replace Desiccant Y	SRW 372	
Tighten Guy Wires OK	STF 50.2	

Suspect Data
Soil Temp depths ->
See Notes

Clean Battery Terminals N

Clean Snow Depth Area plywood

Brush Station Vicinity NA

Tighten elements on YAGI welded

Take Site Photos y

STF2 50.8

STF3 49.9

STF4

ATF HMP

ATF ThermX

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	F4010005	HMP45	X3410043		
Solar Radiation						
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Swap HMP 45 y

Determine depth of ST2 ✓

Take Trimble GPS Coordinate None

STF - Before After After Values
 STF 10 cm 10 cm 50.5
 STF2 10 cm 20 cm 50.7
 STF3 10 cm 50 cm 50.2

Wires had been pulled on (Bear?) but minimum damage.
 Repaired with e-tape

-SOILS RE-INSTALLED + RE-LABELLED AT DATALOGGER. ALL DATA AT 10CM +
 HAD BEEN PULLED ON DATA ENCLOSURE.

WFM! Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Toklat	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	8/21/2017	phone: (757) 824-7450	phone: (208) 387-5475
Operators	Ken, Pam, Mark Hall, Mike	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather' -->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude 63.5255	Temp	N	
Longitude -150.046481	Temp/RH	Y (HMP45)	
NESDIS ID 396063EA	Solar Radiation	Y	
Tx Time (mm:ss) 0:33:30	Wind Speed/Dir	N	
Tx Channel 172	Snow Depth	N	
Antenna Azimuth (Deg Mag) 141	Soil Temp 1	N	
Antenna Elev. (Deg.) 17	Soil Temp 2	N	
Currently activated? Y	Soil Temp 3	N	
Currently transmitting? Y	Precipitation	N	
NWS Site ID TKLA2	Datalogger	N	
	Transmitter	Y	
	Battery	N	
	Fence	N/A	

Record Site Conditions

Time visit begins:	13:45	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	27	27.04	
ProgName	Toklat2017	Toklat 2017	
StartTime	8/14/17 15:28	8/14/17 15:28	
12 V Battery Voltage	12.9	12.9	
Panel Temperature	16.0	13.8	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.5	3.5	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative	13.75		
SR50a height	81.9		

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	13.75
RNIN before program update	13.75	WSM	5.3
SR50 height before	81.9	WDD	310.9
Upload new program	N	ATF	55.2
Re-enter RNIN after		FTF	
Measure and re-enter SR50		RHP	74.9
Clean Rain Gage	OK	BVV	12.9
Clean Temp Shield	OK	WDDP	313
Level Solar sensor	OK	WSMPH	5.6
OS Version updated?	No	SDI	0
Replace Desiccant	Y	SRW	98.6
Tighten Guy Wires	N	STF	55.9

Clean Battery Terminals	<u>Y</u>	One $\ominus$ is corroded	STF2	<u>52.3</u>	
Clean Snow Depth Area	<u>OK</u>		STF3	<u>48.8</u>	
Brush Station Vicinity	<u>NA</u>		STF4	<u>—</u>	
Tighten elements on YAGI	<u>NA - WIND</u>		ATF HMP	<u>54.9</u>	
Take Site Photos	<u>Y</u>		ATF ThermX	<u>54.6</u>	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	D362 ???	HMP45	X3410044		
Solar Radiation	Li200x	Py60145	Li200x	83212		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Swap HMP45 ☒
 Swap Li200x ☒
 Swap Transmitter ☒
 Check Battery (consider swapping) ☒
 Check Soil Probe Depths ☒ SENSORS LOOKED UNDISMAGED. DID NOT PULL OUT TO VERIFY DEPTHS.
SOIL SENSORS WERE CHANGED ON BY GROUND SPURMS, ONLY CHANGED ON SHEATH. PUT ETC. WIRE/MASTFE ON THEM BUT SHOULD CONSIDER ADDING CONDUIT. LOTS OF SIGN OF GROUND SPURMS IN AREA.
- SWAP BOTH BATTERIES, BATTERY CABLE + MASTFE BATTERY BOX NEXT YEAR.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			

CORROSION ON
 NEGATIVE TERMINAL
 OF 1 BATTERY,
 OTHERWISE
 LOOKS OK.

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name

Eielson VC

Date of this visit

8/21/2017

Operators

Sousanes/Hill

DCS - Sat. TX Check

phone: (757) 824-7450

24/7 technical support

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather' -->'Select Station')

GOES Information:

Latitude	63.430911
Longitude	-150.310761
NESDIS ID	39604506
Tx Time (mm:ss)	0:33:10
Tx Channel	172
Antenna Azimuth (Deg Mag)	141
Antenna Elev. (Deg.)	17
Currently activated?	Y
Currently transmitting?	Y
NWS Site ID	EVCA2

Sensors

Swap?

(Y/N)

Recent error events (list)?

Temp	N	
Temp/RH	Y (HMP45)	
Solar Radiation	N	
Wind Speed/Dir	N	
Snow Depth	N	
Soil Temp 1	N/A	
Soil Temp 2	N/A	
Soil Temp 3	N/A	
Precipitation	N	
Datalogger	N	
Transmitter	Y	
Battery	N	
Fence	N/A	

Record Site Conditions

Time visit begins:	12:30	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
 (Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26	26	
ProgName	Eielson2017	Eielson2017	
StartTime	8/16/17 10:23	8/16/17 10:23	
12 V Battery Voltage	13.6	13.5	
Panel Temperature	12.3	12.6	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.5	3.5	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative	15.24		
SR50a height	87		

Maintenance Checklist

	Completed? (Y/N)	
Download Hourly Data	Y	
RNIN before program update	15.24	
SR50 height before	87	87 in 2017
Upload new program	N	
Re-enter RNIN after	N	
Measure and re-enter SR50	N	
Clean Rain Gage	OK	
Clean Temp Shield	OK	
Level Solar sensor	No	
OS Version updated?	No	
Replace Desiccant	Y	

Check transmitted values:

	Value	OK? (Y/N)
RNIN	15.24	
WSM	6.4	
WDD	190	
ATF	51.9	
FTF		
RHP	80.8	
BBV	12.5	
WDDP	785	
WSMPH	7.7	
SDI	0	
SRW	210	

Tighten Guy Wires OK
 Clean Battery Terminals No
 Clean Snow Depth Area YES
 Brush Station Vicinity NA
 Tighten elements on YAGI welded
 Take Site Photos my

ATF HMP 52.0
 ATF ThermX 54.3
 TCOT 88.1
58.1

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Temp/RH	HMP45	F4010023	HMP45	D3520097		
Solar Radiation						
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Swap HMP45 ✓
 Swap Transmitter ✓
 Take Trimble Coordinate ✓

Consider replacing enclosure next visit

SITE VISIT IN CONJUNCTION W/CAN MAINTENANCE TRIP. MARK/MIKE

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			