

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name	Coal Creek	DCS - Sat. TX Check	
Date of this visit	5/16/2019	phone: (757) 824-7450	
Operators	Ken Hill, Sousanes	24/7 technical support	

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:		Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	65.304131	Temp	N	
Longitude	143.157011	Temp/RH	Y (EE181)	
NESDIS ID	39605670	Solar Radiation	Y	
Tx Time (mm:ss)	0:33:20	Wind Speed/Dir	N	
Tx Channel	172	Snow Depth	N	
Antenna Azimuth (Deg Mag)	171	Soil Temp 1	N	
Antenna Elev. (Deg.)	16	Soil Temp 2	N	
Currently activated?	Y	Soil Temp 3	N	
Currently transmitting?	Y	Precipitation	N	
NWS Site ID	CLCA2	Datalogger	N	
		Transmitter	N	Check Firmware/Get SN#
		Battery	N	
		Fence	N/A	

Record Site Conditions

Time visit begins:	09:00	Time visit ends:	10:30
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select Datalogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	25	25	
ProgName	CoalCreek_2017	CoalCreek_2019	
StartTime	6/14/17 9:45	6/15/2018 9:15	9.54 5/16/2019
12 V Battery Voltage	13.3	13.3	
Panel Temperature	15.6	15.3	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.4	3.4	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative	1.82		
SR50a height	72		

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
Download Hourly Data	Y	Value	OK? (Y/N)
RNIN before program update	1.82	RNIN	1.82
SR50 height before	72	WSM	0.77
Upload new program	Y	WDD	145
Re-enter RNIN after	1.82	ATF	55.1
Measure and re-enter SR50	72.5	FTF	NAN
Clean Rain Gage	OK	RHP	31.7
Clean Temp Shield	Y	BVV	13.3
Level Solar sensor	Y	WDDP	145
		WSMPH	1.67

OS Version updated?	N
Replace Desiccant	Y
Tighten Guy Wires	OK
Clean Battery Terminals	N
Clean Snow Depth Area	Y (plywood)
Brush Station Vicinity	N
Tighten elements on YAGI	Welded
Take Site Photos	

SDI	0	
SRW	523	
STF	33.6	10 cm
STF2	31.3	50 cm
STF3	31.3	90 cm
STF4		
ATF HMP	55.1	EE181
ATF ThermX	55.2	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	X3410061	EE181	1831160000674F		
Solar Radiation	LI200X	PY60148	LI200X	90559		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

To do:
 Install EE181 ☒ ; Swap LI200X ☒ ; Add interpretive sign to Enclosure None Check/update firmware on TX321, record TX serial

changed SRS0a height from 72 to ~~72~~ 72.5 inches.

TX321 Firmware 11.05 2017-09-14
 TX321 SN 174141946 (from Dev Conf.g)
 SN 1719 (sticker on transmitter)

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring
Site Visit Worksheet
Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907) 455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Chicken Creek	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/24/19	phone: (757) 824-7450	phone: (208) 387-5475
Operators	SOUSANES K SWANSON	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov -> Login -> 'Weather' -> 'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y (EE181)	
NESDIS ID	Solar Radiation	N	
Tx Time (mm:ss)	Wind Speed/Dir	N	
Tx Channel	Snow Depth	N	
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	
Antenna Elev. (Deg.)	Soil Temp 2	N	
Currently activated?	Soil Temp 3	N	
Currently transmitting?	Soil Temp 4	Y	ST4 bad? Replaced
NWS Site ID	Precipitation	N	
	Datalogger	N	
	Transmitter	N	
	Battery	N	

Record Site Conditions

Time visit begins:	1:20 PM	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE -> Connect Button -> Measurements Tab -> Select 'Status' from Table Drop-Down Box)
(Laptop: Device config utility -> Select DataLogger CR1000 -> Connect Button -> Data Monitor tab -> Status table)

Before Maintenance:	After Maintenance:
OSVersion	26
ProgName	Chicken_2018
StartTime	7/12/18 13:50
12 V Battery Voltage	13.3
Panel Temperature	15.5
Watchdog Errors	0
Lithium Batt Volt	3.4
Low 12V Batt Count	0
Skipped Scan	0
Reset if >0	0
Replace if <2.9	3.4
Reset if >0	0
Reset if >0	0

Maintenance Checklist

Completed? (Y/N)	Check transmitted values:
Download Hourly Data	Value OK? (Y/N)
RNIN before program update	RNIN 6.88
SR50 height before	WSM 8.32
Upload new program	WDD 71.5
Re-enter RNIN after	ATF 55.3
Measure and re-enter SR50	FTF -
Clean Rain Gage	RHP 49.2
Clean Temp Shield	BBV 13.3
Level Solar sensor	WDDP 13.5
OS Version updated?	WSMPH 84
Replace Desiccant	SDI 0.2
Tighten Guy Wires	SRW 292
Clean Battery Terminals	STF 55.2
	STF2 52.2

Clean Snow Depth Area N
Brush Station Vicinity N
Tighten elements on YAGI old style
Take Site Photos Y

STF3 42.1
STF4 43.9 (just installed)
ATF_ThermX 54.3
EE181 ATF_HMP45 54.9

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	EE181	F4010022	183116	EE181	171160000992A
Solar Radiation	L1200x		600039AF	H200x		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter	FXS29		FXS21			

Comments

To do:

Swap EE181 ☒ Check/Replace? STF4 Installed at 80cm
Replace battery cable and conduit ☒ RISK ASSESSMENT
BATTERY CONNECTION LOOKED FINE (PHOTO) DID NOT REPLACE.
RAINING HARD, DID NOT TAKE NOTES ON SITE. REPLACED 4th SOIL - GOT TO 80CM w/ soil pounder.

- TIGHTENED NORTH
FACING Guy wire

- SOILS ARE
PULLED OUT A
BIT. 3 SHALLOW
SENSORS SEEM
OK, PULLED MORE
FROM ENCLOSURE
THAN SOIL B/C
CABLE TIE AT
BOTTOM WAS
TIGHT. THE
DEEP SENSOR HAD
BEEN PULLED
OUT BELOW
BOTTOM OF MILD
LEG.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Camera Image #	Direction	Comp. Image #
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

- SWANSON DID
SOIL CHARACTERIZATION
ON SITE + PLANT
DESCRIPTIONS.

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Chititu	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/27/2019	phone: (757) 824-7450	phone: (208) 387-5475
Operators	SOUSANES + SWANSON	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather' -->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	?
Longitude	Temp/RH	Y (EE181)	?
NESDIS ID	Solar Radiation	N	?
Tx Time (mm:ss)	Wind Speed/Dir	N	?
Tx Channel	Snow Depth	N	?
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	?
Antenna Elev. (Deg.)	Soil Temp 2	N	?
Currently activated?	Soil Temp 3	N	?
Currently transmitting?	Precipitation	N	?
NWS Site ID	Datalogger	N	?
	Transmitter	N	No TX after 1/1/19. Yagi?
	Battery	N	?
	Fence	N/A	

Record Site Conditions

Time visit begins:	2:46pm	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26		
ProgName	Chititu_2018		
StartTime	7/11/18 11:56		
12 V Battery Voltage	13.4		
Panel Temperature	17.2		
Watchdog Errors	0	Reset if >0	Reset if >0
Lithium Batt Volt	3.5	Replace if <2.9	Replace if <2.9
Low 12V Batt Count	0	Reset if >0	Reset if >0
Skipped Scan	0	Reset if >0	Reset if >0

Maintenance Checklist

	Completed? (Y/N)	Value	OK? (Y/N)
Download Hourly Data	Y	RNIN 4.51	
RNIN before program update	Y 4.51	WSM 10.4	
SR50 height before	96.5	WDD 351	
Upload new program	N	ATF 63.7	
Re-enter RNIN after	—	FTF	
Measure and re-enter SR50	—	RHP 28.9	
Clean Rain Gage	Y	BVV 13.3	
Clean Temp Shield	N	WDDP 308	
Level Solar sensor	N	WSMPH 11.2	
OS Version updated?	N	SDI 0	
Replace Desiccant	Y	SRW 725	

- KEEP EYE OUT TX MAY BE BAD

- STIMVS LED LIT UP BEFORE TX
- MANUAL SAID PUSH FAULT FOR 2 SECONDS, WAIT FOR LED. 2 FLASHES

FAILSAFE TRIPPED. PRESSED FAULT FOR 10 SECONDS TO CLEAR.
- confirmed STFY programming

- STFY 4 installed in 2018, in program.

checked status on Dev. Config. Firmware 11.05 2017/09/14
- Watched TX + countdown on Dev. Config. seems ok now.

- Swanson did soil / plant characterization

Tighten Guy Wires	2
Clean Battery Terminals	2
Clean Snow Depth Area	5
Brush Station Vicinity	2
Tighten elements on YAGI	old style
Take Site Photos	

STF	71.9	
STF2	53.8	
STF3	39.2	
STF4	32.9	
EE181 ATF HMP	63.2	
ATF ThermX	63.5	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	(ft)	(in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	EE181 X3410042	164816	EE181	1831160000	328F
Solar Radiation	L200x	00004190				
Wind Speed/Dir	5103					
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter	TX320		TX321			

Comments

To do:
Swap EE181 ☒ Not transmitting since Jan 1 - condition unknown 12V wire RISK ASSESSMENT
- STATION LOOKS GREAT ON ARRIVAL
- POWER FINE; DATA AN THREE
- Re-wired regulator + moved so it had more room. GPS / DATA light came on after reconnection.
loose in charging regulator.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring
Site Visit Worksheet
Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Dunkle Hills	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	8/8/19	phone: (757) 824-7450	phone: (208) 387-5475
Operators	SOUSANES/SWANSON	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->'Weather'-->'Select Station')

GOES Information:		Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	63.300322	Temp	N	
Longitude	-149.541531	Temp/RH	Y	Install EE181
NESDIS ID	39608582	Solar Radiation	Y	Li220X
Tx Time (mm:ss)	0:34:20	Wind Speed/Dir	N	
Tx Channel	172	Snow Depth	N	
Antenna Azimuth (Deg Mag)	141 (?)	Soil Temp 1	N	
Antenna Elev. (Deg.)	18 (?)	Soil Temp 2	N	
Currently activated?	Y	Soil Temp 3	N	
Currently transmitting?	Y	Soil Temp 4	Y	Install ST4
NWS Site ID	DKLA2	Precipitation	N	
		Datalogger		
Camera	N	Transmitter	Y	TX321 Upgrade
Fence	N	Battery	N	

Record Site Conditions

Time visit begins:	11:45am	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
(Laptop: Device config utility-->Select DataLogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26		
ProgName	Dunkle2017		
StartTime	8/8/17 11:24		
12 V Battery Voltage	13.4		
Panel Temperature	16.8		
Watchdog Errors	0		
Lithium Batt Volt	3.4		
Low 12V Batt Count	0		
Skipped Scan	0		
RNIN Cumulative	10.13		
SR50a height	104		

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	10.13
RNIN before program update	10.13	WSM	11.9
SR50 height before	104	WDD	35.2
Upload new program	Y	ATF	61.1
Re-enter RNIN after	Y	FTF	
Measure and re-enter SR50	Y	RHP	43
Clean Rain Gage	N	BVV	13.3
Clean Temp Shield	N	WDDP	11.9
Level Solar sensor	Y	WSMPH	35
OS Version updated?	Y	SDI	693
Replace Desiccant	Y	SRW	55.1
Tighten Guy Wires	Y	STF	

Clean Battery Terminals N
 Clean Snow Depth Area N
 Brush Station Vicinity N
 Tighten elements on YAGI NA
 Take Site Photos .

STF2 57.3
 STF3 51.2
 STF4 52.4
 ATF HMP 61.1
 ATF ThermX 61.1

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	X3410043	EE181	18311600	024988	
Solar Radiation	LI200X	100476	LI200X	0463673		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Install EE181 ☒ Install TX321 ☒ Swap LI200X ☒ Install ST4 ☒

SR READING 0 ON ALL WTS; CABLES HAD BEEN PULLED OUT + CHANGED ON A BIT. SR CABLE SKINNED UP TOP - BIRD?

INSTALLED STF4 AT 90CM.

SWAPPED LI200X, INSTALLED EE181 + CHANGED PROGRAMMING.

SWAPPED TX312 FOR TX321

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

(cont.)

Keep an eye on 20cm Soil Sensor. Erroneous Readings 10/20-11/14/18

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			

DAVE SWANSON
 DID SOIL / VEG
 CHARACTERIZATION
 - WHILE ATTEMPTING
 TO LOAD NEW
 PROGRAM DATA
 STOPPED WORKING,
 NOT SURE WHY.
 NO RESPONSE FROM
 KEYPAD EITHER.
 CYCLED THE
 POWER + TOOK
 OUT THE EXTRA
 TRANSMITTER
 CABLE AND IT
 POWERED BACK
 UP.

CAKN Weather & Climate Monitoring
Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Eielson VC	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/5/2019	phone: (757) 824-7450	phone: (208) 387-5475
Operators	Ken Hill	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y (EE181)	
NESDIS ID	Solar Radiation	Y	
Tx Time (mm:ss)	Wind Speed/Dir	N	
Tx Channel	Snow Depth	N	
Antenna Azimuth (Deg Mag)	Soil Temp 1	N/A	
Antenna Elev. (Deg.)	Soil Temp 2	N/A	
Currently activated?	Soil Temp 3	N/A	
Currently transmitting?	Precipitation	Y	Damaged October 2018
NWS Site ID	Datalogger	N	
	Transmitter	N	
	Battery	N	
	Fence	N/A	

Record Site Conditions

Time visit begins:	12:00	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	N	If no, comment:	Precip cable Damaged.
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

 (WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
 (Laptop: Device config utility-->Select DataLogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26	26	
ProgName	Eielson2017	Eielson-2019	
StartTime	8/16/17 10:23	6/5/2019 13:39	
12 V Battery Voltage	13.4	13.6	
Panel Temperature	12.5	12.7	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.5	3.5	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative	BAD		
SR50a height	87		

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	0
RNIN before program update	7100 (Reset)	WSM	10.9
SR50 height before	87	WDD	196
Upload new program	Y	ATF	48.8
Re-enter RNIN after	0	FTF	-
Measure and re-enter SR50	87	RHP	59
Clean Rain Gage	New	BVV	13.6
Clean Temp Shield	N	WDDP	216
Level Solar sensor	N	WSMPH	11.1
OS Version updated?	N	SDI	0
Replace Desiccant	Y	SRW	846

Tighten Guy Wires
Clean Battery Terminals
Clean Snow Depth Area
Brush Station Vicinity
Tighten elements on YAGI
Take Site Photos

2
2
2
2
2

EE101
ATF HMP
ATF ThermX

49.8	
50.9	

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Temp/RH	HMP45C	D3520097	EE181	183116000086CD		
Solar Radiation	Li200 Rx	182544	Li200x	60144		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation			TE-525	69247-616		
Primary AT						
Datalogger						
Transmitter						

Comments

Replace HMP45 with EE181 ✓
Swap solar radiation sensor ✓ old sensor was Li200 Rx.
Replace damaged Tipping Bucket ✓
Install new 4" NWS Coop rain gage ✓

To do next visit: Batteries (?)

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Gates Glacier	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/27/2019	phone: (757) 824-7450	phone: (208) 387-5475
Operators	SOUSANES + SWANSON +	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov --> Login --> 'Weather' --> 'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y (EE181)	RH out on 6/4
NESDIS ID	Solar Radiation	N	
Tx Time (mm:ss)	Wind Speed/Dir	N	
Tx Channel	Snow Depth	N	
Antenna Azimuth (Deg Mag)	Soil Temp 1	Y	All soils reading errors -99
Antenna Elev. (Deg.)	Soil Temp 2	Y	
Currently activated?	Soil Temp 3	Y	ADD STF 4
Currently transmitting?	Precipitation	N	
NWS Site ID	Datalogger	N	
	Transmitter	N	
Camera	Battery	N	
	Fence	N/A	

Record Site Conditions

Time visit begins:	4:15	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
 (Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26		
ProgName	GatesGl_2018		
StartTime	7/11/18 16:54		
12 V Battery Voltage	13.1		
Panel Temperature	21.5		
Watchdog Errors	0		Reset if >0
Lithium Batt Volt	3.5		Replace if <2.9
Low 12V Batt Count	0		Reset if >0
Skipped Scan	0		Reset if >0

Maintenance Checklist

	Completed? (Y/N)		Value	OK? (Y/N)
Download Hourly Data	Y		RNIN	16.34
RNIN before program update	11.34		WSM	8.2
SR50 height before	103	103 in. 2017	WDD	307
Upload new program	N		ATF	64.6
Re-enter RNIN after	1		FTF	
Measure and re-enter SR50	1		RHP	28.8
Clean Rain Gage	N		BVV	13.7
Clean Temp Shield	Replaced	AT/R4 shield	WDDP	302
Level Solar sensor	N		WSMPH	8.2
OS Version updated?	N		SDI	6 plants - dead
Replace Desiccant	Y		SRW	541
Tighten Guy Wires	Y		STF	1
Clean Battery Terminals	N		STF2	54
Clean Snow Depth Area	Y		STF3	53
Brush Station Vicinity	N		STF4	48

Tighten elements on YAGI
Take Site Photos

No old style

181 ATF HMP
ATF ThermX

64.8

64.3

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	(ft)	(in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	EE181	17141600003057.00	EE181	183118000193310		
Solar Radiation						
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

To do:

Swap EE181 ☒ Replace soil-sensors, add ST4 ☒ Swap SD Card in Camera ☒

Assess condition of CC5MPX ☒ Assess condition of station, something happened on 6/4 ☒ RISK ASSESSMENT

Copy chicken - 2018

- Bear damage - soils pulled out / AT/RH cable pulled out, battery box for camera chewed, wood platform chewed up + moved, AT/RH radiation shield bent 90° to the North, snow/camera crossbar moved NWN 15°.
- Replaced 3 soils at 10, 20 + 50 cm. Replaced AT/RH shield, Swapped EE181.
- Swapped SD card, checked SD card on computer - needed to shutdown +

restart. Adjusted camera angle, but did not have time to look at old image - we had to wing it:
- No time to add 4th soil sensor
- Swanson did

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

Soil/plant characterization

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Ruth Glacier	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/26/2019	phone: (757) 824-7450	phone: (208) 387-5475
Operators	Ken Hill	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y	Install EE181
NESDIS ID	Solar Radiation	N	
Tx Time (mm:ss)	Wind Speed/Dir	N	
Tx Channel	Snow Depth	N	
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	
Antenna Elev. (Deg.)	Soil Temp 2	N	
Currently activated?	Soil Temp 3	N	Add STF4
Currently transmitting?	Precipitation	N	
NWS Site ID	Datalogger	N	
	Transmitter	Y	Upgrade to TX321
	Battery	N	Voltage OK 2018-2019.
	Fence	Y	Bring fence parts

Record Site Conditions

Time visit begins:	10:50	Time visit ends:	13:30
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
 (Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26		26
ProgName	Ruth2017		Ruth2019
StartTime	1/11/18 15:25		6/26/2019 12:55
12 V Battery Voltage	13.3		13.2
Panel Temperature	16.2		16.9
Watchdog Errors	2	Reset if >0	0
Lithium Batt Volt	3.4	Replace if <2.9	3.4
Low 12V Batt Count	119	Reset if >0	0
Skipped Scan	0	Reset if >0	0
RNIN Cumulative	14.20		
SR50a height	69		

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	14.2
RNIN before program update	14.20	WSM	3.3
SR50 height before	69	WDD	191
Upload new program	Y	ATF	59.5
Re-enter RNIN after	14.20	FTF	NAN
Measure and re-enter SR50	69	RHP	13.15
Clean Rain Gage	OK	BVV	73.2
Clean Temp Shield	OK	WDDP	177
Level Solar sensor	OK	WSMPH	6
OS Version updated?	N	SDI	0.6
Replace Desiccant	Y	SRW	760
Tighten Guy Wires	NA	STF	63.7

Clean Battery Terminals N
 Clean Snow Depth Area N
 Brush Station Vicinity NA
 Tighten elements on YAGI Y
 Take Site Photos Y

STF2 57.3
 STF3 56.3
 STF4 47.3
 ATF HMP 59.3 EE181
 ATF ThermX 60.2

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	D3620083	EE181	18316000	25188	
Solar Radiation						
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

To do:

Swap HMP45 for EE181 ☒ Check/Repair Electric fence ☒ Replace Enclosure (if wx and time allow) ☒
 Install TX321 ☒ Install STF4 90cm Load new program for EE181 & STF4 ☒

- Installed ST 4 90cm
 - Fence looked good. one connector replaced
 Unsure what's caused low 12V counts and Watchdogs
 - Need to drill hole in enclosure for power cable conduit.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name

Stampede

Date of this visit

8/8/2019

Operators

SOUSANES, SWANSON

DCS - Sat. TX Check

phone: (757) 824-7450

24/7 technical support

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather' -->'Select Station')

GOES Information:

Latitude	63.747781
Longitude	-150.328053
NESDIS ID	3960A6F4
Tx Time (mm:ss)	0:34:10
Tx Channel	172
Antenna Azimuth (Deg Mag)	141
Antenna Elev. (Deg.)	18
Currently activated?	Y
Currently transmitting?	Y
NWS Site ID	SMPA2
Fence	N
Camera	N

Sensors

Swap?
(Y/N)

Recent error events (list)?

Temp	N	
Temp/RH	Y (HMP45)	
Solar Radiation	Y (LI200X)	
Wind Speed/Dir	N	
Snow Depth	N	
Soil Temp 1	Y	Damaged on 7/27
Soil Temp 2	N	Reinstall
Soil Temp 3	Y	Damaged on 7/27
Soil Temp 4	Y	Install ST4
Precipitation	?	Damaged on 7/27
Datalogger	N	
Transmitter	Y (TX321)	
Battery	N	

Record Site Conditions

Time visit begins:	2:44 pm	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	27	27	
ProgName	Stampede2017	Stampede 2019	
StartTime	8/8/17 13:41	8/8/19 4:40 pm	
12 V Battery Voltage	13.4	13.3	
Panel Temperature	22.7	22.8	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.5	3.5	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative	7.72		
SR50a height	85.4		

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN 7.72	
RNIN before program update	Y	WSM 1.15	
SR50 height before	85.4	WDD 7.08	
Upload new program	Y	ATF 69.4	
Re-enter RNIN after	Y	FTF	
Measure and re-enter SR50	Y	RHP 46.4	
Clean Rain Gage	Y	BBV 13.3	
Clean Temp Shield	Y	WDDP 89.3	
Level Solar sensor	Y	WSMPH 1.76	
OS Version updated?	Y	SDI 0	
Replace Desiccant	Y	SRW 67.8	
Tighten Guy Wires	Y	STF 63.8	
Clean Battery Terminals	Y	STF2 61.6	

Clean Snow Depth Area N
 Brush Station Vicinity N
 Tighten elements on YAGI NA
 Take Site Photos Y

STF3 60.6
 STF4 53.7
 ATF HMP 69.6
 ATF ThermX 70.3

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	B1240007	HMP45	<u>X3410060</u>		
Solar Radiation	LI200X	36882	LI200X	<u>py 90553</u>		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Station Damaged on July 27: Damage to Precip, ST1, 3. Replace/Repair ☒ Swap HMP45 ☒ Swap LI200X ☒
 Install TX321 ☒ Reinstall all soil probes; in Dave's soil pit? ☒ Clear Site of brush ☒

Tipping bucket was hanging off post, evidence of minor bear disturbance. Sal cables disturbed, paw marks on enclosure. Happened on 7/27/19 between 5 pm - 6 pm. Levelled + reattached TB. Next year bring B-Line clamps / small pipe to mount on tripod. Lots of debris in TB, cleaned out.

STF1 = 10 cm
 STF2 = 20 cm
 STF3 = 50 cm

Swapped LI200X.

Installed 4 new soil Sensors in Dave's soil hole. STF4 = 90 cm. Loaded new program w/ 109 programming.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1	385		
2	386		
3	387		
4	388		
5	389		
6	390		
7	391		
8	392		
9	393		
10	394		
11	395		
12	396		
13	397		
14	398		
15	399		
16	400		
17	401		

* Dave Swenson did sal characterization

- Swapped TX312 for the TX321.

- Contact Fire Staff about brushing in 2020.

Sal cables disturbed, paw marks on enclosure. Happened on 7/27/19 between 5 pm - 6 pm.

Loaded new program w/ 109 programming.

Side Note:

Tablet stopped working at site.

Error message:

"no operating system"
 Let it cool down + powered off + then it worked again.

Downloaded data on laptop just to be safe.

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Tana Knob	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/27/2019	phone: (757) 824-7450	phone: (208) 387-5475
Operators	Sousanes + Swanson	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	60.908	Temp N	
Longitude	142.901311	Temp/RH Y	EE181
NESDIS ID	3960709C	Solar Radiation N	
Tx Time (mm:ss)	0:33:40	Wind Speed/Dir Y	
Tx Channel	172	Snow Depth N	
Antenna Azimuth (Deg Mag)	171	Soil Temp 1 N	
Antenna Elev. (Deg.)	21	Soil Temp 2 N	
Currently activated?	Y	Soil Temp 3 N	Install STF4 ADD STF4
Currently transmitting?	Y	Precipitation N	
NWS Site ID	TANA2	Datalogger N	
		Transmitter N	
Camera	N	Battery N	
		Fence Y	

Record Site Conditions

Time visit begins:	12:31 PM	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:	After Maintenance:
OSVersion	2.6
ProgName	TANA-2018
StartTime	7/11/2018 1:49 PM
12 V Battery Voltage	13.4
Panel Temperature	21.6
Watchdog Errors	0
Lithium Batt Volt	3.5
Low 12V Batt Count	992
Skipped Scan	0
Reset if >0	0
Replace if <2.9	0
Reset if >0 ?	3.5
Reset if >0	0

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	11.7
RNIN before program update	11.68	WSM	5.9
SR50 height before	100.0	WDD	12.0
Upload new program	N - Added 2018	ATF	67.4
Re-enter RNIN after	Y	FTF	—
Measure and re-enter SR50	Y	RHP	34.4
Clean Rain Gage	Y	BVV	13.4
Clean Temp Shield	Y	WDDP	142
Level Solar sensor	Y	WSMPH	6.9
OS Version updated?	Y	SDI	0
Replace Desiccant	Y	SRW	823
Tighten Guy Wires	Y	STF	72.7
Clean Battery Terminals	Y	STF2	55.9
Clean Snow Depth Area	Y	STF3	49.4
Brush Station Vicinity	Y	STF4	

Tighten elements on YAGI

Take Site Photos

EE181 ATF HWP

66.7

ATF ThermX

66.1

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	EE181	171216000044AB	EE181	18311600	00020A	
Solar Radiation						
Wind Speed/Dir	05103	53415	05103	105730		
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

To do:

Swap EE181



Swap WS/WD



Check/Repair Fence



Install STF4



Update program for STF4

X NO

RISK ASSESSMENT

- Swanson did soil/plant characterization

- enclosure very fiberglassy

- Reset Low 3' 12V count; left over from last year 7 Batt. secured

- checked SD height w/ test fine.

Program

- Replaced 109 radiation shield; bent over 90°

- Swapped AT/RH, WS/WD.

- rewired ground wire from station to enclosure

- fixed fence . Offset correction -5.0 inches.

WFMI Maintenance Narrative Adjust SD Sensor Height next year

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Tebay	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/27/19	phone: (757) 824-7450	phone: (208) 387-5475
Operators	SOUSANES + SWANSON	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y (EE181)	
NESDIS ID	Solar Radiation	Y	
Tx Time (mm:ss)	Wind Speed/Dir	N	
Tx Channel	Snow Depth	Y	No values all year :(
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	
Antenna Elev. (Deg.)	Soil Temp 2	N	
Currently activated?	Soil Temp 3	N	install 674 ADD STF 4
Currently transmitting?	Precipitation	?	LOW ? CHECK
NWS Site ID	Datalogger	N	
Camera	Transmitter	?	? Check no TX jan-Feb
	Battery	N	
	Fence	Y	

Record Site Conditions

Time visit begins:	9:50am	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)

(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26		26
ProgName	Tebay_2018		Tebay-2018
StartTime	7/10/18 15:22		6/27/2019 10:49am
12 V Battery Voltage	13.1		13.1
Panel Temperature	25.9		25.7
Watchdog Errors	0	Reset if >0	0
Lithium Batt Volt	3.5	Replace if <2.9	3.5
Low 12V Batt Count	0	Reset if >0	0
Skipped Scan	0	Reset if >0	0

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	15.8
RNIN before program update	15.8	WSM	1.6
SR50 height before	92.5	WDD	28.3
Upload new program	N	ATF	72.5
Re-enter RNIN after	Y	FTF	2.2
Measure and re-enter SR50	Y	RHP	39
Clean Rain Gage	Y	BVV	13.2
Clean Temp Shield	Y	WDDP	15.3
Level Solar sensor	Y	WSMPH	2.1
OS Version updated?	Y	SDI	2699
Replace Desiccant	Y	SRW	0.2
Tighten Guy Wires	N none	STF	50.8

Clean Battery Terminals N
 Clean Snow Depth Area Y
 Brush Station Vicinity Y
 Tighten elements on YAGI old style
 Take Site Photos

STF2 55.9
 STF3 53.8
 STF4 ---
 ATF HMP 72.7
 ATF ThermX 72

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	(ft)	(in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	EE181	17101600004379	EE181	1831160000	2307C	
Solar Radiation	LI200X	102541	LI200X	43256		
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

To do:

Swap EE181 ☒ Swap Snow ☒ Swap LI200X ☒ Add STF4 NO
 Change program for STF4 ☒ Check YAGI/Coax ☒ Check Precip (low?) look up

RISK ASSESSMENT

Swapped AT/RH, snow, solar

only sensor head, not cable for snow

- fixed fence

- checked SD w/ test program

- cleaned tipping bucket, minor debris in funnel

- Swanson did soil/plant characterization

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NE Towards	
3		E Towards	
4		SE Towards	
5		South Towards	
6		SW Towards	
7		W Towards	
8		NW Towards	
9		North Away	
10		NE Away	
11		E Away	
12		SE Away	
13		S Away	
14		SW Away	
15		W Away	
16		NW Away	
17		Enclosure	

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Toklat	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	6/5/2019	phone: (757) 824-7450	phone: (208) 387-5475
Operators	Ken Hill	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y (EE181)	
NESDIS ID	Solar Radiation	N	
Tx Time (mm:ss)	Wind Speed/Dir	N	
Tx Channel	Snow Depth	N	
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	
Antenna Elev. (Deg.)	Soil Temp 2	N	
Currently activated?	Soil Temp 3	N	
Currently transmitting?	Precipitation	N	
NWS Site ID	Datalogger	N	
	Transmitter	N	
	Battery	YES?	
	Fence	N/A	

Record Site Conditions

Time visit begins:	15:06	Time visit ends:	16:30
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y/notes	If no, comment:	Batteries beginning to weaken

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
 (Laptop: Device config utility-->Select DataLogger CR1000-->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:	After Maintenance:
OSVersion	27
ProgName	Toklat2017
StartTime	8/14/17 15:28
12 V Battery Voltage	12.9
Panel Temperature	16.0
Watchdog Errors	0
Lithium Batt Volt	3.5
Low 12V Batt Count	0
Skipped Scan	0
RNIN Cumulative	4.95
SR50a height	81.9

Maintenance Checklist

Completed? (Y/N)	Check transmitted values:
Download Hourly Data	Value OK? (Y/N)
RNIN before program update	RNIN 4.95
SR50 height before	WSM 1.0
Upload new program	WDD 146
Re-enter RNIN after	ATF 56.1
Measure and re-enter SR50	FTF -
Clean Rain Gage	RHP 412
Clean Temp Shield	BVV 12.6
Level Solar sensor	WDDP 296
OS Version updated?	WSMPH 9.2
Replace Desiccant	SDI 0
Tighten Guy Wires	SRW 390
	STF 61.5

Clean Battery Terminals
Clean Snow Depth Area
Brush Station Vicinity
Tighten elements on YAGI
Take Site Photos

STF2 56.8
STF3 51.8
STF4 -
EE181 ATF HMP 55.9
ATF ThermX 56.0

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	X3410044	HMP45	183116000009FA		
Solar Radiation						
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Replace HMP45 with EE181 ☒
Swap Batteries ☒
Verify Soil Probe Depths N Looked secure. Did not disturb
- Replaced battery cable

Next visit:
- Verify batteries are charging
- Check Batteries and confirm tight connection

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			

CAKN Weather & Climate Monitoring
Site Visit Worksheet
Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

Site name	Upper Charley	DCS - Sat. TX Check	RAWS HelpDesk:
Date of this visit	5/14/2019	phone: (757) 824-7450	phone: (208) 387-5475
Operators	SOUSANES + HILL	24/7 technical support	Hours: M-F, 6 AM-2:30 PM AST

Pre-Field Information

(Look up the station: www.nifc.blm.gov -> Login -> 'Weather' -> 'Select Station')

GOES Information:		Swap? (Y/N)	Recent error events (list)?
Latitude	64.516919	Temp N	
Longitude	-143.202381	Temp/RH	Y (EE181)
NESDIS ID	3960D064	Solar Radiation	N
Tx Time (mm:ss)	0:38:10	Wind Speed/Dir	? 0 mph between mid Nov-mid Feb
Tx Channel	152	Snow Depth	? 80 between mid Dec-late Feb
Antenna Azimuth (Deg Mag)	171	Soil Temp 1	N
Antenna Elev. (Deg.)	17	Soil Temp 2	N
Currently activated?	Y	Soil Temp 3	Y Add 4th STF at 100cm, uncommnt ✓
Currently transmitting?	Y	Precipitation	N
NWS Site ID	UPRA2	Datalogger	N
		Transmitter	N Check Firmware/ger SN#
Camera	Y	Battery	N
		Fence	Y Condition unknown

Record Site Conditions

Time visit begins:	3:15	Time visit ends:	4:45
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select 'Status' from Table Drop-Down Box)
(Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	25	25	
ProgName	Ucharley_2017	UCharley2019	
StartTime	6/13/17 15:46	5/14/2019 4:25pm	
12 V Battery Voltage	13.4	13.4	
Panel Temperature	14.7	13.9	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.5	3.5	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative	0.3		
SR50a height	80 in 2017		

Maintenance Checklist

Completed? (Y/N)		Check transmitted values:	
		Value	OK? (Y/N)
Download Hourly Data	Y	RNIN	0 Reset to 0" due to tipping bucket 90° off placement on arrival
RNIN before program update	0.3	WSM	7.3
SR50 height before	80	WDD	13.6
Upload new program	Y	ATF	54.1
Re-enter RNIN after	0	FTF	
Measure and re-enter SR50	80	RHP	24.3
Clean Rain Gage	yes	BVV	13.5
Clean Temp Shield	NO	WDDP	10.1
Level Solar sensor	NO	WSMPH	14.8
OS Version updated?	NO	SDI	0.5
Replace Desiccant	Y	SRW	811.5

Tighten Guy Wires NO
 Clean Battery Terminals NO
 Clean Snow Depth Area NA
 Brush Station Vicinity NA
 Tighten elements on YAGI NA old style
 Take Site Photos

STF 40.6
 STF2 37.9
 STF3 31.7
 STF4 32.3
 181 ATF-HMP 54.1
 ATF ThermX 54.5

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	FY010029	EE181	783116000047DE		
Solar Radiation						
Wind Speed/Dir						
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Datalogger						
Transmitter			321	17414846		

Comments

To do:
 Install EE181 ☒; Check WS/WD OK; Check SR50 OK; Add 4th soil sensor 75 cm; Uncomment STF4 in UChalrey2019 program if
 Repair Fence ☒ Swap SD Card in Camera ☒ Assess condition of camera GOOD
 Wind and snow look OK after mid Feb, check sensors. Check/update firmware on TX321, record TX serial # 17414846
 - TIPPING BUCKET NUTAIL LOOSE, BUCKET 90° OFF W/ FUNNEL ON GROUND. RIGHTED + TIGHTENED
 - CHECKED FIRMWARE VERSION ON TX321 11.05 2012/09/14
 - SWAPPED HMP45 FOR EE181
 - INSTALLED STF4 AT 75CM W/DME'S SOIL PENETR. INSTALLER
 - FIXED POLYWIRE REPAIRED BY MATT KAMPE
 - LOADED NEW PROGRAM W/ 181 + STF4. - SWAPPED SD CARD ON CAMERA

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1		N Towards	
2		NW Towards	
3		W Towards	
4		SW Towards	
5		South Towards	
6		SE Towards	
7		E Towards	
8		NE Towards	
9		North Away	
10		NW Away	
11		W Away	
12		SW Away	
13		S Away	
14		SE Away	
15		E Away	
16		NE Away	
17		Enclosure	

Append 181
 102

CAKN Weather & Climate Monitoring

Site Visit Worksheet

Version: 8 March 2017

CAKN Program Contact:

Pam Sousanes/Ken Hill

phone: (907) 455-0677/(907)-455-0678

email: pam_sousanes@nps.gov/kenneth_hill@nps.gov

RAWS HelpDesk:

phone: (208) 387-5475

Hours: M-F, 6 AM-2:30 PM AST

Site name	Wigand	DCS - Sat. TX Check	
Date of this visit	8/8/2017	phone: (757) 824-7450	
Operators	SOUSANES/KEN HILL	24/7 technical support	

Pre-Field Information

(Look up the station: www.nifc.blm.gov-->Login-->'Weather'-->'Select Station')

GOES Information:	Sensors	Swap? (Y/N)	Recent error events (list)?
Latitude	Temp	N	
Longitude	Temp/RH	Y	Install EE181
NESDIS ID	Solar Radiation	Y (LI200X)	HM045
Tx Time (mm:ss)	Wind Speed/Dir	Y (05103)	30' cable
Tx Channel	Snow Depth	N	
Antenna Azimuth (Deg Mag)	Soil Temp 1	N	
Antenna Elev. (Deg.)	Soil Temp 2	N	
Currently activated?	Soil Temp 3	N	
Currently transmitting?	Soil Temp 4	Y	Install ST4
NWS Site ID	Precipitation	N	
	Datalogger	N	
Fence	Transmitter	Y	Install TX321
	Battery	N	

Record Site Conditions

Time visit begins:	5:15	Time visit ends:	
Station accessible? (Y/N)	Y	If no, comment:	
Cables intact? (Y/N)	Y	If no, comment:	
Power source ok? (Y/N)	Y	If no, comment:	
Batteries ok? (Y/N)	Y	If no, comment:	

Record Station Status Table Values

(WMD: PConnectCE-->Connect Button-->Measurements Tab-->'Select Status' from Table Drop-Down Box)
 (Laptop: Device config utility-->Select DataLogger CR1000 -->Connect Button-->Data Monitor tab-->Status table)

Before Maintenance:		After Maintenance:	
OSVersion	26	26	
ProgName	Wigand2017	Wigand2017	
StartTime	8/8/17 15:06	8/8/17 15:06	
12 V Battery Voltage	13.2	13.2	
Panel Temperature	22.7	19.3	
Watchdog Errors	0	0	Reset if >0
Lithium Batt Volt	3.5	3.5	Replace if <2.9
Low 12V Batt Count	0	0	Reset if >0
Skipped Scan	0	0	Reset if >0
RNIN Cumulative	7.95		
SR50a height	77.4		

Maintenance Checklist

Completed? (Y/N)	Check transmitted values:
Download Hourly Data	Value OK? (Y/N)
RNIN before program update	RNIN 9.97
SR50 height before	WSM 4.3
Upload new program	WDD 251
Re-enter RNIN after	ATF 64.4
Measure and re-enter SR50	FTF
Clean Rain Gage	RHP 44.8
Clean Temp Shield	BVV 13.2
Level Solar sensor	WDDP 84.6
OS Version updated?	WSMPH 11.7
Replace Desiccant	SDI 2.5
Tighten Guy Wires	SRW 16.7
	STF 44.6

Clean Battery Terminals ☒
 Clean Snow Depth Area ☒
 Brush Station Vicinity ☒
 Tighten elements on YAGI ☒
 Take Site Photos ☒

STF2 107.2
 STF3 39.1
 STF4
 ATF HMP 64.8
 ATF ThermX 64.5

Record Sensor Configuration Changes

	Model # out	Serial# out	Model # in	Serial# in	Cable length (ft)	Height/depth (in)
Air Temperature 1						
Air Temperature 2						
Temp/RH	HMP45	E3010021	HMP45	73910053		
Solar Radiation	LI200X	46238	LI200X	52878		
Wind Speed/Dir	05103 - 30'	85175	05103 - 30'	159261		
Snow depth						
Soil Temp 1						
Soil Temp 2						
Soil Temp 3						
Precipitation						
Primary AT						
Datalogger						
Transmitter						

Comments

Install EE181 ☒ Swap WS 30' cable ☒ Install TX321 ☒ Swap LI200X ☒ Install STF4 ☐ Did not have time to

Swap HMP45

Did not install EE181, Swapped HMP45. Swapped 30' Wind - getting more tricky b/c tripod legs are sinking making it difficult to undo guy wires. Also metal clip used to lower mast is bent - took brute force to get it undone. Consider replacing tripod w/ lunar lander tripod. Swapped LI200X. Did not change program. Swapped TX321 for TX 312.

To Lower Mast: Disconnect Guy wires, loosens soil temp cables, left the enclosure and mast, lower mast, rest mast on actionpacker, watch wires when raising back up.

Dave did soil characterization - hole immediately filled w/ water.

WFMI Maintenance Narrative

(Fill out prior to submission of NAMS post-trip update. Update may contain several station visits.)

Image identifiers of photos taken




Photo Key	Image on camera #	Direction	On Computer
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			