



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Employee Cabin (chef)

Unit - Location: KATM - Brooks Camp

FMSS ID: 88536, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 10, 2023

Coordinates (DDM): 58° 33.357' N 155° 46.771' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 41

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Brooks Lodge Guest Cabin #25
Unit - Location: KATM - Brooks Camp
FMSS ID: 88532, **Local ID:**
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: S Szturm , August 10, 2023
Coordinates (DDM): 58° 33.341' N 155° 46.738' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Brooks Camp/Brooks Lodge
Revisit Interval: 4 yrs
Map Label: 48

Primary Access: Air
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Brooks Lodge Guest Cabin #24
Unit - Location: KATM - Brooks Camp
FMSS ID: 88531, **Local ID:**
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: S Szturm , August 10, 2023
Coordinates (DDM): 58° 33.336' N 155° 46.730' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Brooks Camp/Brooks Lodge
Revisit Interval: 4 yrs
Map Label: 88

Primary Access: Air
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra, northern hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Guest Shower/Restroom

Unit - Location: KATM - Brooks Camp

FMSS ID: 88527, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 9, 2023

Coordinates (DDM): 58° 33.334' N 155° 46.715' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 53

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND BC Brooks Lodge Guest Cabin #23

Unit - Location: KATM - Brooks Camp

FMSS ID: 88530, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 10, 2023

Coordinates (DDM): 58° 33.352' N 155° 46.701' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 56

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND BC Brooks Lodge Guest Cabin #22

Unit - Location: KATM - Brooks Camp

FMSS ID: 88529, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 10, 2023

Coordinates (DDM): 58° 33.345' N 155° 46.699' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 57

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND BC Brooks Lodge Guest Cabin #21

Unit - Location: KATM - Brooks Camp

FMSS ID: 88528, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 10, 2023

Coordinates (DDM): 58° 33.340' N 155° 46.695' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 89

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Brooks Lodge/Dining Kitchen

Unit - Location: KATM - Brooks Camp

FMSS ID: 88523, **Local ID:**

Structure Type, Use: Building, Public

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 9, 2023

Coordinates (DDM): 58° 33.327' N 155° 46.693' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 60

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Brooks Lodge Office and Store

Unit - Location: KATM - Brooks Camp

FMSS ID: 88525, **Local ID:**

Structure Type, Use: Administrative, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 9, 2023

Coordinates (DDM): 58° 33.312' N 155° 46.684' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 63

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Fish Freezing Building

Unit - Location: KATM - Brooks Camp

FMSS ID: 53657, **Local ID:** BR-45

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 9, 2023

Coordinates (DDM): 58° 33.297' N 155° 46.682' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 90

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Quarters BR-42

Unit - Location: KATM - Brooks Camp

FMSS ID: 38409, **Local ID:** BR-42

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.420' N 155° 46.736' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 86

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and little to no fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Quarters

Unit - Location: KATM - Brooks Camp

FMSS ID: 38408, **Local ID:** BR-41

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 16, 2023

Coordinates (DDM): 58° 33.420' N 155° 46.750' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 83

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and little to no fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Camp Quarters

Unit - Location: KATM - Brooks Camp

FMSS ID: 38411, **Local ID:** BR-46

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.430' N 155° 46.751' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 46

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and little to no fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Camp Quarters BR-48

Unit - Location: KATM - Brooks Camp

FMSS ID: 38410, **Local ID:** BR-43

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.430' N 155° 46.736' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 87

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and little to no fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Camp Quarters BR-48

Unit - Location: KATM - Brooks Camp

FMSS ID: 38413, **Local ID:** BR-48

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.438' N 155° 46.735' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 49

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None



Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Camp Quarters BR-49

Unit - Location: KATM - Brooks Camp

FMSS ID: 38414, **Local ID:** BR-49

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.442' N 155° 46.751' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 93

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Camp Quarters BR-50

Unit - Location: KATM - Brooks Camp

FMSS ID: 38415, **Local ID:** BR-50

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.452' N 155° 46.758' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 80

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Light or no wildland fuels

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Transcient Housing Yurt Tent

Unit - Location: KATM - Brooks Camp

FMSS ID: 54410, **Local ID:** BR-51

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.420' N 155° 46.722' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 51

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and fuels clearance

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Brooks Lodge Tuckerville Employee Cabin #5

Unit - Location: KATM - Brooks Camp

FMSS ID: 88541, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.434' N 155° 46.802' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 33

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Brooks Lodge Tuckerville Employee Cabin #7

Unit - Location: KATM - Brooks Camp

FMSS ID: 88543, **Local ID:**

Structure Type, Use: Building, Residence

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.439' N 155° 46.813' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: Yes

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 29

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: LB-Visitor Food Cache

Unit - Location: KATM - Brooks Camp

FMSS ID: 95876, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 32.775' N 155° 47.612' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Lake Brooks

Revisit Interval: 4 yrs

Map Label: 73

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar, rubberized

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments: No photos, couldn't complete assessment





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Brooks Lodge Tuckerville Utility Storage Bldg

Unit - Location: KATM - Brooks Camp

FMSS ID: 88556, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.441' N 155° 46.825' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 26

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Small Generator Building

Unit - Location: KATM - Brooks Camp

FMSS ID: 95881, **Local ID:** BR-44B

Structure Type, Use: Utility Site (Water, Gas, Elec), Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm, August 8, 2023

Coordinates (DDM): 58° 33.471' N 155° 46.748' W

Rating: High

Protection Level: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 94

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: LB-OH Leach Field Outhouse and Thinking Throne
Unit - Location: KATM - Brooks Camp
FMSS ID: 99575, **Local ID:** LB-OH
Structure Type, Use: Toilet, Public
Owner: National Park Service
Field Crew, Visit Date: S Szturm , June 23, 2008
Coordinates (DDM): 58° 32.735' N 155° 47.518' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Lake Brooks
Revisit Interval: 4 yrs
Map Label: 14

Primary Access: Air
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra, northern hardwood litter
Fuel Load: Very Heavy
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Brooks Lodge Rental Building

Unit - Location: KATM - Brooks Camp

FMSS ID: 88526, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 9, 2023

Coordinates (DDM): 58° 33.302' N 155° 46.692' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 61

Primary Access: Air

Ingress Egress: N/A,access by foot,boat,or air only

Access Width: N/A,access by foot,boat,or air only

Access Condition: N/A,access by foot,boat,or air only

Bridge Condition: N/A,access by foot,boat,or air only

Access and Turnarounds: N/A,access by foot,boat,or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Propane/Dry Storage Bldg

Unit - Location: KATM - Brooks Camp

FMSS ID: 90879, **Local ID:** BR-54

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 16, 2023

Coordinates (DDM): 58° 33.419' N 155° 46.771' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 40

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and little to no fuels clearance

Overhead Hazards: No overhead hazards

Comments: No photos, couldn't complete assessment





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Campground Woodshed

Unit - Location: KATM - Brooks Camp

FMSS ID: 91425, **Local ID:** BR-WS

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.601' N 155° 46.649' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Campground

Revisit Interval: 4 yrs

Map Label: 69

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar, rubberized

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: Adjacent to/under deck of facility

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Propane/Dry Storage Bldg

Unit - Location: KATM - Brooks Camp

FMSS ID: 90894, **Local ID:** BR-54

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 16, 2023

Coordinates (DDM): 58° 33.421' N 155° 46.771' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 42

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Camp Spill Response Shed
Unit - Location: KATM - Brooks Camp
FMSS ID: 95880, **Local ID:** BR-SR
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: S Szturm , August 8, 2023
Coordinates (DDM): 58° 33.462' N 155° 46.733' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Brooks Camp/Brooks Lodge
Revisit Interval: 4 yrs
Map Label: 50

Primary Access: Air
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra, northern hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Log construction
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Golden Squirrel Camp Quarters Unit VR-T4 Tent Frame
Unit - Location: KATM - Brooks Camp
FMSS ID: 95837, **Local ID:** GSCQ-4
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: S Szturm , August 8, 2023
Coordinates (DDM): 58° 32.508' N 155° 46.843' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Golden Squirrel Camp
Revisit Interval: 4 yrs
Map Label: 97

Primary Access: Air
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Heavy
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: VRAA-SHOP W-1

Unit - Location: KATM - Brooks Camp

FMSS ID: 88200, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 9, 2023

Coordinates (DDM): 58° 32.743' N 155° 47.239' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Valley Road Admin Area

Revisit Interval: 4 yrs

Map Label: 16

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: Reliable water source nearby

Propane: Present and fuels clearance

Overhead Hazards: No overhead hazards

Comments: <Null>





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: KATMAILAND Mechanics Shed (BUS parking Lot)

Unit - Location: KATM - Brooks Camp

FMSS ID: 90863, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.047' N 155° 46.819' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 4 yrs

Map Label: 27

Primary Access: Air

Ingress Egress: N/A,access by foot,boat,or air only

Access Width: N/A,access by foot,boat,or air only

Access Condition: N/A,access by foot,boat,or air only

Bridge Condition: N/A,access by foot,boat,or air only

Access and Turnarounds: N/A,access by foot,boat,or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra,northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Falls Trail Lunch Shed
Unit - Location: KATM - Brooks Camp
FMSS ID: 53682, **Local ID:** BFT-LS
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: S Szturm , August 8, 2023
Coordinates (DDM): 58° 33.038' N 155° 46.801' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 4 yrs
Map Label: 34

Primary Access: Air
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra, northern hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Picnic Area Shelter

Unit - Location: KATM - Brooks Camp

FMSS ID: 113776, **Local ID:** BR-PS

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 11, 2023

Coordinates (DDM): 58° 33.372' N 155° 46.712' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 55

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: No defensible space

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Restroom Gear and Food Cache Bldg.

Unit - Location: KATM - Brooks Camp

FMSS ID: 109196, **Local ID:** BR-PG

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 11, 2023

Coordinates (DDM): 58° 33.375' N 155° 46.692' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 62

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Structural Fire Cache

Unit - Location: KATM - Brooks Camp

FMSS ID: 225579, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 9, 2023

Coordinates (DDM): 58° 33.410' N 155° 46.755' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 82

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Camp Sand Filter/Pump Building

Unit - Location: KATM - Brooks Camp

FMSS ID: 53663, **Local ID:** BR-52

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 16, 2023

Coordinates (DDM): 58° 33.413' N 155° 46.781' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 38

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass and shrub, hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Paint Storage

Unit - Location: KATM - Brooks Camp

FMSS ID: 91424, **Local ID:** BR-PS

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 16, 2023

Coordinates (DDM): 58° 33.414' N 155° 46.778' W

Rating: Moderate

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Camp/Brooks Lodge

Revisit Interval: 4 yrs

Map Label: 39

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: Marked and clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Greater than 30in masonry exposed or N/A


Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Camp Quarters (Hilton)
Unit - Location: KATM - Brooks Camp
FMSS ID: 90895, **Local ID:** BR-T5
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: S Szturm , August 8, 2023
Coordinates (DDM): 58° 33.431' N 155° 46.720' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Brooks Camp/Brooks Lodge
Revisit Interval: 4 yrs
Map Label: 52

Primary Access: Air
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra, northern hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: Present and little to no fuels clearance
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Brooks Campground Restrooms

Unit - Location: KATM - Brooks Camp

FMSS ID: 83362, **Local ID:** BR-RR

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 8, 2023

Coordinates (DDM): 58° 33.586' N 155° 46.679' W

Rating: High

ProtectionLevel: Undesignated,

Resources of Concern: Unknown

Occupied: No

In Community: Yes, Brooks Campground

Revisit Interval: 4 yrs

Map Label: 64

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:

