
NPS Wildfire Risk Assessments
Assessment Locations

Mammoth Cave National Park - Overview

National Park Service
U.S. Department of the Interior



Structure Groups

Location

- Job Corps
- MACA - Administration
- MACA - North
- MACA - South
- MACA - Visitor Center

N

0 7 14 Miles

Author: sszturm
2/7/2024 8:50 AM


NPS Wildfire Risk Assessments
NPS Fire GIS
February 2024
Data Sources: ESRI Basedata, NPS

NPS Wildfire Risk Assessment Project

NPS Wildfire Risk Assessments
Assessment Locations

MACA - Administration - Overview

National Park Service
U.S. Department of the Interior



Structure Groups

Location

MACA - Administration

N

0 0.5 1 Miles

Author: sszturm
2/7/2024 10:11 AM


NPS Wildfire Risk Assessments
NPS Fire GIS
February 2024
Data Sources: ESRI Basedata, NPS

Maintenance Area

MACA - Mammoth Cave National Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
22	5975	Q-00000099 Bldg 099, Seasonal Apartment #99
23	5965	Seasonal Apartment #98
24	5848	Bldg 096, Rangers Office and Training Center
25	49134	Generator
27	91959	Bldg 445, Repeater House
28	49136	Bldg 407, Phone Building at Seasonal Quarters
29	5966	Q-00000097 Bldg 097, Seasonal Apartment #97
31	5826	Bldg 060, Paint Shop
32	5782	Bldg 318, Rangers Storage Shed (Veh Wash House)
33	5702	Bldg 204, Restroom Snowball Dining Room
34	50074	Bldg 061, Storage Shed North End of Utility Area
35	5837	Bldg 064, Fitness Center/Evidence Locker
36	6050	Bldg 312, Oil and Gas Storage
37	46908	Bldg 406, Raptor Aviary
38	225067	Transportation Break Room
39	5825	Bldg 059, Automotive Mechanical Garage
40	5833	Contracting and Warehouse
41	50075	Bldg 063, Facility Management Office
42	5830	Bldg 313, Science Resource Office (old warehouse)
43	5832	Bldg 319, Lumber Storage
44	5843	Bldg 333, Curatorial Storage
46	not found	Boat Storage
47	5846	Bldg 065, Craft Shop
48	not found	Storage Garage
49	5828	Bldg 328, YCC Building
50	5824	Bldg 052, Concession Workshop
51	5842	Bldg 102, Equipment Storage Building- Salvage Yard
52	not found	Carport 3
53	NA	Old Chicken Coop
54	51433	Bldg 301, Concession Storage Building
55	not found	Carport 2
56	5829	Bldg 310, Haz-Mat Collection Building
57	49095	Bldg 055, Concession Warehouse
58	not found	Carport 1
59	NA	Recycling shelter
60	49096	Bldg 300, Concessions Warehouse in Utility Area



N

Author: sszturm
2/7/2024 9:55 AM

0 500 Feet

Scale: 1:3,000

NPS Wildfire Risk Assessments
NPS Fire GIS
February 2024
Data Sources: ESRI Basedata, NPS


NPS Wildfire Risk Assessment Project

Superintendents Office

MACA - Mammoth Cave National Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
10	5861	Bldg 033, CCC Constructed Housing Unit
11	5858	Bldg 029, CCC Constructed Housing Unit
12	5948	Bldg 028, CCC Constructed Housing Unit
13	5849	Bldg 037, Interpretation & Fee Program Offices
14	5852	Bldg 044, Residence #44 (VIP House)
15	5853	Bldg 043, Eastern National Office
16	5857	Bldg 039, External Programs Office
17	NA	Raptor Enclosure
18	112706	Bldg 448, Pressure Tank Building
19	49133	Bldg 404, Garage in Residence Area
20	5855	Bldg 040, Administration & Human Resource Office
21	5854	Q-00000042 Bldg 042, Residence #42
26	5856	Bldg 041, Superintendents Office
30	5850	Bldg 038, Piedmont Network Office
4	5860	Q-000000034 Bldg 034, Residence #34
5	49139	Bldg 413, Lift Station - Permament Housing Area
6	5951	Bldg 032, CCC Constructed Housing Unit
7	5949	Bldg 031, CCC Constructed Housing Unit
8	47317	Bldg 035, Administrative Annex
9	5952	Bldg 030, CCC Constructed Housing Unit



Rating

Rating
- High
- Low
- Moderate

N

Author: sszturm
2/7/2024 10:09 AM

0 500 Feet

Scale: 1:3,000

NPS Wildfire Risk Assessments
NPS Fire GIS
February 2024
Data Sources: ESRI Basedata, NPS

NPS Wildfire Risk Assessment Project

NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Q-000000034 Bldg 034, Residence #34


Unit - Location: MACA - MACA - Administration
FMSS ID: 5860
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0577' **Long(WGS84):** -86° 5.39453'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 31% to 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: Adjacent to/under deck of facility
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)



2022_MACA_5860_Q-000000034 Bldg 034, Residence #34_Front.jpg




Score: 69
Rating: High



Asset Priority Index (API): 63



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 413, Lift Station - Permament Housing Area


Unit - Location: MACA - MACA - Administration
FMSS ID: 49139
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.9878' **Long(WGS84):** -86° 5.39121'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope >40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: None visible
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Pump / House (GSF)




2022_MACA_49139_Bldg 413, Lift Station - Permament Housing Area_Front.jpg




Score: 59
Rating: Moderate

Asset Priority Index (API): 52





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 032, CCC Constructed Housing Unit


Unit - Location: MACA - MACA - Administration
FMSS ID: 5951
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0137' **Long(WGS84):** -86° 5.3862'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 21% to 30%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)




2022_MACA_5951_Bldg 032, CCC Constructed Housing Unit_Front.jpg




Score: 59
Rating: Moderate

Asset Priority Index (API): 76





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 031, CCC Constructed Housing Unit


Unit - Location: MACA - MACA - Administration
FMSS ID: 5949
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0328' **Long(WGS84):** -86° 5.37825'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)




2022_MACA_5949_Bldg 031, CCC Constructed Housing Unit_Front.jpg




Score: 57
Rating: Moderate

Asset Priority Index (API): 76





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 035, Administrative Annex


Unit - Location: MACA - MACA - Administration
FMSS ID: 47317
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0698' **Long(WGS84):** -86° 5.37074'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: Facility currently vacant.




2022_MACA_47317_Bldg 035, Administrative Annex_Front.jpg




Score: 62
Rating: Moderate

Asset Priority Index (API): 0





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 030, CCC Constructed Housing Unit


Unit - Location: MACA - MACA - Administration
FMSS ID: 5952
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0428' **Long(WGS84):** -86° 5.36075'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2022_MACA_5952_Bldg 030, CCC Constructed Housing Unit_Front.jpg




Score: 32
Rating: Low



Asset Priority Index (API): 76



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 033, CCC Constructed Housing Unit


Unit - Location: MACA - MACA - Administration
FMSS ID: 5861
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0095' **Long(WGS84):** -86° 5.35881'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)




2022_MACA_5861_Bldg 033, CCC Constructed Housing Unit_Front.jpg




Score: 46
Rating: Moderate

Asset Priority Index (API): 76





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 029, CCC Constructed Housing Unit


Unit - Location: MACA - MACA - Administration
FMSS ID: 5858
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0295' **Long(WGS84):** -86° 5.35032'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)




2022_MACA_5858_Bldg 029, CCC Constructed Housing Unit_Front.jpg




Score: 54
Rating: Moderate

Asset Priority Index (API): 76





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 028, CCC Constructed Housing Unit


Unit - Location: MACA - MACA - Administration
FMSS ID: 5948
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0165' **Long(WGS84):** -86° 5.33705'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2022_MACA_5948_Bldg 028, CCC Constructed Housing Unit_Front.jpg




Score: 38
Rating: Low



Asset Priority Index (API): 76



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 037, Interpretation & Fee Program Offices


Unit - Location: MACA - MACA - Administration
FMSS ID: 5849
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0403' **Long(WGS84):** -86° 5.31446'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Vinyl
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2022_MACA_5849_Bldg 037, Interpretation & Fee Program Offices_Front.jpg




Score: 30
Rating: Low



Asset Priority Index (API): 63



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 044, Residence #44 (VIP House)


Unit - Location: MACA - MACA - Administration
FMSS ID: 5852
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.9877' **Long(WGS84):** -86° 5.31429'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)




2022_MACA_5852_Bldg 044, Residence #44 (VIP House)_Front.jpg




Score: 57
Rating: Moderate

Asset Priority Index (API): 63





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 043, Eastern National Office


Unit - Location: MACA - MACA - Administration
FMSS ID: 5853
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.9666' **Long(WGS84):** -86° 5.30456'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)





2022_MACA_5853_Bldg 043, Eastern National Office_Front.jpg




Score: 53
Rating: Moderate

Asset Priority Index (API): 50





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 039, External Programs Office


Unit - Location: MACA - MACA - Administration
FMSS ID: 5857
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0266' **Long(WGS84):** -86° 5.29607'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2022_MACA_5857_Bldg 039, External Programs Office_Front.jpg




Score: 32
Rating: Low



Asset Priority Index (API): 61



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Raptor Enclosure


Unit - Location: MACA - MACA - Administration
FMSS ID: NA
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0583' **Long(WGS84):** -86° 5.28557'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments:




2022_MACA_NA_Raptor Enclosure_Front.jpg




Score: 52
Rating: Moderate

Asset Priority Index (API): N/A





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 448, Pressure Tank Building


Unit - Location: MACA - MACA - Administration
FMSS ID: 112706
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.922' **Long(WGS84):** -86° 5.27821'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: None visible
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Not Applicable




2022_MACA_112706_Bldg 448, Pressure Tank Building_Front.jpg




Score: 55
Rating: Moderate

Asset Priority Index (API): 61





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 404, Garage in Residence Area


Unit - Location: MACA - MACA - Administration
FMSS ID: 49133
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.063' **Long(WGS84):** -86° 5.24323'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Housing Garage (GSF)




2022_MACA_49133_Bldg 404, Garage in Residence Area_Front.jpg




Score: 56
Rating: Moderate

Asset Priority Index (API): 40





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 040, Administration & Human Resource Office


Unit - Location: MACA - MACA - Administration
FMSS ID: 5855
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0192' **Long(WGS84):** -86° 5.2406'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2022_MACA_5855_Bldg 040, Administration & Human Resource Office_Front.jpg




Score: 34
Rating: Low



Asset Priority Index (API): 61



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Q-00000042 Bldg 042, Residence #42


Unit - Location: MACA - MACA - Administration
FMSS ID: 5854
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.9773' **Long(WGS84):** -86° 5.22981'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Vinyl
Foundation: Closed, < 6in masonry exposed
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: >30 ft from facility
Propane Tanks: Present and little to no fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2022_MACA_5854_Q-00000042 Bldg 042, Residence #42_Front.jpg




Score: 34
Rating: Low



Asset Priority Index (API): 61



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Q-00000099 Bldg 099, Seasonal Apartment #99


Unit - Location: MACA - MACA - Administration
FMSS ID: 5975
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8784' **Long(WGS84):** -86° 5.21472'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Apartment (GSF)



2022_MACA_5975_Q-00000099 Bldg 099, Seasonal Apartment #99_Front.jpg




Score: 41
Rating: Low



Asset Priority Index (API): 71



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Seasonal Apartment #98


Unit - Location: MACA - MACA - Administration
FMSS ID: 5965
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8585' **Long(WGS84):** -86° 5.21307'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Diesel
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Apartment (GSF)




2022_MACA_5965_Seasonal Apartment #98_Front.jpg




Score: 51
Rating: Moderate

Asset Priority Index (API): 71





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 096, Rangers Office and Training Center


Unit - Location: MACA - MACA - Administration
FMSS ID: 5848
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8379' **Long(WGS84):** -86° 5.21133'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: Combustible but separated from facility
Firewood: 5ft to 30ft from facility
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Law Enforcement (GSF)



2022_MACA_5848_Bldg 096, Rangers Office and Training Center_Front.jpg




Score: 36
Rating: Low



Asset Priority Index (API): 88



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Generator


Unit - Location: MACA - MACA - Administration
FMSS ID: 49134
Structure Type: Utility
Structure Use: Unknown
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8462' **Long(WGS84):** -86° 5.20854'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: >30 ft from facility
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Diesel
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Communications Sys (GSF)



2022_MACA_49134_Generator_Front.jpg




Score: 43
Rating: Low



Asset Priority Index (API): 20



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 041, Superintendents Office


Unit - Location: MACA - MACA - Administration
FMSS ID: 5856
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.9909' **Long(WGS84):** -86° 5.20844'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2022_MACA_5856_Bldg 041, Superintendents Office_Front.jpg




Score: 34
Rating: Low



Asset Priority Index (API): 61



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 445, Repeater House


Unit - Location: MACA - MACA - Administration
FMSS ID: 91959
Structure Type: CommSite
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8076' **Long(WGS84):** -86° 5.20841'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Communications Sys (GSF)




2022_MACA_91959_Bldg 445, Repeater House_Front.jpg




Score: 49
Rating: Moderate

Asset Priority Index (API): 40





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 407, Phone Building at Seasonal Quarters


Unit - Location: MACA - MACA - Administration
FMSS ID: 49136
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8492' **Long(WGS84):** -86° 5.20539'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: Adjacent to/under deck of facility
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Diesel
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Housing, Support (GSF)




2022_MACA_49136_Bldg 407, Phone Building at Seasonal Quarters_Front.jpg




Score: 46
Rating: Moderate

Asset Priority Index (API): 7





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Q-00000097 Bldg 097, Seasonal Apartment #97


Unit - Location: MACA - MACA - Administration
FMSS ID: 5966
Structure Type: Building
Structure Use: Residence
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8526' **Long(WGS84):** -86° 5.19001'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Fences/Decks: None or noncombustible
Firewood: >30 ft from facility
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Diesel
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Apartment (GSF)



2022_MACA_5966_Q-00000097 Bldg 097, Seasonal Apartment #97_Front.jpg




Score: 31
Rating: Low



Asset Priority Index (API): 71



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 038, Piedmont Network Office


Unit - Location: MACA - MACA - Administration
FMSS ID: 5850
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 11.0406' **Long(WGS84):** -86° 5.18041'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2022_MACA_5850_Bldg 038, Piedmont Network Office_Front.jpg




Score: 35
Rating: Low



Asset Priority Index (API): 83



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 060, Paint Shop


Unit - Location: MACA - MACA - Administration
FMSS ID: 5826
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8207' **Long(WGS84):** -86° 5.17602'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)



2022_MACA_5826_Bldg 060, Paint Shop_Front.jpg




Score: 32
Rating: Low



Asset Priority Index (API): 0



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 318, Rangers Storage Shed (Veh Wash House)


Unit - Location: MACA - MACA - Administration
FMSS ID: 5782
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8163' **Long(WGS84):** -86° 5.17178'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: None visible
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Warehouse Fire Ca (GSF)




2022_MACA_5782_Bldg 318, Rangers Storage Shed (Veh Wash House)_Front.jpg




Score: 32
Rating: Low



Asset Priority Index (API): 42



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com


Facility: Bldg 204, Restroom Snowball Dining Room

Unit - Location: MACA - MACA - Administration
FMSS ID: 5702
Structure Type: No Wildland Risk
Structure Use: Public
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: NoWildlandRisk
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied?
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.825' **Long(WGS84):** -86° 5.17169'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material:
Siding Material:
Foundation:
Fences/Decks:
Firewood:
Propane Tanks:
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat:
Assessment Comments: No wildfire risk. Believed to be under ground. No facility above the surface at this location.


Score:
Rating:
NoWildlandRisk




Asset Priority Index (API):
93



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 061, Storage Shed North End of Utility Area


Unit - Location: MACA - MACA - Administration
FMSS ID: 50074
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7947' **Long(WGS84):** -86° 5.16799'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Hazmat Storage
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)




2022_MACA_50074_Bldg 061, Storage Shed North End of Utility Area_Front.jpg




Score: 51
Rating: Moderate

Asset Priority Index (API): 23





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 064, Fitness Center/Evidence Locker


Unit - Location: MACA - MACA - Administration
FMSS ID: 5837
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8348' **Long(WGS84):** -86° 5.16184'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Law Enforcement (GSF)



2022_MACA_5837_Bldg 064, Fitness Center/Evidence Locker_Front.jpg




Score: 31
Rating: Low



Asset Priority Index (API): 65



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 312, Oil and Gas Storage


Unit - Location: MACA - MACA - Administration
FMSS ID: 6050
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8005' **Long(WGS84):** -86° 5.15989'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: >100ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Oil and fuel
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Warehouse Chem (GSF)



2022_MACA_6050_Bldg 312, Oil and Gas Storage_Front.jpg




Score: 19
Rating: Low



Asset Priority Index (API): 0



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 406, Raptor Aviary


Unit - Location: MACA - MACA - Administration
FMSS ID: 46908
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8316' **Long(WGS84):** -86° 5.15804'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Animal Shelter (GSF)



2022_MACA_46908_Bldg 406, Raptor Aviary_Front.jpg




Score: 44
Rating: Low



Asset Priority Index (API): 0



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Transportation Break Room

Unit - Location: MACA - MACA - Administration
FMSS ID: 225067
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8656' **Long(WGS84):** -86° 5.15478'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel Depots
Assessment Comments:



2022_MACA_225067_Transportation Break Room_Front.jpg


Score: 31
Rating: Low



Asset Priority Index (API): 20



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 319, Lumber Storage


Unit - Location: MACA - MACA - Administration
FMSS ID: 5832
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7658' **Long(WGS84):** -86° 5.1248'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)



2022_MACA_5832_Bldg 319, Lumber Storage_Front.jpg




Score: 29
Rating: Low



Asset Priority Index (API): 29



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 333, Curatorial Storage


Unit - Location: MACA - MACA - Administration
FMSS ID: 5843
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7901' **Long(WGS84):** -86° 5.12075'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments: attached to science building see for photos



2017_MACA_5843_Bldg 333, Curatorial Storage_Front.jpg




Score: 29
Rating: Low



Asset Priority Index (API): 83



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Boat Storage


Unit - Location: MACA - MACA - Administration
FMSS ID: not found
Structure Type: Shade
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7479' **Long(WGS84):** -86° 5.11204'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments:




2022_MACA_not found_Boat Storage _Front.jpg




Score: 47
Rating: Moderate

Asset Priority Index (API): N/A





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 065, Craft Shop


Unit - Location: MACA - MACA - Administration
FMSS ID: 5846
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7745' **Long(WGS84):** -86° 5.10992'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)




2022_MACA_5846_Bldg 065, Craft Shop_Front.jpg




Score: 29
Rating: Low



Asset Priority Index (API): 42



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Storage Garage


Unit - Location: MACA - MACA - Administration
FMSS ID: not found
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7529' **Long(WGS84):** -86° 5.10493'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: Combustible,adjacent,no veg/debris clearance
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments:




2022_MACA_not found_Storage Garage_Front.jpg




Score: 50
Rating: Moderate

Asset Priority Index (API): N/A





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 328, YCC Building


Unit - Location: MACA - MACA - Administration
FMSS ID: 5828
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.757' **Long(WGS84):** -86° 5.10099'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)




2022_MACA_5828_Bldg 328, YCC Building_Front.jpg




Score: 45
Rating: Moderate

Asset Priority Index (API): 13





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 052, Concession Workshop


Unit - Location: MACA - MACA - Administration
FMSS ID: 5824
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8454' **Long(WGS84):** -86° 5.09288'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)




2022_MACA_5824_Bldg 052, Concession Workshop_Front.jpg




Score: 56
Rating: Moderate

Asset Priority Index (API): 63





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 102, Equipment Storage Building- Salvage Yard


Unit - Location: MACA - MACA - Administration
FMSS ID: 5842
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7479' **Long(WGS84):** -86° 5.09274'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Propane
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)




2022_MACA_5842_Bldg 102, Equipment Storage Building-Salvage Yard_Front.jpg




Score: 39
Rating: Low



Asset Priority Index (API): 42



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Carport 3


Unit - Location: MACA - MACA - Administration
FMSS ID: not found
Structure Type: Shade
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7235' **Long(WGS84):** -86° 5.08369'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Hazmat storage
Assessment Comments:




2022_MACA_not found_Carport 3_Front.jpg




Score: 46
Rating: Moderate

Asset Priority Index (API): N/A





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Old Chicken Coop


Unit - Location: MACA - MACA - Administration
FMSS ID: NA
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8616' **Long(WGS84):** -86° 5.08279'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Heavy
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible,adjacent,no veg/debris clearance
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments:



2022_MACA_NA_Old Chicken Coop_Front.jpg




Score: 65
Rating: High



Asset Priority Index (API): N/A



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 301, Concession Storage Building


Unit - Location: MACA - MACA - Administration
FMSS ID: 51433
Structure Type: Building
Structure Use: Public
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.854' **Long(WGS84):** -86° 5.08128'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Heavy
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: Combustible,adjacent,no veg/debris clearance
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Warehouse (GSF)




2022_MACA_51433_Bldg 301, Concession Storage Building_Front.jpg




Score: 61
Rating: Moderate

Asset Priority Index (API): 17





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Carport 2


Unit - Location: MACA - MACA - Administration
FMSS ID: not found
Structure Type: Shade
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7252' **Long(WGS84):** -86° 5.07506'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Hazmat storage
Assessment Comments:




2022_MACA_not found_Carport 2_Front.jpg




Score: 46
Rating: Moderate

Asset Priority Index (API): N/A





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 310, Haz-Mat Collection Building


Unit - Location: MACA - MACA - Administration
FMSS ID: 5829
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7496' **Long(WGS84):** -86° 5.07183'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: Combustible but separated from facility
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Hazmat storage
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)




2022_MACA_5829_Bldg 310, Haz-Mat Collection Building_Front.jpg




Score: 49
Rating: Moderate

Asset Priority Index (API): 35





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 055, Concession Warehouse


Unit - Location: MACA - MACA - Administration
FMSS ID: 49095
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8308' **Long(WGS84):** -86° 5.07134'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Heavy
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible,adjacent,no veg/debris clearance
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Warehouse (GSF)




2022_MACA_49095_Bldg 055, Concession Warehouse_Front.jpg




Score: 67
Rating: High



Asset Priority Index (API): 40



Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Carport 1


Unit - Location: MACA - MACA - Administration
FMSS ID: not found
Structure Type: Shade
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.7258' **Long(WGS84):** -86° 5.07107'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Hazmat storage
Assessment Comments:




2022_MACA_not found_Carport 1_Front.jpg




Score: 46
Rating: Moderate

Asset Priority Index (API): N/A





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Recycling shelter


Unit - Location: MACA - MACA - Administration
FMSS ID: NA
Structure Type: Shade
Structure Use: Admin
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8382' **Long(WGS84):** -86° 5.0661'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Heavy
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments:




2022_MACA_NA_Recycling shelter_Front.jpg




Score: 59
Rating: Moderate

Asset Priority Index (API): N/A





Factors Driving the Ratings



NPS Wildand Fire Risk Assessment - **Facility Assessment**

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com

Facility: Bldg 300, Concessions Warehouse in Utility Area


Unit - Location: MACA - MACA - Administration
FMSS ID: 49096
Structure Type: Building
Structure Use: Concession
Owner: NPS
Field Crew: castillo/szturm
Last Site Visit Date: 3/10/2022

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Admin Buildings
Lat(WGS84): 37° 10.8506' **Long(WGS84):** -86° 5.0654'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Heavy
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential saftey zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Fuel depot
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Warehouse (GSF)




2022_MACA_49096_Bldg 300, Concessions Warehouse in Utility Area_Front.jpg



Score: 60
Rating: Moderate

Asset Priority Index (API): 30





Factors Driving the Ratings

