
NPS Wildfire Risk Assessments
Assessment Locations

Antietam National Battlefield - Overview

National Park Service
U.S. Department of the Interior



N

0 3 6 Miles

Author: sszturm
3/18/2024 7:36 AM


NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

Cunningham Park

ANTI - Antietam National Battlefield

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
39	40542	Pry Barn
123	44046	Cunningham (Park) Barn
182	48708	Wyand House
38	40544	Pry Cavehouse
29	225202	Newcomer House
37	40540	Pry House
122	44049	Cunningham (Park) Log Dependency House (Ktichen)
121	44051	Cunningham (Park) House
31	44055	Newcomer Barn
180	48711	Fulk House
36	40545	Pry Springhouse
21	55236	Observation Tower



Rating

Rating
Low
High
Moderate

Author: sszturm
3/18/2024 7:40 AM

N

0 0.5 Miles

Scale: 1:12,000


NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Source: ESRI Basedata, NPS

D.R. Miller

ANTI - Antietam National Battlefield

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
103	88134	Cultural Resource/Bookstore Warehouse
2	101145	Maintenance equipment storage building
1	113985	Blackpowder mag
80	43565	Poffenberger Corncrib / Wagonshed
81	43564	Poffenberger Barn
79	43566	Poffenberger Stone Building
77	43563	Poffenberger House
102	48712	Shull House
78	43567	Poffenberger Blackshmith Shop
104	101144	Fire Cache
62	40433	D.R. Miller Wagon Shed
54	40432	D.R. Miller Loafing Shed 2
56	40434	D.R. Miller Spring House
55	40424	D.R. Miller Barn (Historic Foundation)
59	40425	D.R. Miller Wash House
57	40423	D.R. Miller House
60	40431	D.R. Miller Loafing Shed
61	40428	D.R. Miller Paint Shop
58	40426	D.R. Miller Smoke House
189	N/A	Upper Barn



N

Author: sszturm
3/18/2024 7:42 AM

0 0.5 Miles

Scale: 1:12,000


NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Source: ESRI Basedata, NPS

Piper House

ANTI - Antietam National Battlefield

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
175	88479	Smith House
176	48706	Visitor Center
7	43586	Dunker Church
67	41402	Piper Ice House
72	44037	Mumma Springhouse
75	44040	Mumma Hog Pen
66	41400	Piper Slave House
68	41002	Piper House
46	41440	Ice House
74	44038	Mumma Workshop
73	44039	Mumma Tool Shed
48	41434	Roulette House
21	55236	Observation Tower
69	41401	Piper Smoke House
47	41437	Roulette Smokehouse
145	48716	Mary Locher Cabin
76	44031	Mumma Barn
50	41435	Roulette Springhouse
65	41405	Piper Wagon Shed
71	44033	Mumma House
63	41399	Piper Barn
64	41404	Piper Blacksmith Shop
52	41438	Roulette Barn
144	98456	Mary Locher Pavillion
70	44034	Mumma Smoke House
143	N/a	Locher Milkhouse



Rating

Rating
- High
- Low
- Moderate

N

Author: sszturm
3/18/2024 7:51 AM

0 0.5 Miles

Scale: 1:12,000


NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Source: ESRI Basedata, NPS

Sherrick House

ANTI - Antietam National Battlefield

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
151	43585	Maintenance Shop
149	40955	Mule Barn
186	44057	Otto House
184	44058	Otto Outbuilding
188	43575	Sherrick Corn Crib
150	40965	Admininstration Building
152	40956	Lodge Building
185	43573	Sherrick House
187	43574	Sherrick Smokehouse
153	40957	Rostrum



N

Author: sszturm
3/18/2024 8:28 AM

0 0.5 Miles

Scale: 1:12,000

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Source: ESRI Basedata, NPS

NPS Wildfire Risk Assessment Project

NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Cultural Resource/Bookstore Warehouse
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 88134, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 29.360' N 77° 45.174' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 103

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Maintenance equipment storage building
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 101145, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 29.355' N 77° 45.152' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 5 yrs
Map Label: 2

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Blackpowder mag
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 113985, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 29.371' N 77° 45.185' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 1

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Poffenberger Corncrib / Wagonshed
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43565, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 16, 2022
Coordinates (DDM): 39° 29.39117268' N 077° 44.87565324' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 80

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Poffenberger Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43564, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.40884424' N 077° 44.85885318' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 81

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Maintenance Shop
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43585, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.52423482' N 077° 44.52945300' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 151

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Pry Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40542, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Ncr fire guys, June 14, 2022
Coordinates (DDM): 39° 28.57337256' N 077° 42.80205252' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 39

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mule Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40955, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.57437232' N 077° 44.54535300' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 149

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Smith House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 88479, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR, May 18, 2015
Coordinates (DDM): 39° 28.360' N 77° 44.769' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 175

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Cunningham (Park) Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44046, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 18, 2022
Coordinates (DDM): 39° 28.08336558' N 077° 43.68885276' W


Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 123

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Wyand House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 48708, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR fire, June 14, 2022
Coordinates (DDM): 39° 28.46123280' N 077° 42.66538656' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 182

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Library (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Otto House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44057, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.24673692' N 077° 44.22975288' W


Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 186

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Pry Cavehouse
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40544, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NNR fire, June 14, 2022
Coordinates (DDM): 39° 28.56707250' N 077° 42.81615252' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 38

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Not applicable
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Otto Outbuilding
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44058, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.22907226' N 077° 44.24895288' W


Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 184

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Newcomer House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 225202, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 18, 2022
Coordinates (DDM): 39° 27.88096842' N 077° 43.63728150' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 5 yrs
Map Label: 29

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Poffenberger Stone Building
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43566, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.37214140' N 077° 44.90625324' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 79

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Poffenberger House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43563, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.40214446' N 077° 44.92695324' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 77

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Shull House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 48712, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 29.319' N 77° 45.195' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 102

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Poffenberger Blackshmith Shop
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43567, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.35757262' N 077° 44.90775324' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 78

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Pry House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40540, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR fire, June 14, 2022
Coordinates (DDM): 39° 28.56165810' N 077° 42.85005252' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 37

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Cunningham (Park) Log Dependency House (Ktichen)
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44049, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 18, 2022
Coordinates (DDM): 39° 28.12997244' N 077° 43.69935276' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 122

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Sherrick Corn Crib
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43575, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.33418896' N 077° 44.22225288' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 188

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Visitor Center
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 48706, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, January 30, 2024
Coordinates (DDM): 39° 28.453' N 77° 44.672' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 176

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Center (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Admininstration Building
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40965, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.59049960' N 077° 44.53695300' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 150

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Cunningham (Park) House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44051, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 18, 2022
Coordinates (DDM): 39° 28.11493914' N 077° 43.70295276' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 121

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Vinyl
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Dunker Church
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43586, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 16, 2022
Coordinates (DDM): 39° 28.52297250' N 077° 44.80875312' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No, Mary Locher
Revisit Interval: 5 yrs
Map Label: 7

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Newcomer Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44055, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 18, 2022
Coordinates (DDM): 39° 27.84917238' N 077° 43.60305270' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 31

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Fulk House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 48711, ***Local ID:***
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: NCR fire, June 14, 2022
Coordinates (DDM): 39° 28.43783250' N 077° 42.67395246' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 180

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Vinyl
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Lodge Building
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40956, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.60377910' N 077° 44.50905300' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 152

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)








NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Sherrick House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43573, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.31389042' N 077° 44.24115288' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 185

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Pry Springhouse
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40545, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR fire, June 14, 2022
Coordinates (DDM): 39° 28.54127256' N 077° 42.85125252' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 36

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Sherrick Smokehouse
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 43574, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.30635232' N 077° 44.22675288' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 187

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Rostrum
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40957, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 17, 2022
Coordinates (DDM): 39° 27.61007232' N 077° 44.47125300' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 153

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Fire Cache
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 101144, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 29.336' N 77° 45.156' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 104

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: D.R. Miller Wagon Shed
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40433, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.01587256' N 077° 44.90535318' W


Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 62

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Piper Ice House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41402, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 27.979' N 77° 44.510' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 67

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mumma Springhouse
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44037, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.61813676' N 077° 44.45265306' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 72

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mumma Hog Pen
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44040, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.61807250' N 077° 44.44035300' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 75

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Piper Slave House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41400, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 27.992' N 77° 44.520' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 66

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Piper House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41002, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 27.986' N 77° 44.509' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: No
Occupied: Yes
In Community: Yes, Piper Farm Area
Revisit Interval: 5 yrs
Map Label: 68

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Ice House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41440, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.54037250' N 077° 44.28255300' W


Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 46

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mumma Workshop
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44038, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.62179250' N 077° 44.44935306' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 74

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mumma Tool Shed
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44039, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.60409250' N 077° 44.45175300' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 73

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: D.R. Miller Loafing Shed 2
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40432, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.01127734' N 077° 45.00315324' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 54

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Roulette House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41434, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.52477244' N 077° 44.27715300' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 48

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Observation Tower
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 55236, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 18, 2022
Coordinates (DDM): 39° 28.16567244' N 077° 44.15925294' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 5 yrs
Map Label: 21

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: D.R. Miller Spring House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40434, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.02592250' N 077° 44.96505324' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 56

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Piper Smoke House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41401, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, May 19, 2015
Coordinates (DDM): 39° 27.993' N 77° 44.502' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Piper Farm Area
Revisit Interval: 5 yrs
Map Label: 69

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)

NO PHOTO AVAILABLE






NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Roulette Smokehouse
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41437, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.53437244' N 077° 44.27715300' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 47

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: D.R. Miller Barn (Historic Foundation)
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40424, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.00159730' N 077° 44.99415324' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 55

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: D.R. Miller Wash House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40425, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 29.071' N 77° 44.958' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 59

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mary Locher Cabin
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 48716, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 16, 2022
Coordinates (DDM): 39° 28.68674394' N 077° 45.14175324' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 145

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: D.R. Miller House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40423, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 29.063' N 77° 44.964' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 57

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: D.R. Miller Loafing Shed
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40431, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.03600586' N 077° 44.92215318' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 60

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mumma Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44031, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.65600504' N 077° 44.43615300' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 76

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Roulette Springhouse
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41435, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.54337244' N 077° 44.26635294' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 50

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Piper Wagon Shed
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41405, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 28.010' N 77° 44.521' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Piper Farm Area
Revisit Interval: 5 yrs
Map Label: 65

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mumma House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44033, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.63318920' N 077° 44.46975306' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 71

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Piper Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41399, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, April 17, 2023
Coordinates (DDM): 39° 28.042' N 77° 44.580' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 63

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Piper Blacksmith Shop
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41404, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 28.013' N 77° 44.528' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Piper Farm Area
Revisit Interval: 5 yrs
Map Label: 64

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Roulette Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 41438, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.49727510' N 077° 44.22315294' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 52

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mary Locher Pavillion
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 98456, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 16, 2022
Coordinates (DDM): 39° 28.68654336' N 077° 45.14205324' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 144

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: D.R. Miller Paint Shop
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40428, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.06519250' N 077° 44.92095318' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 61

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: D.R. Miller Smoke House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 40426, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR, April 17, 2023
Coordinates (DDM): 39° 29.073' N 77° 44.959' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 58

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Mumma Smoke House
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: 44034, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , November 2, 2022
Coordinates (DDM): 39° 28.62857250' N 077° 44.48085306' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 70

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Locher Milkhouse
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: N/a, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 16, 2022
Coordinates (DDM): 39° 28.63877244' N 077° 45.14805324' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Mary Locher
Revisit Interval: 5 yrs
Map Label: 143

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Upper Barn
Unit - Location: ANTI - Antietam National Battlefield
FMSS ID: N/A, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , August 9, 2022
Coordinates (DDM): 39° 29.04306144' N 077° 44.91913722' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 189

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:





