
NPS Wildfire Risk Assessments
Assessment Locations

Harpers Ferry National Historical Park - Overview

National Park Service
U.S. Department of the Interior



0 3 6 Miles

N

Author: sszturm
3/18/2024 10:56 AM

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS


NPS Wildfire Risk Assessment Project

Bakerton Road

HAFE - Harpers Ferry National Historical Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
3	N/a	Schoolhouse Ridge North Bathroom



Rating

Rating

Moderate

N

Author: sszturm
3/18/2024 11:01 AM

0 0.5 Miles

Scale: 1:12,000

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Source: ESRI Basedata, NPS

Charles Town

HAFE - Harpers Ferry National Historical Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
1	59807	Museum Restoration Building Charlestown, WVA
2	69999	CHARLESTOWN WAREHOUSE



Rating

Rating

No Wildland Risk

N

Author: sszturm
3/19/2024 10:15 AM

0 500 Feet

Scale: 1:3,000

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS


NPS Wildfire Risk Assessment Project

Harper's Ferry Central

HAFE - Harpers Ferry National Historical Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
20	39960	MF03 - Musket Factory; Rolling Mill Power Palnt
84	1005	B58 Morrell house
85	3798	B82 - Office (The Jackson House)
86	28546	B57 Brackett House
87	1027	B56 Lockwood House (Paymasters House)



N

Author: sszturm
3/19/2024 10:30 AM

0 500 Feet

Scale: 1:3,000


NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS

NPS Wildfire Risk Assessment Project

Harper's Ferry East

HAFE - Harpers Ferry National Historical Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
19	3737	B84 - Blacksmith Shop
22	3791	Q-00000048 H48 - Employee's Armorer House
27	3741	B45A - Outhouse
28	3802	Q-0000001D H1D - Quarters
29	3739	B45 - Bookstore
30	3801	Q-0000001C H1C - Quarters
31	33295	B&O Railroad Train Station
32	3729	C1B - Wager House (or Marmion Hall)
33	3738	B44 - Restrooms Lowertown (Philip Coons Bldg)
34	35345	B43A - Cooling Tower
35	3728	B1A - Harper House
36	35344	B43 - McCabemarmion Building (Industry Exhibit)
37	3765	B3 - Civil War Story EXH
38	3731	B33 - Ranger Headquarters & 33A
39	3736	B40 - Frankel Brother Store (or William Richards)
40	3788	Q-000000240 H240 Quarters Second Floor Apartment
41	88258	Q-00000340 H340 Quarters Third Floor Apartment
42	3827	B39 - Transformer Building
43	3727	B16 - Frederick A Roeder House
44	3731	B33A
45	3732	B34 - Provost Marshel's Office
46	3730	B32 - Ice House
47	3735	B38 - Archeologh Exhibit (or Tearney Building)
48	34258	B16A - Frederick Roeder Annex
49	35335	B34A - Smokehouse
50	3734	B37 - Black History Exhibit (or John T. Reily)
51	3725	B15 - Susan Downey House (Soldier Life Exhibit)
52	34253	B14 - Alfred Burton Jewelry Shop
53	35337	B35 - Dry Goods Store
54	33998	B5 - Frederick A Roeder Store
55	3787	Q-00000036 H36 Quarters
56	28559	B12A - Ann Stephenson Outbuilding
57	3733	B36 - Master Armorers Exhibit (New Master Armor)
58	3743	B7 - White Hall Tavern
59	35966	B11A - Anderson Annes
60	28558	B12 - Ann C Stephenson Building
61	28557	B11 - William Anderson Building
62	34012	B8 Gerard Bond Wager Annex
63	28556	B10 - John C Unseld Building
64	28555	B9 - Gerard Bond Wager (J-Brown Story Exhibit)
65	3742	B63 - John Brown Fort (Armory Engine House)
88	3797	Q-0000008 H8 Quarters
89	226673	Bus Shelter Lower Town
90	Na	New storage

N

Author: sszturm
3/19/2024 10:24 AM

0 500 Feet

Scale: 1:3,000


NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS

Harpers Ferry West

HAFE - Harpers Ferry National Historical Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
15	28549	GS - Bolivar Heights Grandview School
68	99806	Custodial Warehouse
66	3815	B93 Equipment Shed Maintenance Yard
67	3767	B55 - Maint Shop & Contract Office
77	28547	B75 - Freewill Baptist Church
72	3775	Camp Hill Shipley School
4	228520	Salt Bin Shed Maintenance Yard
73	3793	Museum & Maintenance Storage Building
69	81983	Bird-Brady Garage
71	28548	B64 - Anthony Library
73	28550	B81 Bomb Shelter Entrance
76	1028	B59 - Mather Training Center
75	28551	B83 - Interpretive Design Center
78	28553	B61 - Cook Hall
70	3749	B69 - Bird Brady (IDC Asministration)
91	NA	saw shed
92	NA	maintenance vehicle bay
93	N/A	Shed
94	N/A	Unkown Storage



Rating

Rating
Moderate
Low

N

Author: sszturm
3/19/2024 10:52 AM

0 500 1,000 1,500 Feet

Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS


NPS Wildfire Risk Assessment Project

Millville Road Area

HAFE - Harpers Ferry National Historical Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
5	N/A	Shack (Quarry Workers)
9	105864	Farm House
7	105863	Shack (Quarry Workers)
8	105861	Shack (Quarry Workers)
10	N/A	School House Privy



N

Author: sszturm
3/18/2024 11:15 AM

0 0.5 Miles

Scale: 1:12,000


NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Source: ESRI Basedata, NPS

Nash House

HAFE - Harpers Ferry National Historical Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
14	N/A	Nash Shed
23	87849	Nash Little House
24	87848	Nash Barn
25	87850	Nash Main House
26	105526	Nash Randolph Cottage



Rating

Rating
Low
Moderate
High

N

Author: sszturm
3/19/2024 10:35 AM

0 500 Feet

Scale: 1:3,000

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS


NPS Wildfire Risk Assessment Project

Visitor Center Area

HAFE - Harpers Ferry National Historical Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
13	3794	Murphy Farm House
12	3799	Q-00000091 H91 Quarters
83	48365	Bus Maint Shop & Grage (Cavalier Heights)
82	3771	B97 Kiosk Cavalier Heights
79	3770	Bus Shelter Cavalier Heights
80	40571	Restrooms Cavalier Heights
81	3769	Visitor Center



Rating

Rating
Moderate
Low

N

Author: sszturm
3/19/2024 11:03 AM

0 500 1,000 1,500 Feet

Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS

NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Nash Little House
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 87849, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , June 14, 2022
Coordinates (DDM): 39° 19.87048830' N 077° 45.26826420' W


Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 23

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: No defensible space
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Cultural Ctr (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Shack (Quarry Workers)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: N/A, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, June 2, 2022
Coordinates (DDM): 39° 17.95324734' N 077° 47.05620870' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 5

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: From FMSS_Export - FRPP_PREDUSE:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name:
Unit - Location:
FMSS ID: 105862, ***Local ID:***
Structure Type, Use: Destroyed, Not a building
Owner: National Park Service
Field Crew, Visit Date: Ncr fire crew,
Coordinates (DDM): 39° 18.16300224' N 077° 47.04639126' W

Rating: Destroyed
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 6

Primary Access:
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Q-00000340 H340 Quarters Third Floor Apartment
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 88258, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.36852542' N 077° 43.83933366' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 41

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE



NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Q-000000240 H240 Quarters Second Floor Apartment
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3788, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.36850754' N 077° 43.83935508' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 40

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B82 - Office (The Jackson House)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3798, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR FIRE, February 12, 2024
Coordinates (DDM): 39° 19.416' N 77° 44.205' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 10 yrs
Map Label: 85

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Greater than 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Vinyl
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Private structure within 30ft with a propane tank in the back.

NO PHOTO AVAILABLE



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Farm House
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 105864, ***Local ID:***
Structure Type, Use: Cultural Resource, Unknown
Owner: National Park Service
Field Crew, Visit Date: NCR FIRE CREW, June 2, 2022
Coordinates (DDM): 39° 18.51152550' N 077° 46.86247146' W


Rating: High
ProtectionLevel: Not Applicable,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 9

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Not applicable
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Museum Restoration Building Charlestown, WVA
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 59807, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ,
Coordinates (DDM): 39° 17.24814162' N 077° 51.83998620' W

Rating: No Wildland Risk
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 1

Primary Access:
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)

NO PHOTO AVAILABLE



NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Shack (Quarry Workers)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 105863, ***Local ID:***
Structure Type, Use: Building, No known use
Owner: National Park Service
Field Crew, Visit Date: NCR fire management , June 2, 2022
Coordinates (DDM): 39° 17.99931042' N 077° 47.03361276' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 7

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with no turnaround
Access and Turnarounds: Less than 300 ft with no turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Heavy
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Shack (Quarry Workers)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 105861, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, June 2, 2022
Coordinates (DDM): 39° 18.29817780' N 077° 46.97354364' W


Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 8

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with no turnaround
Access and Turnarounds: Less than 300 ft with no turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Heavy
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Four additional standing outbuildings in poor condition.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: CHARLESTOWN WAREHOUSE
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 69999, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ,
Coordinates (DDM): 39° 17.24814192' N 077° 51.83998056' W

Rating: No Wildland Risk
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 2

Primary Access:
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Warehouse (GSF)

NO PHOTO AVAILABLE



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Nash Main House
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 87850, ***Local ID:***
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , June 14, 2022
Coordinates (DDM): 39° 19.85815884' N 077° 45.26248314' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 25

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg.Environment Ed. Ctr (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Nash Randolph Cottage
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 105526, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire, June 14, 2022
Coordinates (DDM): 39° 19.88678724' N 077° 45.25556862' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 26

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg.Environment Ed. Ctr (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

<FNT style="Bold Italic">Facility Name: </FNT>GS - Bolivar Heights Grandview School
<FNT style="Bold Italic">Unit - Location: </FNT>HAFE - Harper's Ferry NHP
<FNT style="Bold Italic">FMSS ID: </FNT>28549, <FNT style="Bold Italic">Local ID: </FNT>
<FNT style="Bold Italic">Structure Type, Use: </FNT> Building, Administrative
<FNT style="Bold Italic">Owner: </FNT> National Park Service

Rating: Low
ProtectionLevel: Full,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 5 yrs
Map Label: 15

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Nash Barn
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 87848, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire, June 14, 2022
Coordinates (DDM): 39° 19.87964832' N 077° 45.26486478' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 24

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Barn Stable (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Murphy Farm House
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3794, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Awesome NCR Fire Crew , May 31, 2022
Coordinates (DDM): 39° 18.74254632' N 077° 45.60592182' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 5 yrs
Map Label: 13

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments: 1500' to fire hydrant at KOA on Murphy Road







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Q-00000091 H91 Quarters
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3799, ***Local ID:***
Structure Type, Use: Building, Other
Owner: National Park Service
Field Crew, Visit Date: Ncr fire, June 3, 2022
Coordinates (DDM): 39° 18.92136336' N 077° 45.64021818' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 5 yrs
Map Label: 12

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Vinyl
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: BandO Railroad Train Station
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 33295, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.47120678' N 077° 43.86108390' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 31

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B84 - Blacksmith Shop
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3737, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.31111976' N 077° 44.03346174' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 19

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B37 - Black History Exhibit (or John T. Reily)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3734, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.38213378' N 077° 43.83110832' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 50

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Cont Stat (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B10 - John C Unseld Building
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28556, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.38816426' N 077° 43.80628668' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 63

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: No wildland fuel
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B40 - Frankel Brother Store (or William Richards)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3736, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.36850988' N 077° 43.83936450' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 39

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Custodial Warehouse
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 99806, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.44397302' N 077° 44.56047138' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: yrs
Map Label: 68

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Warehouse (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B14 - Alfred Burton Jewelry Shop
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 34253, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.39245816' N 077° 43.82860296' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 52

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B3 - Civil War Story EXH
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3765, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.38907314' N 077° 43.84268106' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 37

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Interpretive Media (EA)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B93 Equipment Shed Maintenance Yard
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3815, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR FIRE, March 8, 2023
Coordinates (DDM): 39° 19.369' N 77° 44.590' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 66

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg Warehouse Equip/Veh (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Q-0000001D H1D - Quarters
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3802, ***Local ID:***
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.40216718' N 077° 43.86995364' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 28

Primary Access:
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name:
Unit - Location:
FMSS ID: 3727, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.39903728' N 077° 43.83668940' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 43

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B1A - Harper House
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3728, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.38526428' N 077° 43.85339034' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 35

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Lodge/Motel (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B38 - Archeologh Exhibit (or Tearney Building)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3735, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.37211684' N 077° 43.83294252' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 47

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Q-00000048 H48 - Employees Armorer House
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3791, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.32914940' N 077° 44.02212630' W


Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 22

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Q-0000001C H1C - Quarters
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3801, ***Local ID:***
Structure Type, Use: Building, Residence
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.39713696' N 077° 43.86491022' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 30

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B75 - Freewill Baptist Church
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28547, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.50801468' N 077° 44.46096696' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: yrs
Map Label: 77

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Auditorium (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Camp Hill Shipley School
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3775, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.52580942' N 077° 44.48561940' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: yrs
Map Label: 72

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. School (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B12 - Ann C Stephenson Building
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28558, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.38249162' N 077° 43.81475832' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 60

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: No wildland fuel
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B58 Morrell house
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 1005, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.44372594' N 077° 44.26240878' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 84

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B12A - Ann Stephenson Outbuilding
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28559, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.38641940' N 077° 43.82125650' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 56

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B11A - Anderson Annes
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 35966, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.39006758' N 077° 43.81666566' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 59

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Salt Bin Shed Maintenance Yard
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 228520, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR FIRE, March 8, 2023
Coordinates (DDM): 39° 19.404' N 77° 44.612' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 4

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Museum and Maintenance Storage Building
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3793, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.46403564' N 077° 44.47487178' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: yrs
Map Label: 73

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B34A - Smokehouse
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 35335, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.34647020' N 077° 43.83170304' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 49

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


<FNT style="Bold Italic">Facility Name: </FNT>B63 - John Brown Fort (Armory Engine House)
<FNT style="Bold Italic">Unit - Location: </FNT>HAFE - Harper's Ferry NHP
<FNT style="Bold Italic">FMSS ID: </FNT>3742, <FNT style="Bold Italic">Local ID: </FNT>
<FNT style="Bold Italic">Structure Type, Use: </FNT> Building, Public
<FNT style="Bold Italic">Owner: </FNT> National Park Service

Rating: Low
ProtectionLevel: Full,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 65

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Cont Stat (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Bird-Brady Garage
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 81983, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, March 8, 2023
Coordinates (DDM): 39° 19.383' N 77° 44.527' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 69

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Housing Garage (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B43 - McCabemarmion Building (Industry Exhibit)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 35344, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.35872484' N 077° 43.85235558' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 36

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B9 - Gerard Bond Wager (J-Brown Story Exhibit)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28555, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.39125522' N 077° 43.80133914' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 64

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B43A - Cooling Tower
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 35345, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.36099866' N 077° 43.85719812' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 34

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: No defensible space
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B64 - Anthony Library
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28548, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, March 8, 2023
Coordinates (DDM): 39° 19.404' N 77° 44.508' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 71

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Library (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B33A
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3731, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.34011152' N 077° 43.83628290' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 44

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:








NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B45 - Bookstore
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3739, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.34891550' N 077° 43.86790896' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 29

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B57 Brackett House
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28546, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.43440296' N 077° 44.18243796' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 86

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 31% to 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: MF03 - Musket Factory; Rolling Mill Power Palnt
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 39960, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.57718616' N 077° 44.02817016' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 20

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with no turnaround
Access and Turnarounds: Less than 300 ft with no turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Cont Stat (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B8 Gerard Bond Wager Annex
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 34012, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.39622298' N 077° 43.80641760' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 62

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Q-00000036 H36 Quarters
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3787, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.35621936' N 077° 43.82126442' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 55

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Upstairs







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B33 - Ranger Headquarters and 33A
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3731, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.34787768' N 077° 43.83981666' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 38

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:








NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B34 - Provost Marshels Office
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3732, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.35248286' N 077° 43.83434148' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 45

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B81 Bomb Shelter Entrance
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28550, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.46403564' N 077° 44.47487178' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: yrs
Map Label: 73

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)








NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B45A - Outhouse
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3741, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.34634834' N 077° 43.87825800' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 27

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:








NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B35 - Dry Goods Store
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 35337, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.35270090' N 077° 43.82821092' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 53

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B5 - Frederick A Roeder Store
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 33998, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.40682882' N 077° 43.82540508' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 54

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B59 - Mather Training Center
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 1028, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.43981328' N 077° 44.46598692' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: yrs
Map Label: 76

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B83 - Interpretive Design Center
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28551, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, March 8, 2023
Coordinates (DDM): 39° 19.397' N 77° 44.467' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 75

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B56 Lockwood House (Paymasters House)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 1027, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.42327098' N 077° 44.12419170' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 87

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B61 - Cook Hall
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 28553, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.40852220' N 077° 44.43256374' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 78

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: Greater than 100ft treated
Topography: Slope Greater than 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B69 - Bird Brady (IDC Asministration)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3749, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, March 8, 2023
Coordinates (DDM): 39° 19.382' N 77° 44.510' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 70

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Q-0000008 H8 Quarters
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3797, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.39623270' N 077° 43.80641598' W

Rating: Not Surveyed
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 88

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane:
Overhead Hazards: No overhead hazards
Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)

NO PHOTO AVAILABLE



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B36 - Master Armorers Exhibit (New Master Armor)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3733, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.35621486' N 077° 43.82122854' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 57

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name:
Unit - Location:
FMSS ID: 3730, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd ,
Coordinates (DDM): 39° 19.33609458' N 077° 43.83330504' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 46

Primary Access:
Ingress Egress:
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:






NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: B44 - Restrooms Lowertown (Philip Coons Bldg)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3738, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.35486468' N 077° 43.85836974' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 33

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B7 - White Hall Tavern
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3743, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: CUGA WFM, May 20, 2015
Coordinates (DDM): 39° 19.40328912' N 077° 43.81787520' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: yrs
Map Label: 58

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Bus Maint Shop and Grage (Cavalier Heights)
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 48365, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR fire, June 3, 2022
Coordinates (DDM): 39° 18.96694080' N 077° 45.25844754' W


Rating: Moderate
ProtectionLevel: Full,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 83

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: B97 Kiosk Cavalier Heights
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3771, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, June 3, 2022
Coordinates (DDM): 39° 19.00651764' N 077° 45.37909950' W


Rating: Low
ProtectionLevel: Full,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 82

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Entrance Station (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Bus Shelter Cavalier Heights
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3770, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR fire, June 3, 2022
Coordinates (DDM): 39° 18.99188952' N 077° 45.42499242' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: No
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 79

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Restrooms Cavalier Heights
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 40571, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR fire, June 3, 2022
Coordinates (DDM): 39° 19.00329546' N 077° 45.41770998' W


Rating: Low
ProtectionLevel: Full,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 80

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Visitor Center
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 3769, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, June 3, 2022
Coordinates (DDM): 39° 18.99478020' N 077° 45.41731656' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: No
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 81

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Museum Repository (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: School House Privy
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: N/A, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, June 2, 2022
Coordinates (DDM): 39° 18.45747120' N 077° 46.66109544' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 10

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:








NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Nash Shed
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: N/A, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , June 14, 2022
Coordinates (DDM): 39° 19.84513242' N 077° 45.25165164' W

Rating: High
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 14

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Schoolhouse Ridge North Bathroom
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: N/a, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: NCR Wildland Fire , July 21, 2022
Coordinates (DDM): 39° 19.54113654' N 077° 46.01654370' W

Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 5 yrs
Map Label: 3

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Bus Shelter Lower Town
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: 226673, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: J shedd, October 12, 2022
Coordinates (DDM): 39° 19.31982108' N 077° 43.93929852' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 89

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Not applicable
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: New storage
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: Na, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: J shedd , October 12, 2022
Coordinates (DDM): 39° 19.34065218' N 077° 43.88303364' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, John Brownandapos;s Fort
Revisit Interval: 5 yrs
Map Label: 90

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Greater than 40%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: saw shed
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR FIRE, March 8, 2023
Coordinates (DDM): 39° 19.411' N 77° 44.608' W

Rating: Low
ProtectionLevel: ,
Resources of Concern: No
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 91

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: maintenance vehicle bay
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR FIRE, March 8, 2023
Coordinates (DDM): 39° 19.375' N 77° 44.575' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: No
Occupied: Yes
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 92

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Shed
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: N/A, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, March 8, 2023
Coordinates (DDM): 39° 19.367' N 77° 44.573' W

Rating: Low
ProtectionLevel: ,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 93

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Unkown Storage
Unit - Location: HAFE - Harper's Ferry NHP
FMSS ID: N/A, ***Local ID:*** storage shed
Structure Type, Use: Building, Other
Owner: National Park Service
Field Crew, Visit Date: NCR Fire, March 8, 2023
Coordinates (DDM): 39° 19.385' N 77° 44.577' W

Rating: Low
ProtectionLevel: ,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 5 yrs
Map Label: 94

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:



