
Manassas National Battlefield

MANA - Manassas National Battlefield Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
1	47135	Headquarters Well House
10	249277	MJ Dogan House
11	47099	Lucinda Dogan House
12	239573	Featherbed Garage
13	47064	Thornberry House
14	130148	Quarters 5 garage
15	47101	Quarters 5 (Rosefield) (J Dougan)
16	47067	Quarters 9
17	47066	Stone House
18	47118	Henry House
19	1195277	Henry House Outbuilding
2	47134	Park Headquarters
20	47116	Henry Hill Visitor Center
21	1571785	Law Enforcement Storage Shed
22	not found	Hay Barn
23	not found	Portici Shed
24	47126	Black Powder Magazine
25	47127	Maintenance Shop
26	47128	CCC Shed Maintenance
27	47125	Maintenance Well House
28	47121	Maintenance Office Building
29	not found	Shed 2
3	47137	Stuarts Hill Center
30	not found	Shed 1
31	47071	Fire Cache (Old Qtrs 8)
32	47072	Quarters 6 (Sutton House)
33	47069	Visitor Protection Office
34	47070	Tack Room
35		horse shed 3
4	225265	Brawner Farm Restroom Facility
5	47103	Brawner Farm House
6	1274122	Brownsville Pavilion
7	1581585	Brownsville bathroom
8	not found	Quarters 10 Barn
9	47132	Quarters 10



N

Author: sszturm
3/26/2024 9:38 AM

0 4 Miles

Scale: 1:50,000

NPS Wildfire Risk Assessments
NPS Fire GIS
March 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Quarters 5 (Rosefield) (J Dougan)
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47101, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.06074006' N 077° 32.08297170' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 7 yrs
Map Label: 15

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Brownsville Pavilion
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 1274122, ***Local ID:***
Structure Type, Use: Shade/Picnic Structure, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.21125664' N 077° 33.12750048' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 6

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Henry Hill Visitor Center
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47116, ***Local ID:***
Structure Type, Use: Building, Public
Owner:
Field Crew, Visit Date: ,
Coordinates (DDM):


Rating:
ProtectionLevel: ,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 7 yrs
Map Label:

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Center (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Quarters 10 Barn
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: not found, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.65066664' N 077° 32.99304072' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 8

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Quarters 5 garage
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 130148, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.06513968' N 077° 32.08849032' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 14

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Vinyl
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Featherbed Garage
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 239573, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.24322052' N 077° 32.90262138' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 12

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Hay Barn
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: not found , ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.55740936' N 077° 30.37513800' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 22

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Brownsville bathroom
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 1581585, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.21564528' N 077° 33.12695544' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 7

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Stone House
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47066, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.12843974' N 077° 31.56248346' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 17

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Under construction







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: CCC Shed Maintenance
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47128, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.60192966' N 077° 31.53203718' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 26

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Fire Cache (Old Qtrs 8)
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47071, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.61458764' N 077° 31.09754184' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 31

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Vinyl
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Warehouse Fire Ca (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Thornberry House
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47064, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 50.51642658' N 077° 32.24159820' W


Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 13

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Cont Stat (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Quarters 10
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47132, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.65768166' N 077° 32.98553424' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 9

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Maintenance Well House
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47125, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.61312494' N 077° 31.52737608' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 27

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Pump / House (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Lucinda Dogan House
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47099, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.78143994' N 077° 32.94389694' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 11

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Cont Stat (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Stuarts Hill Center
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47137, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.30878982' N 077° 34.24972230' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 7 yrs
Map Label: 3

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Heavy
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Center (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Park Headquarters
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47134, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.30046482' N 077° 34.25977230' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 7 yrs
Map Label: 2

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Heavy
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Headquarters Well House
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47135, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.28801482' N 077° 34.28144730' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 1

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Heavy
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Pump / House (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Visitor Protection Office
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47069, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.63014018' N 077° 31.08397140' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 33

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Tack Room
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47070, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.61424018' N 077° 31.06957140' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 34

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Quarters 6 (Sutton House)
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47072, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.59639018' N 077° 31.08914640' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 32

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. House Single Fam (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Quarters 9
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47067, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.94769024' N 077° 32.02762170' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 7 yrs
Map Label: 16

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Heavy
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Housing, Support (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Maintenance Office Building
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47121, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.58553994' N 077° 31.50367146' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 28

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Maintenance Shop
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47127, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.58343994' N 077° 31.53554646' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 25

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: No wildland fuel
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Black Powder Magazine
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47126, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.62843994' N 077° 31.55834652' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 24

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Brawner Farm House
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47103, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.79943994' N 077° 33.91199724' W


Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 7 yrs
Map Label: 5

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Heavy
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Cultural Ctr (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Henry House
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 47118, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.88741500' N 077° 31.36364646' W


Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 18

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Other than all season
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Cont Stat (GSF)








NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Brawner Farm Restroom Facility
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 225265, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.83589552' N 077° 34.08662880' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 4

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Shed 1
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: not found, ***Local ID:***
Structure Type, Use: Shade/Picnic Structure, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.60397256' N 077° 31.10227608' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 30

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Shed 2
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: not found, ***Local ID:***
Structure Type, Use: Shade/Picnic Structure, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.62572208' N 077° 31.11480408' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 29

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Portici Shed
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: not found, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.44354400' N 077° 30.13158504' W


Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 23

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Very Heavy
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: horse shed 3
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: , ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.64888448' N 077° 31.06476744' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes,
Revisit Interval: 7 yrs
Map Label: 35

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Henry House Outbuilding
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 1195277, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.89954868' N 077° 31.36177542' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 19

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Cont Stat (GSF)







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: MJ Dogan House
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 249277, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 48.77057352' N 077° 32.95968066' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 10

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Log construction
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: under construction







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Law Enforcement Storage Shed
Unit - Location: MANA - Manassas National Battlefield
FMSS ID: 1571785, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo , June 10, 2021
Coordinates (DDM): 38° 49.62503076' N 077° 31.07184480' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 7 yrs
Map Label: 21

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: No wildland fuel
Fuel Load: Light or no wildland fuels
Defensible Space: No defensible space
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Vinyl
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:



