
NPS Wildfire Risk Assessments
Assessment Locations

Glen Canyon National Recreation Area - Overview

National Park Service
U.S. Department of the Interior




Author: sszturm
5/8/2024 10:34 AM

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

NPS Wildfire Risk Assessments
Assessment Locations

Glen Canyon National Recreation Area - Wahweap - Overview

National Park Service
U.S. Department of the Interior



N

0 2.5 5 Miles

Author: sszturm
5/14/2024 2:48 PM

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS

North Entrance

GLCA - Glen Canyon National Recreation Area

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
361	44449	WW North Entrance Micro Flush
362	44445	WW North Entrance Station #4
363	44447	WW North Entrance Station #5



Author: sszturm
5/14/2024 1:42 PM

N

0 500 Feet

Scale: 1:3,000


NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS

Wahweap Aramark

GLCA - Glen Canyon National Recreation Area

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
405	GLCA	WW Aramark Cafeteria
409	GLCA	WW Aramark Dorm #1
415	GLCA	WW Aramark Dorm #2
412	GLCA	WW Aramark Dorm #3
413	GLCA	WW Aramark Dormitory #4
407	GLCA	WW Aramark Dormitory #5
427	GLCA Dry	WW Aramark Dry Storage Office Risk Management
416	GLCA	WW Aramark Employee Housing Dorm #6
406	GLCA	WW Aramark Human Resources/Rec Center
429	GLCA	WW Aramark Property Maint./Laundry
427	85704	WW Aramark Storage (Trailer Park)
447	44432	WW Flammable Storage Building
443	44428	WW Hazmat Storage
446	44552	WW Quadplex #114
455	44527	WW Housing 115
458	44531	WW Housing 116
460	44534	WW Housing 117
463	44536	WW Housing 118
451	44539	WW Housing Quadplex #119
438	44563	WW Housing #120
437	44566	WW Housing #121
441	44567	WW Housing #122
442	44569	WW Housing #123
456	44570	WW Housing #124
459	44573	WW Housing #125
461	44575	WW Housing #126
436	GLCA RV	WW Housing RV Pergola
462	GLCA Lake	WW Lake Powell Sports
453	44408	WW Lower Warehouse
450	44426	WW Lumber/Pipe Storage
469	44422	WW Main Ramp Comfort Station
449	44403	WW Maintenance Building
448	44430	WW Paint Storage Building
397	52490	WW Pressure Building Trailer Village
452	44406	WW Upper Warehouse
470	GLCA	WW Wahweep Grille
431	GLCA	WW Wahweep Trailer Village Community
396	52485	WW Well House #3
476	GLCA NPS	WW NPS Dock Ranger Storage Shed
475	GLCA Dock	WW NPS Dock Storage Shed 1



N

Author: sszturm
5/14/2024 1:51 PM

0 0.5 Miles


Scale: 1:12,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Source: ESRI Basedata, NPS

Wahweap Bay

GLCA - Glen Canyon National Recreation Area

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
372	GLCA Boat	WW Boat Rental Building
373	GLCA Boat	WW Boat Repair Shop
381	GLCA WW	WW Campground Comfort Station Loop D #1
378	236768	WW Campground Comfort Station Loop D #2
369	44420	WW Coves Comfort Station
370	GLCA Cove	WW Coves Shade Structure #1
368	GLCA	WW Coves Shade Structure #2
365	GLCA Cove	WW Coves Shade Structure #3
364	GLCA	WW Coves Shade Structure #4
366	GLCA	WW Living Qtrs Garage and Warehouse
367	GLCA WW	WW Offices 751
403	52502	WW Stateline Boat Pumpout Station
374	GLCA SL	WW Stateline Boat Rental Ticket Booth
399	44412	WW Stateline Comfort Station
421	GLCA	WW Swim Beach Microflush #2
371	52481	WW Well House #4
383	GLCA SL	WW Stateline Boat Rental Shop Shade Bldg.
390	GLCA SL	WW Stateline Fuel Dock Bldg.
375	GLCA SL	WW Stateline Houseboat Cleaning Bldg.
376	GLCA SL	WW Stateline Maintenance Bldgs.
384	GLCA SL	WW Stateline Shade Structure #1
379	GLCA SL	WW Stateline Shade Structure #2
377	GLCA SL	WW Stateline Ski Shack Shade Bldg.
380	GLCA SL	WW Stateline Storage Shed
382	GLCA SL	WW Stateline Store Bldg.

Facility

Rating

- Low
- Moderate
- No Wildland Risk

N

Author: sszturm
5/14/2024 10:12 AM

0 0.5 Miles

Scale: 1:12,000


NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Source: ESRI Basedata, NPS

Wahweap Campground

GLCA - Glen Canyon National Recreation Area

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
411	GLCA CG	WW Campground Amphitheatre
391	GLCA WW	WW Campground Comfort Station Group Site
414	GLCA WW	WW Campground Comfort Station Loop 1
410	GLCA WW	WW Campground Comfort Station Loop 2
402	GLCA WW	WW Campground Comfort Station Loop 3
401	GLCA WW	WW Campground Comfort Station Loop 4
393	GLCA WW	WW Campground Comfort Station Loop A
389	GLCA WW	WW Campground Comfort Station Loop B
385	GLCA WW	WW Campground Comfort Station Loop C
395	GLCA	WW Campground Group Site Shade Structure #1
400	236769	WW Campground Restrooms/Showers
430	52504	WW Fish Cleaning Station
423	GLCA	WW Picnic Area Shade Structure #1
425	44418	WW Picnic Comfort Station
408	44416	WW Swim Beach Comfort Station
396	52485	WW Well House #3
404	GLCA WW	WW Campground Comfort Station Loop F
394	GLCA	WW Campground Group Site Shade Structure #2
392	GLCA	WW Campground Group Site Shade Structure #3
388	GLCA	WW Campground Group Site Shade Structure #4
386	GLCA	WW Campground Group Site Shade Structure #5
387	GLCA	WW Campground Group Site Shade Structure #6
426	GLCA	WW Picnic Area Shade Structure #2
424	GLCA	WW Picnic Area Shade Structure #3
422	GLCA	WW Picnic Area Shade Structure #4
420	GLCA	WW Picnic Area Shade Structure #5
419	GLCA	WW Picnic Area Shade Structure #6
418	GLCA	WW Picnic Area Shade Structure #7
417	GLCA	WW Picnic Area Shade Structure #8



N

Author: sszturm
5/14/2024 10:41 AM

0 500 1,000 1,500 Feet

Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS


NPS Wildfire Risk Assessment Project

Wahweap Lodge

GLCA - Glen Canyon National Recreation Area

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
467	225377	WW Decontamination Station Shade Structure/Storage
439	44401	WW District Ranger Office (Historic)
440	44424	WW Fire Station
473	GLCA	WW Lodge Building #1
474	GLCA	WW Lodge Building #2
477	GLCA	WW Lodge Building #3
471	GLCA	WW Lodge Building #4
471	GLCA	WW Lodge Building #5
464	GLCA	WW Lodge Building #6
464	GLCA	WW Lodge Building #7
454	GLCA	WW Lodge Building #8
485	52494	WW Main Ramp Boat Pumpout Building
468	GLCA WW	WW Pool Bar
466	GLCA	WW Sinclair Gas Station
470	GLCA	WW Wahweep Grille
484	GLCA WW	WW Main Ramp Fuel Dock Mass Fuel Storage
486	GLCA WW	WW Main Ramp Fuel Dock Store Restroom Office Shade
483	GLCA WW	WW Main Ramp Fuel Dock Electrical Building



Rating

Rating — No Wildland Risk; Low

N

Author: sszturm
5/14/2024 10:52 AM

0 500 1,000 1,500 Feet


Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS

Wahweap Marina

GLCA - Glen Canyon National Recreation Area

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
479	GLCA WW	WW Marina Fishing Dock Shade Structure #1
480	GLCA WW	WW Marina Fishing Dock Shade Structure #2
481	GLCA WW	WW Marina Info Booth
482	GLCA	WW Marina Electrical Bldg.
487	230897	WW Marina Restroom Electrical Bldg. #001
488	GLCA WW	WW Marina Office Store
489	GLCA WW	WW Marina Office Store Storage
490	GLCA WW	WW Marina Restroom Electrical Shade #1
491	GLCA WW	WW Marina Restroom Electrical Shade #2
492	GLCA WW	WW Marina Restroom Electrical Shade #3
493	GLCA WW	WW Marina Restroom Electrical Shade #4

Rating

Rating — No Wildland Risk

Low

N

Author: sszturm
5/14/2024 12:22 PM

0 500 1,000 Feet

Scale: 1:5,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Sources: ESRI Basedata, NPS


NPS Wildfire Risk Assessment Project

WW Navajo Mountain

GLCA - Glen Canyon National Recreation Area

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
444	GLCA WW	WW Navajo Mtn Viewpoint Shade Structure #1
445	GLCA WW	WW Navajo Mtn Viewpoint Shade Structure #2
457	228392	WW Wahweep Overlook Shade Structure
398	228393	WW Wahweep View Overlook Shade Structure



N

Author: sszturm
5/14/2024 9:07 AM

0 0.5 Miles

Scale: 1:12,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Source: ESRI Basedata, NPS

NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing #120
Unit - Location: GLCA - Wahweap
FMSS ID: 44563, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.24200002' N 111° 29.51100000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 438

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Group Site Shade Structure #3
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Campground Groupsite #3, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.73000000' N 111° 29.99500002' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 392

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Very sparse fuels, mostly cement structures.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Group Site Shade Structure #4
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Campground Groupsite #4, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.73799998' N 111° 30.01800000' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 388

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Very sparse fuels, mostly cement structures.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Boat Rental Ticket Booth
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Boat Rent Ticket Booth, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.24300000' N 111° 30.19099998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 374

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: Lake Powell or Campground hydrants. Treatment: None. Sparse fuels and metal structure.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Dorm #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Dorm #1, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.50300002' N 111° 29.80800000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 409

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Wahweep Overlook Shade Structure
Unit - Location: GLCA - Wahweap
FMSS ID: 228392, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 58.42000002' N 111° 29.38800000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 457

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Very sparse fuels and a metal structure.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing 118
Unit - Location: GLCA - Wahweap
FMSS ID: 44536, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.25300000' N 111° 29.33400000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 463

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Pool Bar
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Pool Bar, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.72899998' N 111° 29.27700000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 468

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Area Ingress/Egress: Walkway to get in. Water Supply: 1.5 million gallon tank. Building Number: Have to walk behind lodge buildings to see it. Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Houseboat Cleaning Bldg.
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Houseboat Cleaning, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.47200002' N 111° 30.18799998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 375

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock surrounded by water. No wildfire risk.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Shade Structure #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Shade # 1, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.37900002' N 111° 30.06100002' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 384

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Structure is on the dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Flammable Storage Building
Unit - Location: GLCA - Wahweap
FMSS ID: 44432, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.40100002' N 111° 29.45299998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 447

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Area Shade Structure #3
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Picnic Area #3, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.87500002' N 111° 29.68999998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 424

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Restroom Electrical Bldg. #001
Unit - Location: GLCA - Wahweap
FMSS ID: 230897, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.44500000' N 111° 29.04199998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 487

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Structure is in the water on the docks.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Quadplex #114
Unit - Location: GLCA - Wahweap
FMSS ID: 44552, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.24500002' N 111° 29.46400002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 446

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Water Supply: 1.5 million gallon tank.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing #123
Unit - Location: GLCA - Wahweap
FMSS ID: 44569, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.24700000' N 111° 29.48500002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 442

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Water Supply: 1.5 million gallon tank.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lodge Building #6
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lodge Building #6, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.70700002' N 111° 29.31300000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 464

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW NPS Dock Ranger Storage Shed
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA NPS Dock Storage Shed, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.42599998' N 111° 29.22199998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 476

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Structure is on the docks in the middle of the water. Not at risk of wildfire.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Employee Housing Dorm #6
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Aramark Housing, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.45800002' N 111° 29.72599998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 416

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Upper Warehouse
Unit - Location: GLCA - Wahweap
FMSS ID: 44406, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.41000002' N 111° 29.41500000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 452

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. No fuels to treat.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing 116
Unit - Location: GLCA - Wahweap
FMSS ID: 44531, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.26300002' N 111° 29.36700000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 458

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Topography: Drainage behind house.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Main Ramp Fuel Dock Electrical Building
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Main Fuel Dock, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.58300000' N 111° 29.08200000' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 483

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the water.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Group Site Shade Structure #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Campground Groupsite #2, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.73100002' N 111° 29.98099998' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 394

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Very sparse fuels, mostly cement structures.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop A
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Campground loop A, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.94400002' N 111° 29.98800000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 393

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lodge Building #4
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lodge Building #4, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.72800002' N 111° 29.24200002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 471

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 100 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW North Entrance Station #4
Unit - Location: GLCA - Wahweap
FMSS ID: 44445, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.35699998' N 111° 30.94600002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 999 yrs
Map Label: 362

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Sparse, light fuels and building surrounded by asphalt.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Area Shade Structure #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Picnic Area #2, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.86699998' N 111° 29.68300002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 426

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Boat Repair Shop
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Boat Repair, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.14100000' N 111° 30.32800002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 373

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: 1.5 million gallon tank.
Obstacles: Hazmat.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lumber/Pipe Storage
Unit - Location: GLCA - Wahweap
FMSS ID: 44426, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.41099998' N 111° 29.44399998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 450

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Water Supply: 1.5 million gallon tank in WW.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW North Entrance Micro Flush
Unit - Location: GLCA - Wahweap
FMSS ID: 44449, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.35699998' N 111° 30.94600002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 361

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Info Booth
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Info, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.47800000' N 111° 29.11999998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 481

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is located on a dock in the middle of the water. No wildfire risk.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Area Shade Structure #8
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Picnic Area #8, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.86800000' N 111° 29.71900002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 417

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing Quadplex #119
Unit - Location: GLCA - Wahweap
FMSS ID: 44539, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.24899998' N 111° 29.44099998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 451

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Water Supply: 1.5 million gallon tank for the Wahweep area.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Group Site
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW CCS Group Site, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.74500000' N 111° 30.00499998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 391

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Restroom Electrical Shade #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Restroom #2, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.41099998' N 111° 28.89199998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 491

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Amphitheatre
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA CG Amphitheatre, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.83399998' N 111° 29.77099998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 411

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Fencing: Wood treluses over walkway. Treatment: None. No additional work needed. Cement structure and sparse ground cover.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Maintenance Bldgs.
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Maintenance Bldgs, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.48199998' N 111° 30.18100002' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 376

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Buildings are on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing #125
Unit - Location: GLCA - Wahweap
FMSS ID: 44573, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.25600000' N 111° 29.35800000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 459

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Water Supply: 1.5 million gallon tank.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Property Maint./Laundry
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Property/Maint./Laundry, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.42700000' N 111° 29.64799998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 429

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Cafeteria
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Aramark Cafeteria, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.43400002' N 111° 29.84500002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 405

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Wahweep Grille
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Wahweap Grille, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.59300002' N 111° 29.24899998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 470

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Shade Structure #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Shade Structure, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.40699998' N 111° 30.12000000' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 379

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on the dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Dry Storage Office Risk Management
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Dry Storage, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.42800002' N 111° 29.64799998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 427

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop 3
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW CCS loop 3, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.73499998' N 111° 29.87200002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 402

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Coves Shade Structure #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Cove Shade # 1, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.42799998' N 111° 30.50100000' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 370

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: Lake Powell. Treatment: None.
Very sparse fuels, mostly cement structure.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing 117
Unit - Location: GLCA - Wahweap
FMSS ID: 44534, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.25799998' N 111° 29.34799998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 460

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Fishing Dock Shade Structure #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Fishing Dock, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.48400000' N 111° 29.13499998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 479

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Shade structure in the middle of the water on a dock not at risk of wildfire.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Navajo Mtn Viewpoint Shade Structure #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Navajo Mtn Shade #2, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 57.86200002' N 111° 29.46600000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 445

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: Lake Powell. Treatment: None.
Very sparse fuels.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Restrooms/Showers
Unit - Location: GLCA - Wahweap
FMSS ID: 236769, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.91499998' N 111° 29.89600002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 400

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards

Comments: Structure Number: Labeled as registration and store. Propane Tank: Rake around it. Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Boat Pumpout Station
Unit - Location: GLCA - Wahweap
FMSS ID: 52502, ***Local ID:***
Structure Type, Use: Utility Site (Water, Gas,Elec), Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.28699998' N 111° 29.85900000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 403

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Buildings in the water.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lodge Building #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lodge Building #2, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.64100002' N 111° 29.23600002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 474

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop 4
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW CCS Loop 4, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.81200002' N 111° 29.87800002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 401

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Water Supply: 1.5 million gallon tank.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Coves Comfort Station
Unit - Location: GLCA - Wahweap
FMSS ID: 44420, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.35700000' N 111° 30.53700000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 369

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Treatment: None. Sparse fuels.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Dorm #3
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Aramark Dorm, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.45100000' N 111° 29.75500002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 412

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Main Ramp Comfort Station
Unit - Location: GLCA - Wahweap
FMSS ID: 44422, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.53900002' N 111° 29.26000002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 469

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Main Ramp Fuel Dock Store Restroom Office Shade
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Main Fuel Dock Restroom Office Shade, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.57599998' N 111° 29.05500000' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 486

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Buildings are at the end of the dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Pressure Building Trailer Village
Unit - Location: GLCA - Wahweap
FMSS ID: 52490, ***Local ID:***
Structure Type, Use: Utility Site (Water, Gas,Elec), Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.46900000' N 111° 29.96599998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 397

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Hazmat.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop 1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW CCS Loop 1, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.74800000' N 111° 29.73499998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 414

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: 1.5 million gallon tank.
Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Boat Rental Shop Shade Bldg.
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Boat Rent Shade, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.39700002' N 111° 30.09499998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 383

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Buildings are on the dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lake Powell Sports
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lake Powell Sports, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.53900002' N 111° 29.33700000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 462

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Fuel Dock Bldg.
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Fuel Dock, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.42900000' N 111° 30.01099998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 390

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock surrounded by water. It is a fueling station but there is no risk of wildfire.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing #126
Unit - Location: GLCA - Wahweap
FMSS ID: 44575, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.24800002' N 111° 29.34100002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 461

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Water Supply: 1.5 million gallon tank.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop 2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW CCS loop 2, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.73499998' N 111° 29.79300000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 410

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop D #2
Unit - Location: GLCA - Wahweap
FMSS ID: 236768, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.03100002' N 111° 30.15000000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 378

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lodge Building #7
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lodge Building #7, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.70700002' N 111° 29.31300000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 464

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Living Qtrs Garage and Warehouse
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Living Qtrs, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.12199998' N 111° 30.64399998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 366

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: Present and fuels clearance
Overhead Hazards: No overhead hazards

Comments: Propane Tank: Propane BBQ outside back door with 2 extra tanks.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop F
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW CCS Loop F, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.85300000' N 111° 29.84500002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 404

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: 1.5 million gallon tank supporting all of Wahweep.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Restroom Electrical Shade #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Restroom #1, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.42200002' N 111° 28.93200000' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 490

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Dormitory #4
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Aramark Dormitory #4, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.45100000' N 111° 29.75500002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 999 yrs
Map Label: 413

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Offices 751
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Offices, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.13300002' N 111° 30.60900000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 367

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lower Warehouse
Unit - Location: GLCA - Wahweap
FMSS ID: 44408, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.38900002' N 111° 29.40000000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 453

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Developed area with no fuels to treat.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop C
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW CCS Loop C, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.83500000' N 111° 30.04900002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 385

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: 1.5 million gallon tank.
Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lodge Building #5
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lodge Building #5, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.72800002' N 111° 29.24200002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 471

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Area Shade Structure #6
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Picnic Area #6, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.86099998' N 111° 29.70900000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 419

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Area Shade Structure #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Picnic Area, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.86800000' N 111° 29.69299998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 423

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing #122
Unit - Location: GLCA - Wahweap
FMSS ID: 44567, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.26300002' N 111° 29.48500002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 441

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: Adjacent to/under deck of facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Fire Station
Unit - Location: GLCA - Wahweap
FMSS ID: 44424, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.65300002' N 111° 29.49000000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 440

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing 115
Unit - Location: GLCA - Wahweap
FMSS ID: 44527, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.26300002' N 111° 29.39400000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 455

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1.5 lanes (Greater than 18')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Topography: Drainage to the N below the house.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Electrical Bldg.
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Marina Electrical Bldg, ***Local ID:***
Structure Type, Use: Utility Site (Water, Gas,Elec), Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.47500000' N 111° 29.11999998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 482

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: In the water. Fuel Type: All water. Obstacles: Evacuation. Treatment: None. All water.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Storage Shed
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Storage Shed, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.43399998' N 111° 30.10699998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 380

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the middle of the water.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Swim Beach Comfort Station
Unit - Location: GLCA - Wahweap
FMSS ID: 44416, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.97400002' N 111° 29.81200002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 408

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Dorm #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Dorm #2, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.48100000' N 111° 29.73300000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 415

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing #121
Unit - Location: GLCA - Wahweap
FMSS ID: 44566, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.25799998' N 111° 29.51200002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 437

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Water Supply: 1.5 million gallon tank.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lodge Building #8
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lodge Building #8, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.70700002' N 111° 29.39400000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 454

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Sinclair Gas Station
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Sinclair Gas Station, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.61300000' N 111° 29.31000000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 466

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: Adjacent to facility and no fuels clearance
Overhead Hazards: No overhead hazards

Comments: Propane Tank: Propane has tree hanging over it and gas and diesel adjacent to building.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Coves Shade Structure #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Cover Shade Structure # 2, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.41800002' N 111° 30.54700002' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 368

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: Lake Powell. Treatment: None.
Very sparse fuels and a mostly cement structure.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Storage (Trailer Park)
Unit - Location: GLCA - Wahweap
FMSS ID: 85704, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.42800002' N 111° 29.64799998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 427

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Vinyl
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: 5ft to 30ft from facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Fish Cleaning Station
Unit - Location: GLCA - Wahweap
FMSS ID: 52504, ***Local ID:***
Structure Type, Use: Other, Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.81899998' N 111° 29.62900002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 430

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lodge Building #3
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lodge Building #3, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.66200002' N 111° 29.21700000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 477

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW NPS Dock Storage Shed 1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Dock Storage Shed, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.43400002' N 111° 29.23600002' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 475

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is in the water on a dock. Not at risk of wildfire.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Ski Shack Shade Bldg.
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Ski Shack, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.42600000' N 111° 30.15700002' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 377

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW District Ranger Office (Historic)
Unit - Location: GLCA - Wahweap
FMSS ID: 44401, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.65200000' N 111° 29.49199998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 439

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Coves Shade Structure #3
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Cove Shade # 3, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.39600000' N 111° 30.70500000' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 365

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: Lake Powell. Treatment: None.
Very sparse fuels and mostly cement structure.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Boat Rental Building
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Boat Rental Bldg, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.34999998' N 111° 30.33199998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 372

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Structure Number: Old boat rental building, no address.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW North Entrance Station #5
Unit - Location: GLCA - Wahweap
FMSS ID: 44447, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.35699998' N 111° 30.94600002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 999 yrs
Map Label: 363

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Sparse, light fuels and building surrounded by asphalt.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Paint Storage Building
Unit - Location: GLCA - Wahweap
FMSS ID: 44430, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.40199998' N 111° 29.45100000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 448

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material:
Siding Material:
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply:
Propane:
Overhead Hazards:
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Area Shade Structure #5
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Picnic Area #5, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.88700002' N 111° 29.70799998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 420

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Main Ramp Fuel Dock Mass Fuel Storage
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Main Fuel Storage, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.57899998' N 111° 29.08099998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 484

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Diesel/Unleaded gas storage on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Well House #4
Unit - Location: GLCA - Wahweap
FMSS ID: 52481, ***Local ID:***
Structure Type, Use: Utility Site (Water, Gas,Elec), Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.43200000' N 111° 30.43300002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 371

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: 1.5 million gallon tank for all of Wahweep. Obstacles: Hazmat.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Fishing Dock Shade Structure #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Fishing Dock #2, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.47800000' N 111° 29.12299998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 480

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Not at wildfire risk. Structure is in the water on a dock.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Housing RV Pergola
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA RV Pergola, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.23099998' N 111° 29.52199998' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 436

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft

Comments: Water Supply: 1.5 million gallons of water. Siding Material: No siding. Ignition Potential: No eaves. Treatment: None. Sparse fuels.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Coves Shade Structure #4
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Coves Structure, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.39300000' N 111° 30.71899998' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 364

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: Lake Powell. Treatment: None.
Very sparse fuels and mostly cement structure.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Main Ramp Boat Pumpout Building
Unit - Location: GLCA - Wahweap
FMSS ID: 52494, ***Local ID:***
Structure Type, Use: Utility Site (Water, Gas,Elec), Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.62800000' N 111° 29.06100000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 485

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass/tundra,northern hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: 1.5 million gallon tank.
Obstacles: Evacuation. Treatment: None. In the water.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop D #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Campground, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.00000000' N 111° 30.10500000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 381

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Comfort Station Loop B
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Campground loop B, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.89300002' N 111° 30.01600002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 389

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Group Site Shade Structure #5
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Campground Groupsite #5, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.74600002' N 111° 30.03700002' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 386

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Very sparse fuels, mostly cement structures.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Well House #3
Unit - Location: GLCA - Wahweap
FMSS ID: 52485, ***Local ID:***
Structure Type, Use: Utility Site (Water, Gas,Elec), Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.54800002' N 111° 29.96599998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 396

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Human Resources/Rec Center
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Aramark HR/RC, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.46900000' N 111° 29.83099998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 406

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Comfort Station
Unit - Location: GLCA - Wahweap
FMSS ID: 44412, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.18499998' N 111° 29.91199998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 399

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Lodge Building #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Lodge Building #1, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.63700000' N 111° 29.24100000' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 473

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Restroom Electrical Shade #4
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Restroom Shade #4, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.38500000' N 111° 28.80400002' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 493

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Wahweep Trailer Village Community
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Trailer Village, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.52199998' N 111° 29.62399998' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 431

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Vinyl
Foundation: Closed, Less than 6in masonry exposed
Firewood: 5ft to 30ft from facility
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Obstacles: Evacuation, hazmat, junk.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Decontamination Station Shade Structure/Storage
Unit - Location: GLCA - Wahweap
FMSS ID: 225377, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.62999998' N 111° 29.28900000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 467

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Aramark Dormitory #5
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Aramark Dorm #5, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.41500000' N 111° 29.81899998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 407

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Greater than 300 ft with turnaround
Access and Turnarounds: Greater than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope Less than 5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Comfort Station
Unit - Location: GLCA - Wahweap
FMSS ID: 44418, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.85499998' N 111° 29.68999998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 425

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Group Site Shade Structure #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Campground Groupsite, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.74099998' N 111° 29.96700000' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 395

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Very sparse fuels, mostly cement structures.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Restroom Electrical Shade #3
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Restroom #3, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.39899998' N 111° 28.84800000' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 492

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Wahweep View Overlook Shade Structure
Unit - Location: GLCA - Wahweap
FMSS ID: 228393, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 58.13100000' N 111° 29.93899998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 398

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Sparse fuels and metal structure.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Area Shade Structure #7
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Picnic Area #7, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.85300000' N 111° 29.71600002' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 418

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Picnic Area Shade Structure #4
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Picnic Area #4, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.88199998' N 111° 29.69899998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 422

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Obstacles: Evacuation.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Office Store
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Office Store, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.44399998' N 111° 29.04199998' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 488

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Maintenance Building
Unit - Location: GLCA - Wahweap
FMSS ID: 44403, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.40499998' N 111° 29.44500000' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 449

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Obstacles: Hazmat buildings in back.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Stateline Store Bldg.
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA SL Store Bldg, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.38500002' N 111° 30.09900000' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 382

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the water.







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Swim Beach Microflush #2
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Swim Beach Microflush, ***Local ID:***
Structure Type, Use: Building, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 37° 00.10900002' N 111° 29.69899998' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 421

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: Lake Powell. Treatment: None.
In the sand, sparse fuels.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Navajo Mtn Viewpoint Shade Structure #1
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Navajo Mtn Shade #1, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 57.84700002' N 111° 29.47300002' W


Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 444

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Water Supply: Lake Powell. Treatment: None.
Very sparse fuels and metal structure.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Marina Office Store Storage
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA WW Marina Office Store Storage, ***Local ID:***
Structure Type, Use: No Wildland Risk, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.44500000' N 111° 29.02800000' W


Rating: No Wildland Risk
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 489

Primary Access: Road
Ingress Egress:
Access Width:
Access Condition:
Bridge Condition:
Access and Turnarounds:
Facility Number or Sign:
Fuel Type:
Fuel Load:
Defensible Space:
Topography:
Roof Material:
Siding Material:
Foundation:
Firewood:
Water Supply:
Propane:
Overhead Hazards:

Comments: N/A. Building is on a dock in the middle of the water.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Hazmat Storage
Unit - Location: GLCA - Wahweap
FMSS ID: 44428, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.37199998' N 111° 29.47399998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: yrs
Map Label: 443

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: WW Campground Group Site Shade Structure #6
Unit - Location: GLCA - Wahweap
FMSS ID: GLCA Campground Groupsite #6, ***Local ID:***
Structure Type, Use: Other, Unknown
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.76499998' N 111° 30.03600000' W


Rating: Moderate
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied:
In Community: No,
Revisit Interval: yrs
Map Label: 387

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 31% to 40%
Roof Material: Combustible or no roof
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Treatment: None. Very sparse fuels, mostly cement structures.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: WW Housing #124
Unit - Location: GLCA - Wahweap
FMSS ID: 44570, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: ZION WFM, June 19, 2012
Coordinates (DDM): 36° 59.25499998' N 111° 29.38999998' W

Rating: Low
ProtectionLevel: Undesignated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: yrs
Map Label: 456

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 100 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: Overhead hazards will limit aircraft
Comments: Water Supply: 1.5 million gallon tank.

NO PHOTO AVAILABLE

