



Amoco Sight 8/30/1989: Flatbed on Beach



Amoco Sight 8/30/1989: Pond was pumped, scraped, and is in the process of being covered with fresh sand.



Amoco Sight 8/30/1989: Road 4 of 5.



Amoco Sight 8/30/1989: Road 5 of 5.



Amoco sight 8/30/1989: Bulldozer was evidently used for bringing in the sand and possibly scrapping.



Amoco Sight 8/30/1989: Road 2 of 5.



Amoco Sight 8/30/1989: Road 3 of 5.



Amoco Sight 8/30/1989: They have obviously dug the road deeper using the bulldozer. 1 of 5 in series.



Amoco Sight 8/30/1989.



Amoco Sight 8/30/1989: Not all of the water was pumped from the pond. Scrap marks are evident.



Amoco Sight 8/30/1989: Pipe is no longer draining.