

Field Report

12/12/89

11:35 am

Heavy equipment at end of pavement.

Working for Amoco

Waiting for blue pickup "boss"

Backhoe has already gone down to site.

Jim Pulseys J & L Lease Serv.

Oilfield Services Inc.

Continue to Amoco to check on site.

Backhoe on Beach

11:50

"Fire wall buildup at Amoco"

Site

12:00

No change since November 9

Abalino Tamez, foreman

12:08

R & R Oilfield Service

289 - 2813

May be working 2 days on building
up the fire wall around the tanks.

Pavement -

12:17

Amoco, Rep. - maybe 2 hours or so.

Pit - no diesel has not been used to kill vegetation.

Had a tank that failed and spilled into the pit.

Skrew up on Amoco about having a pit.

The pit is not needed.

Working on getting pit cleaned up ^{to your satisfaction} then want
to cover up the pit.

PAIS & RR Comm. will be notified before this happens

