


INTENSIVE LEVEL SURVEY OF THE CAPITOL VIEW NEIGHBORHOOD: PHASE I



PREPARED BY KRISTIN DYER
DYER NEED FOR PRESERVATION LLC
FOR THE CITY OF OKLAHOMA CITY
APRIL 2021

TABLE OF CONTENTS

TABLE OF FIGURES.....	2
ACKNOWLEDGEMENT OF SUPPORT	3
ABSTRACT	4
INTRODUCTION	5
RESEARCH DESIGN	6
PROJECT OBJECTIVES	6
AREA SURVEYED	7
METHODOLOGY	10
RESULTS AND RECOMMENDATIONS.....	11
NUMBER OF RESOURCES SURVEYED	11
CRITERIA FOR DESIGNATION TO THE NATIONAL REGISTER OF HISTORIC PLACES	11
ARCHITECTURAL STYLES & PROPERTY TYPES.....	12
CONSTRUCTION DATES	18
CURRENT USES.....	19
CAPTIOL VIEW HISTORIC DISTRICT	20
PARK TERRACE HISTORIC DISTRICT	22
INDIVIDUAL PROPERTIES THAT WARRANT FURTHER RESEARCH	24
AREAS EXAMINED THAT DO NOT MEET THE INDIVIDUAL ELIGIBILITY CRITERIA	24
AREAS IDENTIFIED FOR PHASE II.....	59
SUMMARY	1
ANNOTATED BIBLIOGRAPHY	2

COVER: “Capitol Complex, photograph, May 25, 1964,” Oklahoma Historical Society.

TABLE OF FIGURES

Figure 1: Map; Proximity of the Capitol View Neighborhood in Oklahoma City	7
Figure 2: Map; Capitol View Survey Boundary	8
Figure 3: Map; Phase I Survey Boundary	9
Figure 4: 948 Northeast 32nd Street	12
Figure 5: 805 Northeast 24th Street	12
Figure 6: 740 Northeast 29th Street	13
Figure 7: 833 Northeast 24th Street	13
Figure 8: 820 Northeast 31st Street	13
Figure 9: 929 Northeast 29th Street	14
Figure 10: 824-826 Northeast 26th Street	14
Figure 11: 915 Northeast 31st Street	15
Figure 12: 2717 North Kelley Avenue	15
Figure 13: 824 Northeast 29th Street	15
Figure 14: 821 Northeast 31st Street	16
Figure 15: 716-718 Northeast 25th Street	16
Figure 16: 2601 North Phillips Avenue	17
Figure 17: Map; Potential Capitol View Historic District	21
Figure 18: Map; Potential Park Terrace Historic District	23

ACKNOWLEDGEMENT OF SUPPORT

The activity that is the subject of this architectural survey has been financed in part with Federal funds from the National Park Service, U.S. Department of the Interior. However, the contents and opinions do not necessarily reflect the views or policies of the Department of the Interior, nor does the mention of trade names or commercial products constitute endorsement or recommendation by the Department of the Interior.

Nondiscrimination Statement

This program receives Federal financial assistance for identification and protection of historic properties. Under Title VI of the Civil Rights Act of 1964, Section 504 of the Rehabilitation Act of 1973, and the Age Discrimination Act of 1975, as amended, the U.S. Department of the Interior prohibits discrimination on the basis of race, color, national origin, disability, or age in its federally assisted programs. If you believe you have been discriminated against in any program, activity, or facility as described above, or if you desire further information, please write to:

Chief, Office of Equal Opportunity
United States Department of the Interior
National Park Service
1849 C St. NW (0008)
Washington, D.C. 20240

ABSTRACT

The intensive-level survey of the Capitol View Neighborhood in Oklahoma City, Oklahoma was conducted between December 2020-April 2021. The Capitol View neighborhood is located northeast of the Oklahoma State Capitol, and the survey area is an excellent mixture of commercial, religious, educational, and residential buildings. This survey is part of a two-phase process with Phase I conducted during this time. The intent of Phase I was to locate, identify, and record 550 buildings, sites, structures, objects, and districts within the survey boundary and document them at the minimum level. The intensive-level survey consists of the preparation of a Historic Preservation Resource Identification Form, survey maps, and photographs documenting the current condition of each resource. Geographic Information System (GIS) geodatabases were created to assist in the identification and location of historic resources to include addressing, building footprints, and various boundaries. The GIS geodatabases encompass the Phase I and Phase II survey boundaries.

This report includes the findings of Phase I of the intensive-level survey with no supplemental historic context. The Phase I report includes but not limited to architectural styles found, properties individually eligible to the National Register of Historic Places, and any potential historic districts.

INTRODUCTION

The Intensive-Level Survey of the Capitol View Neighborhood covers over 700 properties within its boundary. The first phase of the survey is comprised of 550 properties documented, and the construction of properties range between 1923 to the present. Phase I features various architectural styles, land uses, and development periods.

Previous survey efforts of the Capitol View Neighborhood included the Reconnaissance Survey of Portions of Oklahoma City: Northeast Oklahoma City by the City of Oklahoma City Planning Department in 1994. During the reconnaissance survey, one property and one potential historic district was identified for eligibility to the National Register of Historic Places. The Dewey School located at 3500 Lindsay Avenue was identified. The Bellacasa Terrace/Neff's Capitol was identified as a potential historic district bounded by Northeast 23rd Street, North Phillips Avenue, Northeast 26th Street, and North Laird Avenue. In addition, the Dewey School appears in the Architectural/Historical Survey of Oklahoma City's Historic School Buildings by Jo Meacham Associates in 2001.

The Capitol View Neighborhood was adopted to the Strong Neighborhoods Initiative (SNI) in 2018. The Strong Neighborhoods Initiative assists with revitalizing neighborhoods and creates long-term economic stability by using community engagement, planning practices, and private and public investment. Federal funds from the U.S. Department of Housing and Urban Development are used to make targeted investments with the area. Since its adoption into the SNI, infill development has occurred with four new homes constructed by the Oklahoma City Housing Redevelopment Corporation. The new infill houses feature New Traditional styles that attempt to mirror historic architectural styles.

RESEARCH DESIGN

The Intensive Level Survey of Capitol View – Phase I complies with *National Register Bulletin 24: Guidelines for Local Surveys: A Basis for Preservation Planning* as well as the Oklahoma State Historic Preservation Office’s (SHPO) “Oklahoma Architectural/Historic Survey Requirements” and “Architectural/Historic Resource Survey: A Field Guide.” The purpose of the survey is to locate, identify, and record 550 buildings, sites, structures, objects, and districts within the survey boundary and document them at the minimum level. Each resource identified was evaluated for eligibility for the National Register of Historic Places. All documentation is recorded on the “Historic Preservation Resource Identification Form” provided by the SHPO and two accompanying photographs. An overall map with building footprints, addresses, and National Register evaluations have been provided identifying each property surveyed during Phase I.

Architectural styles will be selected based on “National Register Data Categories for Architectural Classification” in *National Register Bulletin 16A: How to Complete the National Register Form*. Residential architectural styles were derived from *A Field Guide to American Houses* by Virginia Lee McAlester, and the majority of commercial architectural styles were derived from *The Buildings of Main Street: A Guide to American Commercial Architecture* by Richard Longstreth.

PROJECT OBJECTIVES

The goals for the preparation of the Intensive Level Survey of Capitol View – Phase 1 in Oklahoma City, Oklahoma:

- Identify and record each property on the Historic Resource Form provided by the Oklahoma State Historic Preservation Office (SHPO); and
- Assess each resource’s potential eligibility for individual listing on the National Register of Historic Places.

AREA SURVEYED

The entire survey area of the Intensive Level Survey of Capitol View encompasses approximately 269.6 acres, and it is roughly bounded by North Lincoln Boulevard to the west, Northeast 36th Street to the north, and North Kelley Avenue to the east. The south boundary line is described as proceeding west along Northeast 23rd Street then north along North Laird Avenue then west along Northeast 24th Street then north along North Lindsay Avenue then west along Northeast 28th Street to North Lincoln Boulevard.

Phase I of the Intensive Level Survey of Capitol View is approximately 202 acres of the overall 269.6 acres. The Capitol View survey area is located northeast to the Oklahoma State Capitol (NRIS 76001572). Within the survey area, 550 resources were surveyed. The area is predominantly residential with commercial buildings located along the outer edges of the survey boundary. Residential buildings are found throughout the interior as well as religious uses dispersed throughout the area and along the eastern boundary line. There are approximately 173 resources remaining to survey for Phase II.




FIGURE 1: MAP; PROXIMITY OF THE CAPITOL VIEW NEIGHBORHOOD IN OKLAHOMA CITY



CAPITOL VIEW SURVEY BOUNDARY

LEGEND


 Survey Boundary

0 500 1,000 1,500 ft



Source: Google Earth; United States Census Bureau; OKMaps Oklahoma; QGIS

FIGURE 2: MAP; CAPITOL VIEW SURVEY BOUNDARY



LEGEND

- Survey Boundary
- PHASE I BOUNDARY
- PHASE II
- Building Footprints

CAPITOL VIEW PHASE I SURVEY BOUNDARY

0 750 1,500 ft

Source: Google Earth; United States Census Bureau; OKMaps Oklahoma; QGIS

FIGURE 3: MAP; PHASE I SURVEY BOUNDARY

METHODOLOGY

Initial preparation for fieldwork included creating a database of all the properties within the entire survey boundary as well as a geodatabase to track properties surveyed during Phase I. This allowed a catalog of properties that need to be surveyed during Phase II. The City of Oklahoma City Interactive GIS and Zoning Land Use as well as the Oklahoma County Assessor provided information regarding current addresses and legal descriptions. The Oklahoma Office of Geographic Information's "OK Maps" provide geographic information including municipal city limits, and most building footprints. Building footprints were created for properties that did have one, and others updated to reflect the current aerial imagery as needed. The United State Census Bureau's Geography Program provided GIS data for city streets and major highways.

The Oklahoma Historical Aerial Digitization Project's ArcGIS interactive map provided access to historic aerial imagery. Oklahoma State Department of Libraries, Oklahoma Geological Survey, and Oklahoma State University provided additional aerial imagery. Other online repositories provided access to city directories and Sanborn Fire Insurance Maps. Architecture literature included *A Field Guide to American Houses* by Virginia Savage McAlester, *The Buildings of Main Street* by Richard Longstreth, Building Heritage Technology online repository,

Fieldwork was conducted between December 11-13, 2020. For Phase I, 550 buildings, sites, structures, and objects appearing to be constructed within the survey boundary were photographed at that time. The location of each property within the survey area is indicated on a map showing the boundary line of the survey area and building footprint. A separate map was created to identify any potential historic districts including the contributing status of each property. For properties not surveyed during Phase I, "TBD" has been annotated on maps.

RESULTS AND RECOMMENDATIONS

NUMBER OF RESOURCES SURVEYED

Within the survey boundary, 550 properties were surveyed. This included one site and 549 buildings. Buildings in the survey area included one to two-story commercial businesses, religious uses, single-family dwellings, multi-family dwellings, warehouses, government offices, and a processing site. There are no buildings previously listed on the National Register of Historic Places.

CRITERIA FOR DESIGNATION TO THE NATIONAL REGISTER OF HISTORIC PLACES

All properties within the Phase I survey boundary were considered for designation in the National Register of Historic Places. This includes listing as an individual property, potential historic district, or combination thereof.

The quality of significance in American history, architecture, archeology, engineering, and culture is present in districts, sites, buildings, structures, and objects that possess integrity of location, design, setting, materials, workmanship, feeling, and association, and:

- A. That are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. That are associated with the lives of persons significant in our past; or
- C. That embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
- D. That have yielded, or may be likely to yield, information important to prehistory or history.

Additionally, a property must have sufficient integrity to convey its significance. According to National Register Bulletin 15, the seven aspects of integrity are as follows:

- Location
- Design
- Setting
- Materials
- Workmanship
- Feeling
- Association

ARCHITECTURAL STYLES & PROPERTY TYPES

Colonial Revival/Dutch Colonial

The Colonial Revival house was the dominant architectural style during the early 20th century, and its popularity increased during the 1910-1930s.

“Colonial Revival” is in reference to the renewed interest in English and Dutch-style houses on the Atlantic Seaboard. Early versions of the Colonial Revival were a series of interpretations of earlier Georgian and Adam styles, and the popularity never faded. As time progressed, forms became simplified or characteristics were incorporated into other architectural styles such as the ranch house. Colonial Revival houses featured characteristics such as multi-light double-hung sashes, accentuated front door, and centered entry or full-width porches. In the survey area, there are 12 examples of Colonial Revival houses and were constructed between 1929-1940. **948 Northeast 32nd Street** is the only example of the Dutch Colonial variation with its side-gabled gambrel roof.



FIGURE 4: 948 NORTHEAST 32ND STREET

Tudor Revival

The Tudor Revival is a loose representation of late Medieval and early Renaissance examples that began in the 1850s in England. Early examples of Tudor Revival architecture in the United States can be dated back to the late 19th century in grandiose examples. The style reached a peak in popularity in the 1920s when brick masonry techniques allowed modest houses to mirror distinct masonry applications to their English prototypes.

The Tudor Revival houses were notable for their asymmetrical design, steeply pitched front facing gables, multiple gables, decorative brickwork, massive chimneys, and half-timbering. In the survey area, there are 37 examples of Tudor Revival houses constructed between 1929 and 1949. The majority of Tudor Revivals are constructed between Northeast 24th Street and Northeast 29th Street. Constructed in 1932, **805 Northeast 24th Street** features a Tudor Revival used as a duplex with separate covered entrances on the façade.



FIGURE 5: 805 NORTHEAST 24TH STREET

Bungalow/Craftsman

The origins of the Bungalow/Craftsman originated with brothers, Charles Sumner Greene and Henry Mather Greene, in California during the early 1900s. The popularity spread across the country with their design publicized in magazines such as *House Beautiful* and *Good Housekeeping* as well as their “ready-to-build” kits that could be ordered and built by local builders. Defining characteristics of the Bungalow/Craftsman include the low-pitched gable roof, roof rafters, open porches with tapered or square columns, and decorative roof beam or brackets.

There are 28 examples of Bungalow/Craftsman in the survey area constructed primarily in the 1920s and 1930s. Some appeared to be moved to the survey based on aerial imagery. **740 Northeast 29th Street**



FIGURE 6: 740 NORTHEAST 29TH STREET

Moderne

The Moderne house was used in residential architecture after 1930. Modernistic architecture became popular during the Arts Décoratifs et Industriels Moderne in 1925, and after the 1930s modernistic building became streamlined to reflect the industrial design for ships, vehicles, and airplanes. Moderne houses features smooth wall surfaces, flat roofs, horizontal grooves or lines, and one or more curved corners. The Moderne house may incorporate glass block and continuous windows around corners.



FIGURE 7: 833 NORTHEAST 24TH STREET

Minimal Traditional

The Minimal Traditional style house was the popular architectural style since it was capable of being built quickly, and it could be financed with FHA-insured loans. The minimal traditional house was able to be built quickly due to its simple form, and builders could abandon any excess forms including unnecessary gables, dormers, breaks in the roof form and wide eaves. These houses were often constructed during the Great Depression as an affordable house as well as used



FIGURE 8: 820 NORTHEAST 31ST STREET

during and after World War II to quickly relocate production workers during the war and for returning service members after the war. Minimal Traditional houses were generally one-story with wood siding, detached garages, and minimal or no eave overhang. In the survey area, there are 75 examples of the minimal traditional houses constructed between 1927 through the 1963. The minimal traditional houses are dispersed throughout the survey area the majority constructed between Northeast 28th Street through Northeast 34th Street. **820 Northeast 31st Street** is an excellent example of a Minimal Traditional house with an attached garage. **804 Northeast 28th Street** is an excellent example of a Minimal Traditional house with Tudor Revival characteristics with an asymmetrical gable-end, arched entry, and an exterior façade chimney.

Ranch/Stylized Ranch

The Ranch style became the popular style of residential architecture in the 1950s and 1960s. The ranch house origins can be traced to Frank Lloyd Wright's Prairie Style and Cliff May's California ranch house designs. Ranch houses were designed with open floor plans, low-pitched roofs and integrated into the landscape. They were made possible with the rise of the automobile since ranch houses were typically on larger lots in suburbs further away from downtown and commercial corridors. Other details include the broad one-story houses with asymmetrical shapes, low-pitched roofs,

one or more types of siding used, picture windows, and integrated garages. Ranch houses that have additional ornamentation from Spanish, Colonial Revival, Neoclassical French, Tudor, or Storybook styles are commonly known as "Stylized Ranch." The Stylized Ranch incorporates the detailing without losing the ranch form. There are 315 examples of Ranch houses within the survey area constructed predominantly between the 1950s - 1970s. Several ranch houses within the survey area feature enclosed garage with windows or doors and have carports. **925 Northeast 29th Street** is an example of an incompatible attached carport located on the front, and **929 Northeast 29th Street** is an example of an attached carport that mirrors character-defining features of the original house.

Contemporary

The Contemporary style is designed from the inside-outside with more attention drawn into the interior spaces rather than the exterior. The exterior features little to no ornamentation with broad expanses of uninterrupted walls with ornamentation derived from decorative brick courses, concrete wall shields, and wall color. Contemporary houses feature details such as low-pitched gabled roofs, wide eave overhangs, exposed roof or eave



FIGURE 9: 929 NORTHEAST 29TH STREET



FIGURE 10: 824-826 NORTHEAST 26TH STREET

beams, and large rear-facing or shielded windows. They are built with a variety of materials including wood, stone, or brick, and feature recessed doors not visible from the street. There are 10 examples of Contemporary style houses within the survey area constructed predominantly between the 1950s - 1970s. Constructed in c. 1963, **824-826 Northeast 26th Street** is a contemporary-style duplex with a deep recessed carport under the wide hipped gable-end.

Split-Level

The Split-Level is known as a form of a structure that mirrors the architectural details of Ranch, Stylized Ranch, and Contemporary Styles. It modifies these one-story architectural styles by creating a second-story use by splitting the one-story in mid-height to create two wings or by integrating the garage into the landscape with the living area on the second story. The three separate levels create a staggered and separated space. The Split-Level became popular for sloped grades by tucking the garage under the house or by separating noisy spaces from quiet spaces. There is one example of a Split-Level house, **915 Northeast 31st Street**, constructed in 1955.



FIGURE 11: 915 NORTHEAST 31ST STREET

Modern Movement

The Modern Movement categorizes structures that express modernism; however, they do not display any emphasis on other modern movement styles such as ranch or contemporary for residential houses or the International Style and New Formalism styles for commercial buildings. The Modern Movement buildings feature minimal detailing and are constructed of brick, concrete, metals, wood, stone, or any combination thereof. In the survey area, there are 43 examples of modern movement buildings constructed between through the 1950s until the 1980s. Many of the churches in the survey area were constructed in the modern movement style such as **2717 North Kelley Avenue** and **2701 North Kelley Avenue**.



FIGURE 12: 2717 NORTH KELLEY AVENUE

Millennium Mansion

Millennium Mansions are typically found within larger subdivisions but have been used for infill development in older neighborhoods. The massing of the millennium mansion allows for taller interior ceiling heights, more square footage, and feature multiple sidings. According to *A Field Guide to American Houses*, that after decades of low, broad houses, the millennium mansion roofs, "...added more complexity, as if to



FIGURE 13: 824 NORTHEAST 29TH STREET

celebrate the new millennium with still more drama.” Notable features of the millennium mansion includes complex roof systems with lower cross gable or hips, tall entries, arched entrances, and various window designs. The only example of a millennium mansion is located at **824 Northeast 29th Street**, which features a complex roof system and arched entry.

New Traditional

New Traditional buildings are based on popular architectural style houses from the early 20th century. The new traditional house roots began as early as the 1970s when there was a renewed interest in historical styles. Early houses were awkwardly portioned to their historic examples until the 1990s when portions, detailing, and design mirrored the historic character-defining massing and features. New traditional commercial buildings found are typically massive with large entrances. There are eight examples of New Traditional house in

Phase I with all being constructed since 2005. **821 Northeast 31st Street** features characteristics of a Bungalow/Craftsman with exposed rater tails and jailhouse-style windows. **945 Northeast 29th Street** features characteristic of an American Foursquare with its square footprint and full-width porch.



FIGURE 14: 821 NORTHEAST 31ST STREET

Commercial

Commercial-style architecture found within the survey area includes eight multi-family buildings, one commercial business, and one school. This includes variation of one-part commercial block featuring a one-story building with simple brick detailing and glass windows. The other common commercial type is the two-part commercial block, which is typically two-stories with a horizontal division between the first-story and the upper stories. All of the commercial-style buildings found in Phase I feature two-stories except **3631 North Kelley Avenue**. The largest concentration of commercial-style buildings are found along **700 block of Northeast 25th Street** with a series of multi-family buildings.



FIGURE 15: 716-718 NORTHEAST 25TH STREET

Multi-Family Residential

There are 33 multi-family buildings and apartment complexes found within the survey area. They were constructed between 1932-1986. The buildings range from duplexes that blend into single-family neighborhoods by featuring architectural styles of the surrounding houses. Other apartment buildings are monolithic in design and range between one to two stories. These buildings feature



FIGURE 16: 2601 NORTH PHILLIPS AVENUE

long rectangular footprints either directly facing the street or perpendicular to the street. Apartment buildings are typically box-like in design, wood-frame with various veneers, exterior or interior stairwells, and may have off-street parking. Apartment buildings also feature balconies or walk-out landings like 2601 North Phillips Avenue and 2700 North Lindsay Avenue.

ARCHITECTURAL STYLES

STYLE	TOTAL	PERCENTAGE
NO DISTINCTIVE STYLE	2	0.4%
COLONIAL REVIVAL	11	2.0%
DUTCH COLONIAL	1	0.2%
TUDOR REVIVAL	37	6.7%
BUNAGLOW/CRAFTSMAN	29	5.1%
MODERNE	1	0.2%
MINIMAL TRADITIONAL	75	13.6%
RANCH	310	56.4%
STYLIZED RANCH	5	0.9%
CONTEMPORARY	10	1.8%
SPLIT LEVEL	1	0.2%
MODERN MOVEMENT	42	7.8%
MILLENNIUM MANSION	1	0.2%
NEW TRADITIONAL	8	1.5%
COMMERCIAL STYLE	8	1.5%
NATIONAL FOLK	1	0.2%
OTHER	7	1.3%
MIXED	1	0.2%
TOTAL	550	100.0%

CONSTRUCTION DATES

The approximate date of construction within the survey area begins in 1923 with a National Folk-style house at 644 Northeast 30th Street. The last building was under construction in December 2020 at 644 Northeast 28th Street. Based on the pattern of Phase I surveyed properties, the earliest properties were constructed along the southern boundary and later properties constructed as development continued north. The trend of construction created a pyramid of development growing from 1920s with 7.3%, peaked in the 1950s with 47.8%, and declined through the 1980s to 2.4%. No properties were constructed during the 1990s as part of Phase I. During the 2000s to the present, infill commercial development has occurred along the western and southern edges of the boundary and residential infill development throughout the interior of the survey area.

CONSTRUCTION DATE RANGES

YEAR RANGE	PROPERTIES	TOTAL %
PRE-1900	0	0.0%
1900-1910	0	0.0%
1911-1920	0	0.0%
1921-1930	40	7.3%
1931-1940	61	11.1%
1941-1950	76	13.8%
1951-1960	263	47.8%
1961-1970	57	10.4%
1971-1980	26	4.7%
1981-1990	13	2.4%
1991-2000	0	0.0%
2001-2010	6	1.1%
2011-2021	7	1.3%
NA	1	0.2%
	550	100.00%

CURRENT USES

The most prevalent use within the survey area are single-family dwellings with 88.2% followed by multi-family dwellings with 6.0%. Other uses found included professional office, government offices, religious buildings, and financial institutions. Most non-residential uses are found on the outer edges of the survey boundary and with residential uses found within the interior of the survey area.

CURRENT USES

SUBCATEGORY	PROPERTIES	TOTAL %
SINGLE DWELLING	485	88.2%
MULTIPLE DWELLING	33	6.0%
BUSINESS	1	0.2%
PROFESSIONAL	2	0.4%
FINANCIAL INSTITUTION	2	0.4%
RESTAURANT	1	0.2%
GOVERNMENT OFFICE	3	0.5%
SCHOOL	1	0.2%
RELIGIOUS STRUCTURE	9	1.6%
MORTUARY	1	0.2%
PROCESSING SITE	1	0.2%
VACANT/NOT IN USE	11	2.0%
TOTAL	550	100.0%

CAPITOL VIEW HISTORIC DISTRICT

The Capitol View Historic District is eligible for listing in the National Register of Historic Places for local significance under Criterion A in the area of Community Planning and Development as a residential area that was developed during the end of the 19th Century through 1970. The potential historic district is roughly bounded by North Laird Avenue to the east, Northeast 24th Street to the south, North Lindsay Avenue to the west, which follow North Phillips Street to Northeast 27th Street to the north. Within the boundary, there are 87 primary buildings and one site. During Phase I of the survey, 62 properties were found to retain sufficient integrity to be contributing, and there are 16 properties that are non-contributing. The remaining ten properties are to be determined during Phase II to evaluate their integrity as part of the potential historic district.

The period of significance is between 1929-1975. The area was primarily developed during the first half of the 20th century with popular architecture styles such as Tudor Revival, Bungalow/Craftsman, Colonial Revival, and Minimal Traditional. There are over 30 examples of Tudor Revival houses displaying various siding materials and methods of construction. During the period of significance, the historic district saw the discovery of oil northeast of the State Capitol Building in the 1930s, and oil wells were frequent within the historic district and surrounding areas. The trolley and streetcar line ran north and south along North Phillips Avenue, which encouraged prospective homeowners to build within the area. The Oklahoma City streetcar line lost its popularity with the rise of the automobile, and several houses would feature a detached garage as early as 1932. In addition, the potential Capitol View Historic District displays the evolution of multi-family housing within the neighborhood with multiple duplexes in various architectural styles, commercial-style brick-box apartments, and modern movement apartment complexes. The potential Capitol View Historic District is an excellent representation of the changing use of the neighborhood northeast of the Oklahoma State Capitol Building.



POTENTIAL CAPITOL VIEW HISTORIC DISTRICT

LEGEND

CAPITOL VIEW BOUNDARY

National Register Evaluation

● CONTRIBUTING

● NON-CONTRIBUTING

○ TBD

Building Footprints

0 100 200 ft




Source: Google Earth; United States Census Bureau; OKMaps Oklahoma; QGIS

FIGURE 17: MAP; POTENTIAL CAPITOL VIEW HISTORIC DISTRICT

PARK TERRACE HISTORIC DISTRICT

The Park Terrace Historic District is eligible for listing in the National Register of Historic Places for local significance under Criterion A in the area of Community Planning and Development as a residential area that was developed during the 1950s and 1960s. The historic district boundary encompasses the entire Park Terrace Addition as well as a few houses along Springlake Drive and East Hill Street that complement the development and match the architectural styles. The potential historic district is roughly bounded by North Phillips Avenue to the west, Northeast 36th Street to the north, and North Kelley Avenue to the east. The south boundary line is described as proceeding west along Northeast 34th Street, then south along Mildred Avenue, then west along East Hill Street, then southeast along North Laird Avenue, then west along Northeast 32nd Street to North Phillips Avenue.

Within the boundary, there are 147 primary buildings. During Phase I of the survey, 62 properties were found to retain sufficient integrity to be contributing, and there are 30 properties that are non-contributing. The remaining 55 properties are to be determined during Phase II to evaluate their integrity as part of the potential historic district. The residential area was primarily developed during the 1950s and 1960s with ranch style houses and few commercial businesses. The development strayed from the traditional grid system by using the existing topography and roads to create the Park Terrace neighborhood. The period of significance begins in 1954 with the first wave of construction up to 1975 when construction waned.



POTENTIAL PARK TERRACE HISTORIC DISTRICT

LEGEND

PARK TERRACE BOUNDARY

Building Footprints

National Register Evaluation

● CONTRIBUTING

● NON-CONTRIBUTING

○ TBD

0 150 300 450 ft



Source: Google Earth; United States Census Bureau; OKMaps Oklahoma; QGIS

FIGURE 18: MAP; POTENTIAL PARK TERRACE HISTORIC DISTRICT

INDIVIDUAL PROPERTIES THAT WARRANT FURTHER RESEARCH

Dewey Elementary School
Criterion A - Education / Criterion C - Architecture

3500 North Lindsay Avenue

Liberty Station Apartments
Criterion A - Community Planning and Development / Criterion C - Architecture

2700 North Lindsay Avenue

North Phillips Apartment Buildings
Criterion A - Community Planning and Development / Criterion C - Architecture

2601 North Phillips Avenue

Trenton Townhomes
Criterion A - Community Planning and Development / Criterion C - Architecture

700-702 Northeast 26th Street

AREAS EXAMINED THAT DO NOT MEET THE INDIVIDUAL ELIGIBILITY CRITERIA

The following properties do not warrant further review for individual eligibility to the National Register of Historic Places.

ADDRESS		ELIGIBILITY
624	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
628	EAST HILL STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
631	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
632	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
636	EAST HILL STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

640	EAST HILL STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
700	EAST HILL STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
721	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
910	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
915	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
935	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
936	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
940	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
944	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
948	EAST HILL STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
950	EAST HILL STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.

2701	NORTH KELLEY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
2717	NORTH KELLEY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
2801	NORTH KELLEY AVENUE	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
3117	NORTH KELLEY AVENUE (CHURCH)	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3117	NORTH KELLEY AVENUE (FELLOWSHIP HALL)	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
3309	NORTH KELLEY AVENUE	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
2708	NORTH LAIRD AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
2712	NORTH LAIRD AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3001	NORTH LAIRD AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3101	NORTH LAIRD AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3107	NORTH LAIRD AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.

3112	NORTH LAIRD AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
3113	NORTH LAIRD AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3116	NORTH LAIRD AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
3119	NORTH LAIRD AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING, FENESTRATION, AND NON-HISTORIC ADDITIONS THAT DETRACT FROM THE HISTORIC STRUCTURE
3212	NORTH LAIRD AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3300	NORTH LAIRD AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
3310	NORTH LAIRD AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACT FROM THE HISTORIC BUILDING.
2900	NORTH LINCOLN BOULEVARD	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
3330	NORTH LINCOLN BOULEVARD	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
3400	NORTH LINCOLN BOULEVARD	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
2612	NORTH LINDSAY AVENUE	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

2700-C	NORTH LINDSAY AVENUE	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
3000	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3006	NORTH LINDSAY AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
3012	NORTH LINDSAY AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO NON-HISTORIC ADDITIONS THAT DETRACT FROM THE HISTORIC STRUCTURE.
3105	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3109	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3113	NORTH LINDSAY AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
3117	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3121	NORTH LINDSAY AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
3201	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3204	NORTH LINDSAY AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

3205	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3209	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3213	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3217	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3301	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3304	NORTH LINDSAY AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
3308	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3321	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3340	NORTH LINDSAY AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3400	MILDRED AVENUE	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
3426	MILDRED AVENUE	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.

2915	NORTH PHILLIPS AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
3011	NORTH PHILLIPS AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
3013	NORTH PHILLIPS AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3121	NORTH PHILLIPS AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
3201	NORTH PHILLIPS AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
3221	NORTH PHILLIPS AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3315	NORTH PHILLIPS AVENUE	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
3408	NORTH PHILLIPS AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
3415	NORTH PHILLIPS AVENUE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
801	NORTHEAST 24TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
724	NORTHEAST 26TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

801	NORTHEAST 26TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS AND NON-HISTORIC ADDITION THAT DETRACTS FROM THE HISTORIC STRUCTURE.
817	NORTHEAST 26TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT DUE TO NON-HISTORIC ADDITIONS THAT DETRACT FROM THE HISTORIC STRUCTURE.
821	NORTHEAST 26TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
905	NORTHEAST 26TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT SINCE IT IS LESS THAN 50 YEARS OLD.
909	NORTHEAST 26TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT SINCE IT IS LESS THAN 50 YEARS OLD.
913	NORTHEAST 26TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT SINCE IT IS LESS THAN 50 YEARS OLD.
917	NORTHEAST 26TH STREET	THIS BUILDING DOES NOT CONTRIBUTE TO THE CAPITOL VIEW HISTORIC DISTRICT SINCE IT IS LESS THAN 50 YEARS OLD.
800	NORTHEAST 27TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
629	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
645	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
701	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

709	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO BOARDED FENESTRATION AND UNABLE TO VERIFY HISTORIC MATERIALS
713	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION AND NON-HISTORIC PORCH.
715	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
719	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
729	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
800	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
801	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
804	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
805	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
808	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
809	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

812	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
816	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
817	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
820	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
821	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
824	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
825	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
828	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
829	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
832	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
833	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

836	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
837	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
840	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
841	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
844	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
845	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
900	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
901	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
904	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
905	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
908	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

909	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
912	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
913	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
916	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
920	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
933	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
937	NORTHEAST 28TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO A NON-HISTORIC CARPORT AND ENCLOSURE OF THE GARAGE THAT DETRACT FROM THE HISTORIC STRUCTURE.
941	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
945	NORTHEAST 28TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
615	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
617	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

619	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
628	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
632	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
636	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
637	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
641	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING BOARDED WINDOWS TO VERIFY HISTORIC MATERIALS.
645-B	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
645	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
704	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
705	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
709	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

712	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
713	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
716	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
717	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
720	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSURE OF THE ATTACHED GARAGE
721	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING THAT DETRACT FROM THE HISTORIC BUILDING.
725	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
729	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
732	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
733	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
737	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO BOARDED FENESTRATION AND UNABLE TO VERIFY HISTORIC MATERIALS

738	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
740	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
743	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
800	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
801	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
804	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
805	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
808	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
812	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
813	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
816	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

817	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
821	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
824	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
825	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
829	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
832	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
833	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
836	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
837	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
840	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
841	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.

844	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
901	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
905	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
909	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
913	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
916	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
917	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
921	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE S FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
922	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
925	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION, AND NON-HISTORIC CARPORT THAT DETRACTS FROM THE HISTORIC STRUCTURE.
929	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO NON-HISTORIC CARPORT THAT DETRACT FROM THE HISTORIC STRUCTURE.

933	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
936	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
937	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
941	NORTHEAST 29TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
945	NORTHEAST 29TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
632	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
635	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
636	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
640	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
644	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
701	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

705	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
709	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
712	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
713	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
717	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
720	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
721	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
724	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
725	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
728	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
729	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

732	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
733	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
736	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
737	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
740	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
741	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
744	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION.
745	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
800	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
801	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
804	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO NON-HISTORIC CARPORT AND ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACT FROM THE HISTORIC STRUCTURE.

805	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
808	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
809	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
812	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
813	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
817	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
820	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
821	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
824	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
825	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
829	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

830	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
832	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
833	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
836	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSING THE ORIGINAL CARPORT WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
840	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
901	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
904	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
905	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
908	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE
912	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
913	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.

920	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
925	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
928	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
929	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
934	NORTHEAST 30TH STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
936	NORTHEAST 30TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
700	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
704	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
705	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
708	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
709	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

712	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
713	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
716	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE PORCH WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
717	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
720	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
721	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
724	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
725	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
728	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
729	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
732	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

733	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
736	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
737	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
740	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
741	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
800	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
801	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
804	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
805	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
808	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
809	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

812	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
816	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
817	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
820	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
821	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
824	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
828	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE.
832	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION.
833	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING, FENESTRATION, AND NON-HISTORIC ADDITIONS THAT DETRACT FROM THE HISTORIC STRUCTURE
837	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
908	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

909	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
912	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
914	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
915	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
916	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
921	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
924	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
925	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
929	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
931	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
937	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING, FENESTRATION, AND NON-HISTORIC ADDITIONS THAT DETRACT FROM THE HISTORIC STRUCTURE.

941	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
945-B	NORTHEAST 31ST STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING, FENESTRATION, AND NON-HISTORIC ADDITIONS THAT DETRACT FROM THE HISTORIC STRUCTURE.
945	NORTHEAST 31ST STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
625	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
629	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
633	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
637	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
641	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
700	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
704	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
708	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

712	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION AND CARPORT ADDITION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
713	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
716	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
717	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
720	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
721	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
724	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
725	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
728	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
729	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
732	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION, A NON-HISTORIC FRONT ADDITIONS AND INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

733	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
736	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
737	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
740	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
741	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
800	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
804	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
808	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
812	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
816	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.
820	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE SINCE IT IS LESS THAN 50 YEARS OLD.

900	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
901	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
905	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
906	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
909	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
910	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
913	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
916	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
920	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
921	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
924	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.

928	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
929	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
931	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
932	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
933	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
936	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
937	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
940	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
941	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
944	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
945	NORTHEAST 32ND STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

948	NORTHEAST 32ND STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
629	NORTHEAST 33RD STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION, NON-HISTORIC CARPORT, AND ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
633	NORTHEAST 33RD STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
637	NORTHEAST 33RD STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
641	NORTHEAST 33RD STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
645	NORTHEAST 33RD STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
621	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
625	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
628	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING WITH NON-HISTORIC MATERIALS AND A NON-HISTORIC CARPORT THAT DETRACTS FROM THE HISTORIC STRUCTURE.
629	NORTHEAST 34TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
632	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS AND A NON-HISTORIC CARPORT THAT DETRACTS FROM THE HISTORIC STRUCTURE.

633	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
636	NORTHEAST 34TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
637	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
640	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING WITH NON-HISTORIC MATERIALS AND A NON-HISTORIC CARPORT THAT DETRACTS FROM THE HISTORIC STRUCTURE.
641	NORTHEAST 34TH STREET	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
644	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
645	NORTHEAST 34TH STREET	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
700	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
701	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
704	NORTHEAST 34TH TERRACE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
705	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

708	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
709	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
712	NORTHEAST 34TH TERRACE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
713	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION, ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS, AND NON-HISTORIC CARPORT THAT DETRACTS FROM THE HISTORIC STRUCTURE.
716	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
717	NORTHEAST 34TH TERRACE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
720	NORTHEAST 34TH TERRACE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
722	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
725	NORTHEAST 34TH TERRACE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
728	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
729	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

733	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
736	NORTHEAST 34TH TERRACE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
737	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.
740	NORTHEAST 34TH TERRACE	WHILE THIS BUILDING HAS SUFFICIENT INTEGRITY, IT IS NOT INDIVIDUALLY ELIGIBLE, IN ADDITION THERE IS NOT ENOUGH SURROUNDING HISTORIC RESOURCES WITH INTEGRITY TO WARRANT A HISTORIC DISTRICT.
741	NORTHEAST 34TH TERRACE	THIS BUILDING IS NOT ELIGIBLE DUE TO ALTERATIONS TO THE SIDING AND FENESTRATION INCLUDING ENCLOSING THE GARAGE WITH NON-HISTORIC MATERIALS THAT DETRACTS FROM THE HISTORIC STRUCTURE.

AREAS IDENTIFIED FOR PHASE II

The following properties were not surveyed during part of the Phase II survey. The following list is to provide an approximate number of properties and their locations for the Intensive Level Survey of Capitol View Phase II. This has not been field-checked for the construction or demolition of properties.

PHASE II PROPERTIES			
NUMBER	CITY STREET		
621	EAST EUBANKS STREET	704	EAST EUBANKS STREET
701	EAST EUBANKS STREET	708	EAST EUBANKS STREET
705	EAST EUBANKS STREET	709	EAST EUBANKS STREET
713	EAST EUBANKS STREET	712	EAST EUBANKS STREET
717	EAST EUBANKS STREET	716	EAST EUBANKS STREET
608	EAST EUBANKS STREET	720	EAST EUBANKS STREET
624	EAST EUBANKS STREET	721	EAST EUBANKS STREET
628	EAST EUBANKS STREET	724	EAST EUBANKS STREET
632	EAST EUBANKS STREET	725	EAST EUBANKS STREET
636	EAST EUBANKS STREET	728	EAST EUBANKS STREET
637	EAST EUBANKS STREET	729	EAST EUBANKS STREET
640	EAST EUBANKS STREET	732	EAST EUBANKS STREET
641	EAST EUBANKS STREET	733	EAST EUBANKS STREET
644	EAST EUBANKS STREET	736	EAST EUBANKS STREET
645	EAST EUBANKS STREET	737	EAST EUBANKS STREET
700	EAST EUBANKS STREET	740	EAST EUBANKS STREET
		744	EAST EUBANKS STREET
		800	EAST EUBANKS STREET

801	EAST EUBANKS STREET
804	EAST EUBANKS STREET
805	EAST EUBANKS STREET
808	EAST EUBANKS STREET
812	EAST EUBANKS STREET
813	EAST EUBANKS STREET
816	EAST EUBANKS STREET
817	EAST EUBANKS STREET
820	EAST EUBANKS STREET
824	EAST EUBANKS STREET
825	EAST EUBANKS STREET
828	EAST EUBANKS STREET
829	EAST EUBANKS STREET
832	EAST EUBANKS STREET
833	EAST EUBANKS STREET
836	EAST EUBANKS STREET
839	EAST EUBANKS STREET
3500	LINCOLN BOULEVARD
806	MARILYN STREET
810	MARILYN STREET
811	MARILYN STREET
814	MARILYN STREET
815	MARILYN STREET
818	MARILYN STREET
821	MARILYN STREET
822	MARILYN STREET
826	MARILYN STREET
830	MARILYN STREET
831	MARILYN STREET
834	MARILYN STREET
835	MARILYN STREET
838	MARILYN STREET
842	MARILYN STREET
2409	NORTH KELLEY AVENUE
3600	NORTH LAIRD AVENUE
3604	NORTH LAIRD AVENUE
3605	NORTH LAIRD AVENUE
3608	NORTH LAIRD AVENUE
3609	NORTH LAIRD AVENUE
3624	NORTH LAIRD AVENUE
3625	NORTH LAIRD AVENUE
3629	NORTH LAIRD AVENUE
3632	NORTH LAIRD AVENUE
3628	NORTH LINCOLN BOULEVARD

3408	NORTH PHILLIPS AVENUE
3508	NORTH PHILLIPS AVENUE
3514	NORTH PHILLIPS AVENUE
3518	NORTH PHILLIPS AVENUE
3522	NORTH PHILLIPS AVENUE
3601	NORTH PHILLIPS AVENUE
3637	NORTH PHILLIPS AVENUE
921	NORTHEAST 23RD STREET
801	NORTHEAST 27TH STREET
806	NORTHEAST 27TH STREET
808	NORTHEAST 27TH STREET
812	NORTHEAST 27TH STREET
819	NORTHEAST 27TH STREET
822	NORTHEAST 27TH STREET
825	NORTHEAST 27TH STREET
826	NORTHEAST 27TH STREET
828	NORTHEAST 27TH STREET
829	NORTHEAST 27TH STREET
832	NORTHEAST 27TH STREET
836	NORTHEAST 27TH STREET
840	NORTHEAST 27TH STREET
844	NORTHEAST 27TH STREET
847	NORTHEAST 27TH STREET
901	NORTHEAST 27TH STREET
904	NORTHEAST 27TH STREET
905	NORTHEAST 27TH STREET
908	NORTHEAST 27TH STREET
909	NORTHEAST 27TH STREET
912	NORTHEAST 27TH STREET
916	NORTHEAST 27TH STREET
917	NORTHEAST 27TH STREET
920	NORTHEAST 27TH STREET
921	NORTHEAST 27TH STREET
620	NORTHEAST 35TH STREET
621	NORTHEAST 35TH STREET
624	NORTHEAST 35TH STREET
625	NORTHEAST 35TH STREET
628	NORTHEAST 35TH STREET
632	NORTHEAST 35TH STREET
633	NORTHEAST 35TH STREET
636	NORTHEAST 35TH STREET
640	NORTHEAST 35TH STREET
641	NORTHEAST 35TH STREET
644	NORTHEAST 35TH STREET

645	NORTHEAST 35TH STREET
701	NORTHEAST 35TH STREET
705	NORTHEAST 35TH STREET
707	NORTHEAST 35TH STREET
709	NORTHEAST 35TH STREET
715	NORTHEAST 35TH STREET
719	NORTHEAST 35TH STREET
723	NORTHEAST 35TH STREET
729	NORTHEAST 35TH STREET
732	NORTHEAST 36TH STREET
733	NORTHEAST 35TH STREET
737	NORTHEAST 35TH STREET
741	NORTHEAST 35TH STREET
610	NORTHEAST 36TH STREET
620	NORTHEAST 36TH STREET
632	NORTHEAST 36TH STREET
636	NORTHEAST 36TH STREET
708	NORTHEAST 36TH STREET
712	NORTHEAST 36TH STREET
718	NORTHEAST 36TH STREET
720	NORTHEAST 36TH STREET
740	NORTHEAST 36TH STREET
746	NORTHEAST 36TH STREET
800	NORTHEAST 36TH STREET
804	NORTHEAST 36TH STREET

808	NORTHEAST 36TH STREET
812	NORTHEAST 36TH STREET
816	NORTHEAST 36TH STREET
820	NORTHEAST 36TH STREET
824	NORTHEAST 36TH STREET
834	NORTHEAST 36TH STREET
2620	URBAN LEAGUE COURT
2621	URBAN LEAGUE COURT
2504-2506	URBAN LEAGUE COURT
2505-2507	URBAN LEAGUE COURT
2508-2510	URBAN LEAGUE COURT
2509-2511	URBAN LEAGUE COURT
2512-2514	URBAN LEAGUE COURT
2513-2515	URBAN LEAGUE COURT
2517-2519	URBAN LEAGUE COURT
2600-2602	URBAN LEAGUE COURT
2601-2603	URBAN LEAGUE COURT
2604-2604	URBAN LEAGUE COURT
2605-2607	URBAN LEAGUE COURT
2608-2610	URBAN LEAGUE COURT
2609-2611	URBAN LEAGUE COURT
2612-2614	URBAN LEAGUE COURT
2613-2615	URBAN LEAGUE COURT
2616-2618	URBAN LEAGUE COURT
2617-2619	URBAN LEAGUE COURT

SUMMARY

The intent of this survey is to assist officials and the public with recognizing and identifying historic properties and provide guidance to known historic properties within the Capitol View Neighborhood. This report comprises the first installment of the Intensive-Level Survey of the Capitol View Neighborhood, and Phase I begins the process of identifying historic properties within its jurisdiction and assist with future planning and preservation efforts as well as determining the eligibility of properties and historic districts to the National Register of Historic Places. The Capitol View and Park Terrace Historic Districts warrant further examination as potential historic districts to the National Register of Historic Places. Both historic districts are excellent representations of different methods of construction and development within the Capitol View Neighborhood. This survey will continue City of Oklahoma City's process of identifying historic properties within its jurisdiction and assist with future planning and preservation efforts.

ANNOTATED BIBLIOGRAPHY

City of Oklahoma City. "Interactive GIS Zoning & Land Use." 2020. City of Oklahoma City. Accessed December 1, 2020 <https://maps.viewprogis.com/ecp/okc-ok>.

This resource provides information regarding legal descriptions, plats, and existing buildings.

City of Oklahoma City Planning Department. "Reconnaissance Survey of Portions of Oklahoma City." Report. Oklahoma State Historic Preservation Office. 1994.

This report identified three study area within Oklahoma City: northeast, northwest, and south Oklahoma City. Portions of the Capitol View neighborhood are within the northeast study area. The report provides a brief historic context and identifies potential properties and historic districts to the National Register of Historic Places.

Jo Meacham Associates. "Architectural/Historical Survey of Oklahoma City's Historic School Buildings." Report. Oklahoma State Historic Preservation Office. 2001.

This resource provides a historic context for the City of Oklahoma's city schools from pre-statehood to post-World War II. The report identifies each school within designated eras, construction, and architectural styles.

Longstreth, Richard. *The Buildings of Main Street: A Guide to American Commercial Architecture*. New York: AltaMira Press, 2000.

This is an excellent resource for identifying and interpreting commercial architectural styles, forms, and variations.

McAlester, Virginia Savage. *A Field Guide to American Houses*. New York: Alfred A . Knopf, 2015.

This is an excellent resource for identifying and interpreting residential architectural styles, forms, variations, and a brief historic background for each style.

Ozan, Lynda S. "The Historic Context for Modern Architecture in Oklahoma: Housing from 1946-1976." Report. Oklahoma State Historic Preservation Office. 2014.

This resource provides a historic context for modern residential housing and including examples of residential architectural styles and criteria for National Register eligibility.

Sanborn Map Company. "Sanborn Fire Insurance Map from Oklahoma City, Oklahoma County, Oklahoma." 1932, 1950, and 1954. Library of Congress. Accessed December 1, 2020.

<https://www.loc.gov/collections/sanborn-maps/?all=true&c=50&fa=location:oklahoma%7Clocation:oklahoma+county%7Clocation:oklahoma+city>.

This resource provides information regarding the built environment of the Capitol View neighborhood.

Wilson, Linda D. "Oklahoma City." *The Encyclopedia of Oklahoma History and Culture*.

<https://www.okhistory.org/publications/enc/entry.php?entry=OK025>.

This provides a historic context and general overview of Oklahoma City's development and history.