


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



Joshua Tree National Park - Overview



0 25 50 Miles

Author: sszturm
1/9/2024 7:23 AM

NPS Wildfire Risk Assessments
NPS Fire GIS
January 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



Joshua Tree National Park - Joshua Tree North - Overview




49 Palms Canyon Vault Toliet

JOTR - Joshua Tree National Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
60	90038	49 Palms Canyon Vault Toilet (single)



Rating
Facility
Moderate



Author: sszturm
1/9/2024 11:19 AM


0 500 1,000 1,500 Feet
Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
January 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project

Joshua Tree Visitor Center

JOTR - Joshua Tree National Park

National Park Service
U.S. Department of the Interior



Author: sszturm
1/9/2024 11:22 AM

0 500 1,000 1,500 Feet

Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
January 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: 49 Palms Canyon Vault Toilet (single)

Unit - Location: JOTR - Joshua Tree North

FMSS ID: 90038, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: L. Catlin, January 19, 2021

Coordinates (DDM): 34° 07.15454466' N 116° 06.71941248' W

Rating: Moderate

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 5 yrs

Map Label: 60

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Surfaced-paved, gradeGreater than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Joshua Tree Visitor Center (Park Center)
Unit - Location: JOTR - Joshua Tree North
FMSS ID: 106703, **Local ID:**
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: L. Catlin, January 19, 2021
Coordinates (DDM): 34° 08.03591088' N 116° 18.93517014' W

Rating: Low
Protection Level: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 5 yrs
Map Label: 59

Primary Access: Road
Ingress Egress: 2 or more roads in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, grade Less than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Less than 6in masonry exposed
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards
Comments:

