


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



NATR - Alabama - Overview



Author: sszturm
1/30/2024 10:03 AM

NPS Wildfire Risk Assessments
NPS Fire GIS
January 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project


CH Buzzard Roost

NATR - Natchez Trace National Parkway

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
5	66732	CH District Office Fire Pump House Bldg. # 224
3	66757	CH District Office Hazmat Storage Bldg. # 339
4	66754	CH District Office Vehicle Storage Bldg. # 223
2	66751	CH District Office Maint & Warehouse Bldg. # 222
1	236883	CH Buzzard Roost Exhibit Shelter Bldg. # 225



Rating	
Rating	
 Low	 Moderate



Author: sszturm
2/5/2024 12:43 PM

0 500 1,000 1,500 Feet
Scale: 1:6,000

NPS Wildfire Risk Assessments
NPS Fire GIS
February 2024
Data Sources: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CH Buzzard Roost Exhibit Shelter Bldg. # 225

Unit - Location: NATR - Cherokee Maintenance MP 320

FMSS ID: 236883

Structure Type: Shade

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 3/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 45.6151' Long(WGS84): -88° 1.3998'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable, load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope 31% to 40%

Roof Material: Fire resistant- tar, rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:




2021_NATR_236883_CH Buzzard Roost Exhibit Shelter Bldg. # 225_Front.jpg


Score: 52
Rating: Moderate



Asset Priority Index (API):
58



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CH District Office Maint & Warehouse Bldg. # 222

Unit - Location: NATR - Cherokee Maintenance MP 320

FMSS ID: 66751

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 3/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 45.5265' Long(WGS84): -88° 0.852353'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: Present and fuels clearance

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: fuel pumps

Assessment Comments:



2021_NATR_66751_CH District Office Maint & Warehouse Bldg. # 222_Front.jpg


Score: 41
Rating: Low



Asset Priority Index
(API):
63



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CH District Office Hazmat Storage Bldg. # 339

Unit - Location: NATR - Cherokee Maintenance MP 320

FMSS ID: 66757

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 3/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 34° 45.5057' **Long(WGS84):** -88° 0.838051'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat: fuel, oil


Assessment Comments:



2021_NATR_66757_CH District Office Hazmat Storage Bldg. # 339_Front.jpg




Score: 35
Rating: Low



Asset Priority Index (API): 52



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CH District Office Vehicle Storage Bldg. # 223

Unit - Location: NATR - Cherokee Maintenance MP 320

FMSS ID: 66754

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 3/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 34° 45.5218' Long(WGS84): -88° 0.829591'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: fuel, oil


Assessment Comments:




2021_NATR_66754_CH District Office Vehicle Storage Bldg. # 223_Front.jpg




Score: 32
Rating: Low



Asset Priority Index
(API):
63



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CH District Office Fire Pump House Bldg. # 224

Unit - Location: NATR - Cherokee Maintenance MP 320

FMSS ID: 66732

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 3/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 34° 45.502' Long(WGS84): -88° 0.828712'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat: hazmat storage adjacent


Assessment Comments:



2021_NATR_66732_CH District Office Fire Pump House Bldg. # 224_Front.jpg




Score: 34
Rating: Low



Asset Priority Index
(API):
52



Factors Driving the Ratings



Access
Environment
Structure
Protection

