


# NPS Wildfire Risk Assessments Assessment Locations

National Park Service  
U.S. Department of the Interior



## Monocacy National Battlefield- Overview



0

2


4

Miles


Author: sszturm  
3/20/2024 12:49 PM

NPS Wildfire Risk Assessments  
NPS Fire GIS  
March 2024  
Data Sources: ESRI Basedata, NPS  
NPS Wildfire Risk Assessment Project

Baker Farm Area  
MONO - Monocacy National Battlefield



Author: sszturm  
3/20/2024 11:20 AM





# NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

**Facility Name:** Equipment Storage

**Unit - Location:** MONO - Baker Farm Area

**FMSS ID:** NA, **Local ID:**

**Structure Type, Use:** Building, Private

**Owner:** National Park Service

**Field Crew, Visit Date:** Vaughn, September 12, 2014

**Coordinates (DDM):** 39° 21.12013512' N 077° 24.03960918' W

**Rating:** Moderate

**ProtectionLevel:** Not Designated,

**Resources of Concern:** Unknown

**Occupied:** No

**In Community:** No,

**Revisit Interval:** yrs

**Map Label:** 3

**Primary Access:** Road

**Ingress Egress:** 1 road in/out

**Access Width:** 1 lane (Less than 18')

**Access Condition:** Surfaced-paved, gradeGreater than 5%

**Bridge Condition:** Less than 300 ft with no turnaround

**Access and Turnarounds:** Less than 300 ft with no turnaround

**Facility Number or Sign:** None or not clearly visible

**Fuel Type:** Grass/tundra,northern hardwood litter

**Fuel Load:** Light or no wildland fuels

**Defensible Space:** Less than 30 ft treated

**Topography:** Slope 5% to 20%

**Roof Material:** Noncombustible or not applicable

**Siding Material:** Wood or open sided

**Foundation:** Closed, Greater than 30in masonry exposed or N/A


**Firewood:** None

**Water Supply:** Limited or dependent on electricity

**Propane:** None

**Overhead Hazards:** No overhead hazards

**Comments:**





# NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

**Facility Name:** Dairy Barn

**Unit - Location:** MONO - Baker Farm Area

**FMSS ID:** NA, **Local ID:**

**Structure Type, Use:** Building, Private

**Owner:** National Park Service

**Field Crew, Visit Date:** Vaughn, September 12, 2014

**Coordinates (DDM):** 39° 21.08826936' N 077° 24.02127780' W

**Rating:** Low

**ProtectionLevel:** Not Designated,

**Resources of Concern:** Unknown

**Occupied:** Yes

**In Community:** No,

**Revisit Interval:** yrs

**Map Label:** 4

**Primary Access:** Road

**Ingress Egress:** 1 road in/out

**Access Width:** 1 lane (Less than 18')

**Access Condition:** Surfaced-paved, grade Greater than 5%

**Bridge Condition:** Less than 300 ft with no turnaround

**Access and Turnarounds:** Less than 300 ft with no turnaround

**Facility Number or Sign:** None or not clearly visible

**Fuel Type:** Grass/tundra, northern hardwood litter

**Fuel Load:** Light or no wildland fuels

**Defensible Space:** 100 ft treated

**Topography:** Slope 5% to 20%

**Roof Material:** Noncombustible or not applicable

**Siding Material:** Wood or open sided

**Foundation:** Closed, Greater than 30in masonry exposed or N/A



**Firewood:** None

**Water Supply:** Limited or dependent on electricity

**Propane:** None

**Overhead Hazards:** No overhead hazards

**Comments:**





# NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

**Facility Name:** Barn

**Unit - Location:** MONO - Baker Farm Area

**FMSS ID:** NA, **Local ID:**

**Structure Type, Use:** Building, Private

**Owner:** National Park Service

**Field Crew, Visit Date:** Vaughn, September 12, 2014

**Coordinates (DDM):** 39° 21.06925272' N 077° 24.05108772' W

**Rating:** Low

**ProtectionLevel:** Not Designated,

**Resources of Concern:** Unknown

**Occupied:** No

**In Community:** No,

**Revisit Interval:** yrs

**Map Label:** 2

**Primary Access:** Road

**Ingress Egress:** 1 road in/out

**Access Width:** 1 lane (Less than 18')

**Access Condition:** Surfaced-paved, gradeGreater than 5%

**Bridge Condition:** Less than 300 ft with no turnaround

**Access and Turnarounds:** Less than 300 ft with no turnaround

**Facility Number or Sign:** None or not clearly visible

**Fuel Type:** Grass/tundra,northern hardwood litter

**Fuel Load:** Light or no wildland fuels

**Defensible Space:** 100 ft treated

**Topography:** Slope 5% to 20%

**Roof Material:** Noncombustible or not applicable

**Siding Material:** Wood or open sided

**Foundation:** Closed, Less than 6in masonry exposed


**Firewood:** None

**Water Supply:** Limited or dependent on electricity

**Propane:** None

**Overhead Hazards:** No overhead hazards

**Comments:**





# NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

**Facility Name:** Barn

**Unit - Location:** MONO - Baker Farm Area

**FMSS ID:** NA, **Local ID:**

**Structure Type, Use:** Building, Private

**Owner:** National Park Service

**Field Crew, Visit Date:** Vaughn, September 12, 2014

**Coordinates (DDM):** 39° 21.03053412' N 077° 24.05776926' W

**Rating:** Moderate

**ProtectionLevel:** Not Designated,

**Resources of Concern:** Unknown

**Occupied:** No

**In Community:** No,

**Revisit Interval:** yrs

**Map Label:** 1

**Primary Access:** Road

**Ingress Egress:** 1 road in/out

**Access Width:** 1 lane (Less than 18')

**Access Condition:** Surfaced-paved, gradeGreater than 5%

**Bridge Condition:** Less than 300 ft with no turnaround

**Access and Turnarounds:** Less than 300 ft with no turnaround

**Facility Number or Sign:** None or not clearly visible

**Fuel Type:** Grass/tundra,northern hardwood litter

**Fuel Load:** Light or no wildland fuels

**Defensible Space:** Less than 30 ft treated

**Topography:** Slope 5% to 20%

**Roof Material:** Noncombustible or not applicable

**Siding Material:** Wood or open sided

**Foundation:** Closed, Less than 6in masonry exposed

**Firewood:** None


**Water Supply:** Limited or dependent on electricity

**Propane:** None

**Overhead Hazards:** No overhead hazards

**Comments:**

NO PHOTO AVAILABLE





# NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

**Facility Name:** Baker House

**Unit - Location:** MONO - Baker Farm Area

**FMSS ID:** 55413, **Local ID:**

**Structure Type, Use:** Building, Private

**Owner:** National Park Service

**Field Crew, Visit Date:** Vaughn, September 12, 2014

**Coordinates (DDM):** 39° 21.11085990' N 077° 24.01302462' W

**Rating:** Moderate

**ProtectionLevel:** Not Designated,

**Resources of Concern:** Unknown

**Occupied:** Yes

**In Community:** Yes,

**Revisit Interval:** yrs

**Map Label:** 5

**Primary Access:** Road

**Ingress Egress:** 1 road in/out

**Access Width:** 1 lane (Less than 18')

**Access Condition:** Surfaced-paved, gradeGreater than 5%

**Bridge Condition:** Less than 300 ft with no turnaround

**Access and Turnarounds:** Less than 300 ft with no turnaround

**Facility Number or Sign:** None or not clearly visible

**Fuel Type:** Grass/tundra,northern hardwood litter

**Fuel Load:** Light or no wildland fuels

**Defensible Space:** 100 ft treated

**Topography:** Slope 5% to 20%

**Roof Material:** Combination of fire resitant and combustible

**Siding Material:** Wood or open sided

**Foundation:** Closed, Less than 6in masonry exposed


**Firewood:** None

**Water Supply:** Limited or dependent on electricity

**Propane:** None

**Overhead Hazards:** No overhead hazards

**Comments:** From FMSS\_Export - FRPP\_PREDUSE:  
Bldg. Cultural Ctr (GSF)





# NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

**Facility Name:** Baker Barn

**Unit - Location:** MONO - Baker Farm Area

**FMSS ID:** 55415, **Local ID:**

**Structure Type, Use:** Building, Private

**Owner:** National Park Service

**Field Crew, Visit Date:** Vaughn, September 12, 2014

**Coordinates (DDM):** 39° 21.15090510' N 077° 24.00321282' W

**Rating:** Moderate

**ProtectionLevel:** Not Designated,

**Resources of Concern:** Unknown

**Occupied:** No

**In Community:** Yes,

**Revisit Interval:** yrs

**Map Label:** 6

**Primary Access:** Road

**Ingress Egress:** 1 road in/out

**Access Width:** 1 lane (Less than 18')

**Access Condition:** Surfaced-paved, gradeGreater than 5%

**Bridge Condition:** Less than 300 ft with no turnaround

**Access and Turnarounds:** Less than 300 ft with no turnaround

**Facility Number or Sign:** None or not clearly visible

**Fuel Type:** Grass/tundra,northern hardwood litter

**Fuel Load:** Light or no wildland fuels

**Defensible Space:** Less than 30 ft treated

**Topography:** Slope 5% to 20%

**Roof Material:** Noncombustible or not applicable

**Siding Material:** Wood or open sided

**Foundation:** Closed, Greater than 30in masonry exposed or N/A

**Firewood:** None

**Water Supply:** Limited or dependent on electricity

**Propane:** None

**Overhead Hazards:** No overhead hazards

**Comments:** From FMSS\_Export - FRPP\_PREDUSE:  
Bldg. Barn Stable (GSF)

