


NPS Wildfire Risk Assessments Assessment Locations

DINO - Dinosaur National Monument Overview

National Park Service
U.S. Department of the Interior




Baker Cabin
DINO - Dinosaur National Monument

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
1	107526	Baker Cabin
91	NA	Baker Cabin Stable



Facility

Rating

High



Author: sszturm
5/20/2024 7:12 AM

0 0.5 Miles
Scale: 1:21,000

NPS Wildfire Risk Assessments
NPS Fire GIS
May 2024
Data Source: ESRI Basedata, NPS
NPS Wildfire Risk Assessment Project



NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Baker Cabin

Unit - Location: DINO - Baker Cabin

FMSS ID: 107526, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: DINO Fire, July 8, 2023

Coordinates (DDM): 40° 26.973' N 108° 47.672' W

Rating: High

ProtectionLevel: Not Designated,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 1 yrs

Map Label: 1

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with no turnaround

Access and Turnarounds: Less than 300 ft with no turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed

Firewood: None

Water Supply: No reliable water source nearby



Propane: None

Overhead Hazards: No overhead hazards

Comments: Turnaround: T6 accessible. Bridge Const.

Material: No Bridge. Maintenance: Dugout attached to main cabin.

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Baker Cabin Stable

Unit - Location: DINO - Baker Cabin

FMSS ID: NA, **Local ID:**

Structure Type, Use: Other, Public

Owner: National Park Service

Field Crew, Visit Date: Dino Fire, July 8, 2023

Coordinates (DDM): 40° 26.998' N 108° 47.680' W

Rating: High

ProtectionLevel: ,

Resources of Concern: Yes

Occupied: No

In Community: No,

Revisit Interval: 5 yrs

Map Label: 91

Primary Access: Road

Ingress Egress: 1 road in/out

Access Width: 1 lane (Less than 18')

Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%

Bridge Condition: Less than 300 ft with turnaround

Access and Turnarounds: Less than 300 ft with turnaround

Facility Number or Sign: None or not clearly visible

Fuel Type: Shrub or timber

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:

NO PHOTO AVAILABLE

