


NPS Wildfire Risk Assessments Assessment Locations

Fort Union National Monument

National Park Service
U.S. Department of the Interior



Structure Groups

● Fort Union (11)



0 2,000 4,000
Feet

Author: cmgallagher
5/3/2022 11:53 AM


Intermountain Region Geographic Resources Division
February 2018
Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project

Fort Union

NPS Wildfire Risk Assessments

National Park Service
U.S. Department of the Interior





NPS Wildand Fire Risk Assessment - Facility Wildfire Risk Assessment Summary

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: FOUN - Fort Union

Label #	Facility Name	Owner	FMSS ID (if NPS owned)	Facility Type	Facility Use	Occupied	Last Site Visit Date*	Resource Of Concern	Score	Rating	Protection Level	Assessment Comments	Restriction
1	VISITOR CENTER	NPS		Building	Public	Y	7/3/13	Unknown	26	Low	Unknown	PUBLIC EVACUATION MAY BE REQUIRED	UNR
2	HEADQUARTERS BUILDING	NPS	55964	Building	Admin	Y	7/3/13	Unknown	30	Low	Not Designated		UNR
3	QUARTERS #1	NPS	55963	Building	Residence	Y	7/3/13	Unknown	26	Low	Not Designated		UNR
4	BUILDING 15 LIBRARY	NPS	55976	Building	Admin	Y	7/3/13	Unknown	30	Low	Not Designated		UNR
5	CURATORIAL STORAGE BUILDING	NPS	55981	Building	Admin	Y	7/3/13	Unknown	23	Low	Not Designated		UNR
6	QUARTERS #3 APPARTMENTS	NPS	55966	Building	Residence	Y	7/3/13	Unknown	39	Low	Not Designated		UNR
7	WELL HOUSE	NPS	55996	Building	Admin	Y	7/3/13	Unknown	31	Low	Not Designated		UNR
8	QUARTERS# 4 STUDIOS	NPS	55970	Building	Residence	Y	7/3/13	Unknown	32	Low	Not Designated		UNR
9	MAIN MAINTENANCE BUILDING	NPS	55956	Building	Admin	Y	7/3/13	Unknown	29	Low	Not Designated		UNR
10	METAL SHED #1	NPS	55958	Building	Admin	Y	7/3/13	Unknown	25	Low	Not Designated		UNR
11	MAINTAINANCE STORAGE BUILDING	NPS	55957	Building	Admin	N	7/3/13	Unknown	28	Low	Not Designated		UNR



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

NPS Unit - Location: FOUN - Fort Union

Label #	Facility/Community Name	Assessment Scale	Site Visit Type	Firewise Zone	Treatment	Treatment Description	Person Hours	Date
0	RESIDENTIAL AREA	Community						
1	VISITOR CENTER	Individual Facility						
10	METAL SHED #1	Facility In Community (RESIDENTIAL AREA)						
11	MAINTAINANCE STORAGE BUILDING	Facility In Community (RESIDENTIAL AREA)						
2	HEADQUARTERS BUILDING	Facility In Community (RESIDENTIAL AREA)						
3	QUARTERS #1	Facility In Community (RESIDENTIAL AREA)						
4	BUILDING 15 LIBRARY	Facility In Community (RESIDENTIAL AREA)						
5	CURATORIAL STORAGE BUILDING	Facility In Community (RESIDENTIAL AREA)						



NPS Wildland Fire Risk Assessment - Recommended Treatments

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

6	QUARTERS #3 APPARTMENTS	Facility In Community (RESIDENTIAL AREA)						
7	WELL HOUSE	Facility In Community (RESIDENTIAL AREA)						
8	QUARTERS# 4 STUDIOS	Facility In Community (RESIDENTIAL AREA)						
9	MAIN MAINTENANCE BUILDING	Facility In Community (RESIDENTIAL AREA)						



NPS Wildland Fire Risk Assessment - Recommended Tactics

For more information on the NPS Wildland Fire Risk Assessment project visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Unit - Location: Fort Union National Monument - Fort Union

Label #	Facility/Community Name	Assessment Scale	Triage Category	Tactic Description	Person Hours	Equipment Description	Equip. Qty
0	RESIDENTIAL AREA	Community	NULL	-		-	
1	VISITOR CENTER	Individual Facility		-		-	
10	METAL SHED #1	Facility In Community (RESIDENTIAL AREA)		-		-	
11	MAINTAINANCE STORAGE BUILDING	Facility In Community (RESIDENTIAL AREA)		-		-	
2	HEADQUARTERS BUILDING	Facility In Community (RESIDENTIAL AREA)		-		-	
3	QUARTERS #1	Facility In Community (RESIDENTIAL AREA)		-		-	
4	BUILDING 15 LIBRARY	Facility In Community (RESIDENTIAL AREA)		-		-	
5	CURATORIAL STORAGE BUILDING	Facility In Community (RESIDENTIAL AREA)		-		-	
6	QUARTERS #3 APPARTMENTS	Facility In Community (RESIDENTIAL AREA)		-		-	
7	WELL HOUSE	Facility In Community (RESIDENTIAL AREA)		-		-	
8	QUARTERS# 4 STUDIOS	Facility In Community (RESIDENTIAL AREA)		-		-	
9	MAIN MAINTENANCE BUILDING	Facility In Community (RESIDENTIAL AREA)		-		-	



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: VISITOR CENTER

Unit - Location: FOUN - Fort Union

FMSS ID:

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Unknown

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 54.2994' Long(WGS84): -105° 0.684822'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: Combustible,adjacent,no veg/debris clearance

Firewood: None

Propane Tanks: Present and fuels clearance

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area


Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat:

Assessment Comments: PUBLIC EVACUATION MAY BE REQUIRED



Score: 26
Rating: Low



Asset Priority Index
(API):
N/A



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: HEADQUARTERS BUILDING

Unit - Location: FOUN - Fort Union

FMSS ID: 55964

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 53.9202' Long(WGS84): -105° 0.832938'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible,adjacent,no veg/debris clearance

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat:


Assessment Comments:

Score: 30
Rating: Low



Asset Priority Index
(API):
63



Factors Driving the Ratings



Access
Environment
Structure



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: QUARTERS #1

Unit - Location: FOUN - Fort Union

FMSS ID: 55963

Structure Type: Building

Structure Use: Residence

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 53.9571' Long(WGS84): -105° 0.828981'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat:


Assessment Comments:

Score: 26
Rating: Low



Asset Priority Index
(API):
63



Factors Driving the Ratings



Access
Environment
Structure



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: **BUILDING 15 LIBRARY**

Unit - Location: **FOUN - Fort Union**

FMSS ID: **55976**

Structure Type: **Building**

Structure Use: **Admin**

Owner: **NPS**

Field Crew: **BAND WFM**

Last Site Visit Date: **7/3/2013**

Rating: **Low**

Protection Level : **Not Designated**

Resources of Concern Present? **Unknown**

Occupied? **Yes**

Local ID: **[Local_ID]**

In a Community? **Yes - RESIDENTIAL AREA**

Lat(WGS84): **35° 53.97'** Long(WGS84): **-105° 0.81269'**

Primary Access: **Road**

Ingress/Egress: **One roads in/out**

Access Width: **1.5 lanes (>18ft)**

Access Condition: **Surfaced-paved, grade<5%**

Bridge Condition: **None/nonflammable,load limit will not limit response**

Access & Turnarounds: **Access is <300 ft from facility w/turnaround**

Facility Number/Sign: **None or not clearly visible**

Defensible Space: **>100ft treated**

Fuel Load (w/in 300 ft): **Light**

Fuel Type (w/in 300ft): **Grass,tundra,northern hardwood litter**

Topography (w/in 300ft): **Slope <5%**

Roof Material: **Noncombustible or not applicable**

Siding Material: **Wood or open sided**

Foundation: **Closed, < 6in masonry exposed**

Fences/Decks: **Combustible, adjacent, clear of veg/debris**

Firewood: **None**

Propane Tanks:

Water Supply: **Pressurized hydrant(s) or fixed sprinkler system**

Overhead Hazards: **No overhead hazards**

Safety Zones: **Potential safety zone(s) in area**

Additional Obstacles: **Hazmat, UXO,etc. , PLEASE COMMENT**


Triage Category:

Hazmat:


Assessment Comments:

Score: **30**
Rating: **Low**



Asset Priority Index
(API):
66



Factors Driving the Ratings



■ Access
■ Environment
■ Structure



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: CURATORIAL STORAGE BUILDING

Unit - Location: FOUN - Fort Union

FMSS ID: 55981

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 53.9789' Long(WGS84): -105° 0.80703'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT



Triage Category:

Hazmat:


Assessment Comments:

Score: 23
Rating: Low



Asset Priority Index
(API):
76



Factors Driving the Ratings



Access
Environment
Structure



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: **QUARTERS #3 APPARTMENTS**

Unit - Location: FOUN - Fort Union

FMSS ID: 55966

Structure Type: Building

Structure Use: Residence

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 53.9846' **Long(WGS84):** -105° 0.792396'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible,adjacent,no veg/debris clearance

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat:


Assessment Comments:

Score: 39
Rating: Low



Asset Priority Index
(API):
63



Factors Driving the Ratings



■ Access
■ Environment
■ Structure



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: WELL HOUSE

Unit - Location: FOUN - Fort Union

FMSS ID: 55996

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 54.0077' Long(WGS84): -105° 0.781014'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat:




Assessment Comments:

Score: 31
Rating: Low

Asset Priority Index
(API):
33



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: **QUARTERS# 4 STUDIOS**

Unit - Location: FOUN - Fort Union

FMSS ID: 55970

Structure Type: Building

Structure Use: Residence

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 53.9832' **Long(WGS84):** -105° 0.753396'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible,adjacent,no veg/debris clearance

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat:


Assessment Comments:

Score: 32
Rating: Low



Asset Priority Index
(API):
63



Factors Driving the Ratings



■ Access
■ Environment
■ Structure





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: MAIN MAINTENANCE BUILDING

Unit - Location: FOUN - Fort Union

FMSS ID: 55956

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 53.9694' Long(WGS84): -105° 0.724429'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat: FUEL STORAGE


Assessment Comments:

Score: 29
Rating: Low



Asset Priority Index
(API):
40



Factors Driving the Ratings



Access
Environment
Structure



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: METAL SHED #1

Unit - Location: FOUN - Fort Union

FMSS ID: 55958

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 53.9568' Long(WGS84): -105° 0.720249'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat: FUEL STORAGE ADJACENT


Assessment Comments:

Score: 25
Rating: Low



Asset Priority Index
(API):
21



Factors Driving the Ratings



Access
Environment
Structure



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: MAINTAINANCE STORAGE BUILDING

Unit - Location: FOUN - Fort Union

FMSS ID: 55957

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: BAND WFM

Last Site Visit Date: 7/3/2013

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - RESIDENTIAL AREA

Lat(WGS84): 35° 53.9529' Long(WGS84): -105° 0.710556'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1.5 lanes (>18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible,adjacent,no veg/debris clearance

Firewood: None

Propane Tanks:

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat: Fuel STORAGE AND FLAMMABLE LOCKER


Assessment Comments:

Score: 28
Rating: Low



Asset Priority Index
(API):
38



Factors Driving the Ratings



Access
Environment
Structure



● Facility
■ NPS Boundary