


NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



KATM - Katmai National Park and Preserve - Overview




NPS Wildfire Risk Assessments
Assessment Locations

National Park Service
U.S. Department of the Interior



KATM - Valley of 10,000 Smokes - Overview




Baked Mountain

KATM - Katmai National Park and Preserve



Map Label	FMSS ID	Common Name
3	83327	Baked Mountain Cabin
4	115996	Baked Mountain Cabin #2
7	115997	Baked Mountain Cabin Outhouse



Rating	Rating	ProtectionLevel
	No Wildland Risk	Full




Margot Falls Comfort Station

KATM - Katmai National Park and Preserve



Map Label	FMSS ID	Common Name
6	90936	VR-MCF/RR Margot Falls Comfort Station



Rating	ProtectionLevel
High	Full



Author: sszturm
8/27/2024 10:18 AM




Overlook

KATM - Katmai National Park and Preserve



Map Label	FMSS ID	Common Name
1	91554	VR-3F/RR Three Forks Overlook Comfort Station
2	53679	VR-OVL Three Forks Valley of 10,000 Smokes Overlook Building



Rating		ProtectionLevel	
Rating			
High		Full	



Author: sszturm
8/27/2024 10:19 AM



VR Storage Building

KATM - Katmai National Park and Preserve



Map Label	FMSS ID	Common Name
5	114535	VR-Storage Building



Author: sszturm
8/27/2024 10:17 AM





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: VR-MCF/RR Margot Falls Comfort Station

Unit - Location: KATM - Valley of 10,000 Smokes

FMSS ID: 90936, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 10, 2023

Coordinates (DDM): 58° 26.500' N 155° 36.308' W

Rating: High

ProtectionLevel: Full,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 4 yrs

Map Label: 6

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Very Heavy

Defensible Space: Less than 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed


Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: VR-3F/RR Three Forks Overlook Comfort Station

Unit - Location: KATM - Valley of 10,000 Smokes

FMSS ID: 91554, **Local ID:**

Structure Type, Use: Toilet, Public

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 10, 2023

Coordinates (DDM): 58° 22.119' N 155° 22.998' W

Rating: High

ProtectionLevel: Full,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 4 yrs

Map Label: 1

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: Less than 30 ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material: Wood or open sided

Foundation: Closed, Less than 6in masonry exposed



Firewood: None

Water Supply: No reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: VR-OVL Three Forks Valley of 10,000 Smokes Overlook Building
Unit - Location: KATM - Valley of 10,000 Smokes
FMSS ID: 53679, **Local ID:**
Structure Type, Use: Administrative, Administrative
Owner: National Park Service
Field Crew, Visit Date: S Szturm , August 10, 2023
Coordinates (DDM): 58° 22.115' N 155° 22.971' W

Rating: High
ProtectionLevel: Full,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 4 yrs
Map Label: 2

Primary Access: Air
Ingress Egress: N/A, access by foot, boat, or air only
Access Width: N/A, access by foot, boat, or air only
Access Condition: N/A, access by foot, boat, or air only
Bridge Condition: N/A, access by foot, boat, or air only
Access and Turnarounds: N/A, access by foot, boat, or air only
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass/tundra, northern hardwood litter
Fuel Load: Moderate
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: Present and little to no fuels clearance
Overhead Hazards: No overhead hazards
Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: VR-Storage Building

Unit - Location: KATM - Valley of 10,000 Smokes

FMSS ID: 114535, **Local ID:**

Structure Type, Use: Building, Administrative

Owner: National Park Service

Field Crew, Visit Date: S Szturm , August 10, 2023

Coordinates (DDM): 58° 30.589' N 155° 41.906' W

Rating: Moderate

ProtectionLevel: Full,

Resources of Concern: Unknown

Occupied: No

In Community: No,

Revisit Interval: 4 yrs

Map Label: 5

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: Grass/tundra, northern hardwood litter

Fuel Load: Moderate

Defensible Space: 30 ft treated

Topography: Slope Less than 5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Open or deck



Firewood: None

Water Supply: Reliable water source nearby

Propane: None

Overhead Hazards: No overhead hazards

Comments:





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Baked Mountain Cabin

Unit - Location: KATM - Valley of 10,000 Smokes

FMSS ID: 83327, **Local ID:**

Structure Type, Use: No Wildland Risk,

Owner:

Field Crew, Visit Date: S Hartsburg Remote,

Coordinates (DDM): 58° 17.61459066' N 155° 12.10191060' W

Rating: No Wildland Risk

ProtectionLevel: Full,

Resources of Concern: Unknown

Occupied:

In Community: No,

Revisit Interval: yrs

Map Label: 3

Primary Access: Air

Ingress Egress: N/A,access by foot,boat,or air only

Access Width: N/A,access by foot,boat,or air only

Access Condition: N/A,access by foot,boat,or air only

Bridge Condition: N/A,access by foot,boat,or air only

Access and Turnarounds: N/A,access by foot,boat,or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material:

Foundation:

Firewood:


Water Supply:

Propane:

Overhead Hazards:

Comments: Photos from NP Gallery, verify that these are the correct structures

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Baked Mountain Cabin #2

Unit - Location: KATM - Valley of 10,000 Smokes

FMSS ID: 115996, **Local ID:**

Structure Type, Use: No Wildland Risk,

Owner:

Field Crew, Visit Date: S Hartsburg Remote,

Coordinates (DDM): 58° 17.61618408' N 155° 12.09838764' W

Rating: No Wildland Risk

ProtectionLevel: Full,

Resources of Concern: Unknown

Occupied:

In Community: No,

Revisit Interval: yrs

Map Label: 4

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material:

Foundation:

Firewood:


Water Supply:

Propane:

Overhead Hazards:

Comments: Photos from NP Gallery, verify that these are the correct structures

NO PHOTO AVAILABLE





NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com/>

Facility Name: Baked Mountain Cabin Outhouse

Unit - Location: KATM - Valley of 10,000 Smokes

FMSS ID: 115997, **Local ID:**

Structure Type, Use: No Wildland Risk,

Owner:

Field Crew, Visit Date: S Hartsburg Remote,

Coordinates (DDM): 58° 17.61921426' N 155° 12.10788486' W

Rating: No Wildland Risk

ProtectionLevel: Full,

Resources of Concern: Unknown

Occupied:

In Community: No,

Revisit Interval: yrs

Map Label: 7

Primary Access: Air

Ingress Egress: N/A, access by foot, boat, or air only

Access Width: N/A, access by foot, boat, or air only

Access Condition: N/A, access by foot, boat, or air only

Bridge Condition: N/A, access by foot, boat, or air only

Access and Turnarounds: N/A, access by foot, boat, or air only

Facility Number or Sign: None or not clearly visible

Fuel Type: No wildland fuel

Fuel Load: Light or no wildland fuels

Defensible Space: Greater than 100ft treated

Topography: Slope 5% to 20%

Roof Material: Noncombustible or not applicable

Siding Material:

Foundation:

Firewood:

Water Supply:

Propane:

Overhead Hazards:

Comments: Photos from NP Gallery, verify that these are the correct structures

NO PHOTO AVAILABLE

