

NPS Wildfire Risk Assessments Assessment Locations

Cape Hatteras National Seashore

National Park Service
U.S. Department of the Interior



Structure Locations			
	Bodie Island (57)		Ocracoke Island (58)
	Hatteras Island (118)		Pea Island (6)



0

50

Miles

Author: sszturm
2/22/2022 11:40 AM

Intermountain Region Geographic Resources Division
April 2021
Data Sources: ESRI Basedata, NPS Park Data


NPS Wildfire Risk Assessment Project

NPS Wildfire Risk Assessments Assessment Locations

National Park Service
U.S. Department of the Interior



Cape Hatteras National Seashore-Bodie Island



0

10
Miles

Author: sszturm
2/22/2022 1:02 PM

Intermountain Region Geographic Resources Division

April 2021


Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project

Bodie Island 1

NPS Wildfire Risk Assessments

National Park Service
U.S. Department of the Interior



Rating


■ High
 ■ Moderate
 ■ Low

Map Label	FMSS ID	Common Name
21	not found	Oregon Inlet Coast Guard shed
22	not found	Electric Vehicle Storage at Oregon Inlet Campground
23	not found	storage building
24	28935	BI BD Oregon Inlet CG Kiosk
25	28944	BI BD Oregon Inlet CG Loop C Comfort Station
26	28940	BI BD Oregon Inlet CG Loop A Comfort Station
27	28939	BI BD Oregon Inlet CG Loop A Shower Building
28	28943	BI BD Oregon Inlet CG Loop C Shower Building
29	28941	BI BD Oregon Inlet CG Loop Shower Building
30	28942	BI BD Oregon Inlet CG Loop B Comfort Station
42	not found	Oregon Inlet Radio Tower
43	not found	Oregon Inlet Coast Guard Shed
44	not found	Oregon Inlet Coast Guard - Admin
45		Oregon Inlet Coast Guard - Boathouse
46	not found	HAZMAT Storage
47	not found	Oregon Inlet Coast Guard - Gatehouse
48	not found	Tool Shed
49	not found	Oregon Inlet Coast Guard - Dock Shed
50	not found	Fishing Center Storage - soundside booth
51	not found	Fishing Center Storage - flammable
52	not found	Fishing Center Storage - sign
53	80998	BI BD Oregon Inlet Fishing Center
54	not found	Fishing Center Storage - old truck box
55	28948	BI BD Oregon Inlet Fishing Center Comfort Station
56	110389	BI BD Oregon Inlet Fishing Center Exhibit Building
57	not found	oregon fishing center fuel tanks.
58	not found	Fishing Center Fuel Kiosk
59	not found	Fishing Center - shed beyond fuel kiosk

Bodie Island 2

NPS Wildfire Risk Assessments

National Park Service
U.S. Department of the Interior



0

5

Miles

Author: sszturm
2/22/2022 10:52 AM

Intermountain Region Geographic Resources Division

April 2021

Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessment Project



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Whalebone Comfort Station

Unit - Location: CAHA - Bodie Island

FMSS ID: 28884

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 54.2559' Long(WGS84): -75° 35.8799'

Primary Access: Road

Ingress/Egress: Two or more roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat: none

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)



2016_CAHA_28884_BI BD Whalebone Confort Station_Front.jpg


Score: 41
Rating: Low



Asset Priority Index
(API):
36



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Whalebone Information Station

Unit - Location: CAHA - Bodie Island
FMSS ID: 28883
Structure Type: Building
Structure Use: Public
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? Yes
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 35° 54.2602' **Long(WGS84):** -75° 35.8636'

Primary Access: Road
Ingress/Egress: Two or more roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Shrub or timber
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: None
Water Supply: Reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Visitor Cont Stat (GSF)



2016_CAHA_28883_BI BD Whalebone Information Station_Front.jpg


Score: 34
Rating: Low




Asset Priority Index (API): 24



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Range Observation Building

Unit - Location: CAHA - Bodie Island

FMSS ID: 28962

Structure Type: Building

Structure Use: Other

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 50.104' **Long(WGS84):** -75° 34.3581'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Non-surfaced- gravel,dirt,grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)

large communication tower nearby and access is behind a locked gate




2016_CAHA_28962_BI BD Range Observation Building_Front.jpg




Score: 57
Rating: Moderate

Asset Priority Index (API):
27



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: storage building

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Other

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 50.102' **Long(WGS84):** -75° 34.3516'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Non-surfaced- gravel,dirt,grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: 5ft to 30ft from facility

Propane Tanks: None

Water Supply: Reliable water source nearby

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: large communication tower nearby and access is behind a locked gate




2016_CAHA__storage building_Front.jpg

Score: 59
Rating: Moderate

Asset Priority Index (API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: US Communication tower site

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: CommSite

Structure Use: Other

Owner: Unknown

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 50.183' **Long(WGS84):** -75° 34.252'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Non-surfaced- gravel,dirt,grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Shrub or timber

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: Adjacent to facility and no fuels clearance

Water Supply: Reliable water source nearby

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: large communication tower nearby and access is behind a locked gate




2016_CAHA__US Communication tower site_Front.jpg

Score: 62
Rating: Moderate

Asset Priority Index (API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: *BI BD Necropsy freezer*

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.4104' **Long(WGS84):** -75° 34.1831'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Heavy

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments:

Score: 52
Rating: Moderate

Asset Priority Index
(API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: *BI BD Necropsy building*

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.4122' **Long(WGS84):** -75° 34.1744'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Heavy

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments:

Score: 59
Rating: Moderate

Asset Priority Index
(API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Boneyard Building

Unit - Location: CAHA - Bodie Island

FMSS ID: 28929

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.395' **Long(WGS84):** -75° 34.1458'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 1 lane (<18ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2016_CAHA_28929_BI BD Boneyard Building_Front.jpg


Score: 36
Rating: Low



Asset Priority Index (API): 27



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD LH Comfort Station

Unit - Location: CAHA - Bodie Island

FMSS ID: 28928

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.1338' **Long(WGS84):** -75° 33.8649'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)




2016_CAHA_28928_BI BD LH Comfort Station_Front.jpg


Score: 40
Rating: Low




Asset Priority Index (API): 62



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: *BI BD shed*

Unit - Location: CAHA - Bodie Island

FMSS ID: none found

Structure Type: Building

Structure Use: Other

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.7657' **Long(WGS84):** -75° 33.8591'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible but separated from facility

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area


Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: Fuel oil tank behind.

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)


Score: 35
Rating: Low



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: LCS 7249-BI HS LH Store House

Unit - Location: CAHA - Bodie Island

FMSS ID: 28926

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.1132' **Long(WGS84):** -75° 33.8501'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)




2016_CAHA_28926_LCS 7249-BI HS LH Store House_Front.jpg




Score: 48
Rating: Moderate

Asset Priority Index (API): 100



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: LCS 7244-BI HS Keepers Quarters (Visitor Center)

Unit - Location: CAHA - Bodie Island

FMSS ID: 28924

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.0967' **Long(WGS84):** -75° 33.8399'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2016_CAHA_28924_LCS 7244-BI HS Keepers Quarters (Visitor Center)_Front.jpg


Score: 40
Rating: Low




Asset Priority Index (API): 100



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI HS Bodie Island lighthouse oil house

Unit - Location: CAHA - Bodie Island

FMSS ID: 229422

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.1119' Long(WGS84): -75° 33.8082'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Rock, concrete, metal

Foundation: Closed, 6in to 30in masonry exposed

Fences/Decks: Combustible but separated from facility

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat: attached to lighthouse


Assessment Comments:




2016_CAHA_229422_BI HS Bodie Island lighthouse oil house_Front.jpg



Score: 49
Rating: Moderate
Asset Priority Index (API): 100



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: LCS 114-BI HS Bodie Island Lighthouse

Unit - Location: CAHA - Bodie Island

FMSS ID: 28923

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.1127' **Long(WGS84):** -75° 33.8004'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Lighthouse (GSF)



2016_CAHA_28923_LCS 114-BI HS Bodie Island Lighthouse_Front.jpg




Score: 21
Rating: Low



Asset Priority Index (API): 100



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI Pond Viewing Area

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Fence

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local ID]

In a Community? No

Lat(WGS84): 35° 49.2118' Long(WGS84): -75° 33.7517'

Primary Access: Foot

Ingress/Egress: N/A, access by foot, boat or air only

Access Width: N/A, access by foot, boat or air only

Access Condition: N/A, access by foot, boat or air only

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: N/A,access by foot,boat,or air only

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible,adjacent,no veg/debris clearance

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: surrounded by water




2016_CAHA__BI Pond Viewing Area_Front.jpg

Score: 58
Rating: Moderate


Asset Priority Index
(API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI HS Coast Guard Station (Hilton)

Unit - Location: CAHA - Bodie Island

FMSS ID: 28912

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.7558' Long(WGS84): -75° 33.5325'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/o turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2016_CAHA_28912_BI HS Coast Guard Station (Hilton)_Front.jpg


Score: 68
Rating: High



Asset Priority Index
(API):
63



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI HS Ranger Station

Unit - Location: CAHA - Bodie Island

FMSS ID: 28913

Structure Type: Administrative

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: High

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied?

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.7234' **Long(WGS84):** -75° 33.5257'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2021_CAHA_28913_BI HS Ranger Station_Front.jpg


Score: 66
Rating: High



Asset Priority Index (API): 63



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Garage of 28913

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.7368' **Long(WGS84):** -75° 33.5255'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE:




2016_CAHA__Garage of 28913_Front.jpg

Score: 62
Rating: Moderate

Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: *BI BD Coquina Sandcastle*


Unit - Location: CAHA - Bodie Island
FMSS ID: 28917
Structure Type: None Found
Structure Use: Public
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021

Rating: None
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? No
Lat(WGS84): 35° 50.0335' **Long(WGS84):** -75° 33.5236'



Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 1.5 lanes (>18ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Heavy
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible,adjacent,no veg/debris clearance
Firewood: None
Propane Tanks: None
Water Supply: Reliable water source nearby
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments: From FMSS_Export - FRPP_PREDUSE:
Bldg.Environment Ed. Ctr (GSF)

Score: 72
Rating: None

Asset Priority Index
(API):
8



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Coquina Comfort Station

Unit - Location: CAHA - Bodie Island

FMSS ID: 28918

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? No

Lat(WGS84): 35° 49.9244' **Long(WGS84):** -75° 33.5194'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible,adjacent,no veg/debris clearance

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)




2016_CAHA_28918_BI BD Coquina Comfort Station_Front.jpg




Score: 52
Rating: Moderate



Asset Priority Index (API): 62



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>


Facility: Oregon Inlet Coast Guard shed

Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Other
Structure Use: Other
Owner: DOD
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Marina - Oregon Inlet Fishing Center
Lat(WGS84): 35° 47.7717' **Long(WGS84):** -75° 33.0322'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: Overhead hazards will limit aircraft
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Unknown contents.
Assessment Comments:


Score: 36
Rating: Low



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Electric Vehicle Storage at Oregon Inlet Campground

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Oregon Inlet

Lat(WGS84): 35° 48.0045' **Long(WGS84):** -75° 32.7276'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Electric Vehicle Storage at Oregon Inlet Campground_Front.jpg




Score: 62
Rating: Moderate



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: storage building

Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Oregon Inlet
Lat(WGS84): 35° 48.0032' **Long(WGS84):** -75° 32.7273'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: None or noncombustible
Firewood: Adjacent to/under deck of facility
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments:



2016_CAHA__storage building_Front.jpg


Score: 40
Rating: Low




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet CG Kiosk

Unit - Location: CAHA - Bodie Island

FMSS ID: 28935

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Oregon Inlet

Lat(WGS84): 35° 48.0051' **Long(WGS84):** -75° 32.7226'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Entrance Station (GSF)




2016_CAHA_28935_BI BD Oregon Inlet CG Kiosk_Front.jpg




Score: 51
Rating: Moderate



Asset Priority Index (API): 50



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet CG Loop C Comfort Station

Unit - Location: CAHA - Bodie Island

FMSS ID: 28944

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Oregon Inlet

Lat(WGS84): 35° 47.8687' **Long(WGS84):** -75° 32.7045'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments:



2016_CAHA_28944_BI BD Oregon Inlet CG Loop C Comfort Station_Front.jpg


Score: 51
Rating: Moderate




Asset Priority Index (API): 52



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet CG Loop A Comfort Station

Unit - Location: CAHA - Bodie Island

FMSS ID: 28940

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Oregon Inlet

Lat(WGS84): 35° 48.0367' **Long(WGS84):** -75° 32.7037'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)




2016_CAHA_28940_BI BD Oregon Inlet CG Loop A Comfort Station_Front.jpg




Score: 58
Rating: Moderate



Asset Priority Index (API): 50



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet CG Loop A Shower Building

Unit - Location: CAHA - Bodie Island

FMSS ID: 28939

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Oregon Inlet

Lat(WGS84): 35° 48.0408' **Long(WGS84):** -75° 32.7008'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)



2016_CAHA_28939_BI BD Oregon Inlet CG Loop A Shower Building_D.jpg




Score: 59
Rating: Moderate



Asset Priority Index (API): 52



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet CG Loop C Shower Building

Unit - Location: CAHA - Bodie Island

FMSS ID: 28943

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Oregon Inlet

Lat(WGS84): 35° 47.864' **Long(WGS84):** -75° 32.6999'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)




2016_CAHA_28943_BI BD Oregon Inlet CG Loop C Shower Building_Front.jpg

Score: 52
Rating: Moderate


Asset Priority Index (API):
52



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet CG Loop Shower Building

Unit - Location: CAHA - Bodie Island

FMSS ID: 28941

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Oregon Inlet

Lat(WGS84): 35° 47.9333' **Long(WGS84):** -75° 32.6883'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments:




2016_CAHA_28941_BI BD Oregon Inlet CG Loop Shower Building_Front.jpg

Score: 52
Rating: Moderate


Asset Priority Index (API): 52



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
— NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet CG Loop B Comfort Station

Unit - Location: CAHA - Bodie Island

FMSS ID: 28942

Structure Type: Building

Structure Use: Public

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Oregon Inlet

Lat(WGS84): 35° 47.9377' **Long(WGS84):** -75° 32.6807'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 30 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)



2016_CAHA_28942_BI BD Oregon Inlet CG Loop B Comfort Station_Front.jpg




Score: 58
Rating: Moderate



Asset Priority Index (API): 52



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Haz-Mat Building

Unit - Location: CAHA - Bodie Island

FMSS ID: 28909

Structure Type: Building

Structure Use: Other

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.7605' **Long(WGS84):** -75° 33.8725'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: Combustible but separated from facility

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: hazmat Building


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg.

Warehouse Chem (GSF)



2016_CAHA_28909_BI BD Haz-Mat Building_Front.jpg


Score: 24
Rating: Low



Asset Priority Index (API): 40



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Gas Shed

Unit - Location: CAHA - Bodie Island
FMSS ID: 28893
Structure Type: Building
Structure Use: Other
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Bodie Island Maintenance
Lat(WGS84): 35° 50.7491' **Long(WGS84):** -75° 33.8651'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Closed, < 6in masonry exposed
Fences/Decks: Combustible but separated from facility
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: Overhead hazards will limit aircraft
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: fuel oil tanks next to
Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)




2016_CAHA_28893_BI BD Gas Shed_Front.jpg



Score: 59
Rating: Moderate
Asset Priority Index (API): 30



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Lumber Shed

Unit - Location: CAHA - Bodie Island

FMSS ID: 28890

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.7711' Long(WGS84): -75° 33.8634'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible but separated from facility

Firewood: Adjacent to/under deck of facility

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: Fuel oil tanks.


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)



2016_CAHA_28890_BI BD Lumber Shed_Front.jpg




Score: 38
Rating: Low



Asset Priority Index
(API):
27



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Traffic Cone Shed

Unit - Location: CAHA - Bodie Island

FMSS ID: 28891

Structure Type: Building

Structure Use: Other

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.7628' Long(WGS84): -75° 33.8564'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible but separated from facility

Firewood: Adjacent to/under deck of facility

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: ZEP cleaner in barrel inside.


Fuel oil tank behind.

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Shed/Outbuilding (GSF)



2016_CAHA_28891_BI BD Traffic Cone Shed_Front.jpg


Score: 38
Rating: Low



Asset Priority Index
(API):
27



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Maintenance Shop

Unit - Location: CAHA - Bodie Island

FMSS ID: 28888

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.748' **Long(WGS84):** -75° 33.8397'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat: gas pumps nearby


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)

adjacent to urban area of Nags Head



2016_CAHA_28888_BI BD Maintenance Shop_Front.jpg


Score: 25
Rating: Low



Asset Priority Index (API):
40



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Utility Shed near Bodie Island Mtce Area

Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Building
Structure Use: Admin
Owner: NPS
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021


Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Bodie Island Maintenance
Lat(WGS84): 35° 50.6697' **Long(WGS84):** -75° 33.8355'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: No defensible space
Fuel Load (w/in 300 ft): Very Heavy
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: Overhead hazards will limit aircraft
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat:
Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Utility Shed near Bodie Island Mtce Area_Front.jpg


Score: 72
Rating: High



Asset Priority Index (API):
N/A



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Carpenter Shop

Unit - Location: CAHA - Bodie Island

FMSS ID: 28887

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.7325' **Long(WGS84):** -75° 33.8292'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Noncombustible or not applicable

Siding Material: Rock, concrete, metal

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: diesel tanks nearby

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Service Shop/Maint (GSF)



2016_CAHA_28887_BI BD Carpenter Shop_Front.jpg


Score: 25
Rating: Low



Asset Priority Index (API): 40



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI QT Q120

Unit - Location: CAHA - Bodie Island

FMSS ID: 28903

Structure Type: Building

Structure Use: Residence

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.6558' **Long(WGS84):** -75° 33.802'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Heavy

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Housing, Support (GSF)



2016_CAHA_28903_BI QT Q120_Front.jpg




Score: 55
Rating: Moderate



Asset Priority Index (API): 33



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI QT Q117

Unit - Location: CAHA - Bodie Island

FMSS ID: 28898

Structure Type: Building

Structure Use: Residence

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.6869' **Long(WGS84):** -75° 33.7886'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Housing, Support (GSF)



2016_CAHA_28898_BI QT Q117_Front.jpg


Score: 28
Rating: Low



Asset Priority Index (API): 33



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI QT Q119

Unit - Location: CAHA - Bodie Island

FMSS ID: 28901

Structure Type: Building

Structure Use: Residence

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.6429' **Long(WGS84):** -75° 33.787'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: <30 ft treated

Fuel Load (w/in 300 ft): Moderate

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Housing, Support (GSF)



2016_CAHA_28901_BI QT Q119_Front.jpg




Score: 49
Rating: Moderate



Asset Priority Index (API): 33



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI QT Q118

Unit - Location: CAHA - Bodie Island

FMSS ID: 28900

Structure Type: Building

Structure Use: Residence

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Bodie Island Maintenance

Lat(WGS84): 35° 50.6737' **Long(WGS84):** -75° 33.7741'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None

Triage Category:


Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Housing, Support (GSF)



2016_CAHA_28900_BI QT Q118_Front.jpg


Score: 26
Rating: Low



Asset Priority Index (API): 33



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Oregon Inlet Radio Tower

Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: CommSite
Structure Use: Other
Owner: DOD
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Marina - Oregon Inlet Fishing Center
Lat(WGS84): 35° 47.7613' **Long(WGS84):** -75° 33.0297'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: Overhead hazards will limit aircraft
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat: Propane tank.
Assessment Comments:



2016_CAHA__Oregon Inlet Radio Tower_Front.jpg


Score: 37
Rating: Low




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
 ■ Environment
 ■ Structure
 ■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Oregon Inlet Coast Guard Shed


Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Other
Structure Use: Other
Owner: DOD
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021

Rating: High
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Marina - Oregon Inlet Fishing Center
Lat(WGS84): 35° 47.7793' **Long(WGS84):** -75° 33.0259'



Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: Overhead hazards will limit aircraft
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: Unknown contents.
Assessment Comments:

Score: 78
Rating: High

Asset Priority Index
(API):
N/A



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Oregon Inlet Coast Guard - Admin

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Admin

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.7704' **Long(WGS84):** -75° 33.0027'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat:

Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA__Oregon Inlet Coast Guard - Admin_Front.jpg


Score: 56
Rating: Moderate




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Oregon Inlet Coast Guard - Boathouse

Unit - Location: CAHA - Bodie Island

FMSS ID:

Structure Type: Building

Structure Use: Other

Owner: DOD

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.7457' **Long(WGS84):** -75° 32.9842'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: Present and fuels clearance

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT


Triage Category:

Hazmat: Fuel tanks near structure.


Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Oregon Inlet Coast Guard - Boathouse_Front.jpg




Score: 54
Rating: Moderate



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: HAZMAT Storage

Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Building
Structure Use: Other
Owner: DOD
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local ID]
In a Community? Yes
Lat(WGS84): 35° 47.7323' **Long(WGS84):** -75° 32.982'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: Marked and clearly visible
Defensible Space: >100ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft): Grass,tundra,northern hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, >30in masonry exposed or N/A
Fences/Decks: None or noncombustible
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: HAZMAT.
Assessment Comments:



2016_CAHA_HAFrontMAT Storage_Front.jpg


Score: 16
Rating: Low




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Oregon Inlet Coast Guard - Gatehouse

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Unknown

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.8046' **Long(WGS84):** -75° 32.9773'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE:




2021_CAHA_not found_Oregon Inlet Coast Guard - Gatehouse_Front.jpg

Score: 56
Rating: Moderate


Asset Priority Index (API):
N/A



Factors Driving the Ratings



Access
Environment
Structure
Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Tool Shed

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Other

Owner: DOD

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Marina

Lat(WGS84): 35° 47.7317' **Long(WGS84):** -75° 32.9752'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: Present and fuels clearance

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: Propane tanks and fuel tanks adjacent.

Assessment Comments:



2016_CAHA__Tool Shed_Front.jpg


Score: 31
Rating: Low




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Oregon Inlet Coast Guard - Dock Shed

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Other

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.7531' **Long(WGS84):** -75° 32.9695'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: >100ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Closed, < 6in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: Fuel tank nearby.

Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Oregon Inlet Coast Guard - Dock Shed_Front.jpg


Score: 55
Rating: Moderate




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Fishing Center Storage - soundside booth

Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Building
Structure Use: Concession
Owner: Private
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Marina - Oregon Inlet Fishing Center
Lat(WGS84): 35° 47.8031' **Long(WGS84):** -75° 32.9015'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: >100ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft):
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: Present and fuels clearance
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: Overhead hazards will limit aircraft
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: None
Triage Category:
Hazmat: propane tank within 20ft
Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Fishing Center Storage - soundside booth_Front.jpg


Score: 29
Rating: Low




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Fishing Center Storage - flammable

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Concession

Owner: Private

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.8158' **Long(WGS84):** -75° 32.8924'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: Marked and clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft):

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: Combustible, adjacent, clear of veg/debris

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: flammable storage

Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Fishing Center Storage - flammable_Front.jpg


Score: 29
Rating: Low




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Fishing Center Storage - sign

Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Building
Structure Use: Concession
Owner: Private
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021


Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Marina - Oregon Inlet Fishing Center
Lat(WGS84): 35° 47.8196' **Long(WGS84):** -75° 32.8903'

Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft):
Topography (w/in 300ft): Slope <5%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: Overhead hazards will limit aircraft
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: large fuel tanks within 300ft
Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Fishing Center Storage - sign_Front.jpg


Score: 33
Rating: Low




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
 ■ Environment
 ■ Structure
 ■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet Fishing Center

Unit - Location: CAHA - Bodie Island

FMSS ID: 80998

Structure Type: Building

Structure Use: Concession

Owner: Private

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.8053' **Long(WGS84):** -75° 32.89'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, 6in to 30in masonry exposed

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: Present and fuels clearance

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: Overhead hazards will limit aircraft

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: there are propane tanks and fuel tanks within 100ft of building

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Office (GSF)



2016_CAHA_80998_BI BD Oregon Inlet Fishing Center_Front.jpg


Score: 35
Rating: Low




Asset Priority Index (API): 65



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Fishing Center Storage - old truck box


Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Other
Structure Use: Concession
Owner: Private
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021

Rating: Low
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Marina - Oregon Inlet Fishing Center
Lat(WGS84): 35° 47.8218' **Long(WGS84):** -75° 32.8875'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: 100 ft treated
Fuel Load (w/in 300 ft): Light
Fuel Type (w/in 300ft):
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Open or deck
Fences/Decks: Combustible, adjacent, clear of veg/debris
Firewood: Adjacent to/under deck of facility
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: fuel tanks within 300ft
Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Fishing Center Storage - old truck box_Front.jpg




Score: 26
Rating: Low



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
 ■ Environment
 ■ Structure
 ■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet Fishing Center Comfort Station

Unit - Location: CAHA - Bodie Island

FMSS ID: 28948

Structure Type: Toilet

Structure Use: Public

Owner: Private

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? Yes

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.8262' **Long(WGS84):** -75° 32.8845'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Closed, >30in masonry exposed or N/A

Fences/Decks: Combustible but separated from facility

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: fuel tanks within 100ft

Assessment Comments: From FMSS_Export - FRPP_PREDUSE: Bldg. Comfort Station (GSF)




2016_CAHA_28948_BI BD Oregon Inlet Fishing Center Comfort Station_Front.jpg


Score: 32
Rating: Low




Asset Priority Index (API): 70



Factors Driving the Ratings



Access
Environment
Structure
Protection



● Facility
■ NPS Boundary



NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: BI BD Oregon Inlet Fishing Center Exhibit Building

Unit - Location: CAHA - Bodie Island

FMSS ID: 110389

Structure Type: Building

Structure Use: Public

Owner: Private

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.8239' **Long(WGS84):** -75° 32.8683'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: large fuel tanks within 100ft and used oil container is behind building .

Assessment Comments: From FMSS_Export - FRPP_PREDUSE:


Bldg.Environment Ed. Ctr (GSF)




2016_CAHA_110389_BI BD Oregon Inlet Fishing Center Exhibit Building_Front.jpg




Score: 33
Rating: Low



Asset Priority Index (API): 57



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: oregon fishing center fuel tanks.


Unit - Location: CAHA - Bodie Island
FMSS ID: not found
Structure Type: Other
Structure Use: Concession
Owner: Private
Field Crew: L. Catlin
Last Site Visit Date: 4/16/2021

Rating: Moderate
Protection Level : Not Designated
Resources of Concern Present? Unknown
Occupied? No
Local ID: [Local_ID]
In a Community? Yes - Marina - Oregon Inlet Fishing Center
Lat(WGS84): 35° 47.8369' **Long(WGS84):** -75° 32.8563'


Primary Access: Road
Ingress/Egress: One roads in/out
Access Width: 2 lanes (>24ft)
Access Condition: Surfaced-paved, grade<5%
Bridge Condition: None/nonflammable,load limit will not limit response
Access & Turnarounds: Access is <300 ft from facility w/turnaround
Facility Number/Sign: None or not clearly visible
Defensible Space: <30 ft treated
Fuel Load (w/in 300 ft): Moderate
Fuel Type (w/in 300ft): Grass,shrub,hardwood litter
Topography (w/in 300ft): Slope <5%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Fences/Decks: Combustible,adjacent,no veg/debris clearance
Firewood: None
Propane Tanks: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Overhead Hazards: No overhead hazards
Safety Zones: Potential safety zone(s) in area
Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT
Triage Category:
Hazmat: large fuel tanks within
Assessment Comments:




2016_CAHA__oregon fishing center fuel tanks._Front.jpg



Score: 56
Rating: Moderate
Asset Priority Index (API):
 N/A



Factors Driving the Ratings





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Fishing Center Fuel Kiosk

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Concession

Owner: Private

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Low

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.8175' **Long(WGS84):** -75° 32.8451'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft):

Topography (w/in 300ft): Slope <5%

Roof Material: Fire resistant- tar,rubberized

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: Hazmat, UXO,etc. , PLEASE COMMENT

Triage Category:


Hazmat: this is a fuel station kiosk

Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA__Fishing Center Fuel Kiosk_Front.jpg


Score: 27
Rating: Low




Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection





NPS Wildand Fire Risk Assessment - Facility Assessment

For more information visit <https://wildfire-risk-assessments-nifc.hub.arcgis.com>

Facility: Fishing Center - shed beyond fuel kiosk

Unit - Location: CAHA - Bodie Island

FMSS ID: not found

Structure Type: Building

Structure Use: Other

Owner: NPS

Field Crew: L. Catlin

Last Site Visit Date: 4/16/2021

Rating: Moderate

Protection Level : Not Designated

Resources of Concern Present? Unknown

Occupied? No

Local ID: [Local_ID]

In a Community? Yes - Marina - Oregon Inlet Fishing Center

Lat(WGS84): 35° 47.7927' **Long(WGS84):** -75° 32.807'

Primary Access: Road

Ingress/Egress: One roads in/out

Access Width: 2 lanes (>24ft)

Access Condition: Surfaced-paved, grade<5%

Bridge Condition: None/nonflammable,load limit will not limit response

Access & Turnarounds: Access is <300 ft from facility w/turnaround

Facility Number/Sign: None or not clearly visible

Defensible Space: 100 ft treated

Fuel Load (w/in 300 ft): Light

Fuel Type (w/in 300ft): Grass,shrub,hardwood litter

Topography (w/in 300ft): Slope <5%

Roof Material: Combustible or no roof

Siding Material: Wood or open sided

Foundation: Open or deck

Fences/Decks: None or noncombustible

Firewood: None

Propane Tanks: None

Water Supply: Pressurized hydrant(s) or fixed sprinkler system

Overhead Hazards: No overhead hazards

Safety Zones: Potential safety zone(s) in area

Additional Obstacles: None


Triage Category:

Hazmat:


Assessment Comments: From FMSS_Export - FRPP_PREDUSE:



2016_CAHA_Fishing Center - shed beyond fuel kiosk_Front.jpg




Score: 52
Rating: Moderate



Asset Priority Index (API):
N/A



Factors Driving the Ratings



■ Access
■ Environment
■ Structure
■ Protection

