
NPS Wildfire Risk Assessments
Assessment Locations

MEVE - Mesa Verde National Park - Overview

National Park Service
U.S. Department of the Interior



N

0 10 20 Miles


Author: sszturm
9/24/2024 6:18 AM

NPS Wildfire Risk Assessments
NPS Fire GIS
September 2024
Data Sources: ESRI Basedata, NPS Park Data

NPS Wildfire Risk Assessments
Assessment Locations

MEVE - Wetherhill - Overview

National Park Service
U.S. Department of the Interior



N

0 2.5 5 Miles

Author: sszturm
9/25/2024 8:38 AM


NPS Wildfire Risk Assessments
NPS Fire GIS
September 2024
Data Sources: ESRI Basedata, NPS Park Data

Rock Springs Ranger Station

MEVE - Mesa Verde National Park

National Park Service
U.S. Department of the Interior

Map Label	FMSS ID	Common Name
174	50265	*(WM) Rock Springs Ranger Station # 82



N

Author: sszturm
9/24/2024 10:25 AM

0 500 Feet


Scale: 1:3,000

NPS Wildfire Risk Assessments
NPS Fire
September 2024
Data Sources: ESRI Basedata, NPS

Wetherhill

MEVE - Mesa Verde National Park

National Park Service
U.S. Department of the Interior



Map Label	FMSS ID	Common Name
182	98795	*(WM) Main Parking Areas Comfort Station # 234
185	93582	CONC (WM) Wetherill Mesa Concession Pavilion/Snack Bar #235
175	NA	Water Tank
176	NA	Vehicle Shelter
177	NA	Fuel Tank
178	NA	Storage Shed
179	NA	Tram Shelter
180	NA	Long House Temp Shelter
181	NA	Picnic Shelter
183	NA	Picnic Shelter
184	NA	Wetherill Storage Shed
186	98795	*(WM) Main Parking Areas Comfort Station # 234
187	NA	Tram Stop Shelter
188	48273	*(WM) Badger House Shelter # 224
189	48281	*(WM) Pueblo Village Shelter # 226
190	48286	*(WM) Basket Maker Pit House Shelter # 225
191	48277	*(WM) Two Raven House Shelter # 227
192	NA	Tram Stop Shelter
193	NA	Tram Stop Shelter

N

Author: sszturm
9/24/2024 8:54 AM

0 0.25 0.5 0.75 1 Miles

Scale: 1:24,000

NPS Wildfire Risk Assessments
NPS Fire GIS
September 2024
Data Sources: ESRI Basedata, NPS

NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Picnic Shelter
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Shade/Picnic Structure, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.76171768' N 108° 32.28115518' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Wetherhill
Revisit Interval: 8 yrs
Map Label: 183

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Not applicable
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: *(WM) Pueblo Village Shelter # 226
Unit - Location: MEVE - Wetherhill
FMSS ID: 48281, ***Local ID:***
Structure Type, Use: Cultural Resource, Public
Owner: National Park Service
Field Crew, Visit Date: Vaughn, March 10, 2014
Coordinates (DDM): 37° 11.22799464' N 108° 31.93974972' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Badger House
Revisit Interval: 8 yrs
Map Label: 189

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane:
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: *(WM) Basket Maker Pit House Shelter # 225
Unit - Location: MEVE - Wetherhill
FMSS ID: 48286, ***Local ID:***
Structure Type, Use: Cultural Resource, Public
Owner: National Park Service
Field Crew, Visit Date: Vaughn, March 10, 2014
Coordinates (DDM): 37° 11.21831526' N 108° 31.86283752' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Badger House
Revisit Interval: 8 yrs
Map Label: 190

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane:
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: *(WM) Two Raven House Shelter # 227
Unit - Location: MEVE - Wetherhill
FMSS ID: 48277, ***Local ID:***
Structure Type, Use: Cultural Resource, Public
Owner: National Park Service
Field Crew, Visit Date: Vaughn, March 10, 2014
Coordinates (DDM): 37° 11.34562680' N 108° 31.81134678' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Badger House
Revisit Interval: 8 yrs
Map Label: 191

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane:
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Tram Stop Shelter
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Vaughn, March 10, 2014
Coordinates (DDM): 37° 11.35858056' N 108° 31.75295808' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Badger House
Revisit Interval: 8 yrs
Map Label: 193

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane:
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: *(WM) Main Parking Areas Comfort Station # 234
Unit - Location: MEVE - Wetherhill
FMSS ID: 98795, ***Local ID:***
Structure Type, Use: Toilet, Public
Owner: National Park Service
Field Crew, Visit Date: Vaughn, March 10, 2014
Coordinates (DDM): 37° 11.37178056' N 108° 32.05235796' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Badger House
Revisit Interval: 8 yrs
Map Label: 186

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, 6in to 30in masonry exposed
Firewood: None
Water Supply: No reliable water source nearby
Propane:
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: *(WM) Rock Springs Ranger Station # 82
Unit - Location: MEVE - Wetherhill
FMSS ID: 50265, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 12.97117836' N 108° 32.75589180' W

Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 8 yrs
Map Label: 174

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: 5ft to 30ft from facility
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments: Approx 100 yd from road.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: *(WM) Main Parking Areas Comfort Station # 234
Unit - Location: MEVE - Wetherhill
FMSS ID: 98795, ***Local ID:***
Structure Type, Use: Toilet, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.77545612' N 108° 32.30020092' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, PROBLEM WITH DUPLICATE RECORD (CHECK LOCATION)
Revisit Interval: 8 yrs

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Fire resistant- tar,rubberized
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Vehicle Shelter
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.91175968' N 108° 32.41007172' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: No,
Revisit Interval: 8 yrs
Map Label: 176

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Water Tank
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Utility Site (Water, Gas,Elec), Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 12.28300758' N 108° 32.67704148' W


Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 8 yrs
Map Label: 175

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Non-surfaced- gravel,dirt,gradeLess than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: CONC (WM) Wetherill Mesa Concession Pavilion/Snack Bar #235
Unit - Location: MEVE - Wetherhill
FMSS ID: 93582, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.74764912' N 108° 32.24732040' W


Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: Yes
In Community: Yes, Wetherhill
Revisit Interval: 8 yrs
Map Label: 185

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: Adjacent to facility and no fuels clearance
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Tram Shelter
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Other, Other
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.55871572' N 108° 32.34488748' W


Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 8 yrs
Map Label: 179

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 21% to 30%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Picnic Shelter
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Shade/Picnic Structure, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.77981542' N 108° 32.32430844' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Wetherhill
Revisit Interval: 8 yrs
Map Label: 181

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope Less than 5%
Roof Material: Noncombustible or not applicable
Siding Material: Not applicable
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Long House Temp Shelter
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Other, Public
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.23975032' N 108° 32.26624314' W


Rating: High
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 8 yrs
Map Label: 180

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Shrub or timber
Fuel Load: Moderate
Defensible Space: No defensible space
Topography: Slope 5% to 20%
Roof Material: Combustible or no roof
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Fuel Tank
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Other, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.92630620' N 108° 32.39742036' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 8 yrs
Map Label: 177

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: No defensible space
Topography: Slope 21% to 30%
Roof Material: Noncombustible or not applicable
Siding Material: Not applicable
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Fuel tank, biodiesel.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: *(WM) Badger House Shelter # 224
Unit - Location: MEVE - Wetherhill
FMSS ID: 48273, ***Local ID:***
Structure Type, Use: Cultural Resource, Public
Owner: National Park Service
Field Crew, Visit Date: Vaughn, March 10, 2014
Coordinates (DDM): 37° 11.34056550' N 108° 31.98578958' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Badger House
Revisit Interval: 8 yrs
Map Label: 188

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Rock, concrete, metal
Foundation: Closed, Greater than 30in masonry exposed or N/A
Firewood: None
Water Supply: No reliable water source nearby
Propane:
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Storage Shed
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Building, Administrative
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.91388626' N 108° 32.38558158' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: No,
Revisit Interval: 8 yrs
Map Label: 178

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 2 lanes (Greater than 24')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 21% to 30%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: Pressurized hydrant(s) or fixed sprinkler system
Propane: None
Overhead Hazards: No overhead hazards

Comments: Fuel tank within 40 feet.







NPS Wildland Fire Risk Assessment - Facility Assessment


For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Tram Stop Shelter
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Building, Public
Owner: National Park Service
Field Crew, Visit Date: Vaughn, March 10, 2014
Coordinates (DDM): 37° 11.20602060' N 108° 31.79648040' W

Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Badger House
Revisit Interval: 8 yrs
Map Label: 192

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Less than 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane:
Overhead Hazards: No overhead hazards
Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/


Facility Name: Wetherill Storage Shed
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Building, Concession (other than lodging)
Owner: National Park Service
Field Crew, Visit Date: Castillo, May 24, 2021
Coordinates (DDM): 37° 11.72197956' N 108° 32.27003394' W


Rating: Moderate
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Wetherhill
Revisit Interval: 8 yrs
Map Label: 184

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Less than 300 ft with turnaround
Access and Turnarounds: Less than 300 ft with turnaround
Facility Number or Sign: None or not clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: 30 ft treated
Topography: Slope 5% to 20%
Roof Material: Noncombustible or not applicable
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane: None
Overhead Hazards: No overhead hazards

Comments:







NPS Wildland Fire Risk Assessment - Facility Assessment

For more information visit https://wildfire-risk-assessments-nifc.hub.arcgis.com/

Facility Name: Tram Stop Shelter
Unit - Location: MEVE - Wetherhill
FMSS ID: NA, ***Local ID:***
Structure Type, Use: Shade/Picnic Structure, Public
Owner: National Park Service
Field Crew, Visit Date: Vaughn, March 10, 2014
Coordinates (DDM): 37° 11.24026590' N 108° 31.99727562' W

Rating: Low
ProtectionLevel: Not Designated,
Resources of Concern: Unknown
Occupied: No
In Community: Yes, Badger House
Revisit Interval: 8 yrs
Map Label: 187

Primary Access: Road
Ingress Egress: 1 road in/out
Access Width: 1 lane (Less than 18')
Access Condition: Surfaced-paved, gradeGreater than 5%
Bridge Condition: Greater than 300ft with no turnaround
Access and Turnarounds: Greater than 300ft with no turnaround
Facility Number or Sign: Marked and clearly visible
Fuel Type: Grass and shrub, hardwood litter
Fuel Load: Light or no wildland fuels
Defensible Space: Greater than 100ft treated
Topography: Slope 5% to 20%
Roof Material: Combination of fire resisitant and combustible
Siding Material: Wood or open sided
Foundation: Open or deck
Firewood: None
Water Supply: No reliable water source nearby
Propane:
Overhead Hazards: No overhead hazards
Comments:



